


## DIN 862 TABLE OF TOLERANCES FOR CALLIPERS


Reference temperature 20°C




Length range . . . mm	0-200	200-300	300-400	400-500	500-600	600-700	700-800
Max. deviation . . . mm	±0.04	±0.05	±0.07	±0.08	±0.09	±0.10	±0.11
Length range . . . mm	800-900	900-1000	1000-1100	1100-1200	1200-1300	1300-1400	1400-1500
Max. deviation . . . mm	±0.12	±0.13	±0.14	±0.16	±0.17	±0.18	±0.19
Length range . . . mm	1500-1600	1600-1700	1700-1800	1800-1900	1900-2000	2000-	
Max. deviation . . . mm	±0.20	±0.21	±0.22	±0.23	±0.24	±0.25	

## FOUR MEASURING FUNCTIONS


Four-function callipers can be used for measuring and marking out:




External  
measurement




Internal  
measurement



Depth  
measurement



Height  
measurement



Marking  
out