INSTALLATION PROCESS

Armor Tough Coatings Signature Series





STEP 1: PREPARATION Preparation includes diamond grinding and/or shot blasting. Dust is minimized by having all grinders hooked up to vacuum systems.



STEP 2: RECONSTRUCTION Armor Tough fillers are used to fix pits and cracks before the process begins. This is a 2 component polyurethane fast setting filler.



Armor Tough's 100% solids, selfpriming basecoat is mixed and applied.



STEP 4: BROADCASTING Immediately after the basecoat application, the flake is generously broadcast by hand, providing both color and texture to the floor.



STEP 5: SCRAPING Once the basecoat is fully cured the floor is scraped and vacuumed to remove any loose or vertical standing flake.



STEP 6: CLEAR COAT The final step is to roll out the uv stable polyaspartic clear coat.



- ◆ ATC POLY TOPCOAT
- ATC CHIPS OR INDUSTRIALIZED QUARTZ SAND
- **ATC BASECOAT**
- **PROPERLY PREPARED CONCRETE**



1-888-PAINTING

DECORATIVE CHIPS

GreenSky NOW YOU CAN GET FINANCING THAT FITS YOUR BUDGET!

FLEXIBLE PAYMENT OPTIONS **AVAILABLE, JUST ASK!**

FLOOR COATING PAINT CHIPFLAKES

Our Decorative Chip Flakes are integrally colored and are produced in our standard 1/4" size.


1/8" and 1/16" chip sizes are available by special order.



STONEWASH

ASK ABOUT SPECIAL ORDER BLENDS!

Choose from our standard 17 color blends!*.





CABIN FEVER



COYOTE



CREEKBED





FEATHER GRAY














SAFARI

Lough Coatings



SHORELINE



STARGAZER



TIDAL WAVE



2130 E Hemphill Rd Burton MI 48529 248-716-0089 www.armortoughcoatings.com



