

SPEC SHEET + MEASUREMENTS

Brooks Brothers

Brooks Brothers® Tall Wrinkle-Free Stretch Nailhead Shirt. TBB18002

Product photo



Balancing a professional look with business-casual style, our nailhead dress shirt features a subtle two-color pattern and a soft hand. A premium wrinkle-free treatment process keeps it looking sharp and stylish all day.

- 4-ounce, 95/5 cotton/spandex fine yarn count
- Button-down collar
- Left chest pocket
- Taped seams
- Dyed-to-match buttons with Brooks Brothers logo
- Rounded, adjustable cuffs
- Rental-friendly

CARE INSTRUCTIONS

Machine Wash Warm With Like Colors. Only Non-Chlorine Bleach If Needed. Tumble Dry Low. Remove Promptly And Hang. Warm Iron If Needed.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



Brooks Brothers® Tall Wrinkle-Free Stretch Nailhead Shirt. TBB18002

PRODUCT MEASUREMENTS

	LT	XLT	2XLT	3XLT	4XLT
Body Length at Back	33	33 1/2	34	34 1/2	35
Chest	24	26	28	30 1/2	33 1/2
Sleeve Length from Center Back	37 1/2	38 1/4	39	39 3/4	40 1/2
Neck Circumference	17 1/2	18 1/4	19	19 7/8	20 7/8
Chest Pocket Height	5	5	5	5	5 1/4
Chest Pocket Width	4 5/8	4 5/8	4 5/8	4 5/8	4 7/8

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Neck Circumference: Measure from center of button to end of buttonhole along the center of the collar stand.

Chest Pocket Height: Measure from top to bottom at center.

SPEC SHEET + MEASUREMENTS




Brooks Brothers® Tall Wrinkle-Free Stretch Nailhead Shirt. TBB18002

SIZE CHARTS

	LT	XLT	2XLT	3XLT	4XLT
Chest	41-43	44-46	47-49	50-53	54-57
Neck	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2
Arm	36 1/2	38	39	40	41

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.

Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS



Cobalt Blue



Deep Black
PMS BLACK
C



Newport Blue
PMS 7681C



White