CARVERTICAL

Mercedes-Benz S 560

WDD2221861A375543

2018 | Gasoline | Automatic | Sedan | Grey

Generated on 30/09/2026

Scan for full report

Damage

Attention

We found 3 records for this vehicle.

Emissions

Attention

High CO_2 emission rating: 200 g/km.

Commercial use check

No issues found

No records of commercial use found.

Mileage

No issues found

Last recorded mileage: 134,077 km.

Legal status check

No issues found

No financial or legal risk records found.

Theft

No issues found

No theft records found.

+44

Data sources
We checked 1000+ data sources in **48 countries**

Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.

No issues found
No records of vehicle being used in irregular manner

Here's what we checked:

Taxi

No evidence of being used as a taxi

Transport

No evidence of being used as a transport vehicle

Rental

No evidence of being used as a rental

Police

No evidence of being used by police

Demo

No evidence of being used as a demo vehicle

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Driving school vehicle

No evidence of being used as a driving school vehicle

Theft

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.

No issues found

We didn't find any records that the vehicle was stolen.

Here's what we checked:

Is it currently wanted as stolen?

No records indicate that this vehicle is currently reported as stolen and is being searched for.

Was it stolen in the past?

No past theft records found for this vehicle.

Police database stolen vehicle check completed in **7 countries**:

Romania Slovakia Czechia Slovenia Hungary Italy Canada

Mileage

We checked if the mileage looks accurate or if it may have been tampered with.

Summary

- Last known mileage: 134,077 km
- Average mileage for similar models: 146,414 km
- 12 mileage records found

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.



Driving habits

See how intensely this car was driven over time. Lighter use usually means less wear, while intense driving may lead to faster wear on key parts.

Limited driving **< 600 km/month** 23% of analyzed period

Driven less than typical. Limited use can sometimes lead to aging of unused parts.

Normal driving **600 - 1,500 km/month** 53% of analyzed period

A typical driving pattern. Often means steady use and balanced wear.

Intense driving **> 1,500 km/month** 24% of analyzed period

Driven much more than typical. Often means parts have to work harder and may need to be replaced.

No driving 0% of analyzed period

A break in use for an extended period. Cars with long periods of no use may need extra checks (battery, brakes, tires).

Odometer records	
01/2018	**12 km**
01/2019	**18,066 km**
05/2020	**39,155 km**
04/2021	**43,969 km**
05/2022	**48,958 km**
12/2022	**54,562 km**

Odometer records	
06/2023	**69,000 km**
09/2024	**109,858 km**
12/2024	**115,000 km**
01/2025	**117,000 km**
10/2025	**126,000 km**
09/2026	**134,077 km**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Driving habits		
01/2018 - 05/2020	Normal driving	1,380 km/month
05/2020 - 05/2022	Limited driving	403 km/month
05/2022 - 12/2022	Normal driving	786 km/month
12/2022 - 01/2025	Intense driving	2,458 km/month
01/2025 - 09/2026	Normal driving	842 km/month

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.

No issues found
No records about the legal status of this vehicle were found

Legal

Insured? ✓ Insured 09/2026 Romania

Insurance valid from 08/2026 until 02/2027

Passed technical inspection (MOT)? Passed 09/2026 Romania

Has successfully passed technical inspection

Valid until 09/2028

Was it scrapped?

No record of this vehicle being marked as scrapped.

Recommended service schedule

For full past and upcoming service details, view the digital report.

Summary
- Last scheduled maintenance was 9,077 km ago – check what maintenance may have been required
- Based on recorded mileage, the next recommended service is due in 15,923 km

Next recommended service **at 150,000 km**

What should be serviced:

Service time approx. 84 min

Engine sump plug (Renew) | Engine oil filter (Renew) | Road wheels (Interchange) | Cabin filter (if fitted) (Renew) | Central locking/alarm remote control batteries (Renew) | Brake efficiency test (Carry out) | +49 service items

Service time approx. 12 min

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Air filter (Renew)

Service time approx. 12 min

Sunroof guide rails (Clean/lubricate)

Service time approx. 72 min

Spark plugs (Renew)

Service time approx. 6 min

Towing hitch (Check/report) Towing hitch (Lubricate)

Previous recommended service **at 125,000 km**

What should have been serviced:

Service time approx. 48 min

Engine sump plug (Renew) Engine oil filter (Renew) Cabin filter (if fitted) (Renew)
Central locking/alarm remote control batteries (Renew) Brake efficiency test (Carry out) +19 service items

Service time approx. 108 min

Automatic transmission fluid (ATF) (Drain/refill) Transfer box oil (Drain/refill)
Automatic transmission fluid (ATF) filter (Renew)

Service time approx. 12 min

AC drive belt (Renew) +3 service items

Service time approx. 0 min

Air conditioning (Recharge)

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

Attention
We found 3 records for this vehicle

Damage records

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

05/2023 Romania

Exterior affected

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Front left / Bumper | Front / Bumper | Front right / Bumper | Exterior body parts

Past repair cost estimate

€3,501 – €4,000

Repair cost rating

Very low 6% of the vehicle's value at that time

1 similar record

12/2024 Romania



Exterior affected

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Right / Front door | Rear / Bumper | Rear right / Bumper | Exterior body parts | Structural elements of the body

Past repair cost estimate

€7,001 – €7,500

Repair cost rating

Low 12% of the vehicle's value at that time

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Damage reported, parts not listed

Past repair cost estimate

€1,501 – €2,000

Repair cost rating

Very low 3% of the vehicle's value at that time

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

Past repair cost estimate
If the vehicle has reported damage, the past repair cost is estimated based on where the damage was assessed and is shown in that country's currency. This amount may differ from what you'd expect locally. Here's why:
Repair prices vary between countries due to differences in labor rates and parts costs.
The estimate is based on work that is done at official service centers, which are typically more expensive than independent garages.

Repair cost rating
It helps you understand the severity of past damage by comparing repair costs to the vehicle's value. When repair costs approach or exceed a large portion of the vehicle's value, it may indicate a potential total loss.

Very low	<10% of the vehicle's value at that time
Low	10-24% of the vehicle's value at that time
Moderate	25-49% of the vehicle's value at that time
High	50-74% of the vehicle's value at that time
Very high	>75% of the vehicle's value at that time

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Market price

We checked how this vehicle's market price has changed over time, based on available historical data and price estimates.

The timeline shows a limited period and does not reflect the vehicle's full lifetime pricing.

Highest price €52,000

Average price **€20,707**

Lowest price €12,244

Criteria for market price evaluation:

Make: **Mercedes-Benz** | Model: **S 560** | Fuel type: **Gasoline** | Transmission type: **Automatic** | Year: **2018** | Market: **Eastern EU**



Market price | Market price range

Year	Market price	↘ Lowest market value	↗ Highest market value
2024	**€52,153**	€28,122	€78,178
2025	**€46,017**	€24,287	€67,676
2026	**€20,707**	€12,244	€52,000

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Market price insights

Selling time
Similar vehicles typically sell within 30 days based on recent market data

Note: Forecasts are based on current market trends and historical data. Actual resale value may change due to market shifts, condition, location, or other factors.

Emissions

We analysed how much CO_2 this car model typically produces and what taxes or fees may apply.

carVertical Insight
This vehicle has high emissions. That could mean higher emission taxes. Check local regulations to avoid surprises.

CO_2 emissions

Specs

The vehicle's core technical and mechanical build.

Summary
Make sure the vehicle's specs match what the seller told you.

Vehicle specifications

Overview

Make **Mercedes-Benz**	Model **S 560**	Fuel type **Gasoline**
Model generation **217/222**	Manufacture year **2018**	Category **m1**
Manufacturer label **S 560**	Type approval **e1*2001/116*0335*36**	

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Performance & efficiency

Transmission type **Automatic**	Drive type **AWD**	Engine displacement **4 L**
Power **345 kW (463 hp / 469 PS)**	Number of cylinders **8**	Number of gears **9**
CO2 emissions **200 g/km**	Emissions standard **euro 6**	Engine code **M176**
Powertrain type **Internal combustion**		

Body & dimensions

Body type **Sedan**	Steering wheel placement **LHD**	Color **Grey**
Number of seats **5**	Length **5,302 mm**	Width **1,914 mm**
Wheel size **20 in**	Unladen weight **2,805 kg**	Gross weight **4,990 kg**

Equipment

The installed features, options, and technology.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

Summary

Make sure the vehicle's equipment matches what the seller tells you.

Feature list

As received from the manufacturer

02B Operating instructions and service booklet-German

Operating instructions and service booklet in German

08U Mercedes-Benz Connect - Services for Vehicle Setup (HERMES)

Mercedes-Benz Connect services available for vehicle setup

09U Mercedes-Benz Connect - Vehicle Monitoring (HERMES)

Mercedes-Benz Connect offers vehicle monitoring capabilities

12U Mercedes-Benz Connect - Services for Mercedes me Concierge Service (HERMES)

Connect services for Mercedes Me Concierge service

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

14U Smartphone integration package

Package for smartphone integration included

16U Apple Carplay smartphone integration

Supports Apple CarPlay smartphone integration

17U Android Auto smartphone integration

Supports Android Auto smartphone integration

1A4 Torque converter/wet clutch 4/8 cyl. gasoline AMG

8-cylinder gasoline AMG engine converter

1U6 R744 refrigerant

Use of refrigerant R744

21A Generation EHS

Generation EHS

223 Electric backrest adjustment and head restraints

Electric adjustment for backrest and head restraints

228 Additional warm water heating

Additional warm water heating system

229L Germany

Vehicle manufactured for Germany

231 Garage door opener

Includes a garage door opener

233 Adaptive cruise control Plus (DISTRONIC PLUS)

Adaptive cruise control feature

235 Active Parking Assist

Active parking assist system

23P Driving package

Driving package included

249 Automatic dimming inside rearview mirror and outside mirrors

Automatic dimming rearview mirror and side mirrors

255B Mb-Mobilo with DSB and GGD

Mobile service with repair and breakdown assistance

266 DISTRONIC PLUS transverse support (DTR+Q)

Additional transverse support for adaptive cruise control

275 Memory Package (driver's seat, steering column and mirrors)

Memory package for driver's seat, steering column, and mirrors

276 Memory feature in rear

Memory function for rear seating

293 Sidebags in rear

Equipped with side airbags in the rear

297 Electric roller sun blind in left and right rear door

Electric roller sun blind for rear doors

2A1 Converter variant 2

Second Version of Converter

2XXL Federal Republic of Germany

Manufactured in the Federal Republic of Germany

305 Rear PRE-SAFE

Rear PRE-SAFE system for added safety

306 Rear seat belt with integrated airbag

Rear seat belt integrated with airbag for enhanced protection

308 Refrigerator box / insulated compartment in the rear passenger compartment

The vehicle has a refrigerator box or insulated compartment in the rear passenger area.

310 Double cup holder

Double cup holder included for convenience

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

320 Single CD drive preinstallation

Preinstalled single CD drive

332B Language of instrument cluster/HU - German

Instrument cluster language in German

351 Ecall emergency call system

E-Call emergency call system integrated

362 HERMES communications module LTE

Hermes communications module with LTE capabilities

367 Pre-installation for Live Traffic Information

Preparation for receiving live traffic information

380 Car telephony package

Car telephony package

3U1 Head unit for Europe/CIS states/Mongolia

Entertainment head unit configured for Europe/CIS states/Mongolia

401 Climatised front seats

Front seats with climate control function

402 Rear seat climate control

Climate control system for rear seats

406 Multicontour rear seat

Multicontour rear seating for improved comfort

413 Automatic panoramic sliding sunroof

Automatic panoramic sliding sunroof

421 9-speed automatic transmission

Nine-speed automatic transmission

432 Dynamic seats left and right

Dynamic seats with adjustments for left and right

439 Intelligent / folding front comfort head restraint

Intelligent folding front head restraints for comfort

443 Heated steering wheel

Heated steering wheel

448 Touchpad with rotary pushbutton

Touchpad with rotary pushbutton control

452 Front passenger seat chauffeur position

Chauffeur position feature for front passenger seat

453 Seat with reclining function

features SEAT WITH RECLINING FUNCTION for added comfort

463 Front visual display (head-up display)

Front visual display or head-up display feature

472 Gasoline particulate filter (OPF) without sensor system

Gasoline particulate filter without sensor system

475 Tire pressure monitor (TPM)

Tire pressure monitoring system

4A7 Shift element equipment (4 gears)

Assembly of actuators for all four wheels

500A Exclusive leather

Exclusive black and anthracite leather

501 360° camera

360-degree camera system

501A Exclusive leather - black/anthracite

Exclusive black and anthracite leather interior

502 Multi-year free map updates

Free map updates for multiple years

503 Remote-controlled parking

Remote-controlled parking assistance

50A Torque distribution 45/55

Torque distribution ratio of 45/55

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

513 **Road sign recognition system**
System for recognizing road signs

531 **COMAND APS NTG5/NTG5.5**
Comand APS navigation system

537 **Digital Radio standard DAB (Digi. Audio Broadc.)**
Standard digital radio with DAB technology

53V **Speed/load index 99Y XL + 102Y XL**
Speed/load index rating 99Y XL + 102Y XL for performance

540 **Electric roller blind for rear window**
Electric roller blind for rear window

543 **Sun visor with additional function**
Sun visor with additional function included

546 **Automatic speed control**
Automatically maintains the vehicle's speed as set by the driver

551 **Standard anti-theft alarm system (ATA)**
Standard anti-theft alarm system

581 **Automatic climate control**
Automatic climate control feature

582 **Air conditioning, rear**
Rear air conditioning system

596 **IR-active glazing**
IR-reflective glazing for enhanced comfort

5A1 **Electrohydraulic controller unit converter**
Electrohydraulic controller unit for the converter

610 **Night view system**
Night view system for better visibility during night-time driving

61U **black microfiber headliner**
Black microfiber headliner

628 **Automatic high beam control plus (IHC+)**
Automatic high beam control

642 **Dynamic LED headlamps, right-hand traffic**
Dynamic LED headlamps for right-hand traffic

682 **Fire extinguisher**
Includes fire extinguisher

6A2 **Joint flange with GW 110/3, 3-arm X 110**
Joint flange with specifications 110 / 3, 3-arm x 110

6P5 **Control code for Sales**
Control code used for sales purposes

70B **Safety vest - driver**
Driver's safety vest provided

735 **Additional scope of trim elements**
Additional trim elements for customization

772 **AMG styling - Front spoiler, side skirts**
AMG styling with front spoiler and side skirts

775U **Iridium silver - Metallic finish**
Painted in iridium silver metallic finish

776 **Wider wheel arch for AMG wheels**
Wider wheel arches to accommodate AMG wheels

808 **YoM X7/1**
Year of manufacture code

810 **Premium sound system**
Premium sound system installed

856 **Telephone handset in rear armrest**
equipped with TELEPHONE HANDSET IN REAR ARMREST for rear passengers

864 **Rear Seat Entertainment System (2 screens)**
Rear seat entertainment system equipped with 2 screens

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

865 digital TV

Digital TV

871 Hands-free access

Hands-free access features allow you to unlock and access the vehicle without using a key.

874 Magic Vision Control incl. heated windshield washer system

Magic Vision Control with heated windshield washer

881 Boot lid convenience closing feature

Convenient boot lid closing feature

882 Sensor system and siren for anti-theft alarm system

Security system with sensor and siren

883 Power locking

Power locking feature

884 Trunk lid auxiliary lock (TAL)

includes TRUNK LID AUXILIARY LOCK (TAL) for extra security

889 KEYLESS-GO

Keyless-go system for entry and start

891 Premium ambiance illumination

Premium ambiance illumination

896 Vehicle access and authorization via smartphone

Vehicle access and authorization via smartphone

898 Wireless telephone charging in rear passenger compartment

Wireless charging capability for mobile phones in the rear seating area

899 Front wireless telephone charging and antenna

Front wireless telephone charging and antenna feature

8U0 Heated washer fluid reservoir

Reservoir for heated washer fluid

8U6 Assistance system steering wheel control changeover

Assistance system control switch on steering wheel

8U8 i-Size marking (Isofix successor)

I-Size marking for child seat attachment

902 Front comfort seat heating

Heated front comfort seats

903 Rear comfort seat heating

Heated rear comfort seats

906 Front heated rests

Heated front armrests

907 Rear heated rests

Heated rear armrests

927 Exhaust treatment, Euro 6 technology

Exhaust system compliant with Euro 6 technology

936 Cylinder cut-out system

System that cuts out cylinders for efficiency

950 AMG line

AMG Line package included

969 Euro 6 technology COC document - with motor vehicle registration certificate, part 2

Euro 6 technology document for registration

97B Engine noise reduction via speakers (EOC)

Engine noise reduction via speakers (EOC)

99B Active adjustment damping "Normally Open"

Active Adjustment Damping system offers flexible suspension settings

A035 Oil offset quantity +350 g oil

An additional 350 grams of oil to offset any quantity discrepancies in the oil level

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

A104 Noise-optimized toothing
Noise-optimized gearing for reduced sound

B09 Refrigerant compressor with magnetic clutch
Refrigerant compressor with magnetic clutch

B24 Remote control for Auxiliary heating
Remote control for auxiliary heating system

B51 TIREFIT
Equipped with Tirefit system

E16 Rim lock set
Set of rim locks for securing wheels

F222 Model series 222
Belongs to model series 222

FV Long sedan
Long sedan body style

G041 Transmission code version 41
Transmission code version 41 installed

GA Automatic transmission
Equipped with automatic transmission

GA7 Automatic transmission
Automatic transmission included

H16 Trim elements - Black striped piano lacquer wood
Black striped piano lacquer wood trim elements

HA Rear axle
Rear axle configuration

K11 Adaptive brake light, flashing
Adaptive brake light with flashing feature

K13 Control code for service interval 25000 km
Service interval control code 25000 KM

K27 Software control for unpowered in position "D"
Software control for unpowered in position D

K31 Noise regulations as per ECE R51-03
Compliance with noise regulations per ECE R51-03

K32 Active Lane Change Assist
Assists in changing lanes safely

K33 Extended restart in stop-and-go traffic
Allows extended engine restart in stop-and-go traffic conditions

K34 Route-based speed adaptation
Adapts vehicle speed based on the route taken

L Left-hand drive
Left-hand drive configuration

L2D Luxury leather steering wheel with trim element
Luxury leather steering wheel with trim element

LS2 Body-in-white load stage 2
Body-in-white load stage 2

M005 Vehicles with 4MATIC/all-wheel drive
Vehicle equipped with 4Matic all-wheel drive system

M176 V8 spark-ignition engine M176
V8 spark-ignition engine

M40 Displacement 4.0 liter
Displacement 4.0 Liter

N8A Plant control code
Plant control code for manufacturing location

P07 Chauffeur package with memory function
Chauffeur package with memory function

P09 Sun protection package
Sun protection package

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

P17 KEYLESS-GO package

Keyless-go package included

P21 Air quality package

Air quality package included

P34 Exclusive Package

Exclusive package

P35 Light Package

Includes a light package

P36 Safety package in rear passenger compartment

Safety features located in the back passenger area of the vehicle.

P43 Seat Comfort Package in rear passenger compartment

Seat comfort package designed for rear passenger compartment

P46 Rear-Seat Entertainment Package

Rear-seat entertainment package for enhanced in-car entertainment

P54 Anti-Theft Protection package

Anti-theft protection package

P64 Front memory package

Front memory package included

P69 Front and rear comfort heating package

Package providing comfort heating for both the front and rear seats

P72 Active comfort package

Active Comfort package

PBG MBUX Navigation Premium

MBUX Navigation Premium

PBH Remote Parking package

Package for remote parking

R01 Summer tyres

Summer tires equipped

RRM AMG spoke wheels 20" mixed tires

20-inch AMG spoke wheels with mixed tires

U01 Rear seat belt status indicator

Indicator for rear seat belt status

U10 Front passenger seat with weight sensor

Front passenger seat with weight sensor

U25 Illuminated door sill

Door sills with illumination feature

U26 Floor mats - AMG

Floor mats are branded as AMG

U28 Higher-power braking system

Higher-power braking system

U58 Headphones for Rear Seat Entertainment System (quantity 2)

Includes two headphones for the rear seat entertainment system

U60 Pedestrian protection - Active hood

Active hood system for pedestrian protection

U72 DVD player with region code 2 Europe, Japan

DVD player with region code 2 for selected regions

U82 USB charge socket in rear passenger compartment

USB charge socket in rear passenger compartment

VL Left front axle half

Left front axle assembly

VR Right front axle half

Right front axle assembly

Timeline

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

7 records found

The timeline of records for this vehicle

01/2018 Country unknown

Manufactured

This vehicle's manufacturing date has been recorded. The listed country may reflect a production or registration location.

05/2023 Romania

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

09/2024 Romania

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

12/2024 Romania

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

10/2025 Romania

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

08/2026 Romania

Insured

An insurance record was found for this vehicle in this country (or state). It may refer to liability, comprehensive, or reinsurance policies.

From: **29/08/2026** To: **28/02/2027**

09/2026 Romania

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

+44

Data sources
We checked 1000+ data sources in **48 countries**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Based on this report:

- [ ] **Get a professional assessment**

  This car has a history of issues – past damage records, recalls, or inspection concerns. A mechanic can verify if everything was properly addressed and if the car is in good shape now.

  - [ ] Get a full inspection focusing on steering, suspension, and braking systems.
  - [ ] Request a written estimate for all repairs needed to make the car roadworthy.

- [ ] **Do a mid-life health check**

  Moderate wear means key parts are getting old and might need replacing soon. Find out what's nearing the end of its lifespan.

  - [ ] Have your mechanic inspect aging parts like the alternator, water pump, and suspension.
  - [ ] Check if the timing belt/chain is due for replacement based on age, not just mileage.

Do these checks before buying a car:

- [ ] **Get a professional inspection**

  An expert mechanic can spot hidden issues you might miss. Here's what to do next:

  - [ ] Book a pre-purchase inspection at an independent or authorised service
  - [ ] Ask the mechanic to check key systems: engine, brakes, suspension, electronics
  - [ ] Request written notes or a report of any issues found

- [ ] **Ask for service records**

  Service records show how well the car has been looked after. Here's what to do next:

  - [ ] Ask the seller for the car's service book or maintenance records
  - [ ] Check for regular oil changes, filter replacements, and timing belt work
  - [ ] Note any missing or overdue services

- [ ] **Check if the mileage matches**

  Make sure the mileage in this report matches the car's odometer readings. Your latest known mileage is **134,077 km**. Here's what to do next:

  - [ ] Check the odometer reading against the mileage in the report
  - [ ] Watch for signs of tampering (worn pedals, suspicious dashboard fixes)
  - [ ] Ask the seller about any differences

- [ ] **Take a real test drive**

  A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

  - [ ] Drive on different road types: highway, city traffic, and bumpy or uneven surfaces
  - [ ] Listen for strange noises or vibrations
  - [ ] Pay attention to handling and comfort

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Compare with similar cars

Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:

- [ ] Search for similar cars online (same make, model, year, mileage)
- [ ] Compare asking prices
- [ ] Look at car condition and equipment
- [ ] Use this info to negotiate with the seller

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.