CARVERTICAL

Audi A6

Generated on **14/09/2026**

Scan for full report

VIN: **WAUZZZF24MN029498** | Body type: **Sedan** | Fuel: **Gasoline** | Year: **2020**

Transmission Type: **Automatic** | Engine displacement: **2 L** | Power: **195 kW (261 hp / 265 PS)**

Damage

Attention

We found 3 records for this vehicle.

Emissions

Attention

High CO_2 emission rating: 172.5 g/km.

Commercial use check

No issues found

No records of commercial use found.

Mileage

No issues found

Last recorded mileage: 163,193 km.

Legal status check

No issues found

No financial or legal risk records found.

Theft

No issues found

No theft records found.

+44

Data sources
We checked 1000+ data sources in **48 countries**

Photos

We found **18 photos** of this vehicle. Scan report QR code to see all.

01/2023



Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.

No issues found
No records of vehicle being used in irregular manner

Here's what we checked:

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Taxi

No evidence of being used as a taxi

Transport

No evidence of being used as a transport vehicle

Rental

No evidence of being used as a rental

Police

No evidence of being used by police

Demo

No evidence of being used as a demo vehicle

Driving school vehicle

No evidence of being used as a driving school vehicle

Theft

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.

No issues found
We didn't find any records that the vehicle was stolen.

Here's what we checked:

Is it currently wanted as stolen?

No records indicate that this vehicle is currently reported as stolen and is being searched for.

Was it stolen in the past?

No past theft records found for this vehicle.

Police database stolen vehicle check completed in **7 countries**:

Italy Romania Slovenia Slovakia Czechia Hungary Canada

Mileage

We checked if the mileage looks accurate or if it may have been tampered with.

Summary

- Last known mileage: 163,193 km
- Average mileage for similar models: 120,433 km
- 10 mileage records found

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.



Odometer records	
11/2020	**15 km**
02/2022	**22,578 km**
08/2022	**29,975 km**
01/2023	**43,690 km**
02/2023	**43,671 km**

Odometer records	
04/2023	**43,706 km**
07/2023	**53,981 km**
01/2025	**138,000 km**
04/2025	**149,966 km**
03/2026	**163,193 km**

Driving habits

11/2020 - 01/2023	**Normal driving**	**1,657 km/month**
01/2023 - 02/2023	**Unrated driving**	
02/2023 - 07/2023	**Normal driving**	**2,062 km/month**
07/2023 - 01/2025	**Intense driving**	**4,584 km/month**
01/2025 - 03/2026	**Normal driving**	**1,783 km/month**

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.

No issues found

No records about the legal status of this vehicle were found

Legal

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Insured? ✓ Insured 07/2026 Romania

Insurance valid from 11/2025 until 11/2026

Was it exported? ⚠ Record found 05/2023

This vehicle was previously exported to another country. If it was re-registered elsewhere, some records may be missing. It's worth checking whether all its legal paperwork is in order.

Exported from Sweden

Passed technical inspection (MOT)? Passed 04/2025 Romania

Has successfully passed technical inspection

Valid until 04/2027

Was it scrapped?

No record of this vehicle being marked as scrapped.

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

Attention
We found 3 records for this vehicle

Damage records

12/2024 Romania



Reported damage

This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Front left / Bumper | Front / Bumper | Front / Windshield | Front right / Bumper | Roof / Structure

Past repair cost estimate

€2,501 – €3,000

Repair cost rating

Very low 7% of the vehicle's value at that time

Damage Groups

Exterior body parts | Glass

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

01/2025 Romania

Reported damage

This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Right / Front door

Past repair cost estimate

€251 – €500

Repair cost rating

Very low 1% of the vehicle's value at that time

Damage Groups

Exterior body parts

01/2025 Romania

Reported damage

This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Rear / Bumper Rear right / Bumper

Past repair cost estimate

€501 – €750

Repair cost rating

Very low 2% of the vehicle's value at that time

Damage Groups

Exterior body parts External lightning

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Past repair cost estimate
If the vehicle has reported damage, the past repair cost is estimated based on where the damage was assessed and is shown in that country's currency. This amount may differ from what you'd expect locally. Here's why:
Repair prices vary between countries due to differences in labor rates and parts costs.
The estimate is based on work that is done at official service centers, which are typically more expensive than independent garages.

Repair cost rating
It helps you understand the severity of past damage by comparing repair costs to the vehicle's value. When repair costs approach or exceed a large portion of the vehicle's value, it may indicate a potential total loss.

Very low	<10% of the vehicle's value at that time
Low	10-24% of the vehicle's value at that time
Moderate	25-49% of the vehicle's value at that time
High	50-74% of the vehicle's value at that time
Very high	>75% of the vehicle's value at that time

Market price

We checked how this vehicle's market price has changed over time, based on available historical data and price estimates.

The timeline shows a limited period and does not reflect the vehicle's full lifetime pricing.

Highest price	€36,499
Average price	**€29,500**
Lowest price	€22,900

Criteria for market price evaluation:

Make: **Audi** | Model: **A6** | Fuel type: **Gasoline** | Transmission type: **Automatic** | Year: **2020** | Market: **Romania**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.



Year	Market price	↘ Lowest market value	↗ Highest market value
01/2023 Selling price **€30,700**			
2024	**€34,940**	€26,500	€39,450
2025	**€32,450**	€25,300	€38,555
2026	**€29,500**	€22,900	€36,499
2027	**€28,000**	€21,736	€34,643
2028	**€24,167**	€18,760	€29,901
2029	**€20,333**	€15,784	€25,157
2030	**€16,500**	€12,808	€20,415
2031	**€14,788**	€11,479	€18,297
2032	**€13,075**	€10,150	€16,177
2033	**€11,362**	€8,820	€14,058

Market price insights

Price trend forecast
This vehicle is expected to lose -61% of its market price over the next 7 years.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Selling time
Similar vehicles typically sell within 31 days based on recent market data

Note: Forecasts are based on current market trends and historical data. Actual resale value may change due to market shifts, condition, location, or other factors.

Emissions

We analysed how much CO_2 this car model typically produces and what taxes or fees may apply.

carVertical Insight
This vehicle has high emissions. That could mean higher emission taxes. Check local regulations to avoid surprises.

CO_2 emissions



Specs

The vehicle's core technical and mechanical build.

Summary
Make sure the vehicle's specs match what the seller told you.

Vehicle specifications

Overview

Make **Audi**	Model **A6**	Fuel type **Gasoline**
Model generation **C8**	Model year **2021**	Manufacture year **2020**
Category **m1**	Model market **Sweden**	Type approval **e1*2007/46*1801*25**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Performance & efficiency

Transmission type **Automatic**	Drive type **AWD**	Engine displacement **2 L**
Power **195 kW (261 hp / 265 PS)**	Number of cylinders **4**	Number of gears **7**
CO2 emissions **172.5 g/km**	Emissions standard **euro 6; 715/2007*2018/1832 ap**	Fuel consumption (combined) **6.32 l/100km**
Engine code **DMTA**	Transmission name **ULD**	Powertrain type **Hybrid**

Body & dimensions

Body type **Sedan**	Steering wheel placement **LHD**	Color **Black**
Number of seats **5**	Length **4,939 mm**	Width **1,886 mm**
Wheel size **18 in**	Unladen weight **2,340 kg**	Gross weight **4,340 kg**

Equipment

The installed features, options, and technology.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

Summary
Make sure the vehicle's equipment matches what the seller tells you.

Feature list

As received from the manufacturer

0FA Standard manufacturing sequence
Manufacturing Sequence Followed as Standard

0JK Weight category front axle weight range 10
Front axle weight range 10

0K4 Mild hybrid
Mild hybrid technology included

0LE With special labels safety certificates for Sweden
Includes safety certificates specific to Sweden

0M0 Fuel tank
Fuel tank

0N1 Without all-wheel steering
Without all-wheel steering system

0NA Without nameplate set (without model designation)
Without nameplate set

0P0 Standard exhaust system
Standard exhaust system for optimal performance

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

0RC Starter switch locking system

Starter switch locking system

0TD Floor mats in front and rear

Front and rear floor mats

0VV Manual in Swedish

Manual in Swedish language

0Y3 Cold zones

Cold zones for temperature control in specific areas.

0YV Weight range 20 installation control only, no requirement forecast

Installation control for a weight range of 20 units

1A2 Fuel system for SI engine with direct injection (FSI)

Fuel System with Direct Injection

1BA Series production suspension

Standard production suspension setup

1D8 Trailer hitch preparation

Preparation for a trailer hitch attachment on the vehicle

1EX Special identification label (EU)

Special identification label for the European Union

1G8 Tire mobility system

Tire mobility system

1I0 Passenger presence detection

Includes Passenger presence detection

1KF Disc brakes in rear, 17-inch (ECE)

17-inch rear disc brakes

1LE Disc brakes in front, 17-inch (ECE)

This vehicle comes equipped with front disc brakes and 17-inch (ECE) wheels.

1P0 Standard suspension

Standard suspension setup

1PR Anti-theft wheel bolts and loose wheel warning

Anti-theft wheel bolts and loose wheel warning included

1S2 Tool kit

Tool Kit

1SJ Additional front underbody guard

Additional front underbody guard

1T3 First aid kit with warning triangle and safety vests

Includes First aid kit with warning triangle and safety vests

1TN Vehicle class differentiation-4K0/4KA-

Differentiation of vehicle class as 4K0/4KA

1VG Installation parts for four-cylinder engine

Installation parts for four-cylinder engine

1X1 quattro

quattro all-wheel drive

1XW Leather-wrapped multi-function sports steering wheel with shift paddles

Comes with a leather-wrapped multi-function sports steering wheel that includes shift paddles.

1Z1 Increase in initial standard fuel filling

Increase in initial standard fuel filling

20A Without electric motor (hybrid)

No electric motor (hybrid system) included

2C5 Safety steering column

Safety steering column for enhanced driver protection

2F0 Without locking and starting systems

No Locking and Starting Systems Added

2H9 Audi drive select

Audi Drive Select

2K6 Sport line bumpers

Sporty bumpers for a dynamic look

2KR Labels in English and German

Labels in English and German

2V5 Without air quality package

No air quality package included

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

2WA **Without additional tires**

No Additional Tires Provided

2Z7 **Without engine power/technology nameplate**

No engine power/technology nameplate included

3B3 **ISOFIX child seat anchors and top tether for outer rear seats**

ISOFIX child seat anchors for outer rear seats

3CA **Without partition**

Without partition

3FA **Without roof insert (standard roof)**

No Roof Insert Provided

3G0 **Without child seat anchora in front (ISOFIX)**

No front ISOFIX child seat anchors

3GA **Without luggage/load compartment floor**

Without luggage/load compartment floor

3HL **Without leather parts scope**

No leather components included in the vehicle's interior

3L3 **Front seats, manually adjustable**

Manually adjustable front seats

3M3 **Passenger car design**

Passenger car design

3NT **Folding rear bench seat (rear seats: 2+1-seater)**

Folding rear bench seat (rear seats: 2+1-seater) included

3S0 **Elimination of roof rails**

No roof rails

3Y0 **Without roll-up sunshade**

Without roll-up sunshade

40R **Alloy wheels, 5-arm style, 8.0J x 18, model-specific tires**

The vehicle is equipped with alloy wheels in a 5-arm style, size 8.0J x 18, with tires specific to this model.

4A3 **Seat heaters in front**

Heated front seats

4BI **Emission standard EU6 AP**

Emission standard EU6 AP for compliance

4D0 **Without seat ventilation/massage seat**

No Seat Ventilation/Massage Feature

4E2 **Luggage compartment lid, automatically opening**

Luggage compartment lid that automatically opens for convenience.

4GF **Windshield with heat-insulating glass**

Windshield with heat-insulating glass included

4I6 **Remote control key with SAFELOCK**

Remote control key with SAFELOCK

4KC **Heat-insulating glass**

Heat-insulating glass

4L6 **Auto-dimming interior rearview mirror, frameless**

Auto-dimming interior rearview mirror

4UF **Driver and front passenger airbag with front passenger airbag deactivation**

Driver and Front Passenger Airbag with Front Passenger Airbag Deactivation

4V0 **Without front passenger seat control**

No front passenger seat control

4X3 **Side airbags in front and curtain airbag system**

Front side airbags and curtain airbag system

4ZB **High-Gloss styling package**

High-gloss styling package

5C0 **Without special body measures**

No Special Body Measures Applied

5D1 **Carrier frequency 433.92 MHz-434.42 Mhz**

Carrier frequency 433.92 MHz-434.42 MHz

5J0 **Without rear spoiler**

No rear spoiler

5K5 **Adhesive film**

Adhesive film

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

5L0 Without front spoiler

Without front spoiler

5MU Decorative inserts in Aluminum Fragment

Aluminum Fragment interior inserts for a stylish look

5RU Exterior mirror on the right (large field of view), convex

Exterior mirror on the right (large field of view), convex

5SL Left exterior mirror, aspherical

Aspherical left exterior mirror

5XC Sun visor on driver and front passenger side

Sun visors for driver and front passenger

5ZF Head restraints in front

Head restraints in front included

6A0 Without fire extinguisher

Without fire extinguisher

6E3 Comfort center armrest in front

Front comfort center armrest

6EA Without additional side body covers (stone guard)

Without Additional Side Body Covers (Stone Guard)

6F0 Without decorative films/emblems

No decorative films or emblems

6FA Body-colored exterior mirror housings

Body-colored exterior mirror housings

6I6 Adaptive cruise assist with emergency assist

Adaptive cruise control with emergency assist

6K8 Audi pre sense front

Includes Audi pre sense front

6NJ Headliner in fabric

Fabric headliner for a premium interior feel.

6RA Dashboard and door trim panel one-piece, single color

Dashboard and door trim panel one-piece, single color

6V1 Rear trim panel (ECE)

Rear trim panel (ECE)

6W6 Front license plate carrier

Front license plate carrier

6XD Exterior mirrors, power-adjustable and heated

Exterior mirrors that are power-adjustable and heated

6Y2 Speed limiter

Speed limiter

73A Without grid connection cable for industrial plug, for the e-tron charging system

No grid connection cable for industrial plug included for the e-tron charging system

76A Without Mode 3 charging cable for public charging

No Mode 3 charging cable for public charging included

7A0 Without CD changer/CD player

No CD changer or player included

7AL Anti-theft alarm system

Anti-theft alarm system included

7E0 Without heat accumulator/auxiliary heater

Without heat accumulator/auxiliary heater

7F9 Gearshift/selector lever knob

Gearshift/selector lever knob

7G0 Without preparation for VTS (vehicle tracking system)

No preparation for vehicle tracking system

7HA Without leather

No leather upholstery specified

7K1 Tire pressure monitoring system

Tire pressure monitoring system

7L8 Start/stop system

Start/stop system

7M1 Scuff plates with aluminum inserts in front and rear

Aluminum scuff plates in front and rear

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

7P1 4-way lumbar support for the front seats
Front seats with 4-way lumbar support

7UG MMI navigation plus with MMI touch response
MMI navigation plus with MMI touch response

7W1 Audi pre sense basic
Audi pre sense basic included

7Y0 Without lane change assist
Without lane change assist

8G1 High-beam assist
High-beam assist feature

8IT LED headlamps
LED Headlamps Equipped

8K1 Separate daytime running light
Individual daytime running lights

8SK LED rear combination lamps
LED rear combination lamps

8T5 Adaptive cruise control with speed limiter, efficiency assist, swerve assist and turn assist
Adaptive cruise control with various safety assists

8X1 Headlamp washer system
Headlamp washer system

8Y1 Two-tone horn
Two-Tone Horn Included

8Z5 Not hot country
Not Configured for Hot Climate Conditions

9AK 2-zone climate control system
Dual-zone climate control system for personalized comfort

9B0 Without integrated toll system
No integrated toll system included

9G9 Belt-driven integrated starter alternator 12 V, 130 - 200 A
Belt-driven integrated starter alternator 12V, generating power between 130 to 200 A

9JA Non-smoker package
Non-smoker package included

9M0 Without auxiliary heater/parking heater
No auxiliary heater/parking heater included

9PA Standard wiper arms and blades
Standard wiper arms and blades included

9R0 Without night vision
Without night vision

9S7 Driver information system with color display
Driver information system with color display

9TA Without additional warning lights
No additional warning lights included

9VD Audi sound system
Audi sound system

9WC Without "Multimedia" in vehicle
No 'multimedia' in vehicle

9X9 Parking aid Plus with 360° display
Parking aid Plus system with 360-degree display

9ZX Bluetooth interface
Bluetooth interface

A00 No self-collection
No self-collection

A51 Audi AG
Produced by Audi AG

A9D sport
Sport package included

AQ0 Standard-production quality
Standard production quality

AV1 Driving on the right
Designed for Driving on the Right Side of the Road

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

B07 Type approval country Sweden

Type approval from Sweden

B0A Part set without country-specific prescriptive standard

Part set without country-specific prescriptive standard

C36 Operating permit, alteration

Permission to make changes to the vehicle's specifications.

D3Q 4-cylinder SI engine 2.0 l/195 kW (16 V), turbo FSI, homog., base engine: TA2/TT6/T57/T2B/T3V/T4H/T1F/T3J/T4E

Turbocharged 4-cylinder 2.0-liter engine with 195 kW power, 16 valves

E0A No special edition

Standard Edition, No Special Version

EP0 Without noise cancellation

Without noise cancellation

ER1 Regional code " ECE " for radio

Regional Radio Code 'ECE' Enabled

ES0 Without vehicle inlet

No Vehicle Inlet Included

EV0 Without grid connection cable for household plug, for the e-tron charging system

No grid connection cable for household plug included for the e-tron charging system

F0A No special purpose vehicle, standard equipment

Standard Equipment, No Special Purpose Vehicle

FA0 Control of series production

Control of series production

FK0 Without AdBlue® tank

No AdBlue® tank included

FM0 Basic equipment variant

Basic equipment variant

FP1 Preparation for features on demand

Preparation for additional features that can be added later

FQ0 Production wheels

Production wheels

FT0 Without parking assistance/garage parking assist

No parking assistance or garage parking assist

FU0 Country group A

Country group A

FZ1 N.N.N. Type 1

Type 1 specific feature

G1D S tronic (for four-wheel drive)

S tronic transmission for all-wheel drive

GA0 Without preconditioning

No preconditioning feature

GB0 Without antenna amplifier

No antenna amplifier included

GH4 quattro (with ultra technology)

Quattro all-wheel drive technology with ultra efficiency

GJ0 Without combined lateral and longitudinal control

No combined lateral and longitudinal control

GM0 Without acoustic vehicle alerting system

No acoustic vehicle alerting system

GP0 Vehicles without special upgrade measures

Vehicle Does Not Include Special Upgrade Measures

GS0 Operating buttons in Matte Black

Operating buttons are in Matte Black finish

GZ0 Manually operated doors

Manual operation for doors

I54 225/55 R 18 tires

The vehicle comes with 225/55 R 18 tires.

I8Y Top infotainment system High (MIB3)

High-end infotainment system with advanced features (MIB3)

IT4 Audi connect Navigation & Infotainment

Audi's navigation and infotainment system

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

IU1 Audi smartphone interface

Includes Audi smartphone interface

IW3 Audi connect Emergency Call & Service with Audi connect Remote & Control

Includes Audi connect Emergency Call & Service with Audi connect Remote & Control features

IX1 SI engine

Powered by a spark ignition (SI) engine.

J2D Battery 380 A (68 Ah)

Battery 380 A (68 AH)

JE3 Data module for Europe

Front cross traffic assist feature

JX0 Without front cross traffic assist

No front cross traffic assist feature

K8B Notchback

Notchback body style

KA0 Without camera systems/accident sensors

Without camera systems/accident sensors

KK3 Refrigerant R1234yf

Uses Refrigerant R1234YF for Cooling

KS0 Without head-up display

Without head-up display

L0L Left-hand drive

Left-Hand Drive Configuration

LY9B/ Brilliant Black/Brilliant Black

Brilliant Black color

N5F Fabric "Rhythmus"

The interior features fabric upholstery called 'Rhythmus'.

NJ0 Without wall bracket

No wall bracket included

NT1 Transit coating (type 2)

Transit coating (Type 2)

PCC Tour assistance package

Includes a tour assistance package for added convenience during journeys

Q1D Sports seats in front

Sport seats installed in the front

QE0 Without Storage package

Excludes the Storage package

QI6 Service indicator 30 000 km or 2 years (variable)

Service indicator set for 30,000 km or 2 years

QK1 With multifunction camera

Multifunction Camera Installed

QL1 Rear window, rear door windows and side windows in clear glass

Clear glass for rear window, rear door windows, and side windows

QQ1 Ambient Lighting package

Ambient lighting package

QR9 Camera-based traffic sign recognition

Traffic sign recognition using cameras

QV3 Digital audio broadcasting

Digital audio broadcasting for enhanced entertainment options

QW0 Without central control unit

Vehicle is equipped without a central control unit

QZ7 Progressive steering

Progressive steering system for better control

T2B 4-cylinder SI engine 2.0 l unit 06N.B 888evo4

4-cylinder 2.0-liter engine with 888evo4 unit

U5A Instrument cluster, km/h speedometer

Instrument Cluster with Km/h Speedometer

UF7 Audi music interface

Audi music interface included

V0A Tires without specification of tire brand

Tires without specification of tire brand

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

VC0 **Without garage door opener**

Without garage door opener

VF0 **Standard pedal cluster**

Standard Pedal Cluster

VH0 **Standard electric**

Standard electric system

VL1 **Extended pedestrian protection**

Extended pedestrian protection included

WSI **Equipment package for Sweden**

Customized equipment package for Swedish cars

X1D **Equipment options subset for Sweden**

Equipment options subset specifically for Sweden

YB7 **Internal control code**

Internal control code

YEZ **Internal control code**

Internal code for management purposes

EA0 **Without follow-on warranty**

No Follow-On Warranty Included

EW0 **Without maintenance contract**

No maintenance contract included.

Timeline

18 records found

The timeline of records for this vehicle

10/2020 Country unknown

Manufactured

This vehicle's manufacturing date has been recorded. The listed country may reflect a production or registration location.

11/2020 Sweden

Ownership changed

An ownership change or document update was recorded for this vehicle. Some changes may be formal, such as end-of-lease transfers.

11/2020 Sweden

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

11/2020 Sweden

Registered

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

11/2020 Sweden

Registered

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

01/2021 Country unknown

Registered

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

12/2022 Sweden

Ownership changed

An ownership change or document update was recorded for this vehicle. Some changes may be formal, such as end-of-lease transfers.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

12/2022 Sweden

Deregistered

A deregistration event was recorded for this vehicle. This could be due to ownership change, documentation update, or similar administrative reasons.

carVertical Insight: Deregistration

This vehicle was deregistered at some point. This could be due to damage, long-term storage, or something else. It's worth taking a closer look into its history.

01/2023 Sweden

Listed for sale

A listing record shows this vehicle was put up for sale. Sometimes, the listing country may differ from the vehicle's actual location.

03/2023 Sweden

Ownership changed

An ownership change or document update was recorded for this vehicle. Some changes may be formal, such as end-of-lease transfers.

04/2023 Romania

Registered

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

carVertical Insight: Different country registration

This vehicle was registered in more than two countries. Different road conditions and maintenance standards may have affected its condition. Checking its service records can help you see if it was properly cared for.

05/2023 Sweden

Exported

This vehicle was marked as exported. The record indicates it left the country listed in the report.

05/2023 Sweden

Deregistered

A deregistration event was recorded for this vehicle. This could be due to ownership change, documentation update, or similar administrative reasons.

carVertical Insight: Deregistration

This vehicle was deregistered at some point. This could be due to damage, long-term storage, or something else. It's worth taking a closer look into its history.

12/2024 Romania

Damage detected

We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.

01/2025 Romania

Damage detected

We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.

01/2025 Romania

Damage detected

We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

04/2025 Romania

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

11/2025 Romania

Insured

An insurance record was found for this vehicle in this country (or state). It may refer to liability, comprehensive, or reinsurance policies.

From: **05/11/2025** To: **04/11/2026**

+44

Data sources
We checked 1000+ data sources in **48 countries**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Based on this report:

- [ ] ## Do a mid-life health check

Moderate wear means key parts are getting old and might need replacing soon. Find out what's nearing the end of its lifespan.

- [ ] Have your mechanic inspect aging parts like the alternator, water pump, and suspension.
- [ ] Check if the timing belt/chain is due for replacement based on age, not just mileage.

- [ ] ## Check the car's export history

Cars imported from other countries often have hidden history gaps. Records don't always transfer across borders, so you need to dig deeper into what happened before export.

- [ ] Search international auction records to check if it was sold as salvage before being exported.
- [ ] Verify all lighting and safety systems meet local regulations – imports often need modifications to pass registration.

Do these checks before buying a car:

- [ ] ## Get a professional inspection

An expert mechanic can spot hidden issues you might miss. Here's what to do next:

- [ ] Book a pre-purchase inspection at an independent or authorised service
- [ ] Ask the mechanic to check key systems: engine, brakes, suspension, electronics
- [ ] Request written notes or a report of any issues found

- [ ] ## Ask for service records

Service records show how well the car has been looked after. Here's what to do next:

- [ ] Ask the seller for the car's service book or maintenance records
- [ ] Check for regular oil changes, filter replacements, and timing belt work
- [ ] Note any missing or overdue services

- [ ] ## Check if the mileage matches

Make sure the mileage in this report matches the car's odometer readings. Here's what to do next:

- [ ] Check the odometer reading against the mileage in the report
- [ ] Watch for signs of tampering (worn pedals, suspicious dashboard fixes)
- [ ] Ask the seller about any differences

- [ ] ## Take a real test drive

A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

- [ ] Drive on different road types: highway, city traffic, and bumpy or uneven surfaces
- [ ] Listen for strange noises or vibrations
- [ ] Pay attention to handling and comfort

- [ ] ## Compare with similar cars

Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:

- [ ] Search for similar cars online (same make, model, year, mileage)
- [ ] Compare asking prices
- [ ] Look at car condition and equipment
- [ ] Use this info to negotiate with the seller

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.