CARVERTICAL

Mercedes-Benz S 580

Generated on **10/09/2026**

Scan for full report

VIN: **W1K6F6BB7PA207036** | Body type: **Sedan** | Fuel: **Gasoline** | Year: **2023**

Transmission Type: **Automatic** | Engine displacement: **3 L** | Power: **280 kW (375 hp / 381 PS)**

Damage

Attention

We found 4 records for this vehicle.

Emissions

Attention

High CO_2 emission rating: 189 g/km.

Commercial use check

No issues found

No records of commercial use found.

Mileage

No issues found

Last recorded mileage: 97,448 km.

Legal status check

No issues found

No financial or legal risk records found.

Theft

No issues found

No theft records found.

+44

Data sources
We checked 1000+ data sources in **48 countries**

Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.

No issues found
No records of vehicle being used in irregular manner

Here's what we checked:

Taxi

No evidence of being used as a taxi

Transport

No evidence of being used as a transport vehicle

Rental

No evidence of being used as a rental

Police

No evidence of being used by police

Demo

No evidence of being used as a demo vehicle

Driving school vehicle

No evidence of being used as a driving school vehicle

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Theft

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.

No issues found

We didn't find any records that the vehicle was stolen.

Here's what we checked:

Is it currently wanted as stolen?

No records indicate that this vehicle is currently reported as stolen and is being searched for.

Was it stolen in the past?

No past theft records found for this vehicle.

Police database stolen vehicle check completed in **7 countries**:

Slovenia · Slovakia · Romania · Hungary · Italy · Czechia · Canada

Mileage

We checked if the mileage looks accurate or if it may have been tampered with.

Summary

- Last known mileage: 97,448 km
- Average mileage for similar models: 66,131 km
- 9 mileage records found



This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Odometer records	
01/2023	**11 km**
02/2024	**15,247 km**
04/2024	**18,000 km**
08/2024	**31,152 km**
03/2025	**48,280 km**

Odometer records	
10/2025	**63,091 km**
02/2026	**70,000 km**
05/2026	**81,118 km**
09/2026	**97,448 km**

Driving habits		
01/2023 - 02/2026	**Normal driving**	**1,863 km/month**
02/2026 - 09/2026	**Intense driving**	**3,882 km/month**

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.

No issues found
No records about the legal status of this vehicle were found

Legal

Insured? ✓ Insured 09/2026 Romania

Insurance valid from 05/2026 until 05/2027

Passed technical inspection (MOT)? Passed 06/2026 Romania

Has successfully passed technical inspection

Valid until 06/2028

Was it scrapped?

No record of this vehicle being marked as scrapped.

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

Attention
We found 4 records for this vehicle

Damage records

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

04/2024 Romania

Reported damage

This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Front / Windshield

Past repair cost estimate

€1,001 – €1,500

Repair cost rating

Very low 1% of the vehicle's value at that time

Damage Groups

Glass

03/2025 Romania

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Front / Bumper Front / Windshield

Past repair cost estimate

€1,001 – €1,500

Repair cost rating

Very low 1% of the vehicle's value at that time

Damage Groups

Glass

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

02/2026 Romania

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Front / Bumper | Front / Windshield

Past repair cost estimate

€2,001 – €2,500

Repair cost rating

Very low 2% of the vehicle's value at that time

Damage Groups

Exterior body parts | Glass

02/2026 Romania

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Rear left / Bumper

Past repair cost estimate

€251 – €500

Repair cost rating

Very low 1% of the vehicle's value at that time

Damage Groups

External lightning

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be related to the use, maintenance or

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

Past repair cost estimate
If the vehicle has reported damage, the past repair cost is estimated based on where the damage was assessed and is shown in that country's currency. This amount may differ from what you'd expect locally. Here's why:
Repair prices vary between countries due to differences in labor rates and parts costs.
The estimate is based on work that is done at official service centers, which are typically more expensive than independent garages.

Repair cost rating
It helps you understand the severity of past damage by comparing repair costs to the vehicle's value. When repair costs approach or exceed a large portion of the vehicle's value, it may indicate a potential total loss.

Very low	<10% of the vehicle's value at that time
Low	10-24% of the vehicle's value at that time
Moderate	25-49% of the vehicle's value at that time
High	50-74% of the vehicle's value at that time
Very high	>75% of the vehicle's value at that time

Market price

We checked how this vehicle's market price has changed over time, based on available historical data and price estimates.

The timeline shows a limited period and does not reflect the vehicle's full lifetime pricing.

Highest price	€131,796
Average price	**€106,278**
Lowest price	€94,000

Criteria for market price evaluation:

Make: **Mercedes-Benz** | Model: **S 580** | Fuel type: **Gasoline** | Transmission type: **Automatic** | Year: **2023** | Market: **Romania**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Market price Market price range

Year	Market price	↘ Lowest market value	↗ Highest market value
2025	**€119,405**	€99,499	€144,000
2026	**€106,278**	€94,000	€131,796
2027	**€95,325**	€84,312	€118,213

Market price insights

Price trend forecast
This vehicle is expected to lose -10% of its market price over the next 1 year.

Selling time
Similar vehicles typically sell within 28 days based on recent market data

Note: Forecasts are based on current market trends and historical data. Actual resale value may change due to market shifts, condition, location, or other factors.

Emissions

We analysed how much CO_2 this car model typically produces and what taxes or fees may apply.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

carVertical Insight

This vehicle has high emissions. That could mean higher emission taxes. Check local regulations to avoid surprises.

CO_2 emissions

Specs

The vehicle's core technical and mechanical build.

Summary

Make sure the vehicle's specs match what the seller told you.

Vehicle specifications

Overview

Make **Mercedes-Benz**	Model **S 580**	Fuel type **Gasoline**
Model generation **223**	Manufacture year **2023**	Category **m1**
Manufacturer label **S 580**	Type approval **e1*2007/46*2115*09**	

Performance & efficiency

Transmission type **Automatic**	Drive type **AWD**	Engine displacement **3 L**
Power **280 kW (375 hp / 381 PS)**	Number of gears **9**	CO2 emissions **189 g/km**
Emissions standard **euro 6; 715/2007*2018/1832 ap**	Engine code **256.830**	Powertrain type **Internal combustion**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Body & dimensions

Body type **Sedan**	Color **Black**	Number of seats **5**
Number of doors **4**	Length **5,210 mm**	Width **1,954 mm**
Unladen weight **2,795 kg**	Gross weight **4,980 kg**	

Equipment

The installed features, options, and technology.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

Summary
Make sure the vehicle's equipment matches what the seller tells you.

Feature list

As received from the manufacturer

01U Mercedes-Benz Connect - Services for navigation
Mercedes-Benz Connect: Services for navigation

053 YoM X2/2
Year of manufacture is X2/2

0B3 Vehicle production location Sindelfingen
Vehicle produced in Sindelfingen location

0S3 Country collector for Red certification for HU ECE
Country collector for red certification for Hungary ECE

0U1 HU country set for ECE (NTG7/NTG 20X)
Head Unit Country Set for ECE (NTG7/NTG 20X)

14U Smartphone integration package
Package for smartphone integration included

16U Apple Carplay smartphone integration
Supports Apple CarPlay smartphone integration

17U Android Auto smartphone integration
Supports Android Auto smartphone integration

197U Obsidian black - Metallic finish
Obsidian Black metallic finish

1B3 Communication module ECE version
ECE version communication module

20U Keyless rental
Keyless rental feature

216 Rear axle steering with large angle
Rear axle steering that allows for a large turning angle

21U Dashcam
Comes equipped with a dashcam for recording driving footage

233 Adaptive cruise control Plus (DISTRONIC PLUS)
Adaptive cruise control feature

235 Active Parking Assist
Active parking assist system

243 Active Lane Keeping Assist (camera)
Active lane keeping assist with camera technology

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

249 Automatic dimming inside rearview mirror and outside mirrors

Automatic dimming rearview mirror and side mirrors

255B Mb-Mobilo with DSB and GGD

Mobile service with repair and breakdown assistance

266 DISTRONIC PLUS transverse support (DTR+Q)

Additional transverse support for adaptive cruise control

275 Memory Package (driver's seat, steering column and mirrors)

Memory package for driver's seat, steering column, and mirrors

282 Through-loading feature over armrest in rear passenger compartment

Includes a through-loading feature over the armrest in the rear passenger compartment for easy storage of long items

292 PRE-SAFE® Impulse Side

Pre-Safe® Impulse Side

2S0 Package - Multimedia/digital content

Package for multimedia and digital content

2U1 Radiator shutter

Includes a radiator shutter

2U8 Alternative refrigerant

Uses alternative refrigerant

30U Projection function via headlamps - lines

Projection Function via Headlamps - Lines

318 Digital LED headlamps, right-side traffic

Digital LED Headlamps for Right-Side Traffic

31U Control code - Mercedes-Benz Connect anti-theft protection

Utilizes control code for Mercedes-Benz Connect anti-theft protection features

321 Fingerprint scanner

Fingerprint Scanner

325 Center airbag

Center Airbag

327B Language of instrument cluster/HU - Romanian

Instrument cluster language set to Romanian for ease of use

32U Sound personalization

Customized sound settings for the vehicle

33B Operating instructions and service booklet-Romanian

Operating instructions and service booklet in Romanian for convenience

34U Services for remote access premium

Includes services for premium remote access capabilities

351 Ecall emergency call system

E-Call emergency call system integrated

355 Preinstallation for retrofitting navigation system

Preinstallation for retrofitting navigation system available

365 Hard drive navigation

Equipped with a hard drive navigation system

367 Pre-installation for Live Traffic Information

Preparation for receiving live traffic information

384 Ramses High communication module (4G)

High communication module for fast 4G connectivity

3S6 Hotend technology, Type II-A

Hotend technology that is Type II-A

3V2 Speed/load index 104Y XL

Tires rated for high speed and load capacity

401 Climatised front seats

Front seats with climate control function

413 Automatic panoramic sliding sunroof

Automatic panoramic sliding sunroof

421 9-speed automatic transmission

Nine-speed automatic transmission

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

42U Projection function via headlamps - symbols
Projection Function via Headlamps - Symbols

43U Projection function via headlamps - animation
Projection Function via Headlamps - Animation

475 Tire pressure monitor (TPM)
Tire pressure monitoring system

489 AIRMATIC DC / semi-active air suspension
Airmatic DC/semi-active air suspension system for superior ride quality and handling

4S6 Cold end technology, type 0
Cold end technology that is Type 0

502 Multi-year free map updates
Free map updates for multiple years

51B Rating, country group EURO-NCAP
Euro-NCAP country group rating

534 Connect 20 Premium (NTG7)
Premium connectivity system with navigation

546 Automatic speed control
Automatically maintains the vehicle's speed as set by the driver

567L Romania
Vehicle is designated for Romania

587 Logo projection via mirror
Logo projection via mirror adds a stylish touch to the vehicle's exterior

628 Automatic high beam control plus (IHC+)
Automatic high beam control

726 Center console - High-gloss black IMD plastic (2C00)
Center console made of high-gloss black IMD plastic

772 AMG styling - Front spoiler, side skirts
AMG styling with front spoiler and side skirts

7B4 WIPPS countries WEU+COC
Designed for countries within WEU+COC

438 Head-up display, Classic
Display system that projects important information onto the windshield for easy viewing while driving

451 3D combination display
3D combination display for enhanced visual effects

481 Sump shield
Protective shield for the undercarriage

49U MBUX Entertainment incl. video streaming
Entertainment system with MBUX and video streaming capabilities

501 360° camera
360-degree camera system

513 Road sign recognition system
System for recognizing road signs

51U Headliner, black fabric
Black fabric headliner

537 Digital Radio standard DAB (Digi. Audio Broadc.)
Standard digital radio with DAB technology

551 Standard anti-theft alarm system (ATA)
Standard anti-theft alarm system

581 Automatic climate control
Automatic climate control feature

5XXL Europe
Euro-spec vehicle

6P5 Control code for Sales
Control code used for sales purposes

72B USB package
USB package includes USB ports for easy device connectivity

79B Pre-installation for digital radio standard DAB/DMB
Preparation for digital radio standard DAB/DMB

800A Leather / nappa / semi-aniline
Interior design with leather and nappa materials

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

803 **YoM X2/1**

Year of manufacture X2/1

804A **Leather / nappa / semi-aniline - Brown**

Brown leather upholstery made of a high-quality material blend.

810 **Premium sound system**

Premium sound system installed

840 **Glas dunkel getönt**

Dark tinted glass

868 **Central display size L**

Large central display provides clear visibility of information

871 **Hands-free access**

Hands-free access features allow you to unlock and access the vehicle without using a key.

872 **Left and right rear seat heating**

Heating system for rear seats

874 **Magic Vision Control incl. heated windshield washer system**

Magic Vision Control with heated windshield washer

878 **Connected Light ambient lighting**

Ambient lighting system that synchronizes with vehicle actions

881 **Boot lid convenience closing feature**

Convenient boot lid closing feature

882 **Sensor system and siren for anti-theft alarm system**

Security system with sensor and siren

883 **Power locking**

Power locking feature

887 **Separate boot lid lock**

Separate locking mechanism for the boot lid

889 **KEYLESS-GO**

Keyless-go system for entry and start

891 **Premium ambiance illumination**

Premium ambiance illumination

897 **Front wireless telephone charging**

Front wireless charging allows for convenient device charging on the go

8B2 **48 V PTC heater booster**

48 V PTC Heater Booster

8P3 **Control code for Sales**

Special control code for sales purposes

8S3 **Control code - YoM 22/2 for axles**

Control code for model year 2022 applicable to axles

8U0 **Heated washer fluid reservoir**

Reservoir for heated washer fluid

8U8 **i-Size marking (Isofix successor)**

I-Size marking for child seat attachment

902 **Front comfort seat heating**

Heated front comfort seats

916 **Fuel tank with large capacity - Volume 1**

Fuel tank with larger capacity

927 **Exhaust treatment, Euro 6 technology**

Exhaust system compliant with Euro 6 technology

942 **Load compartment/trunk package**

Package for the load compartment/trunk included

94B **Integrated starter alternator Gen. 2**

Integrated Starter Alternator Generation 2

950 **AMG line**

AMG Line package included

968 **Euro 6 technology COC document - without motor vehicle registration certificate, part 2**

Euro 6 technology COC document without vehicle registration certificate

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

986 Different VIN with model year

Vehicle identification number is unique to the model year

989 Identification label under windshield

Identification label under the windshield

998 Control code for conversion to WLTP with RDE

Control code for conversion to WLTP with RDE

9U8 Control code for engine technical further development/facelift

Control code for engine technical further development or facelift

AA5 Standard power variant

Standard power variant provides reliable performance

B01 48V technology

48V technology

B10 Fuel tank packages for Euro-6D standard

Fuel tank packages compliant with EURO-6D standard

B13 Loading sill protection - Chrome

Chrome loading sill protection is included

B51 TIREFIT

Equipped with Tirefit system

F223 Model series 223

Belongs to model series 223

FW Sedan

Body type: Sedan

GA Automatic transmission

Equipped with automatic transmission

H02 Trim elements - Fineline anthracite open-grained wood (2B95)

Interior trim elements featuring fineline anthracite open-grained wood

HA Rear axle

Rear axle configuration

K15 Control code for service interval 15000 km

Service interval set to 15,000 km

K32 Active Lane Change Assist

Assists in changing lanes safely

K33 Extended restart in stop-and-go traffic

Allows extended engine restart in stop-and-go traffic conditions

K34 Route-based speed adaptation

Adapts vehicle speed based on the route taken

K40 Emergency corridor with driving over lane marking

Assistive technology for emergency situations on the road

K41 Emergency stop assistant with hands-off lane change

Emergency stop assistant with hands-off lane change feature

L Left-hand drive

Left-hand drive configuration

L5C Supersport steering wheel - leather deep-embossed

Supersport steering wheel with deep-embossed leather finish

LS1 Body-in-white load stage 1/1.5

Body-in-white load stage 1/1.5

M005 Vehicles with 4MATIC/all-wheel drive

Vehicle equipped with 4Matic all-wheel drive system

M014 Engine uprated

Upgraded engine specifications

M256 Inline 6-cylinder spark-ignition engine, M256

Inline 6-cylinder spark-ignition engine M256 ensures powerful performance

M30 Displacement 3.0 liter

Engine has a displacement of 3.0 liters

N2T Exhaust gas/range test in plant 67

Exhaust gas and range testing conducted during manufacturing at Plant 67

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

O82 Software Fresh-Up 5.2

Software update version 5.2

P20 Driving assistance package (L2)

The driving assistance package includes advanced Level 2 assistance systems to enhance safety and comfort while driving.

P47 Parking Package High

High-level parking package

P53 Air cleaning package

Package for air cleaning purposes

P64 Front memory package

Front memory package included

P82 Anti-Theft Protection Package Plus

Comprehensive anti-theft protection package with extra security features

PBG MBUX Navigation Premium

MBUX Navigation Premium

PYB Control code for Sales

Control code for sales

PYH Control code for Sales

Control code used for sales purposes

PYU Control code for Sales

Control code used for sales purposes

R01 Summer tyres

Summer tires equipped

R7K Wheel size 19" all-round variant 1

Wheel size is 19 inches for all wheels, variant 1

RRG AMG double-spoke wheels 19" "all-round"

AMG double-spoke wheels with a 19" size for all-around use

U01 Rear seat belt status indicator

Indicator for rear seat belt status

U10 Front passenger seat with weight sensor

Front passenger seat with weight sensor

U19 Augmented reality video

Incorporates augmented reality video technology

U22 Front lumbar support adjustment

Front lumbar support adjustment enables customization of the lumbar support in the front seats for added comfort during the drive.

U25 Illuminated door sill

Door sills with illumination feature

U26 Floor mats - AMG

Floor mats are branded as AMG

U29 Sport brake system

Brake system designed for sporty driving

U35 12 V socket in load compartment

12V socket in the load compartment

U60 Pedestrian protection - Active hood

Active hood system for pedestrian protection

VL Left front axle half

Left front axle assembly

VR Right front axle half

Right front axle assembly

Timeline

8 records found

The timeline of records for this vehicle

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

01/2023 Country unknown

Manufactured

This vehicle's manufacturing date has been recorded. The listed country may reflect a production or registration location.

05/2023 Romania

First registration

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

04/2024 Romania

Damage detected

We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.

03/2025 Romania

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

02/2026 Romania

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

02/2026 Romania

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

05/2026 Romania

Insured

An insurance record was found for this vehicle in this country (or state). It may refer to liability, comprehensive, or reinsurance policies.

From: **30/05/2026** To: **29/05/2027**

06/2026 Romania

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

+44

Data sources
We checked 1000+ data sources in **48 countries**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Do these checks before buying a car:

- [ ] ## Get a professional inspection

An expert mechanic can spot hidden issues you might miss. Here's what to do next:

- [ ] Book a pre-purchase inspection at an independent or authorised service
- [ ] Ask the mechanic to check key systems: engine, brakes, suspension, electronics
- [ ] Request written notes or a report of any issues found

- [ ] ## Ask for service records

Service records show how well the car has been looked after. Here's what to do next:

- [ ] Ask the seller for the car's service book or maintenance records
- [ ] Check for regular oil changes, filter replacements, and timing belt work
- [ ] Note any missing or overdue services

- [ ] ## Check if the mileage matches

Make sure the mileage in this report matches the car's odometer readings. Your latest known mileage is **97,448 km**. Here's what to do next:

- [ ] Check the odometer reading against the mileage in the report
- [ ] Watch for signs of tampering (worn pedals, suspicious dashboard fixes)
- [ ] Ask the seller about any differences

- [ ] ## Take a real test drive

A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

- [ ] Drive on different road types: highway, city traffic, and bumpy or uneven surfaces
- [ ] Listen for strange noises or vibrations
- [ ] Pay attention to handling and comfort

- [ ] ## Compare with similar cars

Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:

- [ ] Search for similar cars online (same make, model, year, mileage)
- [ ] Compare asking prices
- [ ] Look at car condition and equipment
- [ ] Use this info to negotiate with the seller

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.