CARVERTICAL

Mercedes-Benz GLE Coupé 53 AMG

W1N1673611A274756

2020 | Gasoline | Automatic | SUV | Blue

Generated on 01/10/2026

Scan for full report

Damage

Attention

We found 2 records for this vehicle.

Recalls

Attention

2 open or past safety recalls found for this vehicle.

Emissions

Attention

High CO_2 emission rating: 246 g/km.

Commercial use check

No issues found

No records of commercial use found.

Mileage

No issues found

Last recorded mileage: 97,567 km.

Legal status check

No issues found

No financial or legal risk records found.

+44

Data sources
We checked 1000+ data sources in **48 countries**

Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.

No issues found
No records of vehicle being used in irregular manner

Here's what we checked:

Taxi

No evidence of being used as a taxi

Transport

No evidence of being used as a transport vehicle

Rental

No evidence of being used as a rental

Police

No evidence of being used by police

Demo

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

No evidence of being used as a demo vehicle

Driving school vehicle

No evidence of being used as a driving school vehicle

Theft

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.

No issues found

We didn't find any records that the vehicle was stolen.

Here's what we checked:

Is it currently wanted as stolen?

No records indicate that this vehicle is currently reported as stolen and is being searched for.

Was it stolen in the past?

No past theft records found for this vehicle.

Police database stolen vehicle check completed in **7 countries**:

Slovenia Canada Hungary Romania Czechia Slovakia Italy

Mileage

We checked if the mileage looks accurate or if it may have been tampered with.

Summary

- Last known mileage: 97,567 km
- 13 mileage records found

carVertical Insight

This vehicle has 13 mileage records available. This gives us high confidence that its mileage is authentic.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.



Driving habits

See how intensely this car was driven over time. Lighter use usually means less wear, while intense driving may lead to faster wear on key parts.

Limited driving **< 600 km/month** 20% of analyzed period

Driven less than typical. Limited use can sometimes lead to aging of unused parts.

Normal driving **600 - 1,500 km/month** 49% of analyzed period

A typical driving pattern. Often means steady use and balanced wear.

Intense driving **> 1,500 km/month** 30% of analyzed period

Driven much more than typical. Often means parts have to work harder and may need to be replaced.

No driving 0% of analyzed period

A break in use for an extended period. Cars with long periods of no use may need extra checks (battery, brakes, tires).

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Odometer records	
01/2020	**11 km**
12/2020	**2,623 km**
06/2021	**14,000 km**
07/2021	**20,649 km**
03/2022	**36,000 km**
05/2022	**39,183 km**
12/2022	**50,985 km**

Odometer records	
04/2023	**55,176 km**
04/2024	**69,545 km**
12/2024	**79,058 km**
03/2025	**86,014 km**
03/2026	**96,371 km**
08/2026	**97,567 km**

Driving habits		
01/2020 - 12/2020	**Limited driving**	**234 km/month**
12/2020 - 12/2022	**Intense driving**	**1,988 km/month**
12/2022 - 03/2026	**Normal driving**	**1,148 km/month**
03/2026 - 08/2026	**Limited driving**	**235 km/month**

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.

No issues found
No records about the legal status of this vehicle were found

Legal

Insured? ✓ Insured 10/2026 Romania

Insurance valid from 03/2026 until 03/2027

Passed technical inspection (MOT)? Passed 12/2024 Romania

Has successfully passed technical inspection

Valid until 12/2026

Was it scrapped?

No record of this vehicle being marked as scrapped.

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Attention
We found 2 records for this vehicle

Damage records

05/2021 — Romania

Exterior affected

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Front / Windshield | Glass

Past repair cost estimate

€751 – €1,000

2 similar records

03/2022 — Romania

Assessment

This entry indicates the vehicle was **inspected or serviced** by a professional - for example, for repairs, diagnostics, or warranty service. This doesn't necessarily mean the vehicle was in an accident.

Parts affected

Damage reported, parts not listed

Past repair cost estimate

€1,501 – €2,000

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

Past repair cost estimate
If the vehicle has reported damage, the past repair cost is estimated based on where the damage was assessed and is shown in that country's currency. This amount may differ from what you'd expect locally. Here's why:
Repair prices vary between countries due to differences in labor rates and parts costs.
The estimate is based on work that is done at official service centers, which are typically more expensive than independent garages.

Market price

We checked how this vehicle's market price has changed over time, based on available historical data and price estimates.

The timeline shows a limited period and does not reflect the vehicle's full lifetime pricing.



Selling prices	
08/2026	**€66,900**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Emissions

We analysed how much CO_2 this car model typically produces and what taxes or fees may apply.

carVertical Insight

This vehicle has high emissions. That could mean higher emission taxes. Check local regulations to avoid surprises.

CO_2 emissions

Specs

The vehicle's core technical and mechanical build.

Summary

Make sure the vehicle's specs match what the seller told you.

Vehicle specifications

Overview

Make **Mercedes-Benz**	Model **GLE Coupé 53 AMG**	Fuel type **Gasoline**
Model generation **167**	Manufacture year **2020**	Category **m1g**
Type approval **e1*2007/46*1885*09**	Model year range **2024**	

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Performance & efficiency

Transmission type **Automatic**	Drive type **AWD**	Engine displacement **3 L**
Power **324 kW (434 hp / 441 PS)**	Number of cylinders **6**	Number of gears **9**
CO2 emissions **246 g/km**	Emissions standard **euro 6; 715/2007*2018/1832 dg**	Engine code **256.930**
Transmission name **SPEEDSHIFT TCT 9G**	Powertrain type **Internal combustion**	

Body & dimensions

Body type **SUV**	Color **Blue**	Number of seats **5**
Number of doors **5**	Length **4,961 mm**	Width **1,947 mm**
Wheelbase **2,935 mm**	Unladen weight **3,050 kg**	Gross weight **6,650 kg**

Equipment

The installed features, options, and technology.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

Summary
Make sure the vehicle's equipment matches what the seller tells you.

Feature list

As received from the manufacturer

01U Mercedes-Benz Connect - Services for navigation

Mercedes-Benz Connect: Services for navigation

02J Invalid changeover of world manufacturer to Mercedes-Benz AG (ASF)

Invalid changeover of world manufacturer to Mercedes-Benz AG (ASF)

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

02V Speed/load index 110Y + 114Y XL

The vehicle comes with tires rated for higher speed and load capacity, suitable for XL (extra load) with a speed/load index of 110Y front and 114Y rear.

050 YoM X9/2

Year of manufacture X9/2

085 World manufacturer conversion to Mercedes-Benz AG

World manufacturer conversion to Mercedes-Benz AG

08U Mercedes-Benz Connect - Services for Vehicle Setup (HERMES)

Mercedes-Benz Connect services available for vehicle setup

09U Mercedes-Benz Connect - Vehicle Monitoring (HERMES)

Mercedes-Benz Connect offers vehicle monitoring capabilities

14U Smartphone integration package

Package for smartphone integration included

16B Operating instructions and service booklet-Polish

Operating instructions and service booklet in Polish

16U Apple Carplay smartphone integration

Supports Apple CarPlay smartphone integration

17U Android Auto smartphone integration

Supports Android Auto smartphone integration

189 Changeover of Co2Mpas-3

Update to new CO2MPAS-3 system

1A2 Torque converter, 6 cylinder gasoline

1B3 Communication module ECE version

ECE version communication module

20U Keyless rental

Keyless rental feature

215 Adaptive damping system plus (ADS+)

Adaptive Damping System Plus enhances ride comfort by adjusting suspension continuously

21A Generation EHS

Generation EHS

228 Additional warm water heating

Additional warm water heating system

233 Adaptive cruise control Plus (DISTRONIC PLUS)

Adaptive cruise control feature

235 Active Parking Assist

Active parking assist system

23U Active Stop-and-Go Assist

Includes active stop-and-go assist feature.

242 Right electrically adjustable driver's seat with memory

Electrically adjustable driver's seat with memory function

249 Automatic dimming inside rearview mirror and outside mirrors

Automatic dimming rearview mirror and side mirrors

255B Mb-Mobilo with DSB and GGD

Mobile service with repair and breakdown assistance

256 Track Pace

Track Pace

260 Model badge on trunk lid - Omission

Model badge on trunk lid is omitted

266 DISTRONIC PLUS transverse support (DTR+Q)

Additional transverse support for adaptive cruise control

270 GPS aerial

GPS antenna included

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

273 Exit warning assistant

Alerts the driver about nearby obstacles when exiting

274 Telephone antenna

Telephone antenna present

275 Memory Package (driver's seat, steering column and mirrors)

Memory package for driver's seat, steering column, and mirrors

292 PRE-SAFE® Impulse Side

Pre-Safe® Impulse Side

293 Sidebags in rear

Equipped with side airbags in the rear

294 Kneebag

Kneebag protection included

2A8 Converter variant 9

2S1 SC for vehicle width/length over 2 m/6 m

Special Control for Vehicle Width/Length Over 2m/6m

2U8 Alternative refrigerant

Uses alternative refrigerant

311 Temperature-controlled cup holder

Equipped with a temperature-controlled cup holder.

343B Language of instrument cluster/HU - Polish

Language of instrument cluster and HU display in Polish

351 Ecall emergency call system

E-Call emergency call system integrated

355 Preinstallation for retrofitting navigation system

Preinstallation for retrofitting navigation system available

355K As of engine batch EAA

362 HERMES communications module LTE

Hermes communications module with LTE capabilities

365 Hard drive navigation

Equipped with a hard drive navigation system

367 Pre-installation for Live Traffic Information

Preparation for receiving live traffic information

399 Front multicontour seat with massage function

Front multicontour seat with massage function

3U6 HU country set for ECE/ROW

HU country set for ECE/ROW

401 Climatised front seats

Front seats with climate control function

413 Automatic panoramic sliding sunroof

Automatic panoramic sliding sunroof

421 9-speed automatic transmission

Nine-speed automatic transmission

436 Driver and front passenger luxury head restraint

Luxurious head restraints for driver and front passenger

463 Front visual display (head-up display)

Front visual display or head-up display feature

465 Electric Active Roll Stabilization (EARS)

This feature is Electric Active Roll Stabilization, also known as EARS.

475 Tire pressure monitor (TPM)

Tire pressure monitoring system

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

489 AIRMATIC DC / semi-active air suspension

Airmatic DC/semi-active air suspension system for superior ride quality and handling

4A7 Shift element equipment (4 gears)

500 Electrically folding exterior mirrors

Exterior mirrors that electrically fold

501 360° camera

360-degree camera system

502 Multi-year free map updates

Free map updates for multiple years

513 Road sign recognition system

System for recognizing road signs

51B Rating, country group EURO-NCAP

Euro-NCAP country group rating

537 Digital Radio standard DAB (Digi. Audio Broadc.)

Standard digital radio with DAB technology

546 Automatic speed control

Automatically maintains the vehicle's speed as set by the driver

549 Connect 20 High (NTG6)

Connect 20 high package included

550 Trailer coupling

Trailer coupling feature

551 Standard anti-theft alarm system (ATA)

Standard anti-theft alarm system

553 Trailer Assist

Assistance system for towing a trailer safely and easily

557 Increased towing capacity (trailer hitch)

Enhanced towing capacity with trailer hitch

559L Poland

Vehicle configured for Poland

560A Exclusive leather

The interior of this vehicle is equipped with exclusive high-quality leather.

561A Exclusive leather - black/anthracite

Black and anthracite exclusive leather upholstery

581 Automatic climate control

Automatic climate control feature

587 Logo projection via mirror

Logo projection via mirror adds a stylish touch to the vehicle's exterior

596 IR-active glazing

IR-reflective glazing for enhanced comfort

5A1 Electrohydraulic controller unit converter

5XXL Europe

Euro-spec vehicle

61U black microfiber headliner

Black microfiber headliner

628 Automatic high beam control plus (IHC+)

Automatic high beam control

642 Dynamic LED headlamps, right-hand traffic

Dynamic LED headlamps for right-hand traffic

668 Prod. prot. f. freight pkging with tie-down hooks

Protected during freight packaging with tie-down hooks

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

682 **Fire extinguisher**

Includes fire extinguisher

6A5 **Add-on flange**

Additional Flange included

6P5 **Control code for Sales**

Control code used for sales purposes

71B **Safety vest - driver and passengers**

Safety Vest for Driver and Passengers

724 **Preparation for roof carrier system**

Preparation for roof carrier system

72B **USB package**

USB package includes USB ports for easy device connectivity

772 **AMG styling - Front spoiler, side skirts**

AMG styling with front spoiler and side skirts

79B **Pre-installation for digital radio standard DAB/DMB**

Preparation for digital radio standard DAB/DMB

7A1 **Different length torque converter housing**

7B2 **Flared wheel arch (cladding) size L**

Features flared wheel arch (cladding) in size L.

800 **YoM X9/1**

YOM X9/1

811 **High End sound system**

High-end sound system

840 **Glas dunkel getönt**

Dark tinted glass

846 **Running board in aluminum look with rubber naps**

Running board in aluminum look with rubber naps

866 **Pre-installation for Rear Seat Entertainment System**

Pre-installation for rear seat entertainment system

868 **Central display size L**

Large central display provides clear visibility of information

871 **Hands-free access**

Hands-free access features allow you to unlock and access the vehicle without using a key.

872 **Left and right rear seat heating**

Heating system for rear seats

874 **Magic Vision Control incl. heated windshield washer system**

Magic Vision Control with heated windshield washer

876 **Interior lighting package**

Interior lighting package included

882 **Sensor system and siren for anti-theft alarm system**

Security system with sensor and siren

883 **Power locking**

Power locking feature

889 **KEYLESS-GO**

Keyless-go system for entry and start

890 **Automatic rear-end door**

Automatic rear-end door

896 **Vehicle access and authorization via smartphone**

Vehicle access and authorization via smartphone

896U **MANUFAKTUR brilliant blue - METALLIC finish**

Brilliant Blue Metallic Finish by the manufacturer

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

897 Front wireless telephone charging

Front wireless charging allows for convenient device charging on the go

8U6 Assistance system steering wheel control changeover

Assistance system control switch on steering wheel

8U8 i-Size marking (Isofix successor)

I-Size marking for child seat attachment

901 Interior Chrome Package

Chrome accents inside the vehicle enhance its interior design

902 Front comfort seat heating

Heated front comfort seats

906 Front heated rests

Heated front armrests

915 Fuel tank with increased capacity volume 2

Larger capacity fuel tank

927 Exhaust treatment, Euro 6 technology

Exhaust system compliant with Euro 6 technology

93B Integrated starter alternator Gen. 1

Integrated starter alternator generation 1 improves fuel efficiency

961 Exhaust system with OPF, generation 2.0

Generation 2.0 exhaust system with OPF

968 Euro 6 technology COC document - without motor vehicle registration certificate, part 2

Euro 6 technology COC document without vehicle registration certificate

998 Control code for conversion to WLTP with RDE

Control code for conversion to WLTP with RDE

9U5 Control code, wheel diameter, medium (size 790)

Medium-size wheels with a diameter of 790mm for optimal performance

9U7 Control code for aerodynamics features package

Aerodynamics features package enhances vehicle efficiency

A030 Oil offset quantity +300 g oil

A104 Noise-optimized toothing

Noise-optimized gearing for reduced sound

AA6 Uprated power variant 1

Power upgrade variant 1

B00 Suspension measures for countries with rough roads

Suspension measures catered for rough road conditions for a smoother ride

B01 48V technology

48V technology

B10 Fuel tank packages for Euro-6D standard

Fuel tank packages compliant with EURO-6D standard

B16 Tailpipe Trim

Tailpipe trim addition

B24 Remote control for Auxiliary heating

Remote control for auxiliary heating system

B51 TIREFIT

Equipped with Tirefit system

F167 Model series 167

Vehicle belongs to model series 167

FC Coupe

Vehicle type: coupe

G031 Transmission code version 31

Transmission Code Version 31

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

GA Automatic transmission

Equipped with automatic transmission

GA7 Automatic transmission

Automatic transmission included

H31 Trim elements - Gray open-pore oak wood (2B35)

Gray open-pore oak wood trim elements add a touch of elegance

HA Rear axle

Rear axle configuration

K14 Control code for service interval 20000 km

Service interval schedule code

K27 Software control for unpowered in position "D"

Software control for unpowered in position D

K31 Noise regulations as per ECE R51-03

Compliance with noise regulations per ECE R51-03

K32 Active Lane Change Assist

Assists in changing lanes safely

K33 Extended restart in stop-and-go traffic

Allows extended engine restart in stop-and-go traffic conditions

K34 Route-based speed adaptation

Adapts vehicle speed based on the route taken

L Left-hand drive

Left-hand drive configuration

L6J Nappa leather AMG steering wheel

Nappa leather AMG steering wheel

M016 Uprated engine

Enhanced engine performance

M256 Inline 6-cylinder spark-ignition engine, M256

Inline 6-cylinder spark-ignition engine M256 ensures powerful performance

M30 Displacement 3.0 liter

Engine has a displacement of 3.0 liters

P17 KEYLESS-GO package

Keyless-go package included

P20 Driving assistance package (L2)

The driving assistance package includes advanced Level 2 assistance systems to enhance safety and comfort while driving.

P21 Air quality package

Air quality package included

P47 Parking Package High

High-level parking package

P49 Mirror package

Mirror package specification

P54 Anti-Theft Protection package

Anti-theft protection package

P60 AMG Exterior Night package

Exterior night package with AMG styling elements

P64 Front memory package

Front memory package included

P68 Front comfort heating package

Heating Package for Front Seats

P71 AMG Dynamic Plus Package

AMG Dynamic Plus package

PAF Acoustic Comfort package

Package for improved acoustic comfort

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

PBR Fit and Healthy package - High

Package promoting fitness and health for occupants

PSH Control code for Sales

Allows for customization and configuration for sales purposes.

PWG Control code for Sales

Control code related to sales

R01 Summer tyres

Summer tires equipped

RXV AMG double-spoke wheels 22" "mixed tires"

The vehicle is equipped with AMG double-spoke wheels that are 22 inches in size. The wheels come with 'mixed tires' for enhanced performance and style.

U01 Rear seat belt status indicator

Indicator for rear seat belt status

U10 Front passenger seat with weight sensor

Front passenger seat with weight sensor

U19 Augmented reality video

Incorporates augmented reality video technology

U25 Illuminated door sill

Door sills with illumination feature

U26 Floor mats - AMG

Floor mats are branded as AMG

U38 Leather-clad instrument panel and beltline (genuine leather)

Genuine Leather Cladding on Instrument Panel and Beltline

U40 Cargo net behind driver's seats

Contains a cargo net behind the driver's seats

U47 AMG spoiler lip

AMG spoiler lip for enhanced aerodynamics

U70 red-painted brake callipers

Red-painted brake calipers for a sporty look

U78 Switchable exhaust system

Switchable exhaust system

U88 AMG steering wheel buttons (AMG Drive Unit)

AMG steering wheel buttons (AMG Drive Unit)

VL Left front axle half

Left front axle assembly

VR Right front axle half

Right front axle assembly

Recalls

We checked if the manufacturer issued any safety recalls affecting this vehicle.

Attention

2 recalls found

Recall status: **Active**

We found a recall announcement. The manufacturer has announced a recall for this particular vehicle.

Title Screw connection of 48 V ground point at front passenger seat

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Recall risk level Low

This vehicle has an active safety recall that may pose a risk of injury. For details and the latest updates, please check the recall information on the manufacturer's official website.

Recall status: **Active**

We found a recall announcement. The manufacturer has announced a recall for this particular vehicle.

Title M256 engine wiring harness – protection of insulation via software update

Recall risk level Low

This vehicle has an active recall, but it does not involve a safety or injury risk. For details and the latest updates, please review the recall information on the manufacturer's official website.

If a recall is issued for a vehicle, the vehicle or its components are defective. They must be (1) Repaired, (2) Replaced, or the purchase must be (3) Refunded by the manufacturer. Safety recalls are the most common type of recall – they are issued when the vehicle or its equipment poses a safety risk or does not meet motor vehicle safety standards. Manufacturers may also issue recalls for other reasons, such as emissions or compliance issues, performance concerns, or problems with the vehicle's components or software that do not directly pose a safety risk.

Timeline

8 records found

The timeline of records for this vehicle

01/2020 **Country unknown**

Manufactured

This vehicle's manufacturing date has been recorded. The listed country may reflect a production or registration location.

12/2020 **Romania**

Registered

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

05/2021 **Romania**

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

03/2022 Romania

Assessment detected

We found a record showing that this vehicle underwent a condition assessment in this country (or state). Check the 'Damage' section for more details.

12/2022 Romania

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

12/2024 Romania

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

03/2026 Romania

Insured

An insurance record was found for this vehicle in this country (or state). It may refer to liability, comprehensive, or reinsurance policies.

From: **31/03/2026** To: **30/03/2027**

08/2026 Romania

Listed for sale

A listing record shows this vehicle was put up for sale. Sometimes, the listing country may differ from the vehicle's actual location.

+44

Data sources
We checked 1000+ data sources in **48 countries**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Based on this report:

- [ ] ## Verify maintenance history

The mileage looks accurate, which is good news. Now check if the car was properly maintained throughout its life.

- [ ] Cross-reference the mileage with service book stamps or digital invoices.
- [ ] Inspect wear on key parts to make sure it matches the mileage shown.

- [ ] ## Don't drive until recall is fixed

This is a serious safety recall. The car shouldn't be driven until it's repaired.

- [ ] Find out exactly what the safety risk is before making any decisions (e.g., airbag or fire risk).
- [ ] Get proof the repair was completed, or take the car straight to a dealer for the free fix.

Do these checks before buying a car:

- [ ] ## Get a professional inspection

An expert mechanic can spot hidden issues you might miss. Here's what to do next:

- [ ] Book a pre-purchase inspection at an independent or authorised service
- [ ] Ask the mechanic to check key systems: engine, brakes, suspension, electronics
- [ ] Request written notes or a report of any issues found

- [ ] ## Ask for service records

Service records show how well the car has been looked after. Here's what to do next:

- [ ] Ask the seller for the car's service book or maintenance records
- [ ] Check for regular oil changes, filter replacements, and timing belt work
- [ ] Note any missing or overdue services

- [ ] ## Check if the mileage matches

Make sure the mileage in this report matches the car's odometer readings. Your latest known mileage is **97,567 km**. Here's what to do next:

- [ ] Check the odometer reading against the mileage in the report
- [ ] Watch for signs of tampering (worn pedals, suspicious dashboard fixes)
- [ ] Ask the seller about any differences

- [ ] ## Take a real test drive

A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

- [ ] Drive on different road types: highway, city traffic, and bumpy or uneven surfaces
- [ ] Listen for strange noises or vibrations
- [ ] Pay attention to handling and comfort

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Compare with similar cars

Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:

- [ ] Search for similar cars online (same make, model, year, mileage)
- [ ] Compare asking prices
- [ ] Look at car condition and equipment
- [ ] Use this info to negotiate with the seller

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.