CARVERTICAL

Land Rover Range Rover Velar

Generated on **09/09/2026**

Scan for full report

VIN: **SALYA2BN1LA244994** | Body type: **SUV** | Fuel: **Diesel** | Year: **2019**

Transmission Type: **Automatic** | Engine displacement: **2 L**

Power: **182 kW (244 hp / 247 PS)**

Damage

Attention

We found 1 record for this vehicle.

Emissions

Attention

High CO_2 emission rating: 169 g/km.

Commercial use check

No issues found

No records of commercial use found.

Mileage

No issues found

Last recorded mileage: 137,105 km.

Legal status check

No issues found

No financial or legal risk records found.

Theft

No issues found

No theft records found.

+44

Data sources
We checked 1000+ data sources in **48 countries**

Commercial use check

We checked if this vehicle was used for commercial purposes - like a taxi, rental, or another service vehicle. These vehicles often see heavier use, so it's worth looking closer for signs of wear.

No issues found
No records of vehicle being used in irregular manner

Here's what we checked:

Taxi

No evidence of being used as a taxi

Transport

No evidence of being used as a transport vehicle

Rental

No evidence of being used as a rental

Police

No evidence of being used by police

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Demo

No evidence of being used as a demo vehicle

Driving school vehicle

No evidence of being used as a driving school vehicle

Theft

We checked if the vehicle is currently listed as stolen, if it was ever reported stolen in the past, and whether it's been recovered.

No issues found

We didn't find any records that the vehicle was stolen.

Here's what we checked:

Is it currently wanted as stolen?

No records indicate that this vehicle is currently reported as stolen and is being searched for.

Was it stolen in the past?

No past theft records found for this vehicle.

Police database stolen vehicle check completed in **7 countries**:

Hungary Romania Czechia Slovenia Slovakia Italy Canada

Mileage

We checked if the mileage looks accurate or if it may have been tampered with.

Summary

- Last known mileage: 137,105 km
- Average mileage for similar models: 135,952 km
- 8 mileage records found

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.



Odometer records	
08/2019	**12 km**
12/2020	**33,913 km**
01/2022	**67,220 km**
07/2023	**101,565 km**
11/2023	**101,012 km**

Odometer records	
07/2024	**105,230 km**
01/2026	**133,000 km**
07/2026	**137,105 km**

Driving habits		
08/2019 - 07/2023	**Normal driving**	**2,150 km/month**
07/2023 - 11/2023	**Unrated driving**	
11/2023 - 07/2024	**Limited driving**	**521 km/month**
07/2024 - 07/2026	**Normal driving**	**1,310 km/month**

Legal status check

We checked if the vehicle passed technical inspections and whether it was marked as scrapped.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

No issues found

No records about the legal status of this vehicle were found

Legal

Passed technical inspection (MOT)?

Passed 07/2026 Romania

Has successfully passed technical inspection

Valid until 07/2028

Was it scrapped?

No record of this vehicle being marked as scrapped.

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

Attention

We found 1 record for this vehicle

Damage records

12/2025 Romania

Reported damage

This record indicates damage to the vehicle, usually related to a traffic accident or similar incident.

Parts affected

Front / Bumper

Past repair cost estimate

€1,001 – €1,500

Repair cost rating

Very low 4% of the vehicle's value at that time

Damage Groups

Exterior body parts

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or non-warranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident – they may also be related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

Past repair cost estimate
If the vehicle has reported damage, the past repair cost is estimated based on where the damage was assessed and is shown in that country's currency. This amount may differ from what you'd expect locally. Here's why:
Repair prices vary between countries due to differences in labor rates and parts costs.
The estimate is based on work that is done at official service centers, which are typically more expensive than independent garages.

Repair cost rating
It helps you understand the severity of past damage by comparing repair costs to the vehicle's value. When repair costs approach or exceed a large portion of the vehicle's value, it may indicate a potential total loss.

Very low	<10% of the vehicle's value at that time
Low	10-24% of the vehicle's value at that time
Moderate	25-49% of the vehicle's value at that time
High	50-74% of the vehicle's value at that time
Very high	>75% of the vehicle's value at that time

Market price

We checked how this vehicle's market price has changed over time, based on available historical data and price estimates.

The timeline shows a limited period and does not reflect the vehicle's full lifetime pricing.

Criteria for market price evaluation:

Make: **Land Rover** | Model: **Range Rover Velar** | Fuel type: **Diesel** | Transmission type: **Automatic** | Year: **2019** | Market: **Romania**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.



Year	Market price	↘ Lowest market value	↗ Highest market value
2023	**€44,268**	€34,974	€54,999
2024	**€34,990**	€27,000	€43,903
2025	**€28,500**	€18,900	€38,998
2026	**€24,900**	€16,900	€33,000
2027	**€22,410**	€15,210	€29,700
2028	**€20,169**	€13,689	€26,730
2029	**€18,152**	€12,320	€24,057
2030	**€16,337**	€11,088	€21,651
2031	**€14,703**	€9,979	€19,486
2032	**€13,233**	€8,981	€17,538
2033	**€11,910**	€8,083	€15,784

Market price insights

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Price trend forecast
This vehicle is expected to lose -52% of its market price over the next 7 years.

Selling time
Similar vehicles typically sell within 32 days based on recent market data

Note: Forecasts are based on current market trends and historical data. Actual resale value may change due to market shifts, condition, location, or other factors.

Emissions

We analysed how much CO_2 this car model typically produces and what taxes or fees may apply.

carVertical Insight
This vehicle has high emissions. That could mean higher emission taxes. Check local regulations to avoid surprises.

CO_2 emissions



Specs

The vehicle's core technical and mechanical build.

Summary
Make sure the vehicle's specs match what the seller told you.

Vehicle specifications

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Overview

Make **Land Rover**	Model **Range Rover Velar**	Fuel type **Diesel**
Model generation **1.Generation**	Model year **2020**	Variant **P565**
Manufacture year **2019**	Category **m1g**	Manufacturer label **Range Rover Velar**
Type approval **e5*2007/46*1057*02**		

Performance & efficiency

Transmission type **Automatic**	Drive type **AWD**	Engine displacement **2 L**
Power **182 kW (244 hp / 247 PS)**	Number of gears **8**	CO2 emissions **169 g/km**
Emissions standard **euro 6; 715/2007*2018/1832 dg**	Engine code **200BC**	Engine description **2L AJ20 D4H**
Transmission name **8 Speed Auto Trans ZF 8HP45**	Powertrain type **Internal combustion**	

Body & dimensions

Body type **SUV**	Steering wheel placement **LHD**	Color **Black**
Number of seats **5**	Number of doors **5**	Length **4,797 mm**
Width **1,930 mm**	Unladen weight **2,510 kg**	Gross weight **5,010 kg**

Equipment

The installed features, options, and technology.
This section includes simplified AI-generated descriptions to help you better understand each vehicle feature.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Summary

Make sure the vehicle's equipment matches what the seller tells you.

Feature list

As received from the manufacturer

001CD 2020 Model Year
Manufactured for the 2020 Model Year.

002AS Italian Owner Handbook
Includes Italian Owner Handbook

011BJ In Control Remote
InControl Remote System

017TA Drive Pack
Comprehensive drive pack for enhanced driving experience

020BG With Non Painted Brake Calipers
Equipped with non-painted brake calipers

020DB Front Disc And Caliper Size 17
Features Front Discs and Calipers sized at 17 inches

020DM Brake Booster - Standard
Standard brake booster installed

021AO Standard Duty Battery
Standard Duty Battery

021ZE Trim Level JT1
Trim Level designation for this vehicle is JT1.

022AY 2 Zone Air Con
Vehicle equipped with 2-zone air conditioning

022CF A/C HF01234YF w/o Intrnl HT Exchng
Air conditioning system with HF01234YF refrigerant and no internal heat exchange

022DB With Label A/C Charge
Vehicle equipped with A/C charge label

022GB Cabin Air Quality Ionisation
Cabin Air Quality Ionisation: Ionization system for cabin air quality improvement.

025EZ Voice Input System
System with voice input for controls

025JB Digital Audio Broadcast
Equipped with digital audio broadcast

025LM Hi Line Audio System - 600 W
High-end audio system with 600 watts output

025NE Infotainment NGI Head Unit Mid
Infotainment NGI Head Unit Mid

025OA With Navigation System
Built-in navigation system

025QA TCU Module
Transmission Control Unit Module

025QF SOS / Assistance Call
SOS and Assistance Call Capability

025RC 3G Cellular Connectivity
3G cellular connectivity for enhanced features

026AR except knee protection
Vehicle does not have knee protection feature

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

026FK Seatbelt Pyrotechnic Lap Pret. LHD

Seatbelt with Pyrotechnic Pretensioner for Driver's Lap (Left Hand Drive)

027CI With Standard Duty Coil Spring Susp

Standard Duty Coil Spring Suspension

027CW With Continuous Variable Damping

Variable damping system for improved ride quality

027DH Rear Axle Open Diff w/TVBB

Rear Axle Open Differential with TVBB

027FC Front Spring Load Class-C

Front springs with load class-C

027GD Rear Spring Load Class-D

Rear springs designed for a certain load class-D

028FE Tow Eye Cover - Black

Black tow eye cover

029CD Michelin Tyre Vendor

Michelin Tyre Vendor - The vehicle comes with Michelin tires from the vendor.

029SJ Instant Mobility System - High

Emergency spare tire mobility system designed for high performance

030BV With Black Exterior Mirror

Black Exterior Mirrors

030DL With Standard Glove Box

Standard Glove Box Included

030IA Tyre Standard

Standard tires equipped

030NK Dual Pwr/Htd/Fld/E'Chro/Pudd Lamp

Advanced power-adjustable front lamps

030NT Auto Dip Fr/Rr High Beam Ast

Has Auto Dip Front/Rear High Beam Assist

030NW With Occupant Sensor

Occupant sensor included for safety

030SB 265/45 R21 A/T Tyre

All-terrain tires sized 265/45 R21

031BG 2 1400MM Convex Mirror

Rearview mirrors with 1400mm convex design

031CG With Electrochromic R/View Mirror

Interior mirror with electrochromic functionality

031PC 21" X 8.5 TreeEVO DT Dark Grey

21-inch diameter and 8.5-inch width TreeEVO DT Dark Grey wheels

032BC Steering Wheel - Leather / Chrome

Steering Wheel - Leather / Chrome: Steering wheel featuring leather and chrome accents for a premium touch

032BU Ebony Headliner

Interior features ebony headliner

032HM Standard Interior

Standard interior features

032IQ Ext Pack R Dynamic

Exterior package: R Dynamic

033CT Electric Front Seat Adj Drv Memory

Electric Front Seats with Driver Memory Adjustment

033LM Rear Centre Armrest With Cupholder

Rear center armrest with cupholder

033LP With 40/20/40 Split Fold Rear Seat

Has a 40/20/40 Split Fold Rear Seat

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

033WX 40:20:40 Fxd Squab Armrst Rear Seat Pack

Rear seats with armrest in 40:20:40 configuration

033YH Perforated Suede/Leather Trim

Interior features a combination of suede and leather trim with a perforated design for added style and comfort

034BA Rear Seat Remote Release

The rear seat can be remotely released in this vehicle.

034DU Ebony Black/Ebony Black Interior

Ebony Black Interior

036AC Euro/Russia 3YR Conctd Service Pack

3-year connected service pack for Euro/Russia region

037AB Single Exhaust

Single exhaust system

038AP With KMH Speedo

Includes Kilometer per Hour Speedometer

038DL I/P Facia Contrast - Ebony Black

Interior Facia Contrast in Ebony Black

038ID Full TFT/LCD Instrument Cluster

Instrument cluster with full TFT/LCD display

040AU Starter - Stop/Start System

Includes stop/start system for better fuel efficiency

041GL Version - R-Dynamic

Vehicle version is R-Dynamic.

043AP With Ptc Heater

Vehicle features a Ptc heater

046AD With Diesel Exh Fluid Emission Tank

Includes a diesel exhaust fluid emission tank

046AK Fuel Tank-Diesel

Diesel fuel tank

047AB With Privacy Glass

Comes with privacy glass for added security

048BW Rear Scuff Plates - Bright

Bright rear scuff plates to protect the bumper from scratches

048CH Treadplt-Frt Metal/RR Plastic R Dyn

Front and Rear Treadplates - Metal front, Plastic rear with Dynamic branding

049AS With Locking Steering Column

Steering column with locking mechanism

049AT Manual Strng Col - W/O Pyro Tecnics

Steering column without pyrotechnics

051AJ Unique Met Finish Foot Pedals Pads

Foot pedals with unique metallic finish

053BD Fuel Tank Filler Neck With Inhibit

Fuel filler neck with inhibit feature

053BI Fuel Filler Flap - Central Locking

Central locking for fuel filler flap

053CT EU6D Diesel + DPF Emissions

Compliant with EU6D Diesel + DPF Emissions standards.

054AQ Power Base

Power adjustable seats

054ER PowerPack 15

Comes with PowerPack 15 configuration.

055AF Non Locking Lug Nuts

Lug Nuts Are Non-Locking

056AY With Breakdown Warning Sign

Includes a Breakdown Warning Sign

056DD SERVICE TIME, 24 MONTHS

24-Month Service Interval

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

056EG SERVICE DISTANCE 34,000 KM

34,000 km Service Interval

057JJ Badge - Dark Atlas

Dark Atlas Badge

057PF Velar R Dynamic Badge

Velar R Dynamic badge

057TG Trunk Badge - S

Trunk Badge - S - The trunk of the vehicle features a 'S' badge.

062AD With Tyre Pressure Sensors

Includes tyre pressure sensors for monitoring

062DB TPMS WARNING LIGHT 20%

20% TPMS Warning Light

064AP With Front Fog Lamps

Vehicle equipped with front fog lamps

064BU With Daytime Running Lamps

Daytime Running Lamps

064BV With Headlamp Power Wash

Equipped with headlamp power wash feature

064FC Ambient Lighting-Premium Interior

Premium interior ambient lighting

064HL H/Lamp Operation LHD-Right Justify

Left-hand Drive Headlamp Operation - Right Justified

064JG Grille-GBlk Mesh/ShdAtlas/NBlk Surr

Front Grille with Gloss Black Mesh, Shadow Atlas accents, and Gloss Black surround

064QB Headlamps - LED Premium

LED Premium Headlamps

065AM ACC + Stop/go

ACC + Stop/go: Adaptive cruise control with stop and go functionality for improved driving convenience

065EC Adv Emrg Brkng-LEV2 CTY And URB+PED

Adv Emrg Brkng-LEV2 CTY And URB+PED: Advanced emergency braking system for city, urban, and pedestrian safety.

066AC Keyless Entry/Start - Passive

Keyless entry and start system

070AR With Rear Spoiler

Sporting a Rear Spoiler

070AV Tailgate-Powered Upper

Powered upper tailgate feature

076CW Dual Note Electric Horn

Electric dual note horns for safety

076DF 434 MHZ Door Lock Frequency

Door lock system with 434 MHz frequency

076EI Double Locking Power Lock Latch

Double Locking Power Lock Latch Mechanism

076EL Perimeter / Volume Theft System

Features perimeter/volume theft system

077BB Exterior Protection Cat 2

Exterior Protection Category 2

078BZ 8 Speed Auto Trans ZF 8HP45

Paired with 8-speed ZF 8HP45 Automatic Transmission

078CC Paddle Shift - Noble

Noble paddle shifters for manual control

079AJ Front Floor Carpet Mats

Front floor carpet mats provided

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

080AC With Body Coloured Roof
Comes with a Body Coloured Roof

080CM With Lower Body Cladding - Painted
Lower Body Cladding is painted to match the vehicle.

080GI Rear Bmp Lower Valance-Indus Silver
Lower Rear Bumper Valance in Indus Silver

080HD Side Vents - Burnished Copper
Side vents color: Burnished Copper

080LH Front Bumper-NBk/GlBk/Cop/GlBk/Satl
Front Bumper in Narvik Black, Gloss Black, Copper, Gloss Black, and Satin finish

080QB DOOR TRIM PANEL TPO/PVC
Door trim panel made of TPO/PVC material

081EG Hood Scoop - Burnished Copper
Hood scoop color: Burnished Copper

086BG Lane Departure Warning+Keep Assist
Lane Departure Warning and Keep Assist

086DC Traffic Sing Recogn./Speed Limiter
Traffic sign recognition with speed limiter

086DH Driver Drowiness Monitoring
Driver Drowsiness Monitoring System

086FA Rear View Camera-Fixed
Rearview camera fixed in the vehicle

086GM Blind Spot Assist
Blind Spot Assist Technology

086IB Forward Facing Camera
Forward facing camera for enhanced visibility

087AU Navigation
Navigation System Included

087CB INTELLIGENT EMERGENCY BRAKING
Intelligent Emergency Braking System

087XL Nav Data - Reg 1 - Europe
Navigation data for Europe region

088FA With Leather Console Material
Console material is leather

088HH Interior Trim - Morzine
Interior trim design is Morzine

088IE Terrain Responce With Dynamic Mod
Terrain Response system with Dynamic Mode

088JA HAND BOOK COVER
Handbook Cover Included

088JW Finisher - Shadow Aluminium
Shadow Aluminium finish on exterior trim

088OC With TPO/PVC Facia
Dashboard facia made of TPO/PVC material

089AD Standard Appliques
Standard Appliques are added

094AA With Smokers Package
Equipped with Smokers Package

095DB Export Shipping Requirements
Meets Export Shipping Standards

095JB Internal Sound Enhancement
Internal Sound Enhancement: Enhancements for internal sound quality.

095RD Mapcare - Euro/Russ 3yr
Mapcare service for Euro/Russia region

096FA Fuel Label - ROW
Fuel label compliant with ROW standards

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

096TA Air Bag Label - Pictoral

Air bag label with pictorial representation

096TL 'E' Approval Label

'E' approval label for regulatory compliance

096UF Tyre Recommended Plate-Non English

Plates recommending tire specifications

097AJ Whole Vehicle Type Approval

Whole vehicle type approval

099AA 5 Door

Vehicle with 5 doors

100LR Land Rover

Land Rover: The vehicle is a Land Rover model.

101AG Standard Wheelbase

Standard wheelbase

103AA With Diesel Fuel Capability

Capable of using diesel fuel

109AA All Wheel Drive

All-wheel drive system for enhanced traction

117AH Rotary Gear Shift Knob

Rotary Gear Shift Knob

121AF Engine Cooling Fan 400W

High Capacity 400W Engine Cooling Fan

130AD Air Cleaner with Stub

Air cleaner with stub feature

145CE 2020 Model Year Parts

2020 Model Year Part Upgrades

152CA Engine Power Source - 245PS/500NM

Engine power: 245PS/500NM

179AB Thermal Encapsulation Covers

Thermal Encapsulation Covers are provided.

180AC Seat Cushion Power Fore/Aft

Power Fore/Aft adjustment for Seat Cushion is available.

180BC Seat Cushion Power Height

Seat Cushion Power Height adjustment feature is present.

180CA With Front Seat Cushion Power Tilt

Front Seat Cushion has Power Tilt functionality.

180DB Seat Squab Power Recline

Seat Squab can be Power Reclined.

180FA Front Headrest Manual Height

Front Headrest can be adjusted manually for height.

180KB Seat Lumbar - 4 Way

4-Way Lumbar Support for the seats.

183AB Apple Carplay

Apple CarPlay Integration

183CB Android Auto

Android Auto Integration

185AC Badge-Engine Power Diesel 240 PS

Badge indicating engine power of 240 horsepower for the diesel model

186AB Smartphone Pack

Smartphone pack included

189AD Front And Rear Parking Aid

Both Front and Rear Parking Aid sensors are included.

1AT Ebony black-JBC1807

Ebony Black Exterior Color Code JBC1807

200BC 2.0L I4 DSL HIGH DOHC AJ200

2.0L I4 Diesel engine with high output

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

210AA **Cockpit CCR**

CCR cockpit design

211AA **Centre Console CCR**

CCR Center Console

212AA **Seats CCR**

CCR seats

214AA **Front Bumpers CCR**

CCR front bumpers

215AA **Rear Bumpers CCR**

CCR rear bumpers

216AA **Door Casing CCR**

CCR door casing

217AA **Headlining CCR**

CCR headlining

218AA **Rear Spoiler - CCR**

Rear Spoiler - CCR: Rear spoiler designed for aerodynamic performance, part of the CCR package

219AA **CCR INSTRUMENT PANEL HARNESS**

Instruments panel harness for CCR system

220AA **KSK Cabin Harness**

Interior cabin harness for KSK system

223AA **CCR FRONT DAMPER**

CCR front damper included

224AA **CCR REAR DAMPER**

CCR rear damper included

252SF **LHD**

Left-Hand Drive

300JU **14-Way D Mem Front Seat Pack**

Front seats with 14-way adjustable memory function

300SE **L560 Range Rover Velar**

Model: L560 Range Rover Velar

301QU **Seat Combination 300JU/033WX**

Combination of seat features from 300JU and 033WX

352HY **R-Dynamic S 240PS Auto**

Model variant R-Dynamic S with 240 horsepower engine and automatic transmission for a dynamic driving experience

370AC **D7A**

Model variant: D7A

800IJ **(+)"I"**

Additional Feature: (+) "I"

900AD **Solihull Plant Built**

Manufactured at Solihull Plant

HP560 **L560 2.0D i4 Mid AWD 5DR SWB**

Model: L560 2.0D i4 Mid AWD 5DR SWB

TQA **Ebony S**

Interior color option in Ebony S, providing a dark and sophisticated aesthetic

Timeline

7 records found

The timeline of records for this vehicle

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

08/2019 Country unknown

Manufactured

This vehicle's manufacturing date has been recorded. The listed country may reflect a production or registration location.

09/2019 Italy

First registration

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

11/2023 Italy

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

11/2023 Italy

Deregistered

A deregistration event was recorded for this vehicle. This could be due to ownership change, documentation update, or similar administrative reasons.

carVertical Insight: Deregistration

This vehicle was deregistered at some point. This could be due to damage, long-term storage, or something else. It's worth taking a closer look into its history.

07/2024 Romania

Registered

A registration record was added for this vehicle. This could reflect first registration, ownership change, or other official documentation.

carVertical Insight: Different country registration

This vehicle was registered in more than two countries. Different road conditions and maintenance standards may have affected its condition. Checking its service records can help you see if it was properly cared for.

12/2025 Romania

Damage detected

We found a record indicating this vehicle was damaged. Check the 'Damage' section for more details.

07/2026 Romania

Inspected

A technical inspection (MOT) was recorded for this vehicle. This may include various checks related to roadworthiness or emissions. Both successful and failed inspections can be included.

+44

Data sources
We checked 1000+ data sources in **48 countries**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Helpful tips after reading the report

Every tip you check off helps you avoid unwelcome surprises later. The more you check, the safer your car deal.

Based on this report:

- [ ] ## Do a mid-life health check

Moderate wear means key parts are getting old and might need replacing soon. Find out what's nearing the end of its lifespan.

- [ ] Have your mechanic inspect aging parts like the alternator, water pump, and suspension.
- [ ] Check if the timing belt/chain is due for replacement based on age, not just mileage.

Do these checks before buying a car:

- [ ] ## Get a professional inspection

An expert mechanic can spot hidden issues you might miss. Here's what to do next:

- [ ] Book a pre-purchase inspection at an independent or authorised service
- [ ] Ask the mechanic to check key systems: engine, brakes, suspension, electronics
- [ ] Request written notes or a report of any issues found

- [ ] ## Ask for service records

Service records show how well the car has been looked after. Here's what to do next:

- [ ] Ask the seller for the car's service book or maintenance records
- [ ] Check for regular oil changes, filter replacements, and timing belt work
- [ ] Note any missing or overdue services

- [ ] ## Check if the mileage matches

Make sure the mileage in this report matches the car's odometer readings. Your latest known mileage is **137,105 km**. Here's what to do next:

- [ ] Check the odometer reading against the mileage in the report
- [ ] Watch for signs of tampering (worn pedals, suspicious dashboard fixes)
- [ ] Ask the seller about any differences

- [ ] ## Take a real test drive

A proper test drive helps you spot problems with performance, handling, or comfort – you'll notice much more on the road than you will in the parking lot. Here's what to do next:

- [ ] Drive on different road types: highway, city traffic, and bumpy or uneven surfaces
- [ ] Listen for strange noises or vibrations
- [ ] Pay attention to handling and comfort

- [ ] ## Compare with similar cars

Checking other listings helps you know if the asking price is fair – or worth negotiating. Here's what to do next:

- [ ] Search for similar cars online (same make, model, year, mileage)
- [ ] Compare asking prices
- [ ] Look at car condition and equipment
- [ ] Use this info to negotiate with the seller

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.