

# TR 319

|                     |  |
|---------------------|--|
| <b>TIRE SIZE</b>    | <b>26X12.00 - 12</b>   |
| <b>UM</b>           | IS STANDARD  |
| <b>CONSTRUCTION</b> |  BIAS                                   |
| <b>MACHINERY</b>    | IMPLEMENTOS AGRÍCOLAS /<br>MAQUINA PARA RECOLHA DOS<br>FRUTOS / ESCAVADOR DE VALAS /<br>CEIFEIRA / IMPLEMENTOS AGRÍCOLAS |
| <b>VERSÃO</b>       | STANDARD   |
| <b>TIRE TYPE</b>    | TL   |
| <b>LI/SS</b>        | 116 A3   |



## DIMENSÕES IS STANDARD

|                 |      |                |                        |
|-----------------|------|----------------|------------------------|
| <b>SW (MM)</b>  | 318  | <b>RIM REC</b> | 10.50 AT               |
| <b>OD (MM)</b>  | 640  | <b>RIM ALT</b> | 8.0 AT; 8.5 AT; 9.0 AT |
| <b>SLR (MM)</b> | 290  | <b>ECE</b>     | E11-106R-003560        |
| <b>RC (MM)</b>  | 1908 | <b>PR</b>      | 8                      |

## LOAD CAPACITY (KG/TIRE)

|                   |             |
|-------------------|-------------|
| <b>KM/H / BAR</b> | <b>3.00</b> |
| 15                | 1250        |

Rolling Circumference & SLR values are at rated Load and inflation pressure. These values may vary at different Load and pressure condition.