LEVEL 1 - ASSESSMENT					
BANK					
Property Address: 12818 Coit Rd	Bldg 1	of 1	Review	Reviewer's Name: William Beard	
Permanent Parcel Number: 111-20-020	510g			of Site Visit: May 14, 2021	
Source: Forfeiture			Listoria District Norro		
Neighborhood: Forest Hills Ward: 08	Historic District: None Landmark District:None				
Site Data					
Structure	Describe Street Characteristics: pho			photo	
Type (Field Verify): Industrial	Commercial & Industrial Business District				
Style:	Property Status:				
Year Built:0	Secured or Vnsecured				
Sq. Ft. (Structure): 193,680, 0 units Sq. Ft. (Basement):	□ NO ENTRY – Pre-Foreclosure				
Bedrooms/Baths/ ½ Baths: 0/0/0	 Appears Occupied 				
Lot Size: 0' X 0' (. S.F.) -	✓ Unoccupied				
Garage: None	•			5.14.2021 08:50	
Structural Evaluation					
Exterior (Describe General Conditions) Foundation:					
Roofing: Poor	Cracks: 🗆 Major 🔅 Minor 🔅 Yes, but no issue				
Multiple Roof Layers Description Missing/Det	□ Settling or Sinking				
Missing/Deteriorated Fascia & Soffits	Foundation Notes: N/A				
Downspouts/Storm Crocks (Condition):N/	Basement: None				
□ Missing/Deterioriated □ Present	Cracks Water in Basement Mold on walls				
	□ Structural Defects:				
Siding (Condition):Poor					
🗆 Aluminum 🗆 Vinyl 🗆 Wood	Mechanicals:				
🖌 Brick 🛛 Other	HVAC: N/A				
Windows (Condition): Poor	 □ Furnace Missing □ Outdated System □ A.C. 				
Original Dbl. Hung Z Replacement Wit		Joystem	\square A.C.		
	Electrical: N/A				
Porches: Poor	Newer Panel Outdated System				
Deteriorated Deck Deteriorated Colu	Plumbing: N	/A			
2-Story Porches	□ Missing Supply Lines □ Updated Drain System				
- <u>-</u> .					
<u>Driveway</u> :	Interior Walls, Ceilings & Flooring :				
Poor Concrete		Poor			
Garage :		Kitchen/Bat	ths :		
Poor		N/A			
🗆 Secured 💋 Unsecured 🗆 Insufficie	ent room for garage				
Recommendation					
Extensive Renovation Moderate Renovation Minimal Renovation Demolition Vacant Lot					
Summary: This property is collapsing and is a hazard to the area it needs to come down					
I could not gain full access to all floors safely. It should come down. (Meter not Accessible) (Brick Siding)					
				RRN 2102.05	

12

















RRN 2102.05











RRN 2102.05











RRN 2102.05



















