

Annex 1

Information sheet on some of the repairs need to be done at the Maldives Bar Council

1-Meeting Room Toilet NO-1 (4TH Floor)	
	• Attach the toilet tissue holder
	• Drain replacement
2- DA Room Toilet- NO-1	
	• Flash tank issues
	• Toilet water leakage
	• Muslim shower replacement
	• Attach the toilet tissue holder
3- DA Room Toilet-No-2	
	• Wash basin gully fixing
	• Muslim shower replacement
	• Drain replacement
4- BE Room and Toilet- 1	
	• Muslim shower replacement
	• Water valve replacement
	• Flash Tank home button replacement
	• Removing and Refixing Metal Bar in BE room
Floor Area Toilet No-2 (5th Floor)	
	• Flash Tank home button replacement
	• Muslim shower replacement
Floor Area Toilet No-3 (5th Floor)	
	• Muslim shower replacement
	• Drain replacement

#	Fungus Treatment and painting (All wall)
1	Meeting room (Fungus infested areas)
2	Bar Exam room
3	Director Admin room
4	Prayer room (prayer room to install wall fan)
5	Reception Area (affected arears)
6	GC Room Fungus Infested Areas

#	Meeting Room Pocket Door changes
1	Pocket Doors fixing (Repairing existing doors) – 8 Doors