

Secretariat of the Maaleatholhu Atoll Council

Ameeru Ameen Magu, K.Thulusdhoo, Republic of Maldives

TOURING 36 "Ranfaru" Launch

Steering helm and meter holes need to be closed.





* Racor filter bolts and hull through holes need be closed.



Steering hose hull through hole need to be closed



Cracks were need to be fixed

