



BEALS + THOMAS

BEALS AND THOMAS, INC.
Reservoir Corporate Center
144 Turnpike Road
Southborough, MA 01772-210



PROGRESS INSPECTION REPORT

Inspection Date: 9/20/2017

Inspector: Eric J. Las, PE, LEED AP, Beals and Thomas, Inc.

Inspection Report Number: 1

PERMIT COMPLIANCE

Proceeding per approved site plan?

YES NO If not, note area and explain:

This report has been prepared in compliance with Specific Condition IX.M.4 of the Site Plan Decision, dated July 26, 2016

Project Name:

West Medway II

Location: Medway, MA

B+T Job#: 1422.10

Local Approvals: Order of Conditions DEP File No. 216-0879, Site Plan Decision, Host Community Agreement

Introduction:

Exelon West Medway II LLC respectfully submits the first construction progress inspection report for the West Medway II project. The purpose of this report is to document the in-progress work with respect to the approved site plans and associated conditions for the Planning and Economic Development Board. This report summarizes noteworthy activities conducted on site from commencement of construction in August 2017, to September 20, 2017. Please also refer to the enclosed Photo Log.

Current Work Activities, Comments, and Observations:

- Silt fences and straw bales have been installed around jurisdictional areas
- Crushed stone has been placed at the construction entrance to decrease off-site sediment tracking.
- 6-foot wire-mesh fencing and privacy screening was installed around the perimeter of the work site.
- 24/7 security details are in place
- Sediment basins have been installed.
- Catch basins in Summer Street around the site entrance are protected with silt sacks.
- Various material and soil stockpiles have been created throughout the site and are actively stabilized via seeding where necessary.
- The Contractor Parking Area off West St. has been created
- Installation of temporary utilities (power, water) to the construction trailers is in progress
- Concrete washout station has been installed and maintained appropriately.
- Wetland replication has been completed and stabilized.
- Site has been completely cleared, grubbed and stumped, and leveled.
- Construction has begun on the foundations for the acoustic wall

Authorized Signature

9/20/17

Date

PROPERTY OWNER:

Exelon West Medway II, LLC

Attn: Todd Cutler, Esq.
Associate General Counsel

Phone: 610-765-5602

Email: todd.cutler@exeloncorp.com

Attn: Pete Callahan,
Project Director

Phone: 617-381-2332

Email: Pete.Callahan@constellation.com

Attn: Doug Blakeley,
Environmental Monitor

Phone: 518-265-7354

Email: doug.blakeley@aptim.com

TOWN OF MEDWAY

Attn: Michael E. Boynton,
Town Administrator

Phone: 508-533-3264

Email: mboynton@townofmedway.org

Attn: Bridget Graziano,
Conservation Agent

Phone: 508-533-3292

Email: bgraziano@townofmedway.org

Attn: Susan Affleck-Childs, Planning &
Economic Development Coordinator

Phone: 508-533-3291

Email: sachilds@townofmedway.org

ENVIRONMENTAL CONSULTANTS

Beals and Thomas, Inc.

Attn: Eric J. Las, PE, LEED AP
Principal

Phone: 508-366-0560

Email: elas@bealsandthomas.com

Epsilon Associates, Inc.

Attn: Jeremy Fennell, PWS, CWS, CESSWI
Senior Scientist

Phone: 978-461-6237

Email: jfennell@epsilonassociates.com



BEALS + THOMAS



Exelon Generation

PHOTOGRAPHIC LOG

Client Name:
Exelon West
Medway II

Photo: West Medway II
Location: Medway, MA

Project No:
1422.10

Photo No: 1 **Date:** 9/16/17

Description:

Aerial view of site looking northwest. Site is completely cleared. Various material stockpiles have been created.



Client Name:
Exelon West
Medway II

Photo: West Medway II
Location: Medway, MA

Project No:
1422.10

Photo No: 2 **Date:** 9/16/17

Description:

Aerial view of site looking northeast. Construction entrance and parking has been created in the southern portion of the property along West Street.



Client Name: Exelon West Medway II	Photo: West Medway II Location: Medway, MA	Project No: 1422.10
--	---	-------------------------------

Photo No: 3	Date: 9/20/17
--------------------	----------------------

Description:

Crushed stone construction access road viewed to the south. Temporary offices and construction parking to the east of the road and site work to the west.



Client Name: Exelon West Medway II	Photo: West Medway II Location: Medway, MA	Project No: 1422.10
--	---	-------------------------------

Photo No: 4	Date: 9/20/17
--------------------	----------------------

Description:

Excavation and removal of large boulders was observed in the western portion of the site.

