LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	NOTES ON BASIS OF MATERIAL CLASSIFICATION
250TH-603	N	C	N	1"	2002	C	1"	2006	SF	N	C		2006		Installation record	Y			Field inspection only	Y	
250TH-653	N	C	N	1"	2002	C	1"	2004	SF	Y	C		2004		Installation record	Y			Field inspection only	Y	
250TH-654	N	C	N	1"	2002	C	1"	2005	SF	Y	C		2005		Installation record	Y			Field inspection only	Y	
250TH-655	N	C	N	1"	2002	C	3/4"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
250TH-656	N	C	N	1"	2002	C	1"	2007	SF	Y	C		2007		Installation record	Y			Field inspection only	Y	
250TH-657	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
250TH-658	N	C	N	1"	2002	C	1"	2005	SF	Y	C		2005		Installation record	Y			Field inspection only	Y	
250TH-659	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
250TH-660	N	C	N	1"	2002	C	1"	2007	SF	Y	C		2007		Installation record	Y			Field inspection only	Y	
250TH-661	N	C	N	1"	2002	C	1"	2003	SF	Y	C		2003		Installation record	Y			Field inspection only	Y	
250TH-662	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
250TH-664	N	C	N	1"	2002	C	1"	2006	SF	N	C		2006		Installation record	Y			Field inspection only	Y	
250TH-695	N	C	N	1"	2002	C	3/4"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y	
BEE-216	UNK	UNK-LG	UNK		1923	C	3/4"	1960	SF	Y	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
BEST #1-415	N	C	N	1"	2021	C	1"		NONRES		C				Installation record	Y			Field inspection only	Y	
BEST #2-415	N	C	N	1"	2021	C	3/4"		NONRES		C				Installation record	Y			Field inspection only	Y	
BEST-400	N	DI	N	6"	2021	DI	6"		NONRES						Installation record	Y			Field inspection only	Y	
BEST-400	N	DI	N	6"	2021	DI	6"		NONRES						Installation record	Y			Field inspection only	Y	
BEST-425	N	DI	N	6"	2021	C	6"		NONRES						Installation record	Y			Field inspection only	Y	
BEST-425	N	DI	N	6"	2021	C	6"		NONRES						Installation record	Y			Field inspection only	Y	
BIRCH-101	N	C	N	1"	1991	C	3/4"	1999	SF	N	C		1999		Installation record	Y			Field inspection only	Y	
BIRCH-102	N	C	N	1"	1991	C	1"	1992	SF	Y	C		1992		Installation record	Y			Field inspection only	Y	
BIRCH-103	N	C	N	1"	1991	C	1"	1997	SF	N	C		1997		Installation record	Y			Field inspection only	Y	
BIRCH-104	N	C	N	1"	1991	C	1"	1992	SF	N	C		1992		Installation record	Y			Field inspection only	Y	
BIRCH-200	N	C	N	1"	1991	C	1"	1996	SF	Y	C		1996		Installation record	Y			Field inspection only	Y	
BIRCH-202	N	C	N	1"	1991	C	1"	1998	SF	N	C		1998		Installation record	Y			Field inspection only	Y	
BIRCH-300	N	C	N	1"	1991	C	1"	1997	SF	N	C		1997		Installation record	Y			Field inspection only	Y	
BIRCH-302	N	C	N	1"	1991	C	3/4"	1999	SF	N	C		1999		Installation record	Y			Field inspection only	Y	
BIRCH-400	N	C	N	1"	1991	C	3/4"	1999	SF	N	C		1999		Installation record	Y			Field inspection only	Y	
BIRCH-402	N	C	N	1"	1991	C	1"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y	
BIRCH-404	N	C	N	1"	1991	C	1"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y	
BLACKHAWK-200	N	C	N	1"	2002	C	3/4"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
BLACKHAWK-201	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
BLACKHAWK-202	N	C	N	1"	2002	P	1"	2010	SF	N	O		2010	PLUMBING MATERIAL-PLASTIC	Installation record	Y			Field inspection only	Y	
BLACKHAWK-203	N	C	N	1"	2002	C	1"	2005	SF	Y	C		2005		Installation record	Y			Field inspection only	Y	
BLACKHAWK-204	N	C	N	1"	2002	P	1"	2005	SF	Y	O		2005	PLUMBING MATERIAL-PLASTIC	Installation record	Y			Field inspection only	Y	
BLACKHAWK-205	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
BLACKHAWK-206	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
BLACKHAWK-207	N	C	N	1"	2002	C	3/4"	2018	SF				2018		Installation record	Y			Field inspection only	Y	
BLACKHAWK-208	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
BLACKHAWK-209	N	C	N	1"	2002	C	1"	2008	SF	Y	C		2008		Installation record	Y			Field inspection only	Y	
BLACKHAWK-210	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
BLACKHAWK-211	N	P	N	1"	2024	P	1"	2024	SF	N	O		2023	Building Plumbing Material-Plastic	Installation record	Y			Field inspection only	Y	
BLACKHAWK-212	N	C	N	1"	2002	C	1"	2005	SF	N	C		2005		Installation record	Y			Field inspection only	Y	
BLACKHAWK-213	N	C	N	1"	2002	C	3/4"	2007	SF	N	C	C	2007		Installation record	Y			Field inspection only	Y	
BLACKHAWK-214	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
BOUNDARY EAST-501	N	C	N	1"	1998	C	1"	2000	SF	Y	C		2000		Installation record	Y			Field inspection only	Y	
CHURCH-100	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-105	UNK	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-106	UNK	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-110	UNK	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-111	UNK	C	N	3/4"	1968	C	3/4"	1960	SF	Y	C	C	1960		Installation record	Y			Field inspection only	Y	
CHURCH-115	UNK	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-116	UNK	C	N	3/4"	1968	C	1"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-120	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-121	UNK	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-123	N	C	N	3/4"	1968	C	3/4"	1981	SF	N	C		1981		Installation record	Y			Field inspection only	Y	
CHURCH-125	N	C	N	3/4"	1968	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-126	N	C	N	3/4"	1968	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-215	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-221	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-225	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-231	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-235	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-240	N	DI	N	2"	1968	DI	2"		MF						Installation record	Y			Field inspection only	Y	
CHURCH-241	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
CHURCH-242	N	C	N	3/4"	1968	C	3/4"	1968	SF	N	C		1968		Installation record	Y			Field inspection only	Y	
CHURCH-244	N	C	N	3/4"	1968	C	3/4"	1979	SF	N	C		1979		Installation record	Y			Field inspection only	Y	
CHURCH-246	N	C	N	3/4"	1968	C	3/4"	1975	SF	N	C		1975		Installation record	Y			Field inspection only	Y	
CHURCH-247	N	C	N	3/4"	1968	C	3/4"	1975	SF	N	C		1975		Installation record	Y			Field inspection only	Y	
CHURCH-248	N	C	N	3/4"	1968	C	3/4"	1979	SF	N	C		1979		Installation record	Y			Field inspection only	Y	
CHURCH-300	N	C	N	3/4"	1968	C	3/4"	1994	SF	N	C		1994		Installation record	Y			Field inspection only	Y	
CHURCH-315	N	C	N	3/4"	1968	C	3/4"	1972	SF	N	C		1972		Installation record	Y			Field inspection only	Y	
CHURCH-319	N	C	N	3/4"	1968	C	3/4"	1973	SF	N	C		1973		Installation record	Y			Field inspection only	Y	
CHURCH-380	N	C	N	3/4"	1968	C	3/4"	1992	SF	N	C		1992		Installation record	Y			Field inspection only	Y	
CHURCH-401	N	C	N	3/4"	1968	C	3/4"	1974	SF	N	C		1974		Installation record	Y			Field inspection only	Y	
CHURCH-404	N	C	N	3/4"	1968	C	3/4"	1997	SF	N	C		1997		Installation record	Y			Field inspection only	Y	
CHURCH-402	N	C	N	3/4"	1968	C	3/4"	1974	SF	N	C		1974		Installation record	Y			Field inspection only	Y	
CHURCH-406	N	C	N	3/4"	1968	P	3/4"	1995	SF	N	O		1995	PLUMBING MATERIAL-PLASTIC	Installation record	Y			Field inspection only	Y	
CHURCH-408	N	C	N	3/4"	1968	C	3/4"	1996	SF	N	C		1996		Installation record	Y			Field inspection only	Y	
CHURCH-501	N	C	N	3/4"	1968	C	3/4"	1976	SF	N	C		1976		Installation record	Y			Field inspection only	Y	

CHURH-245	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
CTY B-539	N	C	N	1"	2001	C	3/4"		NONRES	N	C				Installation record	Y			Field inspection only	Y		
CTY B-545	N	C	N	1"	2021	C	3/4"	2021	NONRES	N	C		2021		Installation record	Y			Field inspection only	Y		
DAKOTA N-408	N	DI	N	6"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
DAKOTA S-307	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
DAKOTA-300	N	C	N	1"	2002	C	1"	2002	SF	Y	C		2002		Installation record	Y			Field inspection only	Y		
DAKOTA-301	N	C	N	1"	2002	C	1"	2006	SF	N	C		2006		Installation record	Y			Field inspection only	Y		
DAKOTA-302	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y		
DAKOTA-303	N	C	N	1"	2002	C	1"	2005	SF	Y	C		2005		Installation record	Y			Field inspection only	Y		
DAKOTA-304	N	C	N	1"	2002	C	1"	2005	SF	N	C		2005		Installation record	Y			Field inspection only	Y		
DAKOTA-305	N	C	N	1"	2002	C	3/4"	2006	SF	N	C		2006		Installation record	Y			Field inspection only	Y		
DAKOTA-306	N	C	N	1"	2002	P	1"	2010	SF	N	O		2010	PLUMBING MATERIAL-PLASTIC	Installation record	Y			Field inspection only	Y		
DAKOTA-308	N	C	N	1"	2002	C	1"	2005	SF	N	C		2005		Installation record	Y			Field inspection only	Y		
DAKOTA-400	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y		
DAKOTA-401	N	C	N	1"	2002	C	1"	2003	SF	Y	C		2003		Installation record	Y			Field inspection only	Y		
DAKOTA-402	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y		
DAKOTA-403	N	C	N	1"	2002	C	1"	2003	SF	Y	C		2003		Installation record	Y			Field inspection only	Y		
DAKOTA-405	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y		
DAKOTA-407	N	C	N	1"	2002	C	1"	2004	SF	Y	C		2004		Installation record	Y			Field inspection only	Y		
DAKOTA-409A	N	C	N	1"	2002	C	1"	2003	MF	N	C		2003		Installation record	Y			Field inspection only	Y		
DAKOTA-409B	N	C	N	1"	2002	C	1"	2003	MF	N	C		2003		Installation record	Y			Field inspection only	Y		
DAKOTA-410	N	C	N	1"	2002	C	1"	2016	SF	N	C		2016		Installation record	Y			Field inspection only	Y		
DAKOTA-411A	N	C	N	1"	2002	C	1"	2003	MF	N	C		2003		Installation record	Y			Field inspection only	Y		
DAKOTA-411B	N	C	N	1"	2002	C	1"	2003	MF	N	C		2003		Installation record	Y			Field inspection only	Y		
DIVISION-106	N	C	N	1"	2008	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-110	N	C	N	1"	2008	C	3/4"	1968	SF	N	C		1968		Installation record	Y			Field inspection only	Y		
DIVISION-111	N	C	N	1"	2008	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-115	N	C	N	1"	2008	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-116	N	C	N	1"	2008	C	1"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-121	N	C	N	1"	2008	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-124	N	C	N	1"	2008	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-125	N	C	N	1"	2008	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-128	N	C	N	1"	2008	C	3/4"	1972	SF	Y	C		1972		Installation record	Y			Field inspection only	Y		
DIVISION-134	N	C	N	1"	1998	C	3/4"	1977	SF	N	C		1977		Installation record	Y			Field inspection only	Y		
DIVISION-135	N	C	N	1"	2008	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
DIVISION-203	N	C	N	1"	1992	C	3/4"	1972	SF	Y	C		1972		Installation record	Y			Field inspection only	Y		
DIVISION-204	N	C	N	1"	1992	C	1"	1970	SF	N	C		1970		Installation record	Y			Field inspection only	Y		
DIVISION-207	N	C	N	1"	2021	C	1"	2021	SF	N	C		2021		Installation record	Y			Field inspection only	Y		
DIVISION-207	N	C	N	1"	1992	C	3/4"	1980	SF	N	C		1980		Installation record	Y			Field inspection only	Y		
DIVISION-209	N	C	N	1"	1998	C	3/4"	1977	SF	Y	C		1977		Installation record	Y			Field inspection only	Y		
DIVISION-213	N	C	N	1"	1998	C	3/4"	1976	SF	Y	C		1976		Installation record	Y			Field inspection only	Y		
DIVISION-215	N	C	N	1"	1998	C	1"	1990	SF	Y	C		1990		Installation record	Y			Field inspection only	Y		
DIVISION-218	N	C	N	1"	2021	C	1"	2021	SF	N	C		2021		Installation record	Y			Field inspection only	Y		
DIVISION-222	N	C	N	1"	1998	C	3/4"	1980	SF	Y	C		1980		Installation record	Y			Field inspection only	Y		
ELDER-121	N	C	N	1"	2016	C	1"	1980	SF	N	C		1980		Installation record	Y			Field inspection only	Y		
ELM-216	N	C	N	3/4"	1986	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
ELM-302	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
ELM-304	N	C	N	3/4"	1986	C	3/4"		SF						Installation record	Y			Field inspection only	Y		
ELM-306	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
ELM-308	N	C	N	3/4"	1986	C	1"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
ERICKSON-501	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
ERICKSON-503	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
ERICKSON-505	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
ERICKSON-507	N	C	N	3/4"	1986	P	3/4"		SF	N	O				Installation record	Y			Installation record	Y		
FINVOLD-106	N	C	N	1"	2016	C	3/4"	2022	SF				2022		Installation record	Y			Field inspection only	Y		
FINVOLD-110	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
FINVOLD-111	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
FINVOLD-115	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
FINVOLD-116	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
FINVOLD-121	N	C	N	1"	2016	C	3/4"	1981	SF	N	C		1981		Installation record	Y			Field inspection only	Y		
FINVOLD-303	N	C	N	1"	2004	C	1"	2006	SF	N	C		2006		Installation record	Y			Field inspection only	Y		
FINVOLD-305	N	C	N	1"	2024	P	1"	2024							Installation record	Y			Field inspection only	Y		
FINVOLD-307	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
FINVOLD-400	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
FINVOLD-401	N	C	N	1"	2004	C	1"	2006	SF	N	C		2006		Installation record	Y			Field inspection only	Y		
GEORGE-303	N	C	N	3/4"	1968	C	3/4"	1985	SF	N	C		1985		Installation record	Y			Field inspection only	Y		
GEORGE-305	N	C	N	3/4"	1968	C	3/4"	1986	SF	Y	C		1986		Installation record	Y			Field inspection only	Y		
GEORGE-307	N	C	N	3/4"	1968	C	3/4"	1976	SF	Y	C		1976		Installation record	Y			Field inspection only	Y		
GEORGE-309	N	C	N	3/4"	1968	C	1/2"	1975	SF	N	C		1975		Installation record	Y			Field inspection only	Y		
GEORGE-404	N	C	N	3/4"	1968	C	3/4"	1974	SF	N	C		1974		Installation record	Y			Field inspection only	Y		
GEORGE-406	N	C	N	3/4"	1968	C	3/4"	1980	SF	N	C		1980		Installation record	Y			Field inspection only	Y		
GEORGE-408	N	C	N	3/4"	1968	C	3/4"	1981	SF	N	C		1981		Installation record	Y			Field inspection only	Y		
GEORGE-410	N	C	N	3/4"	1968	C	3/4"	1974	SF	N	C		1974		Installation record	Y			Field inspection only	Y		
HAGEN-101	N	DI	N	6"	1996	DI	6"		NONRES		C	C			Installation record	Y			Field inspection only	Y		
HAGEN-102	N	DI	N	6"	1996	DI	6"		NONRES		C	O			Installation record	Y			Field inspection only	Y		
HAGEN-103	N	DI	N	6"	1996	C	1"		NONRES		C	O			Installation record	Y			Field inspection only	Y		
HAGEN-105	N	DI	N	6"	1998	C	1"		NONRES						Installation record	Y			Field inspection only	Y		
HAGEN-107	N	DI	N	6"	1996	DI	6"		NONRES		C	C			Installation record	Y			Field inspection only	Y		
HAGEN-108	N	C	N	1"	1996	C	1"		NONRES	N	C				Installation record	Y			Field inspection only	Y		
HANSON-301	N	C	N	3/4"	1970	C	3/4"		SF	N	O				Installation record	Y			Field inspection only	Y		
HANSON-302	N	C	N	3/4"	1970	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-303	N	C	N	3/4"	1970	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-304	N	C	N	3/4"	1970	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-305	N	C	N	3/4"	1970	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-306	N	C	N	3/4"	1970	C	3/4"		SF						Installation record	Y			Field inspection only	Y		
HANSON-307	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
HANSON-308	N	C	N	3/4"	1970	C	3/4"		SF						Installation record	Y			Field inspection only	Y		
HANSON-309	N	C	N	3/4"	1970	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-310	N	C	N	3/4"	1970	C	3/4"		SF						Installation record	Y			Field inspection only	Y		

HANSON-311	N	C	N	3/4"	1970	P	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-312	N	C	N	3/4"	1970	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-313	N	C	N	3/4"	1970	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-314	N	C	N	3/4"	1970	P	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-316	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
HANSON-318	N	C	N	3/4"	1970	P	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HANSON-320	N	C	N	3/4"	1970	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
HAZELNUT-301	N	C	N	1"	1997	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
HAZELNUT-302	N	C	N	1"	1997	C	1"	1999	SF	N	C		1999		Installation record	Y			Field inspection only	Y		
HAZELNUT-303	N	C	N	1"	1997	C	1"	2001	SF	Y	C		2001		Installation record	Y			Field inspection only	Y		
HAZELNUT-304	N	C	N	1"	1997	C	1"	1999	SF	N	C		1999		Installation record	Y			Field inspection only	Y		
HAZELNUT-305	N	C	N	1"	1997	C	3/4"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y		
HAZELNUT-306	N	C	N	1"	1997	C	1"	2001	SF	Y	C		2001		Installation record	Y			Field inspection only	Y		
HAZELNUT-307	N	C	N	1"	1997	C	1"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y		
HAZELNUT-308	N	C	N	1"	1997	C	1"	2000	SF	Y	C		2000		Installation record	Y			Field inspection only	Y		
HAZELNUT-309	N	C	N	1"	1997	C	1"	2002	SF	N	C		2002		Installation record	Y			Field inspection only	Y		
HAZELNUT-310	N	C	N	1"	1997	C	3/4"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
HAZELNUT-311	N	C	N	1"	1997	C	1"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
HAZELNUT-312	N	C	N	1"	1997	C	1"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y		
HICKORY-201	N	C	N	1"	1991	C	1"	1999	SF	N	C		1999		Installation record	Y			Field inspection only	Y		
HICKORY-202	N	C	N	1"	1991	C	1"	1994	SF	Y	C		1994		Installation record	Y			Field inspection only	Y		
HICKORY-203	N	C	N	1"	1991	C	1"	1992	SF	Y	C		1992		Installation record	Y			Field inspection only	Y		
HICKORY-204	N	C	N	1"	1991	C	1"	1993	SF	Y	C		1993		Installation record	Y			Field inspection only	Y		
HICKORY-205	N	C	N	1"	1991	C	1"	1995	SF	N	C		1995		Installation record	Y			Field inspection only	Y		
HICKORY-206	N	C	N	1"	1991	C	1"	1991	SF	N	C		1991		Installation record	Y			Field inspection only	Y		
HICKORY-207	N	C	N	1"	1991	C	3/4"	1993	SF	N	C		1993		Installation record	Y			Field inspection only	Y		
HIMO-200	N	C	N	1"	1998	C	1"	2017	SF	Y	C		2017		Installation record	Y			Field inspection only	Y		
HIMO-210	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
HIMO-211	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
HIMO-216	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
HIMO-220	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
HIMO-300	N	C	N	1"	1998	C	1"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y		
HIMO-305	N	C	N	1"	1998	C	3/4"	1973	SF	N	C		1973		Installation record	Y			Field inspection only	Y		
HIMO-306	N	C	N	1"	1998	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y		
HIMO-310	N	C	N	1"	1998	C	1"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y		
HIMO-314	N	C	N	1"	1998	C	1"	1990	SF	Y	C		1990		Installation record	Y			Field inspection only	Y		
HIMO-401	N	C	N	1"	1998	C	1"	1994	SF	Y	C		1994		Installation record	Y			Field inspection only	Y		
IVY-101	N	C	N	1"	1991	C	3/4"	1993	SF	N	C		1993		Installation record	Y			Field inspection only	Y		
IVY-102	N	C	N	1"	1991	C	1"	1995	SF	N	C		1995		Installation record	Y			Field inspection only	Y		
IVY-103	N	C	N	1"	1991	C	3/4"	1993	SF	N	C		1993		Installation record	Y			Field inspection only	Y		
IVY-104	N	C	N	1"	1991	C	3/4"	1999	SF	N	C		1999		Installation record	Y			Field inspection only	Y		
IVY-105	N	C	N	1"	1991	C	1"	1995	SF	Y	C		1995		Installation record	Y			Field inspection only	Y		
JOHNSON-201	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-205	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-211	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-215	N	C	N	1"	2015	C	1"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-221	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-225	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-231	N	C	N	1"	2015	C	1"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-235	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-241	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-245	N	C	N	1"	2015	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-251	N	C	N	1"	2015	C	1"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
JOHNSON-255	N	C	N	1"	2015	C	3/4"	1976	SF	N	C		1976		Installation record	Y			Field inspection only	Y		
JOHNSON-401	N	C	N	3/4"	1970	C	3/4"	1994	SF	N	C		1994		Installation record	Y			Field inspection only	Y		
JOHNSON-402	N	C	N	3/4"	1986	P	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-403	N	C	N	3/4"	1970	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-404	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-405	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
JOHNSON-406	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-407	N	C	N	3/4"	1970	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-408	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-409	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
JOHNSON-410	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-411	N	C	N	3/4"	1970	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-412	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-413	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
JOHNSON-414	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-415	N	C	N	3/4"	1971	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
JOHNSON-416	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-417	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
JOHNSON-418	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-419	N	C	N	3/4"	1970	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
JOHNSON-420	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
LENA-301	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
LENA-302	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
LENA-303	N	C	N	3/4"	1986	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
LENA-304	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
LENA-305	N	C	N	3/4"	1986	C	3/4"		SF						Installation record	Y			Field inspection only	Y		
LENA-306	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
LENA-307	N	C	N	3/4"	1986	P	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
LENA-308	N	C	N	3/4"	1986	P	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y		
LILAC-703	N	C	N	1"	1997	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y		
LILAC-704	N	C	N	1"	1997	C	1"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y		
LILAC-705	N	C	N	1"	1997	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y		
LILAC-706	N	C	N	1"	1997	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y		
LILAC-707	N	C	N	1"	1997	C	1"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y		
LILAC-708	N	C	N	1"	1997	C	1"	2002	SF	N	C		2002		Installation record	Y			Field inspection only	Y		
LILAC-709	N	C	N	1"	1997	C	3/4"	2002	SF	N	C		2002		Installation record	Y			Field inspection only	Y		

LILAC-710	N	C	N	1"	1997	C	3/4"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y	
LILAC-711	N	C	N	1"	1997	C	1"	2001	SF	N	C		2001		Installation record	Y			Field inspection only	Y	
LILAC-712	N	C	N	1"	1997	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
LOCKWOOD-101	N	C	N	1"	2018	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
LOCKWOOD-200	N	C	N	3/4"	1985	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y	
LOCKWOOD-210	N	DI	N	6"		DI	6"		MF						Installation record	Y			Field inspection only	Y	
LOCKWOOD-220	N	DI	N	6"	1985	DI	6"		NONRES						Installation record	Y			Field inspection only	Y	
LOCKWOOD-221	N	C	N	1"	2015	C	3/4"		NONRES	N					Installation record	Y			Field inspection only	Y	
LOCKWOOD-241	UNK	UNK-LG	N	3/4"	1950	C	3/4"	1960	SF	Y	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
LOCKWOOD-245	UNK	UNK-LG	N	3/4"	1950	C	3/4"	1960	SF	Y	O	O	1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
LOCKWOOD-251	UNK	C	N	3/4"	1950	C	3/4"	1980	SF	Y	C		1980		Installation record	Y			Field inspection only	Y	
LOCKWOOD-261	N	C	N	3/4"	1992	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
LOCKWOOD-300	UNK	C	N	3/4"	1962	C	3/4"		SF	N	C				SL repair/replace record	Y			Field inspection only	Y	
LOCKWOOD-305	N	C	N	3/4"	1950	C	3/4"	1962	SF	Y	C		1962		Installation record	Y			Field inspection only	Y	
LOCKWOOD-306	UNK	C	N	3/4"	1962	C	3/4"		SF	N	C				SL repair/replace record	Y			Field inspection only	Y	
LOCKWOOD-310	UNK	C	N	3/4"	1962	C	1/2"		SF	N	C				SL repair/replace record	Y			Field inspection only	Y	
LOCKWOOD-315	UNK	UNK-LG	N	3/4"	1950	C	3/4"	1960	SF	N	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
LOCKWOOD-316	UNK	C	N	3/4"	1962	C	3/4"		SF	N	C				SL repair/replace record	Y			Field inspection only	Y	
LOCKWOOD-321	UNK	UNK-LG	N	3/4"	1950	C	3/4"	1960	SF	N	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
LOCKWOOD-330	UNK	C	N	3/4"	1950	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
LOCKWOOD-331	UNK	UNK-LG	N	3/4"	1950	C	3/4"	1965	SF	N	C		1965		Other - describe in notes	N			Field inspection only	Y	eet side: no records
LOCKWOOD-335	UNK	UNK-LG	N	3/4"	1950	C	3/4"	1960	SF	Y	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
LOCKWOOD-340	N	C	N	3/4"	1950	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
LOCKWOOD-341	UNK	C	N	3/4"	1950	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
MAIN-102	N	C	N	1"	2019	C	1"		NONRES		C	C			Installation record	Y			Field inspection only	Y	
MAIN-110	N	C	N	1"	1998	C	3/4"	1960	NONRES	N	C	C	1960		Installation record	Y			Field inspection only	Y	
MAIN-114	N	C	N	1"	1998	C	3/4"	1960	MF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAIN-120	N	C	N	1"	1998	C	3/4"	1960	SF	N	C	C	1960		Installation record	Y			Field inspection only	Y	
MAIN-124	N	C	N	1"	1998	C	3/4"	1998	NONRES	N	C	C	2012		Installation record	Y			Field inspection only	Y	
MAIN-130	N	C	N	1"	2019	C	3/4"		NONRES		C	C			Installation record	Y			Field inspection only	Y	
MAIN-131	N	DI	N	4"	1998	DI	4"		NONRES		O	C			Installation record	Y			Field inspection only	Y	
MAIN-134	N	C	N	1"	1998	C	3/4"	1977	MF	N	C		1977		Installation record	Y			Field inspection only	Y	
MAIN-140	N	C	N	1"	1998	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
MAIN-145	N	C	N	1"	1998	C	1"		NONRES		C	C			Installation record	Y			Field inspection only	Y	
MAIN-206	N	C	N	1"	2019	C	3/4"		NONRES		C	O			Installation record	Y			Field inspection only	Y	
MAIN-207	N	C	N	1"	2019	C	1"	1980	MF	N	C	C	1980		Installation record	Y			Field inspection only	Y	
MAIN-209	N	C	N	1"	2019	C	1"	1974	MF	N	C	C	1974		Installation record	Y			Field inspection only	Y	
MAIN-210	N	C	N	1"	2019	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAIN-211	N	C	N	1"	2019	C	3/4"	1970	MF	N	C		1970		Installation record	Y			Field inspection only	Y	
MAIN-213	N	C	N	1"	2019	C	3/4"	1970	MF	N	C		1970		Installation record	Y			Field inspection only	Y	
MAIN-216	N	C	N	1"	2019	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAIN-220	N	C	N	1"	2019	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAIN-226	N	C	N	1"	2019	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAIN-230	N	C	N	1"	2019	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAIN-400	N	C	N	1"	2001	C	1"	2001	SF				2001	HOUSE GUTTED/WATER SHUT-OFF	Installation record	Y			Installation record	Y	
MAPLE-300	N	C	N	1"	2016	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
MAPLE-301	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-305	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-306	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-307	N	C	N	1"	2016	C	3/4"	1980	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-314	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-315	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-320	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-321	N	C	N	1"	2016	C	3/4"	1960	MF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-325	N	C	N	1"	2016	C	3/4"	1960	SF	N	C	O	1960	PLUMBING MATERIAL 2-PLEX	Installation record	Y			Field inspection only	Y	
MAPLE-400	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-406	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-410	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-411	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-415	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-416	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-420	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-421	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-426	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MAPLE-428	N	C	N	1"	2016	C	3/4"	1986	SF	N	C		1986		Installation record	Y			Field inspection only	Y	
MAPLE-429	N	C	N	2"	2022	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
MATHISON-105	UNK	UNK-LG	UNK		1923	C	3/4"	1960	SF	Y	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
MATHISON-111	UNK	UNK-LG	UNK		1923	G	1"	1960	SF	N	O		1960	PLUMBING MATERIAL-STEEL	Other - describe in notes	N			Field inspection only	Y	eet side: no records
MATHISON-115	UNK	UNK-LG	UNK		1923	G	3/4"	1960	SF	N	O		1960	PLUMBING MATERIAL-STEEL	Other - describe in notes	N			Field inspection only	Y	eet side: no records
MATHISON-121	UNK	UNK-LG	UNK		1923	C	3/4"	1960	SF	N	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records
MATHISON-122	N	C	N	3/4"	1985	C	3/4"	1962	SF	Y	C		1962		Installation record	Y			Field inspection only	Y	
MATHISON-125	N	C	N	3/4"	1985	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MATHISON-131	N	C	N	1"	1985	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MATHISON-301	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
MCMILLAN #1-300	N	C	N	1"	1988	C	3/4"		NONRES		C				Installation record	Y			Field inspection only	Y	
MCMILLAN-470	N	DI	N	6"	1980	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
MEADOW-101	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
MEADOW-102	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
MEADOW-103	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
MEADOW-105	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
MEADOW-107	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
MEADOW-109	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
MEADOW-111	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
MEADOW-201	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
MEADOW-202	N	C	N	1"	2002	C	1"	2004	SF	Y	C		2004		Installation record	Y			Field inspection only	Y	
MEADOW-203	N	C	N	1"	2002	C	1"	2003	SF	Y	C		2003		Installation record	Y			Field inspection only	Y	
MEADOW-205	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
MEADOW-207	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
MEADOW-209	N	C	N	1"	2002	C	3/4"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	

MEADOW-211	N	C	N	1"	2002	C	3/4"	2003	SF	Y	C		2003		Installation record	Y			Field inspection only	Y	
MEADOW-301	N	C	N	1"	2002	C	3/4"	2003	SF				2003		Installation record	Y			Field inspection only	Y	
MEADOW-303	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
NORDIC MALL #3	N	DI	N	6"	1978	DI	6"		NONRES						Installation record	Y			Field inspection only	Y	
NORSKE-300	N	C	N	1"	2004	C	3/4"	2022	SF				2022		Installation record	Y			Field inspection only	Y	
NORSKE-302	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-303	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-304	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-305	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-306	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-307	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-308	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-309	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-310	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-311	N	C	N	1"	2004	C	3/4"	2019	SF				2019		Installation record	Y			Field inspection only	Y	
NORSKE-312	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-313	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-314	N	C	N	1"	2004	C	3/4"	2019	SF				2019		Installation record	Y			Field inspection only	Y	
NORSKE-315	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-316	N	C	N	1"	2004	C	3/4"	2019	SF				2019		Installation record	Y			Field inspection only	Y	
NORSKE-317	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-318	N	C	N	1"	2004	C	3/4"	2018	SF				2018		Installation record	Y			Field inspection only	Y	
NORSKE-319	N	C	N	1"	2004	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
NORSKE-320	N	C	N	1"	2004	C	3/4"	2018	SF				2018		Installation record	Y			Field inspection only	Y	
NORSKE-321	N	C	N	1"	2004	C	1"	2006	SF	Y	C		2006		Installation record	Y			Field inspection only	Y	
NORSKE-322	N	C	N	1"	2004	C	3/4"	2021	SF				2021		Installation record	Y			Field inspection only	Y	
OAK #1-331	N	C	N	3/4"	1978	C	3/4"	1991	MF	N	C		1991		Installation record	Y			Field inspection only	Y	
OAK #1-333	N	C	N	3/4"	1978	C	3/4"	1990	MF	N	C		1990		Installation record	Y			Field inspection only	Y	
OAK #1-335	N	C	N	3/4"	1978	C	3/4"	1989	SF	N	C		1989		Installation record	Y			Field inspection only	Y	
OAK #2-331	N	C	N	3/4"	1978	C	3/4"	1991	MF	N	C		1991		Installation record	Y			Field inspection only	Y	
OAK #2-333	N	C	N	3/4"	1978	C	3/4"	1990	MF	N	C		1990		Installation record	Y			Field inspection only	Y	
OAK #2-335	N	C	N	3/4"	1978	C	3/4"	1989	MF	N	C		1989		Installation record	Y			Field inspection only	Y	
OAK BLDG A-202	N	C	N	1 1/2"	1994	C	1 1/2"	1994	MF				1994		Installation record	Y			Field inspection only	Y	
OAK BLDG B-200	N	C	N	1 1/2"	1994	C	1 1/2"	1994	MF				1994		Installation record	Y			Field inspection only	Y	
OAK BLDG C-204	N	C	N	1 1/2"	1994	C	1 1/2"	1994	MF				1994		Installation record	Y			Field inspection only	Y	
OAK192-1043-30-000	N	DI	N	6"	2023	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
OAK-223	N	C	N	1 1/2"	1978	C	1 1/2"		MF						Installation record	Y			Field inspection only	Y	
OAK-227	N	C	N	3/4"	1978	C	3/4"		MF						Installation record	Y			Field inspection only	Y	
OAK-302	N	C	N	3/4"	1978	C	3/4"	1985	SF	N	C		1985		Installation record	Y			Field inspection only	Y	
OAK-441	N	C	N	3/4"	1978	C	3/4"	1980	SF	N	C		1980		Installation record	Y			Field inspection only	Y	
OAK-443	N	C	N	3/4"	1978	C	3/4"	1979	SF	N	C		1979		Installation record	Y			Field inspection only	Y	
OAK-445	N	C	N	3/4"	1978	C	3/4"	1979	SF	N	C		1979		Installation record	Y			Field inspection only	Y	
OAK-500	N	C	N	3/4"	1978	C	3/4"	1986	SF	N	C		1986		Installation record	Y			Field inspection only	Y	
OAK-551	N	C	N	3/4"	1978	C	3/4"	1985	SF	N	C		1985		Installation record	Y			Field inspection only	Y	
OAK-553	N	C	N	3/4"	1978	C	3/4"	1986	SF	N	C		1986		Installation record	Y			Field inspection only	Y	
OAK-555	N	C	N	3/4"	1978	C	3/4"	1987	SF	N	C		1987		Installation record	Y			Field inspection only	Y	
OAK-602	N	C	N	3/4"	1978	C	1"	1985	SF	N	C		1985		Installation record	Y			Field inspection only	Y	
OAK-640	N	C	N	3/4"	1978	C	3/4"	1989	SF	N	C		1989		Installation record	Y			Field inspection only	Y	
OAK-657	N	C	N	3/4"	1978	C	1"	1985	SF	Y	C		1985		Installation record	Y			Field inspection only	Y	
OLD B-555	N	C	N	1"	2022	C	1"	2022	NONRES	N	C		2022		Installation record	Y			Field inspection only	Y	
OLD B-581	N	C	N	1"	2000	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
OLD B-596	N	C	N	1"	2009	C	1"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y	
OLD B-598	N	C	N	1"	2017	C	1"	2017	SF	Y	C		2017		Installation record	Y			Field inspection only	Y	
OLE-301	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y	
OLE-303	N	C	N	3/4"	1986	P	3/4"		SF	N	O				Installation record	Y			Field inspection only	Y	
OLE-305	N	C	N	3/4"	1986	C	3/4"		SF	N	C	O			Installation record	Y			Field inspection only	Y	
OLE-307	N	C	N	3/4"	1986	C	1/2"		SF	N	C	O			Installation record	Y			Field inspection only	Y	
OLSON-201	UNK	C	N	3/4"	1962	C	3/4"		SF	N	C				SL repair/replace record	Y			Field inspection only	Y	
OLSON-202	N	C	N	3/4"	1970	C	3/4"		SF						Installation record	Y			Field inspection only	Y	
OLSON-204	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
OLSON-206	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
OLSON-207	UNK	C	N	3/4"	1962	P	1/2"		SF	N	C				SL repair/replace record	Y			Field inspection only	Y	
OLSON-208	N	C	N	3/4"	1970	C								EMPTY LOT	Installation record	Y			Field inspection only	Y	ty side: SL does not exist
OLSON-209	UNK	C	N	3/4"	1962	C	1/2"		SF	N	C				Field inspection only	N			Field inspection only	Y	
OLSON-210	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
OLSON-212	N	C	N	3/4"	1970	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
OLSON-214	N	C	N	3/4"	1970	P	3/4"		SF	N	C				Installation record	Y			Field inspection only	Y	
OLSON-215	UNK	C	N	3/4"	1962	C	3/4"		SF	N	C				Field inspection only	N			Field inspection only	Y	
PARK #1-113	N	DI	N	6"	2016	C	2"	2016	NONRES						Installation record	Y			Field inspection only	Y	
PARK #2-113	N	C	N	1"	1985	C	1"		NONRES						Installation record	Y			Field inspection only	Y	
PARK-101	N	C	N	1"	2003	C	1"		NONRES		C	C			Installation record	Y			Field inspection only	Y	
PARK-103	N	DI	N	6"	2003	DI	6"		NONRES		C	C			Installation record	Y			Field inspection only	Y	
PARK-104	N	DI	N	8"	2000	DI	8"		NONRES		C	C			Installation record	Y			Field inspection only	Y	
PARK-192-1053-90-050	N	DI	N	6"	2000	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
PARK-192-1053-90-050	N	DI	N	6"	2000	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
PRAIRIE-100	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
PRAIRIE-102	N	C	N	1"	2002	C	1"	2004	SF	Y	C		2004		Installation record	Y			Field inspection only	Y	
PRAIRIE-103	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
PRAIRIE-104	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
PRAIRIE-105	N	C	N	1"	2002	P	1"	2009	SF	N	O		2009	PLUMBING MATERIAL-PLASTIC	Installation record	Y			Field inspection only	Y	
PRAIRIE-106	N	C	N	1"	2002	C	1"	2008	SF	Y	C		2008		Installation record	Y			Field inspection only	Y	
PRAIRIE-107	N	C	N	1"	2002	C	1"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
PRAIRIE-108	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
PRAIRIE-109	N	C	N	1"	2002	C	1"	2006	SF	Y	C		2006		Installation record	Y			Field inspection only	Y	
PRAIRIE-110	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist
PRAIRIE-111	N	C	N	1"	2002	C	3/4"	2003	SF	N	C		2003		Installation record	Y			Field inspection only	Y	
RIVER-105	N	C	N	3/4"	1992	C	3/4"		SF						Installation record	Y			Field inspection only	Y	
RIVER-106	N	C	N	1"	2018	C	3/4"		SF		C	C			Installation record	Y			Field inspection only	Y	
RIVER-111	N	C	N	1"	1992	C	3/4"	1960	SF	N	UNK		1960		Installation record	Y			Field inspection only	Y	

RIVER-121	N	C	N	1"	1992	C	3/4"		NONRES		C	C			Installation record	Y			Field inspection only	Y		
RIVER-124	N	C	N	1"	1992	C	1"		NONRES		C	C			Installation record	Y			Field inspection only	Y		
RIVER-131	N	C	N	1"	1992	C	3/4"		SF		C	C			Installation record	Y			Field inspection only	Y		
RIVER192-1033-70-000	N	C	N	1"	1992	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
RIVER-211	UNK	C	N	1"	1968	C	1"		NONRES		C	C			Installation record	Y			Field inspection only	Y		
RIVER-215	UNK	C	N	3/4"	1968	C	3/4"	1920	SF	N	C		1920		Installation record	Y			Field inspection only	Y		
RIVER-216	N	DI	N	6"	2013	DI	6"	2013	NONRES		C	C	2013		Installation record	Y			Field inspection only	Y		
RIVER-218	N	C	N	1"	2013	C	3/4"		NONRES		C	O			Installation record	Y			Field inspection only	Y		
RIVER-221	UNK	C	N	3/4"	1968	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y		
RIVER-225	N	C	N	1"	2016	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
RIVER-231	N	C	N	1"	2016	C	3/4"	1960	SF	N				HOUSE GUTTED/WATER SHUT-OFF	Installation record	Y			Installation record	Y		
RIVER-231	N	C	N	1"	2016	C	3/4"	1960	SF				1960		Installation record	Y			Field inspection only	Y		
ROSENLUND-312	N	UNK-LG	UNK		1923	C	3/4"	1960	SF	N	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-314	UNK	UNK-LG	UNK		1923	C	3/4"	1960	SF	Y	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-315	UNK	UNK-LG	UNK		1923	C	1"	1960	SF	N	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-317	UNK	UNK-LG	UNK		1923	C	3/4"	1971	SF	N	C		1971		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-320	UNK	UNK-LG	UNK		1923	C	3/4"	1960	SF	N	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-321	UNK	UNK-LG	UNK		1923	C	3/4"	1971	SF	N	C		1971		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-324	UNK	UNK-LG	UNK		1923	C	3/4"	1960	SF	N	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-330	UNK	UNK-LG	UNK		1923	C	3/4"	1960	SF	Y	C		1960		Other - describe in notes	N			Field inspection only	Y	eet side: no records	
ROSENLUND-415	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
ROSENLUND-417	N	C	N	1"	1998	C	1"	2002	SF	N	C		2002		Installation record	Y			Field inspection only	Y		
ROSENLUND-501	N	C	N	1"	1998	G	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
ROSENLUND-503	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
ROSENLUND-504	N	C	N	1"	1998	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y		
ROSENLUND-505	N	C	N	1"	1998	C	1"	1999	NONRES	Y	C		1999		Installation record	Y			Field inspection only	Y		
ROSENLUND-507	N	C	N	1"	1998	C	1"	1995	SF	N	C		1995		Installation record	Y			Field inspection only	Y		
ROSENLUND-510	N	C	N	1"	1998	G	1"	1960	SF	Y	O		1960	PLUMBING MATERIAL-STEEL	Installation record	Y			Field inspection only	Y		
RUSSEL-203	N	C	N	3/4"	1968	C	3/4"	1974	SF	Y	C		1974		Installation record	Y			Field inspection only	Y		
RUSSEL-205	N	C	N	3/4"	1968	C	3/4"	1976	SF	Y	C		1976		Installation record	Y			Field inspection only	Y		
RUSSEL-207	N	C	N	3/4"	1968	C	3/4"	1970	SF	N	C		1970		Installation record	Y			Field inspection only	Y		
RUSSEL-209	N	C	N	3/4"	1968	C	3/4"	1974	SF	N	C		1974		Installation record	Y			Field inspection only	Y		
RUSSEL-304	N	C	N	3/4"	1968	C	3/4"	1976	SF	Y	C		1976		Installation record	Y			Field inspection only	Y		
RUSSEL-306	N	C	N	3/4"	1968	C	3/4"	1978	SF	N	C		1978		Installation record	Y			Field inspection only	Y		
RUSSEL-308	N	C	N	3/4"	1968	C	3/4"	1978	SF	N	C		1978		Installation record	Y			Field inspection only	Y		
RUSSEL-310	N	C	N	3/4"	1968	C	3/4"	1965	SF	N	C		1965		Installation record	Y			Field inspection only	Y		
SOLUM #1-207	N	C	N	1"	1991	C	3/4"	1995	MF	N	C		1995		Installation record	Y			Field inspection only	Y		
SOLUM #1-209	N	C	N	1"	1991	C	1"	1995	MF	N	C		1995		Installation record	Y			Field inspection only	Y		
SOLUM #2-207	N	C	N	1"	1991	C	1"	1995	MF	N	C		1995		Installation record	Y			Field inspection only	Y		
SOLUM #2-209	N	C	N	1"	1991	C	1"	1995	MF	N	C		1995		Installation record	Y			Field inspection only	Y		
SOLUM-202	N	C	N	1"	1991	C	3/4"	1992	SF	N	C		1992		Installation record	Y			Field inspection only	Y		
SOLUM-203	N	C	N	1"	1991	C	3/4"	1994	SF	N	C		1994		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-345	N	DI	N	6"	2001	C	6"	2019	NONRES	N	C		2019		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-400	N	C	N	3/4"	1983	C	3/4"	1994	SF	N	C		1994		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-407	N	C	N	3/4"	1968	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-500	N	C	N	1"	2009	C	1"	2009	SCH/DC						Installation record	Y			Field inspection only	Y		
SOUTHSIDE-500	N	DI	N	6"	2009	DI	6"	2009	SCH/DC						Installation record	Y			Field inspection only	Y		
SOUTHSIDE-504	N	C	N	3/4"	1968	C	3/4"	1978	SF	Y	C		1978		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-505	N	C	N	3/4"	1968	C	3/4"	1978	SF	N	C		1978		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-507	N	C	N	3/4"	1968	C	3/4"	1975	SF	N	C		1975		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-509	N	C	N	3/4"	1968	C	3/4"	1993	SF	N	C		1993		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-511	N	C	N	3/4"	1968	C	3/4"	1972	SF	N	C		1972		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-603	N	C	N	3/4"	1978	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
SOUTHSIDE-604	N	C	N	1"	2022	C	3/4"	2022	SF	N	O		2022	Building Plumbing Material-Plastic	Installation record	Y			Field inspection only	Y		
SOUTHSIDE-605	N	C	N	3/4"	1978	C	3/4"	1990	SF	N	C		1990		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-606A	N	C	N	1"	2012	C	1"	2012	MF	N	C		2012		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-606B	N	C	N	1"	2012	C	1"	2012	MF	N	C		2012		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-607	N	C	N	3/4"	1978	C	3/4"	1989	SF	N	C		1989		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-608A	N	C	N	1"	2010	C	1"	2010	MF	N	C		2010		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-608B	N	C	N	1"	2010	C	1"	2010	MF	N	C		2010		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-701	N	C	N	1"	1997	C	3/4"	2002	SF	N	C		2002		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-801	N	C	N	1"	1997	C	3/4"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-803	N	C	N	1"	1997	C	3/4"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-901	N	C	N	1"	1997	C	1"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-902	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-903	N	C	N	1"	1997	C	1"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-905	N	C	N	1"	1997	C	1"	2021	SF	N	C		2021		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-906	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-906	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-907	N	C	N	1"	1997	C	1"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-908	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-909	N	C	N	1"	1997	C	3/4"	2007	SF	Y	C		2000		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-910	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-911	N	C	N	1"	1997	P	1"	2007	SF	N	O		2000	PLUMBING MATERIAL-PLASTIC	Installation record	Y			Field inspection only	Y		
SOUTHSIDE-912	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-913	N	C	N	1"	1997	C	1"	2006	SF	N	C		2006		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-914	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-915	N	C	N	1"	1997	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes		Property side: SL does not exist	
SOUTHSIDE-916	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-917	N	C	N	1"	1997	C	3/4"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-918	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-920	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-922	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-924	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-926	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SOUTHSIDE-928	N	C	N	1"	1997	C	1"	2020	SF	N	C		2020		Installation record	Y			Field inspection only	Y		
SPRUCE-301	N	C	N	3/4"	1978	C	3/4"	1984	SF	N	C		1984		Installation record	Y			Field inspection only	Y		
SPRUCE-303	N	C	N	3/4"	1978	C	3/4"	1983	SF	N	C		1983		Installation record	Y			Field inspection only	Y		
SPRUCE-304	N	C	N	3/4"	1978	C	3/4"	1993	SF	N	C		1993		Installation record	Y			Field inspection only	Y		

SPRUCE-305	N	C	N	3/4"	1978	C	3/4"	1982	SF	N	C		1982		Installation record	Y			Field inspection only	Y	
SPRUCE-306	N	C	N	3/4"	1978	C	3/4"	1987	SF	Y	C		1987		Installation record	Y			Field inspection only	Y	
SPRUCE-307	N	C	N	3/4"	1978	C	3/4"	1983	SF	N	C		1983		Installation record	Y			Field inspection only	Y	
SPRUCE-308	N	C	N	3/4"	1978	C	3/4"	1993	SF	N	C		1993		Installation record	Y			Field inspection only	Y	
SPRUCE-309	N	C	N	3/4"	1978	C	3/4"	1991	SF	N	C		1991		Installation record	Y			Field inspection only	Y	
STENE-135	N	DI	N	6"	1978	DI	6"		NONRES	N	C	C			Installation record	Y			Field inspection only	Y	
STOCKMAN-116	N	C	N	1"	2018	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-120	N	C	N	1"	2018	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-121	N	C	N	1"	2018	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-192-1023-40-201	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes	Property side: SL does not exist	
STOCKMAN192-1023-40-250	N	C	N	1"	2002	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes	Property side: SL does not exist	
STOCKMAN-200	N	C	N	1"	2018	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-201	N	C	N	1"	2018	C	3/4"	1965	SF	Y	C		1965		Installation record	Y			Field inspection only	Y	
STOCKMAN-210	N	C	N	1"	2018	C	3/4"	1980	MF	N	C		1980		Installation record	Y			Field inspection only	Y	
STOCKMAN-219	N	C	N	1"	2018	C	3/4"	1965	SF	N	C		1965		Installation record	Y			Field inspection only	Y	
STOCKMAN-301	N	C	N	1"	2018	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-306	N	C	N	1"	2018	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-310	N	C	N	1"	1998	C	3/4"	1960	SF	Y	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-316	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-321	N	C	N	1"	2002	C	1"	2006	SF	Y	C		2006		Installation record	Y			Field inspection only	Y	
STOCKMAN-400	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-410	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-415	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
STOCKMAN-416	N	C	N	1"	1998	C	3/4"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	
STOCKMAN-417	N	C	N	1"	2002	C	1"	2005	SF	N	C		2005		Installation record	Y			Field inspection only	Y	
STOCKMAN-500A	N	C	N	1"	1998	C	1"	1996	MF	N	C		1996		Installation record	Y			Field inspection only	Y	
STOCKMAN-500B	N	C	N	1"	1998	C	1"	1996	MF	N	C		1996		Installation record	Y			Field inspection only	Y	
STOCKMAN-501	N	C	N	1"	2002	C	1"	2007	SF	N	C		2007		Installation record	Y			Field inspection only	Y	
STOCKMAN-503	N	C	N	1"	2002	C	1"	2004	SF	N	C		2004		Installation record	Y			Field inspection only	Y	
STOCKMAN-608	N	C	N	1"	1998	C	1"	1993	SF	Y	C		1993		Installation record	Y			Field inspection only	Y	
THOMPSON-460	N	DI	N	6"	1968	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
THOMPSON-460	UNK	C	N	3/4"	1968	C	3/4"		NONRES						Installation record	Y			Field inspection only	Y	
THOMPSON-480	N	DI	N	6"	1968	DI	6"		NONRES						Installation record	Y			Field inspection only	Y	
TRIENT-101	N	DI	N	6"	1998	DI	6"		NONRES		C	O			Installation record	Y			Field inspection only	Y	
TRIENT-102	N	DI	N	6"	1998	C	1"		NONRES		C	O			Installation record	Y			Field inspection only	Y	
TRIENT-104	N	DI	N	6"	1998	DI	6"		NONRES						Installation record	Y			Field inspection only	Y	
TRIENT-106	N	DI	N	6"	1998	DI	6"		NONRES		C				Installation record	Y			Field inspection only	Y	
WALNUT-401	N	C	N	3/4"	1978	C	3/4"	1983	SF	N	C		1983		Installation record	Y			Field inspection only	Y	
WALNUT-402	N	C	N	3/4"	1978	C	3/4"	1983	SF	N	C		1983		Installation record	Y			Field inspection only	Y	
WALNUT-403	N	C	N	3/4"	1978	C	1"	1979	SF	Y	C		1979		Installation record	Y			Field inspection only	Y	
WALNUT-404	N	C	N	3/4"	1978	C	3/4"	1982	SF	Y	C		1982		Installation record	Y			Field inspection only	Y	
WALNUT-405	N	C	N	3/4"	1978	C	1/2"	1989	SF	N	C		1989		Installation record	Y			Field inspection only	Y	
WALNUT-406	N	C	N	3/4"	1978	C	3/4"	1989	SF	N	C		1989		Installation record	Y			Field inspection only	Y	
WALNUT-407	N	C	N	3/4"	1978	C	3/4"	1993	SF	Y	C		1993		Installation record	Y			Field inspection only	Y	
WATER-100	N	C	N	1"	1998	C	1"	2000	SF	N	C		2000		Installation record	Y			Field inspection only	Y	
WATER-103A	N	C	N	1"	1998	C	1"	2003	MF	N	C		2003		Installation record	Y			Field inspection only	Y	
WATER-103B	N	C	N	1"	1998	C	1"	2003	MF	N	C		2003		Installation record	Y			Field inspection only	Y	
WILLOW-503	N	C	N	3/4"	1978	DNE								EMPTY LOT	Installation record	Y			Other - describe in notes	Property side: SL does not exist	
WILLOW-504	N	C	N	3/4"	1978	C	3/4"	1984	SF	Y	C		1984		Installation record	Y			Field inspection only	Y	
WILLOW-505	N	C	N	3/4"	1978	C	3/4"	1982	SF	N	C		1982		Installation record	Y			Field inspection only	Y	
WILLOW-506	N	C	N	3/4"	1978	C	3/4"	1982	SF	N	C		1982		Installation record	Y			Field inspection only	Y	
WOOD-105	N	C	N	1"	2001	C	1"	2017	SF	N	C		2017		Installation record	Y			Field inspection only	Y	
WOOD-111	N	C	N	1"	2001	C	1"	1960	SF	N	C		1960		Installation record	Y			Field inspection only	Y	