
Item #4 - Extrication Equipment (Includes lots A, B, C, D, E & F)

All extrication pieces worked as they should when recently taken out of service. Includes miscellaneous hydraulic hoses shown in below photo. This was all replaced with battery powered equipment.



(A) Honda GXV120 Motor with HURST hydraulic power unit.



(B) HURST - Electric power unit (120v)





(C) Hurst - Hydraulic spreader with mounting bracket



(D) Hurst – Hydraulic Cutter with mounting bracket



(E) Hurst – 1 Long and 1 Short Hydraulic Ram with mounting brackets



(F) 12V hose reel with Hydraulic hose and quick connect fittings

