

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION		
	1097-1C WOODLAKE ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1989	SF	N	C		1989	Installation record	N				Installed after lead ban	N					
	178 SOUTH ROAD	N	p	Y	1 1/4"	2021	p	1 1/4"	2021	SF	N	C		2021	Sl repair/replace record	Y	2021	sp during install	oSL repair/replace recor	Y	2021	sp during install	or repair			
	375 WOODLAKE ROAD	N	C	N	1"	1983	C	1"	1993	SF	N	C	O	1993	Installation record	N				Installed after lead ban	N					
	708-A TREEHOUSE LANE	N	C	N	1"	1997	C	1"	1981	SF	N	C		1981	Installation record	N				Installed after lead ban	N					
	692-A TREEHOUSE LANE	N	C	N	1"	1997	C	1"	1996	SF	N	C		1996	Installation record	N				Installed after lead ban	N					
	1089-3C CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1990	SF	N	C		1990	Installation record	N				Installed after lead ban	N					
	902 MULBERRY LANE	N	C	N	1"	1981	C	1"	1986	SF	N	C		1986	Installation record	N				Installed after lead ban	N					
	910 MULBERRY LANE	N	C	N	1"	1981	C	1"	1984	SF	N	C		1984	Installation record	N				Installed after lead ban	N					
	922 MULBERRY LANE	N	C	N	1"	1981	C	1"	1982	SF	N	C		1982	Installation record	N				Installed after lead ban	N					
	477 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1990	SF	N	C		1990	Installation record	N				Installed after lead ban	N					
	1092-3D CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1991	SF	N	C		1998	Installation record	N				Installed after lead ban	N					
	340 WOODLAKE ROAD	N	C	N	1"	1983	C	1"	1993	SF	N	C		1993	Installation record	N				Installed after lead ban	N					
	632 SCHOOL STREET	N	C	N	1"	1973	C	1"	1973	SF	N	C		1973	Installation record	N				Installed after lead ban	N					
	556 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1993	SF	N	C		1984	Installation record	N			Visual insp at mete	Field inspection only	Y	2021				
	1116-A ASPEN COURT	N	C	N	1"	1981	C	1"	1984	SF	N	C		1981	Installation record	N				Installed after lead ban	N					
	916 MULBERRY LANE	N	C	N	1"	1981	C	1"	1984	SF	N	C		1984	Installation record	N				Installed after lead ban	N					
	716 GREEN TREE ROAD	N	C	N	1"	1969	C	1"	1975	SF	N	C		1975	Installation record	N				Field inspection only	Y					
	1092-2A CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1990	MF	N	C		1990	Installation record	N				Installed after lead ban	N	2021	sp during install	or repair		
	492 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1992	SF	N	C		1992	Installation record	N				Installed after lead ban	N					
	907 ASPEN ROAD	N	C	N	1"	1981	C	1"	1983	SF	N	C		1983	Installation record	N				Installed after lead ban	N					
	624 SCHOOL STREET	N	C	N	1"	1969	C	1"	1970	SF	N	C		1970	Installation record	N			Visual insp at mete	Field inspection only	Y	2021	'fusal insp at meter			
	920 ASPEN ROAD	N	C	N	1"	1981	C	1"	1984	SF	N	C		1984	Installation record	N				Installed after lead ban	N					
	370 WOODLAKE ROAD	N	C	N	1"	1983	C	1"	1991	SF	N	C		1991	Installation record	N				Installed after lead ban	N					
	638 PINE TREE ROAD	N	C	N	1"	1962	C	1"	1968	SF	N	C			Installation record	N			Visual insp at mete	Field inspection only	Y	2021				
	356 PHILIP DRIVE	N	C	N	1"	2001	C	1"	2002	SF	N	C		2002	Installation record	N				Installed after lead ban	N					
	575 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1992	SF	N	C		1992	Installation record	N				Installed after lead ban	N					
	937 ASPEN ROAD	N	C	N	1"	1981	C	1"	1982	SF	N	C		1982	Installation record	N				Installed after lead ban	N					
	1114-B ASPEN COURT	N	C	N	1"	1981	C	1"	1984	SF	N	C		1984	Installation record	N				Installed after lead ban	N					
	355 WOODLAKE COURT	N	C	N	1"	1993	C	1"	1992	SF	N	C		1992	Installation record	N				Installed after lead ban	N					
	915 MULBERRY LANE	N	C	N	1"	1981	C	1"	1984	SF	N	C		1984	Installation record	N				Installed after lead ban	N					
	698-A TREEHOUSE LANE	N	C	N	1"	1997	C	1"	1997	SF	N	C		1997	Installation record	N				Installed after lead ban	N					
	623 GREEN PLACE	N	C	N	1"	1969	C	1"	1969	SF	N	C			Installation record	N			2021	sp during install	oSL repair/replace recor	Y	2021	'fusal insp at meter		
	PARKSONAGE CHURCH STREET	N	p	N	1 1/4"	2021	p	1 1/4"	2021	SF	N	C		20	Sl repair/replace record	Y	2021	sp during install	o	Field inspection only	Y	2021	'fusal insp at meter			
	1118-B ASPEN COURT	N	C	N	1"	1981	C	1"	1983	SF	N	C		1983	Installation record	N				Installed after lead ban	N					
	4065 5TH ST	N	DI	N			DI			NONRES	N	C			Diameter > 2 inches	N				Diameter > 2 inches	N					
	1077-1A CREEKS CROSS ROAD	N	C	N	1 1/2"	1991	C	1 1/2"	1992	MF	N	C		1992	Installation record	N				Installed after lead ban	N					
	1077-2B CREEKS CROSS ROAD	N	C	N	1 1/2"	1991	C	1 1/2"	1992	MF	N	C		1992	Installation record	N				Installed after lead ban	N					
	128 E PARK LANE	N	C	N	1"	2001	C	1"	2001	SF	N	C		2001	Installation record	N			2001		Installed after lead ban	N				
	1005 ASPEN ROAD	N	C	N	1"	1981	C	1"	1985	SF	N	C		1985	Installation record	N				Installed after lead ban	N					
	901 ASPEN ROAD	N	C	N	1"	1981	C	1"	1989	SF	N	C			Installation record	N				Installed after lead ban	N					
	1003 ASPEN LANE	N	C	N	1"	1981	C	1"	1985	SF	N	C			Installation record	N				Installed after lead ban	N					
	1009 ASPEN LANE	N	C	N	1"	1981	C	1"	1985	SF	N	C			Installation record	N				Installed after lead ban	N					
	939 ASPEN ROAD	N	C	N	1"	1981	C	1"	1985	SF					Installation record	N				Installed after lead ban	N					
	1007 ASPEN ROAD	N	C	N	1"	1981	C	1"	1983	SF					Installation record	N				Installed after lead ban	N					
	390 WOODLAKE ROAD	N	C	N	1"	1983	C	1"	1994	SF					Installation record	N				Installed after lead ban	N					
	908 ASPEN ROAD	N	C	N	1"	1981	C	1"	1986	SF					Installation record	N				Installed after lead ban	N					
	1116-C ASPEN COURT	N	C	N	1"	1981	C	1"	1985	MF					Installation record	N				Installed after lead ban	N					
	460 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1994	SF					Installation record	N				Installed after lead ban	N					
	644 GREEN TREE ROAD	N	C	N	1"	1962	C	1"	1967	SF					Installation record	N				Installed after lead ban	N					
	362 WOODLAKE ROAD	N	C	N	1"	1983	C	1"	1993	SF					Installation record	N				Installed after lead ban	N					
	1090-B CREEKS CROSS ROAD	N	C	N	1 1/2"	1991	C	1 1/2"	1995	MF	N	C			Installation record	N				Installed after lead ban	N					
	626 GREEN TREE ROAD	N	C	N	1"	1962	C	1"	1985	SF					Installation record	N				Installed after lead ban	N					
	1116-A ASPEN COURT	N	C	N	1"	1981	C	1"	1986	MF					Installation record	N				Installed after lead ban	N					
	1098-A CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1995	MF	N	C			Installation record	N				Installed after lead ban	N					
	1114-C ASPEN COURT	N	C	N	1"	1981	C	1"	1984	MF					Installation record	N				Installed after lead ban	N					
	917 BAYBERRY LANE	N	C	N	1"	1981	C	1"	1985	SF					Installation record	N				Installed after lead ban	N					
	1088-A CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1995	MF					Installation record	N				Installed after lead ban	N					
	139 HIGHLAND DRIVE	N	C	N	1 1/4"	2021	C	1 1/4"	2021	NONRES	N	C			Sl repair/replace record	Y	2021	sp during install	oSL repair/replace recor	Y	2021	'fusal insp at meter				
	1114-D ASPEN COURT	N	C	N	1"	1981	C	1"	1984	MF					Installation record	N				Installed after lead ban	N					
	1116-D ASPEN COURT	N	C	N	1"	1981	C	1"	1986	MF					Installation record	N				Installed after lead ban	N					
	641 UPPER ROAD	N	C	N	1"	1976	C	1"	1976	SF					Installation record	N				Installation record	N					
	939 ASPEN ROAD	N	C	N	1"	1981	C	1"	1986	SF					Installation record	N				Installed after lead ban	N					
	824 LINDEN ROAD	N	C	N	1"	1978	C	1"	1979	SF					Installation record	N				Installation record	N					
	940 ASPEN ROAD	N	C	N	1"	1981	C	1"	1985	SF					Installation record	N				Installation record	N					
	634 PINE TREE ROAD	N	C	N	1"	1962	C	1"	1969	SF					Installation record	N				Installation record	N					
	1100 CREEKS CROSS COURT	N	C	N	1"	1986	C	1"	1996	SF	N	C			Installation record	N				Installed after lead ban	N					
	828 BRIARWOOD COURT	N	C	N	1"	1984	C	1"	1996	SF					Installation record	N				Installed after lead ban	N					
	924 BAYBERRY LANE	N	C	N	1"	1981	C	1"	1985	SF					Installation record	N				Installation record	N					
	1075-B CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1995	MF	N	C			Installation record	N				Installed after lead ban	N					
	1099 HIGHLAND DRIVE	N	C	N	1"	1995	C	1"	1995	SF					Installation record	N				Installed after lead ban	N					
	1105 ASPEN ROAD	N	C	N	1"	1981	C	1"	1985	SF					Installation record	N				Installed after lead ban	N					
	901 ASPEN ROAD	N	C	N	1"	1981	C	1"	1985	SF					Installation record	N				Installed after lead ban	N					
	516 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1993	SF	N	C			Installation record	N				Installed after lead ban	N					
	420 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1988	SF					Installation record	N				Installed after lead ban	N					
	420 WOODLAND ROAD	N	C	N	1"	2001	C	1"	2001	SF	N	C			Installation record	N			2001	sp during install	o	Field inspection only	Y	2001	sp during install	or repair
	WAEUDERHAUS	N	C	N	1"		C	1"		NONRES					Installation record	N				Field inspection only	Y		2024	'fusal insp at meter		
	1099 CREEKS CROSS COURT	N	C	N	1"	1991	C	1"	1993	MF					Installation record	N				Installed after lead ban	N					
	927 MULBERRY LANE	N	C	N	1"	1981	C	1"	1986	SF					Installation record	N				Installed after lead ban	N					
	1080 WOODLAKE ROAD	N	C	N	1"	1981	C	1"	1995	MF					Installation record	N				Installed after lead ban	N					

	516 GREEN TREE ROAD	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF					Sl repair/replace record	Y	2021	sp during install	oSL repair/replace record	Y	2021	sp during install or repair	
	1082-B CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1997	MF					Installation record	N		Installed after lead ban	N				
	1077-B CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1992	MF					Installation record	N		Installed after lead ban	N				
	1079 CREEKS CROSS ROAD	N	C	N	1"	1986	C	1"	2000	SF					Installation record	N		Installed after lead ban	N				
	1100 WOODLAKE ROAD	N	C	N	1"	1986	C	1"	1999	SF					Installation record	N		Installed after lead ban	N				
	361 OLMSTED COURT	N	C	N	1"	2001	C	1"	2003	SF					Installation record	N		Installed after lead ban	N				
	1078-A CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1998	MF					Installation record	N		Installed after lead ban	N				
	618 GREEN TREE ROAD	N	C	N	1"	1962	C	1"	1966	MF					Installation record	N		Previous eval	N				
	1020 ASPEN ROAD	N	C	N	3/4"	1981	C	1"	1987	SF					Installation record	N		Installed after lead ban	N				
	665 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2000	SF					Installation record	N		Installed after lead ban	N				
	705 WOODLAND ROAD	N	C	N	1"		C	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	484 SIR HOWARD CIRCLE	N	C	N	1"	1986	C	1"	1994	SF					Installation record	N		Installed after lead ban	N				
	1020 WOODLAKE ROAD	N	C	N	1"	1997	C	1"	1997	SF					Installation record	N		Installed after lead ban	N				
	711 VALLEY ROAD	N	C	N	1"	1965	C	1"	1965	SF					Field inspection only	Y	2021	Mech excav	Field inspection only	Y	2021	Mech excav	
	700 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	1998	SF					Installation record	N		Installed after lead ban	N				
	849 BRIARWOOD COURT	N	C	N	1"	1994	C	1"	2000	SF					Installation record	N		Installed after lead ban	N				
	830 COMMERCE LANE	N	C	N	1"	1997	C	1"	1995	NONRES					Installation record	N		Installed after lead ban	N				
	685 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2001	SF					Installation record	N		Installed after lead ban	N				
	912 BAYBERRY LANE	N	C	N	1"	1981	C	1"	1986	SF					Installation record	N		Installed after lead ban	N				
	704-B TREEHOUSE LANE	N	C	N	1"	1997	C	1"	1981	MF					Installation record	N		Previous eval	N				
	455 WOODLAKE ROAD	N	C	N	1"	1983	C	1"	1991	SF					Installation record	N		Installed after lead ban	N				
	1238 WOODLAND ROAD	N	C	N	1"		C	1"	1960	SF					Installation record	N		Installed after lead ban	N				
	625 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2000	SF					Installation record	N		Installed after lead ban	N				
	1089-2A CREEKS CROSS ROAD	N	C	N	1 1/2"	1986	C	1 1/2"	1990	MF					Installation record	N		Installed after lead ban	N				
	363 OLMSTED COURT	N	C	N	1"	2001	C	1"	2003	SF					Installation record	N		Installed after lead ban	N				
	600 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2001	SF					Installation record	N		Installed after lead ban	N				
	319 PHILIP DRIVE	N	C	N	1"	2001	C	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	229 PHILIP COURT	N	C	N	1"	2001	C	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	357 PHILIP DRIVE	N	C	N	1"	2001	C	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	630 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	1999	SF					Installation record	N		Installed after lead ban	N				
	615 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2001	SF					Installation record	N		Installed after lead ban	N				
	632 GREEN TREE ROAD	N	C	N	1"	1962	C	1"	1969	SF					Installation record	N		Previous eval	N				
	365 OLMSTED COURT	N	C	N	1"	2001	C	1"	2003	SF					Installation record	N		Installed after lead ban	N				
	847 BRIARWOOD COURT	N	C	N	1"	1994	C	1"	2001	SF					Installation record	N		Installed after lead ban	N				
	228 FOREST ROAD	N	C	N	1"	2001	L	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	839 BRIARWOOD COURT	N	C	N	1"	1994	C	1"	1999	SF					Installation record	N		Installed after lead ban	N				
	605 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	355 PHILIP DRIVE	N	C	N	1"	2001	C	1"	2003	SF					Installation record	N		Installed after lead ban	N				
	846 BRIARWOOD COURT	N	C	N	1"	1994	C	1"	2004	SF					Installation record	N		Installed after lead ban	N				
	894 BRIARWOOD COURT	N	C	N	1"	1994	C	1"	2000	SF					Installation record	N		Installed after lead ban	N				
	831 FREDERICK COURT	N	C	N	1"	1997	C	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	1102 CREEKS CROSS COURT	N	C	N	1"		C		1993	SF					Installation record	N		Installed after lead ban	N				
	411 SUMMIT ROAD	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF					Sl repair/replace record	Y	2021	sp during install	oSL repair/replace record	Y	2021	sp during install or repair	
	635 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2001	SF					Installation record	N		Installed after lead ban	N				
	810 BRIARWOOD COURT	N	C	N	1"	1994	C	1"	2002	SF					Installation record	N		Installed after lead ban	N				
	675 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	1999	SF					Installation record	N		Installed after lead ban	N				
	1086-B CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1997	MF					Installation record	N		Installed after lead ban	N				
	1320 WOODLAND ROAD	N	C	N			C		1999	SF					Installation record	N		Installed after lead ban	N				
	436 SIR HOWARD CIRCLE	N	C	N	1"		C	1"	1988	SF					Installation record	N		Installed after lead ban	N				
	490 WOODLAKE ROAD	N	C	N			C		1995	SF					Installation record	N		Installed after lead ban	N				
	359 OLMSTED COURT	N	C	N	1"		C	3/4"	1993	SF					Installation record	N		Installed after lead ban	N				
	447 SIR HOWARD CIRCLE	N	C	N	1"		C	1"	1994	SF					Installation record	N		Installed after lead ban	N				
	222 CHURCH STREET	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF					Sl repair/replace record	Y	2021	sp during install	oSL repair/replace record	Y	2021		
	1073-2A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1987	MF					Installation record	N		Installed after lead ban	N				
	510 WOODLAKE ROAD	N	C	N	1"		C	1"	1989	SF					Installation record	N		Installed after lead ban	N				
	1097-1B WOODLAKE ROAD	N	C	N	1 1/2"		C	1 1/2"	1988	MF					Installation record	N		Installed after lead ban	N				
	1016 WOODLAND ROAD	N	C	N			C		1970	SF					Installation record	N		Installed after lead ban	N				
	817 LINDEN ROAD	N	C	N	1"	1978	C	1"	1980	SF					Installation record	N		Previous eval	N				
	602 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	2000	SF					Installation record	N		Installed after lead ban	N				
	716-A TREEHOUSE LANE	N	C	N		1977	C		1981	MF					Installation record	N		Previous eval	N				
	610 TREEHOUSE PARKWAY	N	C	N	3/4"	1997	C	1"	1999	SF					Installation record	N		Installed after lead ban	N				
	1089-2B CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1990	MF					Installation record	N		Installed after lead ban	N				
	812 BRIARWOOD COURT	N	C	N	1"	1994	C	1"	1997	SF					Installation record	N		Installed after lead ban	N				
	690 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	1999	SF					Installation record	N		Installed after lead ban	N				
	1116-A ASPEN COURT	N	C	N	1"	1981	C	1"	1986	MF					Installation record	N		Installed after lead ban	N				
	440 RIDGE COURT	N	P	Y	1 1/4"	2014	P	1 1/4"	2014	SF					Sl repair/replace record	N	2014	sp during install	o	Installation record	Y	2014	sp during install or repair
	1073 HIGHLAND DRIVE	N	C	N			C		1955	SF					Installation record	N		Installed after lead ban	N				
	473 GREEN TREE ROAD	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF					Sl repair/replace record	N	2021	sp during install	oSL repair/replace record	Y	2021	sp during install or repair	
	1102 ASPEN ROAD	N	C	N	1"	1981	C	1"	1987	SF					Installation record	N		Installed after lead ban	N				
	918 BAYBERRY LANE	N	C	N	1"	1981	C	1"	1998	SF					Installation record	N		Installed after lead ban	N				
	735 WOODLAND ROAD	N	C	N			C		2001	SF					Installation record	N		Installed after lead ban	N				
	222 PHILIP COURT	N	C	N	1"		C	1"	2003	SF					Installation record	N		Installed after lead ban	N				
	452 SIR HOWARD CIRCLE	N	C	N	1"		C	1"	1996	SF					Installation record	N		Installed after lead ban	N				
	305 RIDGEWAY	N	C	Y	1"		C		1965	SF					Installation record	N		Field inspection only	Y	2021	'usual insp at meter		
	500 SCHOOL STREET	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF					Sl repair/replace record	Y	2021	sp during install	oSL repair/replace record	Y	2021	sp during install or repair	
	STABLES-HOUSE	N	C	N	1"	2012	C	1"	2012	SF		N	C	O	Field inspection only	N	2012	sp during install	o	Field inspection only	Y	2012	sp during install or repair
	1112 WOODLAND ROAD	N	C	N	1"		C		1956	SF					Installation record	N		Installed after lead ban	N				
	603 SCHOOL STREET	N	C	N	1 1/4"		C		1965	SF					Installation record	N		Installed after lead ban	N				
	1083-B CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	2004	MF					Installation record	N		Installed after lead ban	N				
	225 PHILIP COURT	N	C	N	1"		C	1"	2003	SF					Installation record	N		Installed after lead ban	N				
	1109-B ASPEN COURT	N	C	N	1"	1981	C	1"	1989	MF					Installation record	N		Installed after lead ban	N				
	352 PHILIP DRIVE	N	C	N	1"		C		2002	SF					Installation record	N		Installed after lead ban	N				
	1083-A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	2004	MF					Installation record	N		Installed after lead ban	N				
	640 TREEHOUSE PARKWAY	N	C	N	1"	2002	C	1"	2002	SF		N	C	2002	Installation record	N		Installed after lead ban	N	Y	2023	'usual insp at meter	
	227 SCHOOL STREET	N	C	Y	1"	2009	C	1"	2009	SF					Sl repair/replace record	Y	2009	sp during install	oSL repair/replace record	Y	2009	sp during install or repair	
	317 FREDERICK COURT	N	C	N	1"	2004	C	1"	2004	SF					Installation record	N		Installed after lead ban	N				
	680 TREEHOUSE PARKWAY	N	C	N	1"	1997	C	1"	1999	SF					Installation record	N		Installed after lead ban	N				
	704 GREEN TREE ROAD	N	C	N	1"		C	1"	1968	SF					Installation record	N		Installed after lead ban	N				
	643 SCHOOL STREET	N	C	N	1"		C	1"	1971	SF					Installation record	N		Installed after lead ban	N				
	607 SCHOOL STREET	N	C	N	1"		C	1"	1970														

	619 SCHOOL STREET	N	C	N	1"	C	1"	1970	SF		Installation record	N		Previous eval	N			
	653 UPPER ROAD	N	C	N	1"	1974	C	1"	1980	SF	Installation record	N		Previous eval	N			
	620 GREEN TREE ROAD	N	C	N	1"		C	1"	1983	SF	Installation record	N		Installation record	N			
	1109-D ASPEN COURT	N	C	N	1"	1981	C	1"	1989	MF	Installation record	N		Installed after lead ban	N			
	931 ASPEN ROAD	N	C	N	1"	1981	C	1"	1982	SF	Installation record	N		Previous eval	N			
	635 SCHOOL STREET	N	C	N	1"		C	1"	1971	SF	Installation record	N		Previous eval	N			
	915 ASPEN ROAD	N	C	N	1"	1981	C	1"	1988	SF	Installation record	N		Installed after lead ban	N			
	611 UPPER ROAD	N	C	N	1"	1978	C	1"	1980	SF	Installation record	N		Installation record	N			
	652 SCHOOL STREET	N	C	N	1"		C	1"	1973	SF	Installation record	N		Installation record	N			
	919 ASPEN ROAD	N	C	N	1"	1981	C	1"	1988	SF	Installation record	N		Installed after lead ban	N			
	613 PINE TREE ROAD	N	C	N	1"		C	1"	1969	SF	Installation record	N		Installation record	N			
	602 PINE TREE ROAD	N	C	N	1"		C	1"	1963	SF	Installation record	N		Previous eval	N			
	1097-K WOODLAKE ROAD	N	C	N	1 1/2"		C	1 1/2"	1990	MF	Installation record	N		Installed after lead ban	N			
	1001 ASPEN LANE	N	C	N	1"	1981	C	1"	1985	SF	Installation record	N		Previous eval	N			
	535 SUMMIT ROAD	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF	N	Sl. repair/replace record	N	2021	sp during install oSL repair/replace recor	Y	2021	sp during install or repair
	625 UPPER ROAD	N	C	N	1"	1978	C	1"	1985	SF	Installation record	N		Previous eval	N			
	704-C TREEHOUSE LANE	N	C	N	1"		C	1"	1981	MF	Installation record	N		Previous eval	N			
	1120-D ASPEN COURT	N	C	N	1"	1981	C	1"	1982	MF	Installation record	N		Previous eval	N			
	716-C TREEHOUSE LANE	N	C	N	1"	1980	C	1"	1981	SF	Installation record	N		Previous eval	N			
	1092-3C CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1991	MF	Installation record	N		Installed after lead ban	N			
	444 SIR HOWARD CIRCLE	N	C	N	1"		C	1"	1994	SF	Installation record	N		Installed after lead ban	N			
	1030 WOODLAKE ROAD	N	C	N	1"		C	1"	2003	SF	Installation record	N		Installed after lead ban	N			
	1084-A CREEKS CROSS ROAD	N	C	N	1 1/4"		C	1 1/4"	1996	MF	Installation record	N		Installed after lead ban	N			
	1000 WOODLAKE ROAD	N	C	N	1"		C	1"		SF	Installation record	N		Installed after lead ban	N			
	545 SIR HOWARD COURT	N	C	N	1"		C	1"	2010	SF	Installation record	N		Installed after lead ban	N			
	616 PINE CIRCLE	N	C	N	1"		C	1"	1963	SF	Installation record	N		Previous eval	N			
	501 VALLEY ROAD	N	C	N	1"		C	3/4"	1964	SF	Field inspection only	Y	2021	Mech excav	Field inspection only	Y	2021	'usual insp at meter
	624 PINE TREE ROAD	N	C	N	1"		C	1"	1967	SF	Installation record	N		Previous eval	N			
	608 PINE CIRCLE	N	C	N	1"		C		1964	SF	Installation record	N		Previous eval	N			
	1116-ASPEN COURT	N	C	N	1"	1981	C	1"	1985	MF	Installation record	N		Previous eval	N			
	640 UPPER ROAD	N	C	N	1"	1978	C	1"	1982	SF	Installation record	N		Previous eval	N			
	620 PINE CIRCLE	N	C	N	1"		C	1"	1964	SF	Installation record	N		Previous eval	N			
	350 WOODLAKE ROAD	N	C	N	1"		C	1"	1992	SF	Installation record	N		Installed after lead ban	N			
	345 WOODLAKE ROAD	N	C	N	1"		C	1"	1992	SF	Installation record	N		Installed after lead ban	N			
	627 SCHOOL STREET	N	C	N	1"		C	1"	1971	SF	Installation record	N		Previous eval	N			
	357 WOODLAKE COURT	N	C	N	1"		C	1"	1991	SF	Installation record	N		Installed after lead ban	N			
	407 RIDGE COURT	N	C	Y			C			SF	Installation record	N		Field inspection only	Y	2021	'usual insp at meter	
	445 AUDUBON ROAD	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF	N	Sl. repair/replace record	Y	2021	sp during install oSL repair/replace recor	Y	2021	sp during install or repair
	1109-C ASPEN COURT	N	C	N	1"		C	1"	1989	SF	Installation record	N		Installed after lead ban	N			
	1011 ASPEN ROAD	N	C	N	1"	1981	C	1"	1982	SF	Installation record	N		Previous eval	N			
	1124 WOODLAND ROAD	N	C	N	1"		C			SF	Installation record	N		Installed after lead ban	N			
	601 GREEN TREE ROAD	N	C	N	1"		C	1"	1962	SF	Installation record	N		Previous eval	N			
	1013 ASPEN ROAD	N	C	N	1"	1981	C	1"	1983	SF	Installation record	N		Previous eval	N			
	397 LAKEWOOD COURT	N	C	N	1"		C	1"	1988	SF	Installation record	N		Installed after lead ban	N			
	613 SCHOOL STREET	N	C	N	1"		C	1971	1"	SF	Installation record	N		Previous eval	N			
	824 GREEN TREE ROAD	N	C	N	1"	1978	C	1"	1981	SF	Installation record	N		Previous eval	N			
	557 UPPER ROAD	N	P	N	1 1/4"	2021	P	1 1/4"	2021	SF	N	Sl. repair/replace record	N	2021	sp during install oSL repair/replace recor	Y	2021	sp during install or repair
	619 GREEN TREE ROAD	N	C	N	1"		C	1"	1963	SF	Installation record	N		Previous eval	N			
	945 ASPEN ROAD	N	C	N	1"	1981	C	1"	1984	SF	Installation record	N		Previous eval	N			
	1025 ASPEN ROAD	N	C	N	1"		C	1"	1984	SF	Installation record	N		Previous eval	N			
	1089-3A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1990	MF	Installation record	N		Installed after lead ban	N			
	400 WOODLAKE ROAD	N	C	N	1"		C	1"	1991	SF	Installation record	N		Installed after lead ban	N			
	640 SCHOOL STREET	N	C	N	1"		C	1"	1974	SF	Installation record	N		Previous eval	N			
	612 SCHOOL STREET	N	C	N	1"		C	1973	1"	SF	Installation record	N		Previous eval	N			
	656 SCHOOL STREET	N	C	N	1"		C	1"	1974	SF	Installation record	N		Previous eval	N			
	367 WOODLAKE COURT	N	C	N	1"		C	1"	1992	SF	Installation record	N		Installed after lead ban	N			
	385 WOODLAKE ROAD	N	C	N	1"		C	1"	1991	SF	Installation record	N		Installed after lead ban	N			
	380 WOODLAKE ROAD	N	C	N	1"		C	1"	1990	SF	Installation record	N		Installed after lead ban	N			
	926 ASPEN ROAD	N	C	N	1"	1981	C	1"	1982	SF	Installation record	N		Previous eval	N			
	647 SCHOOL STREET	N	C	N	1"		C		1970	SF	Installation record	N		Previous eval	N			
	926 ASPEN ROAD	N	C	N	1"	1981	C	1"	1982	SF	Installation record	N		Previous eval	N			
	1119 ASPEN ROAD	N	C	N	1"	1981	C	1"	1992	SF	Installation record	N		Installed after lead ban	N			
	430 WOODLAND ROAD	N	C	N	1"	2008	C	1"	2008	SF	Installation record	N		Installed after lead ban	N			
	1115 ASPEN ROAD	N	C	N	1"	1981	C	1"	1991	SF	Installation record	N		Installed after lead ban	N			
	427 HILL STREET	N	P	Y	1 1/4"	2021	P	1 1/4"	2021	SF	N	Sl. repair/replace record	Y	2021	sp during install oSL repair/replace recor	Y	2021	sp during install or repair
	648 SCHOOL STREET	N	C	N	1"		C	1"	1975	SF	Installation record	N		Previous eval	N			
	470 WOODLAKE ROAD	N	C	N	1"		C	1"	1991	SF	Installation record	N		Installed after lead ban	N			
	1308 WOODLAND ROAD	N	C	N	1"		C	1"		SF	Installation record	N		Installed after lead ban	N			
	429 RIDGE COURT	N	C	N	1"		C	1"		SF	Installation record	N		Field inspection only	Y	2021	'usual insp at meter	
	580 SIR HOWARD CIRCLE	N	C	N	1"		C	1"	1995	SF	Installation record	N		Installed after lead ban	N			
	616 SCHOOL STREET	N	C	N	1"		C	1"	1975	SF	Installation record	N		Previous eval	N			
	1089-3A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1990	MF	Installation record	N		Installed after lead ban	N			
	361 WOODLAKE COURT	N	C	N	1"		C	1"	1992	SF	Installation record	N		Installed after lead ban	N			
	1075-A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1995	MF	Installation record	N		Installed after lead ban	N			
	1092-2B CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1991	MF	Installation record	N		Installed after lead ban	N			
	631 SCHOOL STREET	N	C	N	1"		C	1"	1974	SF	Installation record	N		Previous eval	N			
	900 WOODLAKE ROAD	N	C	N	1"		C	1"	1994	SF	Installation record	N		Installed after lead ban	N			
	617 UPPER ROAD	N	C	N	1"	1978	C	1"	1980	SF	Installation record	N		Previous eval	N			
	1077-1A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1992	MF	Installation record	N		Installed after lead ban	N			
	911 BAYBERRY LANE	N	C	N	1"	1981	C	1"	1983	SF	Installation record	N		Previous eval	N			
	607 GREEN TREE ROAD	N	C	N	1"		C	1"	1963	SF	Installation record	N		Previous eval	N			
	620 SCHOOL STREET	N	C	N	1"		C	1"	1973	SF	Installation record	N		Previous eval	N			
	403 LAKEWOOD COURT	N	C	N	1"		C	1"	1991	SF	Installation record	N		Installed after lead ban	N			
	644 SCHOOL STREET	N	C	N	1"		C	1"	1973	SF	Installation record	N		Previous eval	N			
	1089-1B CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1990	MF	Installation record	N		Installed after lead ban	N			
	611 PINE TREE ROAD	N	C	N	1"		C	1963	1"	SF	Installation record	N		Previous eval	N			
	514 PINE TREE ROAD	N	P	N	1 1/4"	2021	P	1 1/4"	2021	SF	N	Sl. repair/replace record	N	2021	sp during install o Field inspection only	Y	2021	sp during install or repair
	1092-1B CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1991	MF	Installation record	N		Installed after lead ban	N			
	1092-3B CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1991	MF	Installation record	N		Installed after lead ban	N			
	572 SIR HOWARD CIRCLE	N	C	N	1"		C	1"	1989	SF	Installation record	N		Installed after lead ban	N			
	1118-D ASPEN COURT	N	C	N	1"	1981	C	1"	1983	MF	Installation record	N		Installation record	N			
	1092-3A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"	1991	MF	Installation record	N		Installed after lead ban	N			
	816 GREEN TREE ROAD	N	C	N	1"	1978	C	1"	1980	SF	Installation record	N		Installation record	N			
	660 SCHOOL STREET	N	C	N	1"		C	1"	1976	SF	Installation record	N		Installation record	N			
	1118-A ASPEN COURT	N	C	N	1"	1981	C	1"	1983	MF	Installation record	N		Installation record	N			
	628 SCHOOL STREET	N	C	N	1"		C	1"	1972	SF	Installation record	N		Installation record	N			
	612 PINE CIRCLE	N	C	N	1"		C	1"	1962	SF	Installation record	N		Installation record	N			
	716-B TREEHOUSE LANE	N	C	N	1"	1980	C	1"	1981	MF	Installation record	N		Installation record	N			
	721 VALLEY ROAD	N	C	N	1"		C	1"	1964	SF	Field inspection only	Y	2021	sp during install o Field inspection only	Y	2021	'usual insp at meter	
	1097-A WOODLAKE ROAD	N	C	N	1 1/2"		C	1 1/2"	1988	MF	Installation record	N		Installed after lead ban	N			
	250 Woodlake Road	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	530 Clearing Dr	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	571 ClearingDr	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	600 CLEARINGS DRIVE	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	620 Clearing Dr	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	630 ClearingDr	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	540 W. Meadow Dr	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	630 N. Meadow Dr	N	P	N	1 1/4"	2019	P	1 1/4"		SF	Installation record	N		Installed after lead ban	N			
	AMERICAN CLUB	N	DI	N			DI		NONRES		Diameter > 2 inches	N		Diameter > 2 inches	N			
	INN ON WOODLAKE	N	DI	N			DI		NONRES		Diameter > 2 inches	N		Diameter > 2 inches	N			
	DSGN CTR/CARRIAGE	N	DI	N			DI		NONRES		Diameter > 2 inches	N		Diameter > 2 inches	N			
	Schoo/HUM RES/COMM/LAW	N	C	Y	1"		C	1"		NONRES	Installed after lead ban</							

[illegible]

117 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
1227 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
221 SCHOOL STREET	N	C	Y	1"	2009	C	1"	2009	SF	SL repair/replace record	Y	2009	sp during install o/sl repair/replace record	Y	2009	sp during install or repair
436 RIDGE COURT	N	C	Y	1"		C	1"		SF	Installation record	N		Field inspection only	Y	2021	'fusal insp at meter
1114-A ASPEN COURT	N	C	Y	1"		C	1"		MF	Installation record	N		Installed after lead ban	N	2021	
523 SUMMIT ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
154 SOUTH ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
444 AUDUBON ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
229 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
441 HILL STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
514 SCHOOL STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
527 WASHINGTON WALK	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	'fusal insp at meter/sl repair/replace record	Y	2021	sp during install or repair
132 SCHOOL STREET	N	C	Y	1"	2009	C	1"	2009	SF	SL repair/replace record	Y	2009	sp during install o/sl repair/replace record	Y	2009	sp during install or repair
523 LOWER ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
523 AUDUBON ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
116 SOUTH ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
114 MARKET STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
123 ORCHARD ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
1120 EAST ASPEN COURT	N	C	N	1"		C	1"		MF	Installation record	N		Installed after lead ban	N	2021	sp during install or repair
425 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
460 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
127 ORCHARD ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
131 ORCHARD ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
527A WASHINGTON WALK	N	P	Y	11/4"	2021	P	1 1/4"	2021	MF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
900 DAILY STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
435 HILL STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
628 ROOSEVELT ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
527 WASHINGTON SQUARE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
543 VALLEY ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
504 GREEN TREE ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
514 CENTER LANE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
210 GRAFTON COURT	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
900 DAILY STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
235 SCHOOL STREET	N	C	Y	1"	2009	C	1"	2009	SF	Installation record	N		Installed after lead ban	N	2021	sp during install or repair
453 HILL STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
509 RIVERSIDE DRIVE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
825 W PARK LANE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
540 W RIVERSIDE DRIVE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
1089-1A CREEKS CROSS ROAD	N	C	N	1 1/2"		C	1 1/2"		MF	Installation record	N		Installed after lead ban	N	2021	sp during install or repair
446 PINE TREE ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
153 SCHOOL STREET	N	C	Y	1"		C	1"		SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
155 SCHOOL STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
239 UPPER ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
123 SCHOOL STREET	N	C	Y	1"	2009	C	1"	2009	SF	Installation record	N		Installed after lead ban	N	2021	sp during install or repair
411 UPPER ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
524 AUDUBON ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
536 VALLEY ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
1109-C ASPEN COURT	N	C	N	1"		C	1"		MF	Installation record	N		Installed after lead ban	N	2021	sp during install or repair
532 CENTER LANE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
458 PINE TREE ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
536 AUDUBON ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
HUMAN RESOURCES	N	P	Y	11/4"	2021	P	1 1/4"	2021	NONRES	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
817 W PARK LANE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
1129 CIRCLE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
429 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
520 PARKWAY	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
142 ORCHARD ROAD	N	P	Y	11/4"	2021	P	1 1/2"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
132 MARKET STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
205 UPPER ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
505 UPPER ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
563 ROOSEVELT ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
530 SCHOOL STREET	N	C	Y	11/4"	2021	C	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
514 SUMMIT ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
620 VALLEY ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
622 VALLEY ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
618 W RIVERSIDE DRIVE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
627 RIVERSIDE DRIVE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
134 E PARK LANE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
247 SCHOOL STREET	N	C	Y	1"	2009	C	1"	2009	SF	SL repair/replace record	N	2009	sp during install o/sl repair/replace record	Y	2009	sp during install or repair
146 MARKET STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
315 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
108 UNCLON CIRCLE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
229 ORCHARD ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
116 UNCLON CIRCLE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
108 MARKET STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
512 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
118 ORCHARD ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
225 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
110 E PARK LANE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
142 SOUTH ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
517 SCHOOL STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
508 CHURCH STREET	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
545 RIVERSIDE DRIVE	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
160 SOUTH ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
549 LOWER ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
138 GRAFTON COURT	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
163 SOUTH ROAD	N	P	Y	11/4"	2021	P	1 1/4"	2021	SF	SL repair/replace record	Y	2021	sp during install o/sl repair/replace record	Y	2021	sp during install or repair
147 SCHOOL STREET	N	C	Y	1"		C	1"		SF	SL repair/replace record	Y	2009	sp during install o/sl repair/replace record	Y	2009	sp during install or repair
152 GRAFTON COURT	N	P	Y</													

[Click here to open USEPA 2022 Guidance for Developing and Maintaining a Service Line Inventory](#)


Note: Field names that are shaded **navy** are required for every service connection. Field names shaded **blue** are recommended, optional, or only required under certain conditions. See field descriptions for more information.

	Column	Description		
A	SITE ID	PWS that do not wish to report site addresses to the department in column B can use this column to “link” their materials inventory table to a separate service address table for their own use. <i>This column is optional, however, it strongly recommended that PWS enter the site ID for locations that are lead and copper monitoring sites in this column.</i>		
B	LOCATION IDENTIFIER	The location identifier can be the site address, however if there is more than one service connection at a given address, it must include additional detail. If the PWS does not wish to report addresses to the department it can be a block, intersection or landmark. This column is required per sub-subparagraph §141.84 (a)(8)(i) of the LCRR which requires that a location identifier be associated with each service line.		
	Column	Description	Answer options	Answer Option Descriptions
C	GOOSENECK CURRENTLY PRESENT?	Is there a gooseneck, lead connector or pigtail present? <i>PWS are required to track this information, if known. However, PWS are not required to conduct investigations to determine if a gooseneck is present.</i>	Y	YES - WITH CERTAINTY
			N	NO - WITH CERTAINTY
			UNK	NOT KNOWN WITH CERTAINTY
D	CURRENT STREET SIDE SERVICE LINE MATERIAL	Service line pipe material, from the water main to curb stop.	L	CONFIRMED LEAD
			C	CONFIRMED COPPER
			G	CONFIRMED GALVANIZED
			P	CONFIRMED PLASTIC
			DI	CONFIRMED DUCTILE IRON
			CI-L	CONFIRMED LINED CAST IRON
			CI-U	CONFIRMED UNLINED CAST IRON
			UNK-LG	UNKNOWN - MAY CONTAIN LEAD OR GALVANIZED
UNK-NOLG	UNKNOWN - DEFINITELY DOES NOT CONTAIN LEAD OR GALVANIZED			
E	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	Was the service line ever previously lead?	Y	YES – SERVICE LINE WAS PREVIOUSLY LEAD
			N	NO – KNOWS WITH CERTAINTY THAT SERVICE LINE MATERIAL WAS NEVER PREVIOUSLY LEAD
			UNK	NOT KNOWN WITH CERTAINTY IF MATERIAL WAS EVER PREVIOUSLY LEAD
	Column	Description		
F	STREET SIDE SERVICE LINE SIZE	Service line pipe diameter in inches, from the water main to curb stop. This information is useful as a screening tool as <u>most</u> lead service lines are 2 inches or less in diameter. Furthermore, PWSs are required to report service line size to the PSC for their annual report. This column may also be used by PWS that wish to track information required by both agencies in a single document. <i>Column F is optional.</i>		
G	STREET SIDE SERVICE LINE INSTALL DATE	The four-digit year that the utility-side service was installed (i.e. 1974). If the exact year is not known, enter the decade (i.e. enter 1970 for any year in the 1970s) Although this information is not required, it can be used as a screening tool to determine if the service line was installed before or after the lead ban (1986). <i>Column G is optional.</i>		
H	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	Service line pipe material, from the curb stop to water meter. See Row D for answer options.		
I	PROPERTY SIDE SERVICE LINE SIZE ¹	Service line pipe diameter, in inches, from the curb stop to water meter. This information is useful as a screening tool as most lead service lines are 2 inches or less in diameter. Furthermore, PWS are required to report service line size to the PSC for their annual report. This column may also be used by PWS that wish to track information required by both agencies in a single document. <i>Column I is optional.</i>		
J	PROPERTY SIDE SERVICE LINE INSTALL DATE	If the exact year is not known, enter the decade (i.e. enter 1970 for any year in in the 1970s). This information it can be used as a screening tool to determine if the service line was installed before or after the lead ban (1986). <i>Column J is optional.</i>		
	Column	Description	Answer options	Answer Option Descriptions
K	BUILDING TYPE	The type of structure that is served water by the service connection. <i>At a minimum, the PWS must identify the connection either SF, MF or NONRES .</i>	SF	SINGLE-FAMILY RESIDENTIAL
			MF	MULTI-FAMILY RESIDENTIAL
			SCH/CC	SCHOOL OR CHILD CARE <i>This category may be used by the PWSs to track locations that must be monitored under §141.92 .</i>
			RES/CC	RESIDENTIAL & IN-HOME CHILD CARE <i>This category may be used by the PWSs to track locations that must be monitored under §141.92 .</i>
			NONRES	NONRESIDENTIAL ONLY, NO SCHOOL OR CHILD CARE.
			MIX	MIXED RESIDENTIAL & NONRESIDENTIAL, NO SCHOOL OR CHILD CARE.
O	OTHER			
L	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	Is the cold-water kitchen tap treated by point-of-entry or point-of-use softening, filter or other treatment? <i>Column L is optional.</i>	Y	YES - the sample tap is treated by a point of use or point of entry softener or filter
			N	NO - the sample tap is not treated by a point of use or point of entry softener or filter
			UNK	Presence or absence of POU and POE is UNKNOWN
M	BUILDING PLUMBING MATERIAL 1	The type of plumbing materials inside the structure that water is deliver to. If there is more than one known plumbing material type, select the second material type in column N. <i>Columns M and N are optional.</i>	CLS	Copper with lead solder
			C	Copper, no lead solder
N	BUILDING PLUMBING MATERIAL 2		O	Other material that is <u>not</u> copper, or copper with lead solder
			UNK	Unknown
	Column	Description		
O	BUILDING PLUMBING MATERIAL INSTALL DATE	The four-digit year that the interior premise plumbing was installed. If the exact year is not known, you may enter the decade if the decade is not the 1980s. If the decade is the 1980s, you may enter one of the following: 1983-1984, <1983 or >1984. <i>Column O is optional.</i>		
P	COMMENTS	Use this column information to enter any other information that the PWS finds helpful to them or any information they wish to share with the department. <i>Column P is optional.</i>		

	Column	Description	Answer options	Answer Option Descriptions (Chapter 4 of EPA inventory guidance)
Q	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y- Notes on materials classification.	Previous eval	Previous Materials Evaluation
			Installation record	Installation record (e.g., tap card)
			Installed after lead ban	Installation date after lead ban (1986)
			Diameter > 2 inches	Service line diameter is > 2 inches
			SL repair/replace record	Service line repair or replacement record
			Water sampling only	Water sampling only with no records
			Field inspection only	Field inspection only with no records
			Other - describe in notes	Other - if other is selected describe the basis for material classification in the Notes Column Y.
	Column	Description		
R	WAS STREET SIDE MATERIAL FIELD VERIFIED?	Was the street side material field verified? Select "Y" for "Yes" or "N" for "No".		
S	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column R, enter the date (DD/MM/YYYY) or four-digit year that the material was field verified. <i>This field is only required if "Yes" was selected in Column R.</i>		
	Column	Description	Answer options	Answer Option Descriptions (Chapter 5 of EPA inventory guidance)
T	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column R, select the method used for field verification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y. <i>This field is only required if "Yes" was selected in Column R.</i>	Customer self id	Customer self-identification
			CCTV - internal	CCTV investigation at curb stop - internal
			CCTV - external	CCTV investigation at curb stop - external
			Mech excav	Mechanical excavation at one location
			Visual insp at meter	Visual inspection at the meter pit
			Visual insp during install or repair	Visual inspection during construction or repair
			Cross connection survey	Cross Connection survey
			Other	Other - describe in Notes Column Y
	Column	Description		
U	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y. See Column Q for a description of and an explanation of answer options.		
V	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	Was the street side material field verified? Select "Y" for "Yes" or "N" for "No".		
W	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column R, select the method used for field verification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y. <i>This field is only required if "Yes" was selected in Column V.</i>		
X	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column V, select the method used for field verification. See column T for an explanation of answer options. <i>This field is only required if "Yes" was selected in Column V.</i>		
Y	NOTES MATERIAL CLASSIFICATION	If PWS selected "other" in Columns Q, T, U or X, describe the basis for classification or field verification here. <i>This field is only required if "other" was selected in column Q, T, U and/or X.</i>		



Materials Inventory Template For Drinking Water Systems Under The Lead And Copper Rule Revisions



1. Why do Public Water Systems (PWSs) need to provide this information?

Under Section §141.84 of the Lead and Copper Rule Revision (LCRR), all community Public Water Systems (PWS) “must develop an inventory to identify the materials of service lines connected to the public water distribution system. The inventory must include all service lines connected to the public water distribution system regardless of ownership status.”

2. What specifically does the LCRR materials inventory require (columns D, E and H)?

Subparagraph §141.84 (a) (4) of the LCRR states that “each service line, or portion of the service line where ownership is split, must be categorized” as belonging to one of the following groups: lead; non-lead; lead status unknown; or galvanized requiring replacement. *The information provided in columns D, E and H of the materials spreadsheet will enable the department to correctly assign every service line or portion thereof to one of these four categories.*

3. What is the Site ID (column A)? Is this required?

The PWS can use this column to identify the site ID of lead and copper monitoring sites. For all other locations, the site ID is optional. PWSs that do not wish to report site addresses to the department in column B may want to use this column to “link” their materials inventory table to a separate service address table for their own use.

4. What is a locational identifier (column B)?

Sub-subparagraph §141.84 (a)(8)(i) of the LCRR requires a location identifier associated with each service line. The locational identifier can be the site address, or it can be a block, intersection or landmark.

The LCRR defines some categories of materials, such as ‘lead status’ and ‘galvanized downstream of lead’ differently in different sections of the rule. Thus, the spreadsheet is intended to be a simple and easy way for municipal PWSs to collect and report the information required now and in the future. The DNR will use the materials inventory data collected by the water system to categorize each of their service connections appropriately under each section of the LCRR.



Materials Inventory Template For Drinking Water Systems Under The Lead And Copper Rule Revisions

5. Why do PWSs need to indicate whether a gooseneck is present (column C)?

Paragraph §141.86 (a) of the LCRR directs every public water system to “identify a pool of targeted sampling sites based on the service line inventory.” However, the materials information needed to categorize service lines in accordance with §141.84 alone is insufficient to identify these targeted sampling sites. Specifically, as per LCRR sub-paragraph §141.86 (a) (5), Tier 3 sampling sites include both single-family structures served by galvanized lines located downstream of a lead service line (i.e. confirmed galvanized requiring replacement) or downstream of a lead gooseneck, pigtail or connector.

5. Why do PWSs need to indicate whether a service line that is not currently lead was ever previously lead (column E)?

The materials history of the upstream utility service line is needed to correctly categorize customer-side galvanized service lines as either non-lead or galvanized requiring replacement under the LCRR. Sub-subparagraph §141.84 (a)(4)(ii) of the LCRR requires that public water systems identify locations where a galvanized service line “is or was at any time downstream of a lead service line” or “lead status unknown” service line as “galvanized requiring replacement”. If a water system knows with certainty that the utility side of a service line is not now, and never has previously been lead, then the downstream customer-side galvanized service line is identified as “non-lead”. If a PWS does not know this with certainty, the material is categorized as “galvanized requiring replacement.” However, as per paragraph §141.86 (a), galvanized service lines currently or formerly downstream of a lead gooseneck, pigtail, or connector are *not* identified as galvanized requiring replacement.

5. Are PWSs required to track the interior premise plumbing materials and install date at every service location in their system (columns M, N and O)?

This information is only required for service locations that are potential compliance sampling sites. If the PWS has at least as many Tier 1, Tier 2 and/or Tier 3 sampling sites as their required number of monitoring sites, then they are not required to track this information at this time. However, the PWS will be required to collect this information in the future, once all of their lead service lines and galvanized lines requiring replacement are removed. It is recommended that PWS collect this information on an ongoing basis whenever they are inside structures, as part of their normal operations.

5. Are PWSs required to track whether there is a point-of-entry (POE) or point-of-use (POU) treatment device at every service location (column L)?

This information is only required for service connections that are potential monitoring sites. Sub-paragraph §141.86 (1) of the LCRR states that “Sampling sites may not include sites with installed point-of-entry (POE) treatment devices and taps used at sampling sites may not have point-of-use (POU) devices designed to remove inorganic contaminants...” However, the department recommends that PWSs collect this information concurrently with premise plumbing materials at a given residence, so that PWSs don’t need to revisit residences that become potential monitoring sites once their lead and galvanized lines are removed.

5. Are PWSs required to use the DNR template?

No, PWSs are not required to use the DNR template for their materials inventory. However, PWSs that track their drinking water distribution system materials using a different method should provide all of the information requested in the template.

5. Do Municipal PWSs have to report this information to the DNR and PSC both?

Due to differences in the frequency and timing of reporting and the type of information reported, municipal public water systems will continue to report service line information annually to the Public Service Commission (W-22 and W-29) for the foreseeable future. However, the DNR and PSC are in discussions about how they can collaborate to minimize the amount of similar reporting to multiple agencies after the LCRR compliance date.