

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL
	300 NORTHWEST ST	N	C
	713 W MAIN ST	UNK	UNK-LG
	721 W MAIN ST	UNK	UNK-LG
	829 W MAIN ST	UNK	UNK-LG
	837 W MAIN ST	UNK	UNK-LG
	919 W MAIN ST	UNK	UNK-LG
	924 W MAIN ST	UNK	UNK-LG
	912 W MAIN ST	UNK	UNK-LG
	902 W MAIN ST	UNK	UNK-LG
	123 BURR OAK ST	UNK	UNK-LG
	152 BURR OAK ST	UNK	UNK-LG
	216 BURR OAK ST	UNK	UNK-LG
	224 BURR OAK ST	UNK	UNK-LG
	230 BURR OAK ST	UNK	UNK-LG
	620 W MAIN ST	UNK	UNK-LG
	518 W MAIN ST	UNK	UNK-LG
	604 W MAIN ST	UNK	UNK-LG
	517 W MAIN ST	UNK	UNK-LG
	623 W MAIN ST	UNK	UNK-LG
	802 BEACON ST	UNK	UNK-LG
	705 W MAIN ST	UNK	UNK-LG
	305 WEST ST	UNK	UNK-LG
	820 EIGHTH ST	UNK	UNK-LG
	804 S FOURTH ST	UNK	UNK-LG
	413 S FOURTH ST	UNK	UNK-LG
	504 W WILSON ST	UNK	UNK-LG
	122 EIGHTH ST	UNK	UNK-LG
	111 N THIRD ST	UNK	UNK-LG
	403 S THIRD ST	UNK	UNK-LG
	405 S THIRD ST	UNK	UNK-LG
	514 S THIRD ST	UNK	UNK-LG
B	702 S THIRD ST	UNK	UNK-LG
	714 S THIRD ST	UNK	UNK-LG
	202 W BLUFF ST	UNK	UNK-LG
	97 E BLUFF ST	UNK	UNK-LG
	327 S SECOND ST	UNK	UNK-LG
	322 S SECOND ST	UNK	UNK-LG
	116 W WILSON ST	UNK	UNK-LG
	1100 MAPLE ST	UNK	UNK-LG
	1806 STATE ROAD 59	UNK	UNK-LG
	401 WEST ST	UNK	UNK-LG

	818 S FOURTH ST	UNK	UNK-LG
	421 S FOURTH ST	UNK	UNK-LG
	430 S FOURTH ST	UNK	UNK-LG
	517 W WILSON ST	UNK	UNK-LG
	609 W WILSON ST	UNK	UNK-LG
	701 W WILSON ST	UNK	UNK-LG
	515 S THIRD ST	UNK	UNK-LG
	601 S THIRD ST	UNK	UNK-LG
	331 S SECOND ST	UNK	UNK-LG
	325 S SECOND ST	UNK	UNK-LG
	114 S SECOND ST	UNK	UNK-LG
	400 E MAIN ST	UNK	UNK-LG
	906 MAPLE ST	UNK	UNK-LG
	1105 ROYAL LEE DR	UNK	UNK-LG
	430 S FOURTH ST	UNK	UNK-LG
A	412 S FOURTH ST	UNK	UNK-LG
	408 W WILSON ST	UNK	UNK-LG
	429 S FOURTH ST	UNK	UNK-LG
	414 S THIRD ST	UNK	UNK-LG
A	702 S THIRD ST	UNK	UNK-LG
	101 E BLUFF ST	UNK	UNK-LG
	105 E BLUFF ST	UNK	UNK-LG
	332 S SECOND ST	UNK	UNK-LG
	1000 ROYAL LEE DR	UNK	UNK-LG
	1808 STATE ROAD 59	UNK	UNK-LG
	1808 STATE ROAD 59	UNK	UNK-LG
	156 BURR OAK ST	UNK	UNK-LG
	102 BURR OAK ST	UNK	UNK-LG
	723 N FIRST ST	UNK	UNK-LG
	220 N FOURTH ST	UNK	UNK-LG
	309 N FOURTH ST	UNK	UNK-LG
	213 N FOURTH ST	UNK	UNK-LG
	242 NORTHWEST ST	UNK	UNK-LG
	227 NORTHWEST ST	UNK	UNK-LG
	141 NORTHWEST ST	UNK	UNK-LG
	135 NORTHWEST ST	UNK	UNK-LG
	619 TAFT ST	UNK	UNK-LG
	303 N FIRST ST	UNK	UNK-LG
	305 N FIRST ST	UNK	UNK-LG
	114 E JEFFERSON ST	UNK	UNK-LG
	117 LITTLE ST	UNK	UNK-LG
	120 E WISCONSIN ST	UNK	UNK-LG
	412 N FIRST ST	UNK	UNK-LG
	603 N FIRST ST	UNK	UNK-LG
	522 N FIRST ST	UNK	UNK-LG
	611 N FIRST ST	UNK	UNK-LG
	623 N FIRST ST	UNK	UNK-LG

724 N FIRST ST	UNK	UNK-LG
609 NORTHWEST ST	UNK	UNK-LG
605 NORTHWEST ST	UNK	UNK-LG
422 NORTHWEST ST	UNK	UNK-LG
504 N SECOND ST	UNK	UNK-LG
309 W WISCONSIN ST	UNK	UNK-LG
405 W WISCONSIN ST	UNK	UNK-LG
523 N SECOND ST	UNK	UNK-LG
612 POWERS ST	UNK	UNK-LG
614 POWERS ST	UNK	UNK-LG
616 POWERS ST	UNK	UNK-LG
618 POWERS ST	UNK	UNK-LG
585 WASHINGTON AVE	UNK	UNK-LG
571 WASHINGTON AVE	UNK	UNK-LG
733 AIR VIEW DR	UNK	UNK-LG
765 AIR VIEW DR	UNK	UNK-LG
621 LAMPSA ST	UNK	UNK-LG
620 LAMPSA ST	UNK	UNK-LG
732 AIR VIEW DR	UNK	UNK-LG
708 AIR VIEW DR	UNK	UNK-LG
555 LINCOLN ST	UNK	UNK-LG
737 W WISCONSIN ST	UNK	UNK-LG
400 ANEMONE AVE	UNK	UNK-LG
420 ANEMONE AVE	UNK	UNK-LG
440 ANEMONE AVE	UNK	UNK-LG
500 ANEMONE AVE	UNK	UNK-LG
506 ANEMONE AVE	UNK	UNK-LG
410 SHORE DR	UNK	UNK-LG
433 SHORE DR	UNK	UNK-LG
321 SHORE DR	UNK	UNK-LG
166 GERANIUM AVE	UNK	UNK-LG
116 LOCUST ST	UNK	UNK-LG
331 NORTHWEST ST	UNK	UNK-LG
315 NORTHWEST ST	UNK	UNK-LG
522 CHESTNUT ST	UNK	UNK-LG
217 NORTHWEST ST	UNK	UNK-LG
515 TAFT ST	UNK	UNK-LG
901 JEFFERSON ST	UNK	UNK-LG
350 JEFFERSON ST	UNK	UNK-LG
717 N FIRST ST	UNK	UNK-LG
132 E JEFFERSON ST	UNK	UNK-LG
213 E WISCONSIN ST	UNK	UNK-LG
109 E WISCONSIN ST	UNK	UNK-LG
101 E WISCONSIN ST	UNK	UNK-LG
515 N FIRST ST	UNK	UNK-LG
632 N FIRST ST	UNK	UNK-LG
800 N FIRST ST	UNK	UNK-LG

810 N FIRST ST	UNK	UNK-LG
715 N SECOND ST	UNK	UNK-LG
716 N SECOND ST	UNK	UNK-LG
702 N SECOND ST	UNK	UNK-LG
503 NORTHWEST ST	UNK	UNK-LG
423 NORTHWEST ST	UNK	UNK-LG
616 N SECOND ST	UNK	UNK-LG
516 N SECOND ST	UNK	UNK-LG
603 N SECOND ST	UNK	UNK-LG
604 W WISCONSIN ST	UNK	UNK-LG
701 AIR VIEW DR	UNK	UNK-LG
717 AIR VIEW DR	UNK	UNK-LG
749 AIR VIEW DR	UNK	UNK-LG
570 LINCOLN ST	UNK	UNK-LG
728 W WISCONSIN ST	UNK	UNK-LG
736 W WISCONSIN ST	UNK	UNK-LG
747 W WISCONSIN ST	UNK	UNK-LG
705 W WISCONSIN ST	UNK	UNK-LG
615 W WISCONSIN ST	UNK	UNK-LG
416 ANEMONE AVE	UNK	UNK-LG
510 ANEMONE AVE	UNK	UNK-LG
516 ANEMONE AVE	UNK	UNK-LG
409 SHORE DR	UNK	UNK-LG
301 SHORE DR	UNK	UNK-LG
299 SHORE DR	UNK	UNK-LG
150 GERANIUM AVE	UNK	UNK-LG
157 GERANIUM AVE	UNK	UNK-LG
306 SHORE DR	UNK	UNK-LG
318 SHORE DR	UNK	UNK-LG
326 SHORE DR	UNK	UNK-LG
323 N FOURTH ST	UNK	UNK-LG
222 FIFTH ST	UNK	UNK-LG
236 FIFTH ST	UNK	UNK-LG
308 NORTHWEST ST	UNK	UNK-LG
257 NORTHWEST ST	UNK	UNK-LG
317 JEFFERSON ST	UNK	UNK-LG
627 JEFFERSON ST	UNK	UNK-LG
700 BRENNAN RD	UNK	UNK-LG
123 JEFFERSON ST	UNK	UNK-LG
506 N FIRST ST	UNK	UNK-LG
509 N FIRST ST	UNK	UNK-LG
567 N FIRST ST	UNK	UNK-LG
104 NORTHWEST ST	UNK	UNK-LG
709 N FIRST ST	UNK	UNK-LG
631 NORTHWEST ST	UNK	UNK-LG
615 NORTHWEST ST	UNK	UNK-LG
511 NORTHWEST ST	UNK	UNK-LG

417 NORTHWEST ST	UNK	UNK-LG
414 NORTHWEST ST	UNK	UNK-LG
502 NORTHWEST ST	UNK	UNK-LG
620 N SECOND ST	UNK	UNK-LG
524 N SECOND ST	UNK	UNK-LG
610 POWERS ST	UNK	UNK-LG
706 LAMPSA ST	UNK	UNK-LG
707 LAMPSA ST	UNK	UNK-LG
709 AIR VIEW DR	UNK	UNK-LG
725 AIR VIEW DR	UNK	UNK-LG
741 AIR VIEW DR	UNK	UNK-LG
760 W WISCONSIN ST	UNK	UNK-LG
731 W WISCONSIN ST	UNK	UNK-LG
512 ANEMONE AVE	UNK	UNK-LG
428 SHORE DR	UNK	UNK-LG
401 SHORE DR	UNK	UNK-LG
422 JEFFERSON ST	UNK	UNK-LG
310 N FOURTH ST	UNK	UNK-LG
126 E JEFFERSON ST	UNK	UNK-LG
103 LITTLE ST	UNK	UNK-LG
521 ANEMONE AVE	UNK	UNK-LG
431 ANEMONE AVE	UNK	UNK-LG
336 HILLCREST DR	UNK	UNK-LG
100 RIDGE RD	UNK	UNK-LG
324 RIDGE RD	UNK	UNK-LG
321 HILLCREST DR	UNK	UNK-LG
322 SPRING VALLEY CT	UNK	UNK-LG
328 SPRING VALLEY CT	UNK	UNK-LG
333 SPRING VALLEY CT	UNK	UNK-LG
316 WILLOW ST	UNK	UNK-LG
331 WILLOW ST	UNK	UNK-LG
323 WILLOW ST	UNK	UNK-LG
136 VIOLET AVE	UNK	UNK-LG
132 LOCUST ST	UNK	UNK-LG
124 LOCUST ST	UNK	UNK-LG
700 E MAIN ST	UNK	UNK-LG
511 ANEMONE AVE	UNK	UNK-LG
429 ANEMONE AVE	UNK	UNK-LG
104 RIDGE RD	UNK	UNK-LG
119 RIDGE RD	UNK	UNK-LG
103 RIDGE RD	UNK	UNK-LG
106 RIDGE RD	UNK	UNK-LG
115 WILLOW ST	UNK	UNK-LG
140 LOCUST ST	UNK	UNK-LG
408 E MAIN ST	UNK	UNK-LG
418 E MAIN ST	UNK	UNK-LG
534 E MAIN ST	UNK	UNK-LG

	316 HILLCREST DR	UNK	UNK-LG
	326 HILLCREST DR	UNK	UNK-LG
	422 HILLCREST DR	UNK	UNK-LG
	409 HILLCREST DR	UNK	UNK-LG
	112 VIOLET AVE	UNK	UNK-LG
	322 WILLOW ST	UNK	UNK-LG
	128 VIOLET AVE	UNK	UNK-LG
	613 VIOLET AVE	UNK	UNK-LG
	1125 STATE ROAD 106	UNK	UNK-LG
055171-0516-2233-000	055171-0516-2233-000	UNK	UNK-LG
	712 N FIRST ST	UNK	UNK-LG
	423 SHORE DR	UNK	UNK-LG
	608 N FIRST ST	UNK	UNK-LG
	711 Lampsa St	UNK	UNK-LG
	306 WILLOW ST	UNK	UNK-LG
	315 SPRING VALLEY CT	UNK	UNK-LG
	320 VIOLET AVE	UNK	UNK-LG
	126 VIOLET AVE	UNK	UNK-LG
	206 BURR OAK ST	UNK	UNK-LG
	140 BURR OAK ST	UNK	UNK-LG
	409 WEST ST	UNK	UNK-LG
	320 N FOURTH ST	UNK	UNK-LG
	752 BEACH ST A1	N	DI
	160 BURR OAK ST	UNK	UNK-LG
	824 W MAIN ST	UNK	UNK-LG
	507 W WILSON ST	UNK	UNK-LG
	112 E BLUFF ST	UNK	UNK-LG
	752 BEACH ST A1	N	C
	103 EIGHTH ST	UNK	UNK-LG
	1000 ROYAL LEE DR	UNK	UNK-LG
	102 W WISCONSIN ST	UNK	UNK-LG
	700 AIR VIEW DR	UNK	UNK-LG
	316 SHORE DR	UNK	UNK-LG
	314 SPRING VALLEY CT	UNK	UNK-LG
	219 N FOURTH ST	UNK	UNK-LG
	179 NORTHWEST ST	UNK	UNK-LG
	332 BEACON ST	UNK	UNK-LG
	804 S FOURTH ST	UNK	UNK-LG
	959 W MAIN ST	UNK	UNK-LG
	410 ZINNIA AVE	UNK	UNK-LG
Drinking Water Fountain	112 N THIRD ST	N	C
Vacant Service	322 MAPLE ST	N	C
	1201 ROYAL LEE DR	N	C
	701 INDUSTRIAL BLVD	N	C
	600 INDUSTRIAL BLVD	N	C
	400 INDUSTRIAL BLVD	N	C
	1200 ROYAL LEE DR	N	UNK-NOLG

	726 MAPLE ST	N	C
	714 MAPLE ST	N	C
	708 MAPLE ST	N	C
	701 MAPLE ST	N	DI
	626 MAPLE ST	N	C
	618 MAPLE ST	N	C
	610 MAPLE ST	N	C
	602 MAPLE ST	N	C
	520 MAPLE ST	N	C
	605 MAPLE ST	N	C
	513 MAPLE ST	N	C
	339 NORTHWEST ST	UNK	UNK-LG
	414 MAPLE ST	N	C
	327 MAPLE ST	N	C
	310 MAPLE ST	N	C
	220 MAPLE ST	N	C
	219 MAPLE ST	N	C
	227 MAPLE ST	N	C
	309 MAPLE ST	N	C
	420 TAFT ST	N	C
	404 TAFT ST	N	C
	324 TAFT ST	N	C
	203 FIFTH ST	N	C
	300 TAFT ST	N	C
	306 TAFT ST	N	C
	311 TAFT ST	N	C
211 Taft St - Service 1	211 A TAFT ST	N	C
	203 N SECOND ST	N	C
121 N First St - Service 1	121 N FIRST ST	N	C
East Service	162 E MAIN ST	N	C
	414 W MAIN ST	N	C
320 W Main St - Vacant Lot	320 W MAIN ST	N	C
313 W Main St - Church	305 W MAIN ST	UNK	UNK-LG
Drinking Fountain	102 N SECOND ST	N	C
	110 W MAIN ST	N	C
	104 W MAIN ST	N	C
	112 W MAIN ST	N	C
	114 W MAIN ST	N	C
	202 W MAIN ST	N	C
	320 W MAIN ST	N	C
	103 W MAIN ST	N	C
	109 W MAIN ST	N	C
	115 W MAIN ST	N	C
	123 W MAIN ST	N	C
	117 W MAIN ST	N	C
	118 W MAIN ST	N	C
	202 N SECOND ST	N	C

West Service	162 E MAIN ST	N	C
	406 W MAIN ST	N	C
	104 MILL RD	N	C
Corner Service	419 N SECOND ST	UNK	UNK-LG
~119 N 2nd St	~119 N 2nd St	N	C
W Wilson St Vacant Lot 2	208 S THIRD ST	N	C
N 5th St Vacant Lot	N 5th St Vacant Lot	N	C
Anemone Ave Parking Lot	Anemone Ave Parking Lot	N	C
Lot Corner Service	120 W WILSON ST	N	C
~121 N 2nd St	~121 N 2nd St	N	C
	722 W WILSON ST	UNK	UNK-LG
	131 NORTHWEST ST	N	C
	724 AIR VIEW DR	UNK	UNK-LG
	301 WILLOW ST	UNK	UNK-LG
	172 BURR OAK ST	UNK	UNK-LG
	628 W WISCONSIN ST	UNK	UNK-LG
	505 VIOLET AVE	UNK	UNK-LG
	311 HILLCREST DR	UNK	UNK-LG
	624 N FIRST ST	UNK	UNK-LG
	504 E MAIN ST	UNK	UNK-LG
	337 WILLOW ST	UNK	UNK-LG
	525 CHESTNUT ST	UNK	UNK-LG
West Service	120 S FOURTH ST	N	C
W Wilson St Parking Lot	200 W WILSON ST	N	C
	121 W WILSON ST	N	C
	208 GROVE AVE	N	C
	218 GROVE AVE	N	C
	304 GROVE AVE	N	C
	314 GROVE AVE	N	C
	117 S FIRST ST	N	C
	111 E MAIN ST	N	C
	210 N FIRST ST	UNK	UNK-LG
	207 MAPLE ST	UNK	UNK-LG
	312 N SECOND ST	UNK	UNK-LG
	422 N SECOND ST	UNK	UNK-LG
	404 N SECOND ST	UNK	UNK-LG
	212 S THIRD ST	N	C
	119 S THIRD ST	N	C
	201 S THIRD ST	N	C
South Service	223 W MAIN ST	UNK	UNK-LG
South Service	223 W MAIN ST	N	C
	305 W MAIN ST	N	C
	121 N THIRD ST	N	C
	115 N THIRD ST	N	C
	119 S FOURTH ST	N	C
East Service	120 S FOURTH ST	N	C
	702 W WISCONSIN ST	UNK	UNK-LG

	125 W MAIN ST	N	C
	614 N FIRST ST	UNK	UNK-LG
Pre Treatment Plant	1201 ROYAL LEE DR	N	C
	124 N FOURTH ST	UNK	UNK-LG
	209 TAFT ST	UNK	UNK-LG
	117 TAFT ST	UNK	UNK-LG
121 N First St - Service 2	121 N FIRST ST	UNK	UNK-LG
	119 MILL RD	N	C
417 W MAIN ST - East Service	417 W MAIN ST	N	UNK-LG
	409 W MAIN ST	N	C
	405 W MAIN ST	N	C
	111 N FOURTH ST	N	C
	111 N THIRD ST	N	C
Historical Society	112 N THIRD ST	N	C
Museum	112 N THIRD ST	N	C
	218 W MAIN ST	N	C
	206 W MAIN ST	N	C
	212 W MAIN ST	N	C
	214 W MAIN ST	N	C
	104 E MAIN ST	N	C
	127 E MAIN ST	N	C
E Main St Vacant Lot	126 E MAIN ST	N	C
	201 E MAIN ST	N	C
	209 E MAIN ST	N	C
	409 W WILSON ST	N	C
	111 W WILSON ST	N	C
	206 S FIRST ST	UNK	UNK-LG
	202 S FIRST ST	UNK	UNK-LG
	102 E MAIN ST	UNK	UNK-LG
	225 N FIRST ST	UNK	UNK-LG
	230 S SECOND ST	N	C
	211 N SECOND ST	N	C
	210 N SECOND ST	N	C
	212 MAPLE ST	UNK	UNK-LG
	319 N SECOND ST	UNK	UNK-LG
	401 N SECOND ST	UNK	UNK-LG
	322 N SECOND ST	UNK	UNK-LG
	228 S THIRD ST	UNK	UNK-LG
	227 S THIRD ST	N	C
	116 S THIRD ST	N	C
	116 N THIRD ST	N	C
North Service	319 W MAIN ST	N	C
	424 W MAIN ST	N	C
	122 FIFTH ST	N	C
	327 ANEMONE AVE	UNK	UNK-LG
	328 ANEMONE AVE	UNK	UNK-LG
	315 ANEMONE AVE	N	C

	306 ANEMONE AVE	UNK	C
	109 ANEMONE AVE	N	C
	120 W WILSON ST	N	C
	419 N SECOND ST	UNK	UNK-LG
	416 N SECOND ST	UNK	UNK-LG
South Service	319 W MAIN ST	N	C
	128 N THIRD ST	N	C
	125 N THIRD ST	N	C
211 Taft St - Service 2	211 A TAFT ST	N	C
	124 MILL RD	N	C
	211 S FIRST ST	N	C
	307 SPRING VALLEY CT	N	C
	200 W MAIN ST	N	C
	111 N SECOND ST	N	C
	115 N SECOND ST	N	C
Apartment	102 N SECOND ST	N	C
	123 S FIRST ST	UNK	C
226-228	226 S SECOND ST	N	C
	126 N FIRST ST	UNK	UNK-LG
	114 N SECOND ST	N	C
	203 W MAIN ST	UNK	UNK-LG
	144 E JEFFERSON ST	N	C
	314 JEFFERSON ST	N	C
	312 JEFFERSON ST	N	C
	208 JEFFERSON ST	N	C
	204 JEFFERSON ST	N	C
	740 CHESTNUT ST	N	C
	730 CHESTNUT ST	N	C
	719 CHESTNUT ST	N	C
	730 BEACH ST	N	C
	313 GARFIELD ST	N	C
	219 GARFIELD ST	N	C
	303 GARFIELD ST	N	C
	720 BEACH ST	N	C
	315 MAPLE ST	N	C
	332 JEFFERSON ST	N	C
	203 Jefferson St	N	C
	430 JEFFERSON ST	N	C
	620 TAFT ST	UNK	UNK-LG
	216 N FOURTH ST	UNK	UNK-LG
	556 LINCOLN ST	UNK	UNK-LG
	752 MAPLE ST	N	C
	120 SEVENTH ST	UNK	UNK-LG
	422 SHORE DR	UNK	UNK-LG
	100 VIOLET AVE	UNK	UNK-LG
100 Taft St - Village of Palmyra	103 JEFFERSON ST	N	C
	131 JEFFERSON ST	UNK	UNK-LG

	610 WASHINGTON AVE	UNK	UNK-LG
	300 N SECOND ST	N	C
421 Maple St	342 NORTHWEST ST	N	C
	528 W WISCONSIN ST	UNK	UNK-LG
	507 E MAIN ST	UNK	UNK-LG
	302 MAPLE ST	N	C
	197 NORTHWEST ST	N	C
	509 N SECOND ST	UNK	UNK-LG
	132 VIOLET AVE	UNK	UNK-LG
	102 W MAIN ST	N	C
	313 BEACON ST	UNK	UNK-LG
	234 NORTHWEST ST	N	C
	342 NORTHWEST ST	N	C
	217 S SECOND ST	N	C
	244 TROTTERS LN	N	C
	219 E WISCONSIN ST	N	C
	240 TROTTERS LN	N	C
	237 TROTTERS LN	N	C
	231 TROTTERS LN	N	C
	221 E WISCONSIN ST	N	C
	778 AIR VIEW DR	N	C
	786 AIR VIEW DR	N	C
	799 AIR VIEW DR	N	C
	785 AIR VIEW DR	N	C
	779 AIR VIEW DR	N	C
	773 AIR VIEW DR	N	C
	798 AIR VIEW DR	N	C
	210 MILL RD	N	C
	100 W MAIN ST	N	C
	323 GARFIELD ST	N	C
	315 WILLOW ST	UNK	UNK-LG
	127 N FOURTH ST	N	C
	140 VIOLET AVE	UNK	UNK-LG
	115 MILL RD	N	C
	623 NORTHWEST ST	UNK	UNK-LG
	326 BEACON ST	UNK	UNK-LG
417 W MAIN ST - West Service	417 W MAIN ST	N	C
	125 NORTHWEST ST	N	C
	335 MAPLE ST	N	C
	564 LINCOLN ST	UNK	UNK-LG
	340 SPRING VALLEY CT	UNK	UNK-LG
	412 TAFT ST	N	C
	757 AIR VIEW DR	UNK	UNK-LG
	402 HILLCREST DR	UNK	UNK-LG
B	412 S FOURTH ST	UNK	UNK-LG
	104 LOCUST ST	UNK	UNK-LG
	236 BURR OAK ST	UNK	UNK-LG

	804 MAPLE ST	UNK	UNK-LG
	606 POWERS ST	UNK	UNK-LG
	712 W MAIN ST	N	C
	412 W WISCONSIN ST	UNK	UNK-LG
	603 W MAIN ST	N	C
742 BEACH ST	744 BEACH ST	N	C
	101 NORTHWEST ST	N	C
	320 TAFT ST	N	C
	337 SHORE DR	UNK	UNK-LG
	235 NORTHWEST ST	N	C
	746 W WISCONSIN ST	UNK	UNK-LG
	322 MAPLE ST	N	C
	222 NORTHWEST ST	N	C
	793 AIR VIEW DR	N	C
	621 WASHINGTON AVE	UNK	UNK-LG
	702 W MAIN ST	N	C
	121 SIXTH ST	UNK	UNK-LG
	180 BURR OAK ST	UNK	UNK-LG
	723 W WILSON ST	UNK	UNK-LG
	N892 TAMARACK RD	UNK	UNK-LG
	417 SHORE DR	UNK	UNK-LG
	425 WEST ST	UNK	UNK-LG
	717 MAPLE ST	N	C
	318 S SECOND ST	UNK	UNK-LG
	955 EIGHTH ST	N	C
	106 W MAIN ST	N	C
	511 N SECOND ST	UNK	UNK-LG
	116 WILLOW ST	UNK	UNK-LG
	323 BEACON ST	UNK	UNK-LG
	116 SIXTH ST	UNK	UNK-LG
	245 NORTHWEST ST	N	C
	325 SPRING VALLEY CT	UNK	UNK-LG
	305 GROVE AVE	UNK	UNK-LG
	627 W WISCONSIN ST	UNK	UNK-LG
	409 TAFT ST	UNK	UNK-LG
700 N FIRST ST	698 N FIRST ST	UNK	UNK-LG
	698 N FIRST ST	UNK	UNK-LG
	312 TAFT ST	N	C
	319 N FOURTH ST	N	C
	308 WEST ST	UNK	UNK-LG
	147 NORTHWEST ST	UNK	UNK-LG
	208 NORTHWEST ST	UNK	UNK-LG
	314 NORTHWEST ST	UNK	UNK-LG
	326 NORTHWEST ST	UNK	UNK-LG
	228 NORTHWEST ST	UNK	UNK-LG
	103 W WISCONSIN ST	UNK	UNK-LG
	718 W WISCONSIN ST	UNK	UNK-LG

	515 W WISCONSIN ST	UNK	UNK-LG
	117 NORTHWEST ST	UNK	UNK-LG
	579 WASHINGTON AVE	UNK	UNK-LG
	213 MAPLE ST	N	C
222-224	224 S SECOND ST	N	C
	402 MAPLE ST	N	C
	526 MAPLE ST	N	C
	345 SPRING VALLEY CT	UNK	UNK-LG
501A	501 A GARFIELD ST	UNK	UNK-LG
	222 TAFT ST	N	C
594 and 600 Powers St	600 POWERS ST	UNK	UNK-LG
	305 ANEMONE AVE	N	C
	603 W WISCONSIN ST	UNK	UNK-LG
	415 MAPLE ST	UNK	UNK-LG
	506 WASHINGTON AVE	UNK	UNK-LG
	326 VIOLET AVE	UNK	UNK-LG
	115 E WISCONSIN ST	UNK	UNK-LG
	212 MILL RD	N	C
	212 E WISCONSIN ST	UNK	UNK-LG
	719 W WISCONSIN ST	UNK	UNK-LG
	514 WASHINGTON AVE	UNK	UNK-LG
	756 AIR VIEW DR	UNK	UNK-LG
	770 AIR VIEW DR	N	C
W Wilson St Vacant Lot	305 W MAIN ST	N	C
	422 MAPLE ST	UNK	UNK-LG
	608 POWERS ST	UNK	UNK-LG
	622 POWERS ST	UNK	UNK-LG
	501 GARFIELD ST	UNK	UNK-LG
	405 ANEMONE AVE	UNK	UNK-LG
	304 SPRING VALLEY CT	N	C
	223 GROVE AVE	UNK	UNK-LG
	408 ANEMONE AVE	UNK	UNK-LG
	415 ANEMONE AVE	UNK	UNK-LG
	416 HILLCREST DR	UNK	UNK-LG
	319 SHORE DR	UNK	UNK-LG
	317 SHORE DR	UNK	UNK-LG
	416 ZINNIA AVE	UNK	UNK-LG
	120 E JEFFERSON ST	UNK	UNK-LG
	303 JEFFERSON ST	UNK	UNK-LG
	316 BEACON ST	UNK	UNK-LG
	310 BEACON ST	UNK	UNK-LG
	102 E BLUFF ST	UNK	UNK-LG
	95 E BLUFF ST	UNK	UNK-LG
	107 E BLUFF ST	UNK	UNK-LG
	729 CHESTNUT ST	N	C
246 and 250	246 BURR OAK ST	UNK	UNK-LG
	741 CHESTNUT ST	N	C

	221 FIFTH ST	UNK	UNK-LG
	409 N SECOND ST	UNK	UNK-LG
	315 WEST ST	UNK	UNK-LG
	523 W WILSON ST	UNK	UNK-LG
	121 SEVENTH ST	UNK	UNK-LG
	208 S THIRD ST	N	C
	525 MAPLE ST	N	C
	738 MAPLE ST	N	C
	160 MILL RD	N	C
	607 PLANEVIEW DR	UNK	UNK-LG
	615 N SECOND ST	UNK	UNK-LG
	307 SHORE DR	UNK	UNK-LG
	730 N FIRST ST	UNK	UNK-LG
	501 W WILSON ST	UNK	UNK-LG
	405 NORTHWEST ST	N	C
	406 MAPLE ST	N	C
	109 E BLUFF ST	UNK	UNK-LG
	501 W MAIN ST	UNK	UNK-LG
	716 AIR VIEW DR	UNK	UNK-LG
	108 MILL RD	N	C
	518 W WISCONSIN ST	UNK	UNK-LG
	226 GROVE AVE	N	C
	607 WASHINGTON AVE	UNK	UNK-LG
	744 BEACH ST	UNK	UNK-LG
503 W Main St	501 W MAIN ST	UNK	UNK-LG
	131 NORTHWEST ST	N	C
	314 WEST ST	UNK	UNK-LG
	250 TROTTERS LN	N	C
	249 TROTTERS LN	N	C
	243 TROTTERS LN	N	C
	1037 CARRIAGE WAY	N	C
	1024 CARRIAGE CT	N	C
	1036 CARRIAGE CT	N	C
	1054 CARRIAGE CT	N	C
	1071 CARRIAGE WAY	N	C
	115 CARRIAGE WAY	N	C
	1008 CARRIAGE CT	N	C
	1046 CARRIAGE CT	N	C
	1065 CARRIAGE WAY	N	C
	1001 CARRIAGE CT	N	C
	1021 CARRIAGE CT	N	C
	1027 CARRIAGE CT	N	C
	1047 CARRIAGE CT	N	C
1051 Carriage Ct	1049 CARRIAGE CT	N	C
	1061 CARRIAGE CT	N	C
	1088 CARRIAGE CT	N	C
	1084 CARRIAGE CT	N	C

	1066 CARRIAGE WAY	N	C
	1028 CARRIAGE WAY	N	C
	1053 CARRIAGE WAY	N	C
	131 CARRIAGE WAY	N	C
	1015 CARRIAGE CT	N	C
	1031 CARRIAGE CT	N	C
	1061 CARRIAGE CT	N	C
	1075 CARRIAGE CT	N	C
	1049 CARRIAGE CT	N	C
	1053 CARRIAGE CT	N	C
	1016 CARRIAGE CT	N	C
1037 and 1039	1037 CARRIAGE CT	N	C
	1043 CARRIAGE CT	N	C
	1057 CARRIAGE CT	N	C
	1067 CARRIAGE CT	N	C
	1080 CARRIAGE CT	N	C
	1072 CARRIAGE CT	N	C
	1058 CARRIAGE WAY	N	C
	1052 CARRIAGE WAY	N	C
1036 and 1038	1036 CARRIAGE WAY	N	C
	105 CARRIAGE WAY	N	C
	340 S SECOND ST	UNK	UNK-LG
	702 AIR VIEW DR	UNK	UNK-LG
	819 W MAIN ST	UNK	UNK-LG
	1032 CARRIAGE WAY	N	C
	1035 CARRIAGE WAY	N	C
	1059 CARRIAGE WAY	N	C
	232 TROTTERS LN	N	C
	225 TROTTERS LN	N	C

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

UNK		C	3/4"
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		C	3/4"
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-NOLG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
N	4"	2021	UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK	1"	2021	UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK			UNK-LG
UNK	1"	2000	UNK-LG
UNK	1"	2008	UNK-NOLG
N	1"	1987	UNK-NOLG
N	1"	1987	UNK-NOLG
N	1"	1987	UNK-NOLG
N	1"	1987	UNK-NOLG
N	12"	1987	UNK-NOLG

UNK	1"	2008 C	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 C	3/4"
N	1"	DI	
UNK	1"	2008 C	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 C	3/4"
UNK	3/4"	2008 C	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 C	3/4"
UNK	1"	2008 C	3/4"
UNK		UNK-LG	
UNK	1"	2008 C	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 C	3/4"
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-NOLG	
UNK		UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	3/4"
UNK	1"	2000 UNK-LG	3/4"
UNK	1"	2000 UNK-LG	3/4"
UNK	1"	2000 UNK-LG	3/4"
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	3/4"
UNK	1"	2000 UNK-LG	3/4"
UNK	1"	2000 L	3/4"
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	3/4"

UNK	1 1/4"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK		UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-NOLG	
UNK	1"	2000 UNK-NOLG	
UNK	1"	2000 UNK-NOLG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK		C	3/4"
UNK	1"	2022 C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		G	3/4"
UNK	1"	UNK-LG	
UNK	1"	2000 UNK-NOLG	
UNK	1"	2000 UNK-LG	
UNK	1"	UNK-LG	3/4"
UNK	1"	C	3/4"
UNK	1"	2000 UNK-LG	
UNK	1"	UNK-LG	
UNK	1"	2000 C	3/4"
UNK	1"	2000 UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	UNK-LG	
UNK		G	3/4"
UNK	1"	2000 UNK-LG	
UNK	1"	2000 C	1"
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	UNK-LG	
UNK		C	3/4"

UNK	1"	2000 C	3/4"
UNK		C	3/4"
N	1"	1987 C	3/4"
UNK		G	3/4"
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK	1 1/2"	2000 UNK-LG	
UNK		UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1 1/2"	UNK-LG	
UNK	1"	UNK-LG	
UNK	1"	UNK-LG	
UNK	1"	UNK-LG	
UNK	1"	UNK-LG	
UNK	1"	UNK-LG	
UNK	1"	UNK-LG	
UNK	2"	UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	3/4"
UNK	1"	2000 UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 C	3/4"
UNK	1"	2000 UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK		C	3/4"
UNK		UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 G	1"
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK	1"	UNK-LG	

UNK	1"	2000 UNK-LG	
UNK	1"	UNK-LG	3/4"
UNK	1 1/2"	2000 UNK-LG	
UNK		UNK-LG	
UNK		UNK-LG	
UNK	1"	UNK-LG	
UNK	3/4"	UNK-LG	
UNK	3/4"	UNK-LG	
UNK	3/4"	G	3/4"
UNK		UNK-LG	3/4"
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 UNK-LG	
UNK	1"	2000 G	3/4"
UNK	1"	UNK-LG	
UNK	1"	2000 UNK-LG	
UNK		UNK-LG	
UNK		1995 G	3/4"
UNK		1995 UNK-LG	
UNK		1995 UNK-LG	
UNK		1995 UNK-LG	
UNK	1"	1995 UNK-LG	
UNK		2021 UNK-LG	
UNK		2021 UNK-LG	
UNK		2021 UNK-LG	
UNK	1"	2021 UNK-LG	
UNK		2021 UNK-LG	
UNK		2021 UNK-LG	
UNK		2021 UNK-LG	
UNK		2021 UNK-LG	
UNK	1"	2008 G	3/4"
UNK	1"	1994 UNK-LG	
UNK	2"	1994 UNK-LG	1"
UNK	1"	1994 UNK-LG	
UNK	3/4"	G	3/4"
UNK	3/4"	C	3/4"
UNK		1978 C	3/4"
UNK	1"	2008 C	3/4"
UNK		G	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK		C	3/4"

UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK	1"	2022 P	1"
UNK		G	3/4"
UNK		C	3/4"
UNK	1"	G	3/4"
UNK	3/4"	C	3/4"
UNK		G	
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK		C	1"
UNK	1"	G	3/4"
UNK	1"	P	1"
UNK	1"	2000 P	3/4"
N		1999 C	3/4"
N	1"	1999 UNK-NOLG	
N	1"	1999 UNK-NOLG	
N	1"	1999 UNK-NOLG	
N	1"	1999 UNK-NOLG	
N		1999 UNK-NOLG	
N	1"	1996 UNK-NOLG	
N	1"	1996 UNK-NOLG	
N	1"	1996 UNK-NOLG	
N	1"	1996 UNK-NOLG	
N	1"	1996 UNK-NOLG	
N	1"	1996 UNK-NOLG	
N	1"	1996 UNK-NOLG	
N		UNK-NOLG	
UNK	1"	2000 G	3/4"
UNK	1"	2021 C	3/4"
UNK		G	3/4"
UNK	1"	2000 G	3/4"
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK	1"	2022 C	3/4"
UNK	1"	G	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		G	3/4"
UNK		G	3/4"
UNK		C	3/4"

UNK		G	3/4"
UNK		C	3/4"
UNK	1"	2022 C	3/4"
UNK		C	3/4"
UNK	1"	G	3/4"
UNK	1"	2021 C	3/4"
UNK	1"	2022 G	3/4"
UNK	1"	2000 C	3/4"
UNK		C	3/4"
UNK	1"	2022 C	3/4"
UNK		G	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2022 G	3/4"
N	1"	1996 C	3/4"
UNK		C	3/4"
UNK	1"	2022 G	3/4"
UNK		G	3/4"
UNK		C	3/4"
UNK		G	3/4"
UNK		G	
UNK		C	3/4"
UNK		C	3/4"
UNK		2021 G	1"
UNK		C	
N	3/4"	UNK-LG	3/4"
UNK	1"	2000 G	3/4"
UNK		G	3/4"
UNK		C	5/8"
UNK		C	3/4"
UNK		G	3/4"
UNK	1"	C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2000 G	3/4"
UNK	1"	G	3/4"
UNK		C	3/4"
UNK		G	3/4"
UNK		G	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		G	3/4"
UNK		C	3/4"
UNK		C	

UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2000 C	3/4"
UNK	1"	2008 C	3/4"
UNK	1"	2008 G	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2000 G	3/4"
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK		G	3/4"
UNK		G	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		G	3/4"
N		P	
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
N	1"	1996 C	3/4"
UNK	1"	C	3/4"
UNK		G	
UNK		C	3/4"
UNK		C	1"
UNK		G	3/4"
UNK		C	3/4"
UNK	1"	C	3/4"
UNK		C	3/4"
UNK		C	1"
UNK		C	3/4"
UNK		P	1"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		P	1"
UNK		UNK-LG	
UNK		2021 C	3/4"
UNK		C	3/4"
UNK		2021 C	3/4"

UNK		G	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK	1"	2008 C	1"
UNK	1"	2008 C	3/4"
N		C	3/4"
UNK		C	3/4"
UNK		G	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		P	3/4"
UNK	1"	2008 G	3/4"
UNK	1"	2008 C	3/4"
UNK		P	1 1/2"
UNK		C	3/4"
UNK		C	3/4"
UNK	3/4"	2000 C	3/4"
UNK		C	3/4"
UNK	1"	2000 C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK		C	3/4"
UNK	1"	2022 C	3/4"
UNK		C	3/4"
N	1"	1999 C	3/4"
N	1"	1999 C	3/4"
N	1"	1999 C	3/4"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	1"	1978 C	1"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	1"	1978 C	1"
N		1978 UNK-LG	
N		1978 UNK-LG	
N		1978 UNK-LG	
N	3/4"	1978 C	3/4"
N		1978 UNK-LG	
N		1978 UNK-LG	
N	3/4"	1978 C	3/4"

N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	1"	1978 C	1"
N		1978 C	
N		1978 UNK-LG	
N		1978 UNK-LG	
N		1978 UNK-LG	
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N		1978 C	3/4"
N		1978 C	3/4"
N		1978 UNK-LG	
N		1978 UNK-LG	
N		1978 UNK-LG	
N		1978 UNK-LG	
N		1978 C	3/4"
N		1978 UNK-LG	
N		1978 C	3/4"
N		1978 C	2"
UNK		C	1"
UNK		C	3/4"
UNK		G	3/4"
N		1978 UNK-NOLG	
N	3/4"	1978 C	3/4"
N	3/4"	1978 C	3/4"
N	1"	1999 C	3/4"
N	1"	1999 C	3/4"

[illegible]

[illegible]

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

NONRES

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

NONRES

SF

SF

SF

SF

SF

SF

SF

SF

SF
SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF	
SF	

SF
SE

SF

SF
SE

SF

SF
SE

SF
SF

SF
SF
SF
SF
SF
SF
SF
SF
NONRES
NONRES
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
MF
SF
SF
SF
NONRES
SF
SF
NONRES
SF
SF
SF
SF
SF
SF
SF
SF
NONRES
SF
NONRES
SF
NONRES
NONRES
NONRES
NONRES
NONRES

SF
SF
SF
NONRES
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
NONRES
SF
SF
SF
NONRES
SF
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
SF
NONRES
NONRES
NONRES
NONRES
MF
NONRES

NONRES
SF
SF
SF
NONRES
NONRES
NONRES
NONRES
SF
NONRES
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
SF
NONRES
SF
SF
SF
SF
SF
SF
NONRES
SF
SF
SF
SF
SF
NONRES
SF
SF
SF
NONRES
SF
NONRES
NONRES
SF
SF
SF

NONRES
SF
NONRES
SF
NONRES
NONRES
SF
MF
SF
MF
SF
SF
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
NONRES
SF
NONRES
MF
SF
NONRES
SF
SF
SF
NONRES
SF
SF
SF
SF
SF
SF
SF
SF
NONRES
NONRES
MF
NONRES
SF
SF
NONRES
SF
SF
SF

NONRES

SF

SF

SF

SF

SF

SF

NONRES

SF

SF

SF

SF

NONRES

NONRES

NONRES

MF

SF

SF

NONRES

NONRES

NONRES

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

NONRES

NONRES

SF

SF

SF

SF

SF

SF

SF

NONRES

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

NONRES

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

MF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

MF

NONRES

NONRES

NONRES

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SE

SE

SE

SE

SE

SE

SE

SE

SF

SF

SF

SF

SF

SF

SF

65

SF

SF

SF

SF

SF

SF

SF

SF

SF

NONRES

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

NONRES

SF

SF

SF

NONRES

SF

SF

SF

SF

SF

SF

SF

MF

SF

SF

SF

SF

SF

SF

MF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

MF

SF

SF

SF

MF

SF

SF

SF

SF

SF

SF

SF

MF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

SF

ME

MF
NONRES

NONRES

SE

SF

SF

SF

SF

SF

SF

SF

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
SL repair/replace record	N	Field inspection only
SL repair/replace record	N	SL repair/replace record
SL repair/replace record	N	SL repair/replace record
Installed after lead ban	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
SL repair/replace record	N	SL repair/replace record
SL repair/replace record	N	SL repair/replace record
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
SL repair/replace record	N	Field inspection only
Other - describe in notes	N	Field inspection only
SL repair/replace record	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Other - describe in notes
Other - describe in notes	N	Field inspection only
Installation record	N	Field inspection only
Other - describe in notes	N	Field inspection only
Installation record	N	Field inspection only
Installation record	N	Field inspection only
Installation record	N	Field inspection only
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Field inspection only
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Other - describe in notes
Installation record	N	Other - describe in notes
Installation record	N	Other - describe in notes
Installation record	N	Field inspection only
Installation record	N	Other - describe in notes
Installation record	N	Other - describe in notes
Installation record	N	Field inspection only

Installation record	N	Field inspection only
Installation record	N	Field inspection only
Installation record	N	Field inspection only
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Other - describe in note:
Installation record	N	Other - describe in note:
Installation record	N	Other - describe in note:
Installation record	N	Field inspection only
Installation record	N	Installation record
Installation record	N	Installation record
Installation record	N	Field inspection only
Installation record	N	Field inspection only
Installation record	N	Other - describe in note:
Installation record	N	Other - describe in note:
Installation record	N	Other - describe in note:
Installation record	N	Other - describe in note:
Installation record	N	Field inspection only
Installation record	N	Other - describe in note:
Installation record	N	Field inspection only
Installation record	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Other - describe in notes	N	Field inspection only
Installation record	N	Other - describe in note:
Installation record	N	Installation record
Installation record	N	Field inspection only
Installation record	N	Installation record
Installation record	N	Installation record

[illegible]

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N _____

[illegible]

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N _____

[illegible]

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N

N _____

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

N

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

N

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

N

N

Y

Y

Y

Y

Y

Y

Y

Y

Y

Y

[illegible]

Y	
Y	
Y	
Y	
Y	
Y	
N	
N	
Y	
Y	
Y	
Y	
Y	
Y	
N	
N	
Y	
Y	
Y	
Y	
Y	
Y	
Y	
Y	
N	
N	
N	
N	
N	
N	
N	
Y	
N	
N	
N	
N	
N	
Y	
N	
N	
Y	

Y	
Y	
Y	
N	
N	
N	
N	
N	
Y	
N	
N	
Y	
Y	
N	
N	
N	
N	
Y	
N	
Y	
Y	
Y	
Y	
Y	
N	
N	
Y	
N	
N	

[illegible]

[illegible]

[illegible]

[illegible]

Street Side: No records (may contain lead);Property Side: No records (may contain lead);

Property side service was noted as "in poor condition" in 2008

Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);

Vacant lot - may not be an existing property side service Property Side: No records (may contain lead);

Street Side: No records (may contain lead);Property Side: No records (may contain lead);

Property Side: No records (may contain lead);
Property Side: No records (may contain lead);

Property Side: No records (may contain lead);
Property Side: No records (may contain lead);

Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);

--

Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property side water service may not exist - vacant lot
Property side service may not exist - vacant lot
Property side water service may not exist - parking lot Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 10-12-21 Street Side: No records (may contain lead);
Cross connection inspection 10-12-21
Cross connection inspection 7-12-21 Street Side: No records (may contain lead);
Cross connection inspection 8-18-21 Street Side: No records (may contain lead);
Cross connection inspection 4-2-21 Street Side: No records (may contain lead);
Cross connection inspection 5-6-21 Street Side: No records (may contain lead);
Cross connection inspection 5-11-21 Street Side: No records (may contain lead);
Cross connection inspection 5-11-21 Street Side: No records (may contain lead);
Cross connection inspection 2-8-21 Street Side: No records (may contain lead);
Cross connection inspection 2-11-21 Street Side: No records (may contain lead);
Cross connection inspection 2-8-21 Street Side: No records (may contain lead);
Cross connection inspection 2-25-21 Street Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property side service may not exist - parking lot
Property Side: No records (may contain lead);
Cross connection inspection 6-24-20
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 12-14-21
Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 12-22-21
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 3-29-21 Street Side: No records (may contain lead);

Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 8-4-21
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Cross connection inspection 7-7-21
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Street side: Copper previously lead, need physical record; Property side: Cross connection inspection 9-8-2
Street side: Copper, previously lead noted but need physical record; Property side: Cross connection insper
Cross connection inspection 9-15-22
Cross connection inspection 9-15-22
Cross connection inspection 9-15-22; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 9-15-22; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 7-1-22; Pex premise Street Side: No records (may contain lead);
Cross connection inspection 8-29-22
Cross connection inspection 8-29-22 Street Side: No records (may contain lead);

[illegible]

Cross connection inspection 1-25-21 Street Side: No records (may contain lead);
Cross connection 2-8-21 Street Side: No records (may contain lead);
Cross connection inspection 2-4-21
Cross connection inspection 1-20-21 Street Side: No records (may contain lead);
Cross connection 1-11-21
Cross connection inspection 1-14-21
Cross connection inspection 1-12-21
Cross connection inspection 12-15-21
Cross connection inspection 12-15-21 Street Side: No records (may contain lead);
Cross connection inspection 12-14-21
Cross connection inspection (no date listed) Street Side: No records (may contain lead);
Cross connection inspection 1-11-21
Cross connection inspection 12-13-21
Cross connection inspection 12-13-21
Cross connection inspection 12-16-21 Street Side: No records (may contain lead);
Cross connection inspection 12-13-21
Cross connection inspection 3-30-22 Street Side: No records (may contain lead);
Cross connection inspection 4-6-22 Street Side: No records (may contain lead);
Cross connection inspection 9-7-22; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 9-8-22; Copper and galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 6-28-22; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 12-14-20, 6-8-22 Street Side: No records (may contain lead);
Cross connection inspection 8-4-22; Copper premise
Cross connection inspection 10-27-22; Copper premise Street Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 4-26-22
Cross connection inspection 6-27-22; Copper and pex premise Street Side: No records (may contain lead);
Cross connection inspection 8-19-22 Street Side: No records (may contain lead);
Cross connection inspection 9-7-22 Street Side: No records (may contain lead);
Cross connection inspection 9-8-22; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 9-8-22; Copper and pex premise
Cross connection inspection 6-30-22; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-5-22; Galvanized premise
Cross connection inspection 7-6-22; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-12-22; Copper premise
Street Side: No records (may contain lead);
Street Side: No records (may contain lead);
Cross connection inspection 4-4-22
Cross connection inspection 4-4-22
Cross connection inspection 6-30-22; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-14-23; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 4-11-23; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 8-29-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-12-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-12-23 Street Side: No records (may contain lead);
Cross connection inspection 8-30-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-7-23; Copper and pex premise Street Side: No records (may contain lead);

Cross connection inspection 6-12-20, 7-6-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-16-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 9-6-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 9-6-23; Galvanized and copper premise
Cross connection inspection 9-6-23; Copper premise
Cross connection inspection 9-6-23; Pex premise
Cross connection inspection 9-26-23; Galvanized and copper premise
Cross connection inspection 8-31-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 9-6-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 8-29-23; Copper premise
Cross connection inspection 9-6-23 and 9-7-23; Copper premise Street Side: No records (may contain lead)
Cross connection inspection 8-29-23; Copper premise
Cross connection inspection 8-31-23; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 8-31-23; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 8-31-23 Street Side: No records (may contain lead);
Cross connection inspection 8-26-31; Copper pex Street Side: No records (may contain lead);
Cross connection inspection 8-30-23; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 6-1-23
Cross connection inspection 1-24-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-13-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-11-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 6-29-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-6-23; Copper premise
Cross connection inspection 7-6-23; Copper and galvanized premise
Cross connection inspection 7-13-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-13-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-20-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 8-29-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-24-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-20-23; Copper premise
Cross connection inspection 1-10-23; Galvanized premise
Cross connection inspection 7-11-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 6-30-23; Pex premise Street Side: No records (may contain lead);
Cross connection inspection 1-4-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 6-24-20, 5-25-23 Street Side: No records (may contain lead);
Cross connection inspection 1-12-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-14-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-10-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 6-29-23; Copper and pex premise Street Side: No records (may contain lead);
Cross connection inspection 7-13-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 7-20-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 6-29-23; Copper, galvanized, and pex premise Street Side: No records (may co
Cross connection inspection 7-13-23; Copper premise Street Side: No records (may contain lead);
Street Side: No records (may contain lead);Property Side: No records (may contain lead);
Cross connection inspection 1-24-23; Copper premise
Cross connection inspection 3-23-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 1-24-23; Galvanized premise

Cross connection inspection 6-29-23; Pex premise Street Side: No records (may contain lead);
Cross connection inspection 3-22-23; Pex premise Street Side: No records (may contain lead);
Cross connection inspection 7-24-23; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 8-15-23; Galvanized premise Street Side: No records (may contain lead);
Cross connection inspection 7-13-23; 1' Galv before meter; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 5-11-23; Copper premise
Cross connection inspection 7-11-23; Copper and galvanized premise
Cross connection inspection 7-6-23, Pex premise
Cross connection inspection 7-2-24; Copper premise
Cross connection inspection 6-26-24; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 6-26-24; Copper and pex premise Street Side: No records (may contain lead);
Cross connection inspection 6-24-24 Street Side: No records (may contain lead);
Cross connection inspection 6-24-24; Pex premise Street Side: No records (may contain lead);
Cross connection inspection 4-3-24; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 2-19-24; Copper and pex premise
Cross connection inspection (no date); Copper premise Street Side: No records (may contain lead);
Cross connection inspection 2-8-24; Copper premise Street Side: No records (may contain lead);
Cross connection inspection (no date); Copper premise Street Side: No records (may contain lead);
Cross connection inspection 2-6-24; PVC premise
Cross connection inspection 2-6-24; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 2-6-24; Copper premise
Cross connection inspection (no date); Galvanized premise Street Side: No records (may contain lead);
Street Side: No records (may contain lead);
Cross connection inspection 2-8-24; Copper premise Street Side: No records (may contain lead);
Cross connection inspection 10-12-21
Cross connection inspection 2-4-21 Street Side: No records (may contain lead);
Cross connection inspection 6-9-20
Cross connection inspection 1-25-21
Cross connection inspection 1-25-21
Cross connection inspection 12-15-21
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 9-27-21
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 6-3-20

Cross connection inspection 12-16-20
Cross connection inspection 12-16-20
Cross connection inspection 7-14-23; Copper premise
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 9-27-21
Cross connection inspection 3-24-23; Copper premise
Cross connection inspection 3-23-23; Copper premise
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 7-1-20
Property Side: No records (may contain lead);
Cross connection inspection 1-11-23; Copper premise
Cross connection inspection 6-28-22; Copper premise
Cross connection inspection 6-25-18 Street Side: No records (may contain lead);
Cross connection inspection 2-5-18 Street Side: No records (may contain lead);
Cross connection inspection 4-6-22 Street Side: No records (may contain lead);
Property Side: No records (may contain lead);
Cross connection inspection 2-19-18

ntain lead);

contain lead);

[Click here to open USEPA 2022 Guidance for Develop](#)

Note: Field names that are shaded navy are required for every service connection. Field n conditions. See field descriptions

	Column			
A	SITE ID	PWS that do not wish to report site addresses to the department in column B can use this column for their own use. This column is optional, however, it strongly recommends reporting this information. This column is optional, however, it strongly recommends reporting this information.		
B	LOCATION IDENTIFIER	The location identifier can be the site address, however if there is more than one address for a site, it can be a block, intersection, or other identifier. If a PWS does not wish to report addresses to the department it can be a block, intersection, or other identifier which requires that a location identifier be associated with each service connection.		
	Column	Description	Answer options	
C	GOOSENECK CURRENTLY PRESENT?	Is there a gooseneck, lead connector or pigtail present? PWS are required to track this information, if known. However, PWS are not required to conduct investigations to determine if a gooseneck is present.	Y	YES - WITH CERTAIN
			N	NO - WITH CERTAIN
			UNK	NOT KNOWN WITH CERTAIN
D	CURRENT STREET SIDE SERVICE LINE MATERIAL	Service line pipe material, from the water main to curb stop.	L	CONFIRMED LEAD
			C	CONFIRMED COPPER
			G	CONFIRMED GALVANIZED
			P	CONFIRMED PLASTIC
			DI	CONFIRMED DUCTILE IRON
			CI-L	CONFIRMED LINEAR
			CI-U	CONFIRMED UNIFORM
			UNK-LG	UNKNOWN - MATERIAL
UNK-NOLG	UNKNOWN - DEFECTIVE			
E	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	Was the service line ever previously lead?	Y	YES – SERVICE LINE
			N	NO – KNOWS WITH CERTAIN
			UNK	NOT KNOWN WITH CERTAIN
	Column			
F	STREET SIDE SERVICE LINE SIZE	Service line pipe diameter in inches, from the water main to curb stop. The diameter. Furthermore, PWSs are required to report service line size to the department in a single document. Column F is required for all service connections.		
G	STREET SIDE SERVICE LINE INSTALL DATE	The four-digit year that the utility-side service was installed (i.e. 1974). If the year is not known, it can be used as a screening tool. Although this information is not required, it can be used as a screening tool.		
H	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	Service line pipe material, from the curb stop to water meter. See Row D for details.		

I	PROPERTY SIDE SERVICE LINE SIZE1	Service line pipe diameter, in inches, from the curb stop to water meter. Furthermore, PWS are required to report service line size to the information required by both agencies in a single document. Column I is		
J	PROPERTY SIDE SERVICE LINE INSTALL DATE	If the exact year is not known, enter the decade (i.e. enter 1970 for any line was installed before or after the lead ban (1986). Column J is option		
	Column	Description	Answer options	
K	BUILDING TYPE	The type of structure that is served water by the service connection. At a minimum, the PWS must identify the connection either SF, MF or NONRES.	SF	SINGLE-FAMILY R
			MF	MULTI-FAMILY R
			SCH/CC	SCHOOL OR CHIL
			RES/CC	RESIDENTIAL & II
			NONRES	NONRESIDENTIA
			MIX	MIXED RESIDENT
			O	OTHER
L	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	Is the cold-water kitchen tap treated by point-of-entry or point-of-use softening, filter or other treatment? Column L is optional.	Y	YES - the sample
			N	NO - the sample
			UNK	Presence or abse
M	BUILDING PLUMBING MATERIAL 1	The type of plumbing materials inside the structure that water is deliver to. If there is more than one known plumbing material type, select the second material type in column N. Columns M and N are optional.	CLS	Copper with lead
			C	Copper, no lead s
N	BUILDING PLUMBING MATERIAL 2		O	Other material th
			UNK	Unknown
	Column			
O	BUILDING PLUMBING MATERIAL INSTALL DATE	The four-digit year that the interior premise plumbing was installed. If th is the 1980s, you may enter one of the following: 1983-1984, <1983 or >		
P	COMMENTS	Use this column information to enter any other information that the PW optional.		
	Column	Description	Answer options	
Q	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y- Notes on materials classification.	Previous eval	
			Installation record	
			Installed after lead ban	
			Diameter > 2 inches	
			SL repair/replace record	
			Water sampling only	
			Field inspection only	
			Other - describe in notes	
	Column			

R	WAS STREET SIDE MATERIAL FIELD VERIFIED?	Was the street side material field verified? Select "Y" for "Yes" or "N" for "No".																					
S	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column R, enter the date (DD/MM/YYYY) or four digit year in Column R.																					
<table> <tr> <th>Column</th><th>Description</th><th>Answer options</th></tr> <tr> <td>T</td><td>METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE</td><td> Customer self id CCTV - internal CCTV - external Mech excav Visual insp at meter Visual insp during install or repair Cross connection survey Other </td></tr> <tr> <td>U</td><td>BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION</td><td>Use the drop-down menu to select the method used for materials classification in Column Y. See Column Q for a description of and an explanation of the classification.</td></tr> <tr> <td>V</td><td>WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?</td><td>Was the property side material field verified? Select "Y" for "Yes" or "N" for "No".</td></tr> <tr> <td>W</td><td>DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE</td><td>If PWS selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.</td></tr> <tr> <td>X</td><td>METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE</td><td>If you selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.</td></tr> <tr> <td>Y</td><td>NOTES MATERIAL CLASSIFICATION</td><td>If PWS selected "other" in Columns Q, T, U or X, describe the basis for classification in Column Y. This field is only required if "Other" was selected in Columns Q, T, U and/or X.</td></tr> </table>			Column	Description	Answer options	T	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	Customer self id CCTV - internal CCTV - external Mech excav Visual insp at meter Visual insp during install or repair Cross connection survey Other	U	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification in Column Y. See Column Q for a description of and an explanation of the classification.	V	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	Was the property side material field verified? Select "Y" for "Yes" or "N" for "No".	W	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.	X	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.	Y	NOTES MATERIAL CLASSIFICATION	If PWS selected "other" in Columns Q, T, U or X, describe the basis for classification in Column Y. This field is only required if "Other" was selected in Columns Q, T, U and/or X.
Column	Description	Answer options																					
T	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	Customer self id CCTV - internal CCTV - external Mech excav Visual insp at meter Visual insp during install or repair Cross connection survey Other																					
U	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification in Column Y. See Column Q for a description of and an explanation of the classification.																					
V	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	Was the property side material field verified? Select "Y" for "Yes" or "N" for "No".																					
W	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.																					
X	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.																					
Y	NOTES MATERIAL CLASSIFICATION	If PWS selected "other" in Columns Q, T, U or X, describe the basis for classification in Column Y. This field is only required if "Other" was selected in Columns Q, T, U and/or X.																					
T	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column R, select the method used for field verification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y. This field is only required if "Yes" was selected in Column R. Customer self id CCTV - internal CCTV - external Mech excav Visual insp at meter Visual insp during install or repair Cross connection survey Other																					
U	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification in Column Y. See Column Q for a description of and an explanation of the classification.																					
V	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	Was the property side material field verified? Select "Y" for "Yes" or "N" for "No".																					
W	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.																					
X	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column V, select the method used for field verification in Column Y. This field is only required if "Yes" was selected in Column V.																					
Y	NOTES MATERIAL CLASSIFICATION	If PWS selected "other" in Columns Q, T, U or X, describe the basis for classification in Column Y. This field is only required if "Other" was selected in Columns Q, T, U and/or X.																					

Linking and Maintaining a Service Line Inventory
--

<i>Names shaded blue are recommended, optional, or only required under certain circumstances. For more information.</i>

Description

Column B can use this column to “link” their materials inventory table to a separate service address table. It is recommended that PWS enter the site ID for locations that are lead and copper monitoring sites in

addition to the service connection at a given address, it must include additional detail. If the PWS does not have a service connection or landmark. This column is required per sub-subparagraph §141.84 (a)(8)(i) of the LCRR. This column is optional.

Answer Option Descriptions

WITH CERTAINTY

.....

WITH CERTAINTY

.....

WITH CERTAINTY

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

DOES NOT CONTAIN LEAD OR GALVANIZED

.....

Description

This information is useful as a screening tool as most lead service lines are 2 inches or less in diameter. This column may also be used by PWS that wish to track lead service line material. This column is optional.

If the exact year is not known, enter the decade (i.e. enter 1970 for any year in the 1970s). This column is optional. This column may also be used by PWS that wish to track lead service line material. This column is optional.

For answer options.

.....

. This information is useful as a screening tool as most lead service lines are 2 inches or less in
he PSC for their annual report. This column may also be used by PWS that wish to track
; optional.

year in in the 1970s). This information it can be used as a screening tool to determine if the service
ial.

Answer Option Descriptions

RESIDENTIAL

RESIDENTIAL

D CARE

y be used by the PWSs to track locations that must be monitored under §141.92.

V-HOME CHILD CARE

y be used by the PWSs to track locations that must be monitored under §141.92.

L ONLY, NO SCHOOL OR CHILD CARE.

IAL & NONRESIDENTIAL, NO SCHOOL OR CHILD CARE.

tap is treated by a point of use or point of entry softener or filter

tap is not treated by a point of use or point of entry softener or filter

nce of POU and POE is UNKNOWN

| solder

solder

at is not copper, or copper with lead solder

Description

ne exact year is not known, you may enter the decade if the decade is not the 1980s. If the decade
·1984. Column O is optional.

/S finds helpful to them or any information they wish to share with the department. Column P is

Answer Option Descriptions (Chapter 4 of EPA inventory guidance)

Previous Materials Evaluation

Installation record (e.g., tap card)

Installation date after lead ban (1986)

Service line diameter is > 2 inches

Service line repair or replacement record

Water sampling only with no records

Field inspection only with no records

Other - if other is selected describe the basis for material classification in the Notes Column Y.

Description

r "No".

-digit year that the material was field verified. This field is only required if "Yes" was selected in

Answer Option Descriptions (Chapter 5 of EPA inventory guidance)
Customer self-identification
CCTV investigation at curb stop - internal
CCTV investigation at curb stop - external
Mechanical excavation at one location
Visual inspection at the meter pit
Visual inspection during construction or repair
Cross Connection survey
Other - describe in Notes Column Y

Description
fication. If the method you used is not one of the options, select other and describe the basis for lanation of answer options.

r "No".

ication. If the method you used is not one of the options, select other and describe the basis for
d in Column V.

cation. See column T for an explanation of answer options. This field is only required if "Yes" was

assification or field verification here. This field is only required if "other" was selected in column Q,