



Minnesota.
Department of Conservation.
Photographs of State Parks, Monuments,
Recreational Areas, and Staff.

Copyright Notice:

This material may be protected by copyright law (U.S. Code, Title 17). Researchers are liable for any infringement. For more information, visit www.mnhs.org/copyright.

LAKE BEMIDJI

L. B. - 11

Picnic Ground and appurtenances





LAKE BEMIDJI

L. B. - 12

Bathhouse, Lake Elev.





LAKE BEMIDJI

L. B. - 13

BATHHOUSE AND REFECTORY, FROM ENTRANCE ROAD






LAKE BEMIDJI

PRINTS WITHOUT NEGATIVES

Deterioration Prints





Lake Bemidji

The caretakers house
is improperly located
for proper supervision of
PARK at night.

Front yard is built up
from cellar dirt which
will not support grass
growth. Should have a
load of Topsoil.



63
Lake Bemidji

dangerous path
over bluff to
Rocky point



99
Lake Bemudji

Rotted guardpost





Lake Bemidji

Damaged signs
hit by car.



Lake Bemidji

Rotted guardposts



Rotted guardrail

Take Bernadji



8

Lake Bemidji

Use of picnic area
Barisades rotted out in
foreground



Lake Bemidji

Inadequate sign —

should indicate Park entrance

Located just east of the
country club.



Lake Bemidji 

Stagnant pond
should be drained
or sprayed with
oil. Source of
mosquitoes









Lake Bemidji State Park,

Ridge pole needs replacing





Lake Bemidji State Park

Bathhouse roof in bad condition,
ridge timber needs preservation and
replacement.

