



Minnesota.
Department of Conservation.
Photographs of State Parks, Monuments,
Recreational Areas, and Staff.

Copyright Notice:

This material may be protected by copyright law (U.S. Code, Title 17). Researchers are liable for any infringement. For more information, visit www.mnhs.org/copyright.

LAKE CARLOS

Parking Area Filled to Capacity - 2 views

L. C. - 11







LAKE CARLOS

L. C. - 12

Toilet Bldg. in Picnic Grounds





LAKE CARLOS

L. C. - 15

1, 2, 3

Recreation and Crafts Building, Group Camp

(3 views)









LAKE CARLOS

PRINTS WITHOUT NEGATIVES





Lower refectory parking
lot

Sunday - 9-5-48

Gosseberry



Parking AREA

Sept.
1939

Lake Carlos



LAKE CARLOS STATE PARK

No toilets in
camp grounds
area. adjacent
wooded area
littered with
toilet paper.

W J Fontela
supt.

1948




LAKE CARLOS STATE PARK

No road into Camp
grounds

W J Fontola
supt.


VELOX

Top



Looking down into dressing
booth in bath house showing
rotting wooden wall
partition (badly in need
of paint)

W J Fontrol
Supt.



LAKE CARLOS STATE PARK

encircled shows
wood decay - no
paint - boards rotted
~~down~~
(men's dressing room
- bath house)

W J Fontola
Supt.

LAKE CARLOS

PRINTS WITHOUT NEGATIVES







Lake Carlos

Mess Hall & Kitchen in

Youngs Camp

