



Rice County (Minn.).
Superintendent of Schools:
Reports on Rural School Houses.

Copyright Notice:

This material may be protected by copyright law (U.S. Code, Title 17). Researchers are liable for any infringement. For more information, visit www.mnhs.org/copyright.

Report on Rural School House, by

Lucille M. Tammal teacher

DATE October 30 19339 District No. 67 County of RiceSchool Site: Acres 1 Fence No No. of trees 60 Condition of site FairBuilding: Of what material Lumber When erected ✓ Outside condition GoodInside condition Good No. of school rooms 1School room: Length 28' Width 21' Height 12'Length Width Height What other rooms in building: If building was erected after June 1, 1913, have plans been approved by the State? Heating and Ventilation: Has it been approved by the State?

VENTILATING ROOM HEATER

No. 022
conversion

BASEMENT FURNACE

Name of system Manual Smith Heater - Heater Name and No. of furnace When installed Size of fresh air intake Diameter of fire pot 1 1/2' Diameter outside jacket 3 3/4' Outside size of chimney *Size of intake 12" Size of foul air outlet 12" Does chimney have metal stack inside? Is foul air removed with smoke through chimney? Yes Size of school room heat ducts Is there a separate chimney for each room? Yes How high above floor is heat register? Outside dimensions of each chimney Size of school room foul air outlet If one chimney for all rooms, give outside dimensions Is foul air removed through chimney or separate duct? Does chimney have a metal stack inside? No Is lower edge of foul air register level with floor? Size of evaporating pan Use only gal. pan Size of evaporating pan Is the building heated by means of a steam plant? No If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 100 Kind slate Condition good
 Dictionaries—No. of advanced 2 Copyright 1932 Condition V. good
 No. of elementary 3 Copyright 1935 Condition V. good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 4-2-1 Condition V. good
 Maps—No. 50-roller and stand State Map? Roller Condition 3 fair
 Globes—No. 1 Diameter of 12" Kind suspension Condition fair
 Desks—No. of single 21 No. of double 0 Do they fit the pupils? Yes Which, do not?
 Is seat-work material provided? Yes How kept Filed and in boxes
 Water Supply—Drinking Fountain? Yes Individual Cups? Condition good
 Facilities for Washing Hands—Kind Wash basin - paper towel
 Library—No. of Volumes 266 Condition Fair Greatest need Primary - 028
 Latest encyclopedia Kind Home as school Reference No. of volumes 1710 Copyright date 1925
 Outbuildings—No. 2 Distance apart 10' - 15' - 20' Concealed Entrance Yes - good
 Is there a boys' urinal? Yes Condition good Lighted? No Toilet Paper Yes
 Improvement needed: 1. Encyclopedias 2 Library - 028
 Remarks: 3. Some playground equipment such as swings - slides etc.
4. Evaporating pan
5.

Report on Rural School House, by

Teresa M. Topic teacher

DATE Oct. 28 1939 District No. 68 County of RiceSchool Site: Acres 1 Fence No No. of trees 26 Condition of site GoodBuilding: Of what material Wood When erected _____ Outside condition GoodInside condition Good No. of school rooms 2School room: Length 282 inches Width 222 inches Height 140 inches

Length _____ Width _____ Height _____

What other rooms in building: Library

If building was erected after June 1, 1913, have plans been approved by the State? _____

Heating and Ventilation: Has it been approved by the State? _____

VENTILATING ROOM HEATER

Name of system Turbo zone

When installed _____

Diameter of fire pot 21" Diameter outside jacket 47"*Size of intake 16" x 12" Size of foul air outlet 16" x 14"Is foul air removed with smoke through chimney? yesIs there a separate chimney for each room? yes

Outside dimensions of each chimney _____

If one chimney for all rooms, give outside dimensions _____

Does chimney have a metal stack inside? NoSize of evaporating pan 14" long 2" wide 8" deep

Is the building heated by means of a steam plant? _____ If so, fill out the blanks under Basement Furnace.

BASEMENT FURNACE

Name and No. of furnace _____

Size of fresh air intake _____

Outside size of chimney _____

Does chimney have metal stack inside? _____

Size of school room heat ducts _____

How high above floor is heat register? _____

Size of school room foul air outlet _____

Is foul air removed through chimney or separate duct? _____Is lower edge of foul air register level with floor? yes

Size of evaporating pan _____

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 336 and 276 Kind Slate + Hyplate Condition Good
 Dictionaries—No. of advanced 1 Copyright 1927 Condition _____
 No. of elementary 7 Copyright 1930 Condition _____
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) _____ Condition _____
 Maps—No. 9 State Map? yes Condition Good
 Globes—No. 2 Diameter of 18" + 6" Kind Encl. + Stand Condition Good
 Desks—No. of single 25 No. of double _____ Do they fit the pupils? yes Which do not? _____
 Is seat-work material provided? yes How kept _____
 Water Supply—Drinking Fountain? yes Individual Cups? _____ Condition Good
 Facilities for Washing Hands—Kind Basins _____
 Library—No. of Volumes 162 Condition Good Greatest need _____
 Latest encyclopedia—Kind Compton's No. of volumes 26 Copyright date 1937
 Outbuildings—No. 2 Distance apart Over 50' Concealed Entrance yes
 Is there a boys' urinal? yes Condition fair Lighted? yes Toilet Paper yes
 Improvement needed: _____

Remarks: _____

Report on Rural School House, by Margaret Oppengard teacher

DATE Oct. 30 1939 District No. 69 County of Rice
 School Site: Acres 1/2 Fence no No. of trees 10 Condition of site good
 Building: Of what material wood When erected 1898 Outside condition good
 Inside condition good No. of school rooms 1
 School room: Length 24 Width 16 1/2 Height 9
 Length Width Height
 What other rooms in building: wood shed
 If building was erected after June 1, 1913, have plans been approved by the State?
 Heating and Ventilation: Has it been approved by the State?

VENTILATING ROOM HEATER

Name of system I don't know Stone is
 When installed I do not know
 Diameter of fire pot 2 Diameter outside jacket 3 1/2
 *Size of intake 1 1/2 Size of foul air outlet 1 1/2
 Is foul air removed with smoke through chimney? yes
 Is there a separate chimney for each room? only 1
 Outside dimensions of each chimney 15 x 1 1/2
 If one chimney for all rooms, give outside dimensions
 Does chimney have a metal stack inside? yes
 Size of evaporating pan 12 in x 4 in x 8 in
 Is the building heated by means of a steam plant?

BASEMENT FURNACE

Name and No. of furnace X
 Size of fresh air intake
 Outside size of chimney
 Does chimney have metal stack inside?
 Size of school room heat ducts
 How high above floor is heat register?
 Size of school room foul air outlet
 Is foul air removed through chimney or separate duct?
 Is lower edge of foul air register level with floor?
 Size of evaporating pan

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 100 Kind slate ^{cardboard} Condition good ^{coll.} fair
 Dictionaries—No. of advanced 1 Copyright 1937 Condition good
 No. of elementary 6 Copyright 1935 Condition good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 4 Condition good
 Maps—No. 9 State Map? yes Condition good
 Globes—No. 1 Diameter of 12 in. Kind suspension Condition fair
 Desks—No. of single 13 No. of double 0 Do they fit the pupils? yes Which do not? —

Is seat-work material provided? yes How kept in cupboard
 Water Supply—Drinking Fountain? — Individual Cups? yes Condition good
 Facilities for Washing Hands—Kind basin each have own soap
 Library—No. of Volumes 180 Condition good Greatest need encyclopedia
 Latest encyclopedia—Kind new Practical No. of volumes 6 Copyright date 1912
 Outbuildings—No. 2 Distance apart 50 ft Concealed Entrance yes
 Is there a boys' urinal? yes Condition good Lighted? yes Toilet Paper yes
 Improvement needed: —

Remarks: We need some new encyclopedias.
The ones we have are too old—

Report on Rural School House, by

Celia A. Kapet

teacher

DATE October 30 1939District No. 70

County of Rice

School Site: Acres 1 Fence NoNo. of trees 34 Condition of site goodBuilding: Of what material lumberWhen erected 1889 Outside condition goodInside condition goodNo. of school rooms 1School room: Length 24'Width 18' Height 9'

Length

Width Height

What other rooms in building: None

If building was erected after June 1, 1913, have plans been approved by the State?

Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

BASEMENT FURNACE

Name of system Dorvagian

Name and No. of furnace

When installed 1937

Size of fresh air intake

Diameter of fire pot 21" Diameter outside jacket 45"

Outside size of chimney

*Size of intake 12" X 11" Size of foul air outlet 12" X 12"

Does chimney have metal stack inside?

Is foul air removed with smoke through chimney? No

Size of school room heat ducts

Is there a separate chimney for each room? only 1 room

How high above floor is heat register?

Outside dimensions of each chimney 26" X 26"

Size of school room foul air outlet

If one chimney for all rooms, give outside dimensions

Is foul air removed through chimney or separate duct?

Does chimney have a metal stack inside? No

Is lower edge of foul air register level with floor?

Size of evaporating pan 7" X 18" X 6"

Size of evaporating pan

Is the building heated by means of a steam plant? No If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 72 Kind slate Condition good
Dictionaries—No. of advanced 2 Copyright 1935 Condition good
No. of elementary 7 Copyright 1932, 1935, 1939 Condition good
Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 2 Condition good
Maps—No. 8 State Map? yes Condition good
Globes—No. 1 Diameter of 12" Kind stand Condition good
Desks—No. of single 17 No. of double None Do they fit the pupils? yes Which do not? None
Is seat-work material provided? yes How kept In good order
Water Supply—Drinking Fountain? yes Individual Cups? No Condition good
Facilities for Washing Hands—Kind Wash stand, was basin, pitcher
Library—No. of Volumes 171 Condition good Greatest need music
Latest encyclopedia—Kind new Practical Reference Library No. of volumes 6 Copyright date 1912
Outbuildings—No. 2 Distance apart 66' Concealed Entrance yes
Is there a boys' urinal? yes Condition good Lighted? yes Toilet Paper yes
Improvement needed:
Remarks:

Report on Rural School House, by Thelma Johnson teacher

DATE Oct. 26 1939 District No. 1 County of Rice
School Site: Acres .42 Fence yes No. of trees 3 Condition of site fair
Building: Of what material wood When erected 1988 Outside condition good
Inside condition good No. of school rooms one
School room: Length 24 ft. Width 18 ft. Height 10 ft.
Length _____ Width _____ Height _____
What other rooms in building: entry
If building was erected after June 1, 1913, have plans been approved by the State? _____
Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system Smith System
When installed 1920
Diameter of fire pot 22" Diameter outside jacket 14"
*Size of intake 16 by 16 Size of foul air outlet 12 x 15
Is foul air removed with smoke through chimney? _____
Is there a separate chimney for each room? _____
Outside dimensions of each chimney 21 in by 25 in
If one chimney for all rooms, give outside dimensions same
Does chimney have a metal stack inside? _____
Size of evaporating pan 18 in x 9 in
Is the building heated by means of a steam plant? _____ If so, fill out the blanks under Basement Furnace.

BASEMENT FURNACE

Name and No. of furnace _____
Size of fresh air intake _____
Outside size of chimney _____
Does chimney have metal stack inside? _____
Size of school room heat ducts _____
How high above floor is heat register? _____
Size of school room foul air outlet _____
Is foul air removed through chimney or separate duct? _____
Is lower edge of foul air register level with floor? _____
Size of evaporating pan _____

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 92 Kind state painted Condition good
 Dictionaries—No. of advanced 2 Copyright 1932 Condition good
 No. of elementary 6 Copyright 1935 Condition very good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 2 Condition good
 Maps—No. 8 State Map? yes Condition excellent
 Globes—No. 1 Diameter of 12 inch Kind superior Condition good
 Desks—No. of single 22 No. of double 2 Do they fit the pupils? yes Which do not?

 Is seat-work material provided? yes How kept in cupboard
 Water Supply—Drinking Fountain? yes Individual Cups? Condition
 Facilities for Washing Hands—Kind wash dish
 Library—No. of Volumes 200 Condition good Greatest need new books
 Latest encyclopedia—Kind Home School Library No. of volumes 10 Copyright date 1923
 Outbuildings—No. 2 Distance apart 50 Concealed Entrance yes
 Is there a boys' urinal? yes Condition good Lighted? no Toilet Paper yes
 Improvement needed:

Remarks:

Report on Rural School House, by Ella May Sanford teacher

DATE Oct. 30. 1939 District No. 72 County of Rice
 School Site: Acres 1/4 Fence yes No. of trees 13 Condition of site Good
 Building: Of what material stucco When erected unknown Outside condition Good
 Inside condition Good No. of school rooms 1
 School room: Length 27 ft Width 15 ft. Height 9 ft 10"
 Length 27 ft Width 15 ft. Height 9 ft 10"
 What other rooms in building: Hall
 If building was erected after June 1, 1913, have plans been approved by the State? ?
 Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system Waterbury Special
 When installed 1919
 Diameter of fire pot 10 1/2" Diameter outside jacket 23"
 *Size of intake 12x14 Size of foul air outlet 12x14
 Is foul air removed with smoke through chimney? yes
 Is there a separate chimney for each room? yes
 Outside dimensions of each chimney 16" x 24"
 If one chimney for all rooms, give outside dimensions
 Does chimney have a metal stack inside? no
 Size of evaporating pan 132 + Cu. in (6 1/2" x 1")
 Is the building heated by means of a steam plant? no

BASEMENT FURNACE

Name and No. of furnace
 Size of fresh air intake
 Outside size of chimney
 Does chimney have metal stack inside?
 Size of school room heat ducts
 How high above floor is heat register?
 Size of school room foul air outlet
 Is foul air removed through chimney or separate duct?
 Is lower edge of foul air register level with floor?
 Size of evaporating pan
 If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 114 Kind slate & painted Condition Good
 Dictionaries—No. of advanced 2 Copyright 1931 Condition Good
 No. of elementary 5 Copyright 1935 Condition Good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 9 Condition Good
 Maps—No. 9 State Map? yes Condition Good
 Globes—No. 1 Diameter of 12 in. Kind suspension Condition Good
 Desks—No. of single 19 No. of double 0 Do they fit the pupils? yes Which do not?
 Is seat-work material provided? yes How kept well
 Water Supply—Drinking Fountain? yes Individual Cups? Condition Good
 Facilities for Washing Hands—Kind water set for pour method
 Library—No. of Volumes 195 Condition Fair Greatest need for little children
 Latest encyclopedia—Kind World Book No. of volumes 18 Copyright date 1939
 Outbuildings—No. 2 Distance apart 50 ft. Concealed Entrance yes
 Is there a boys' urinal? yes Condition Good Lighted Windows Toilet Paper yes
 Improvement needed:
 Remarks:

Report on Rural School House, by Marie Rossey teacher

DATE October 25th 1939 District No. 73 County of Rice
 School Site: Acres 3 1/2 Fence no No. of trees 14 Condition of site _____
 Building: Of what material frame When erected 1914 Outside condition _____
 Inside condition Good No. of school rooms _____
 School room: Length 24 ft Width 24 ft Height 12 ft
 Length _____ Width _____ Height _____
 What other rooms in building: none
 If building was erected after June 1, 1913, have plans been approved by the State? yes
 Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system Smith
 When installed 1938
 Diameter of fire pot 24" Diameter outside jacket 40"
 *Size of intake 9 1/2" x 18" Size of foul air outlet 12" x 18"
 Is foul air removed with smoke through chimney? yes
 Is there a separate chimney for each room? _____
 Outside dimensions of each chimney _____
 If one chimney for all rooms, give outside dimensions 27" x 27"
 Does chimney have a metal stack inside? _____
 Size of evaporating pan 18" x 6"
 Is the building heated by means of a steam plant? _____

BASEMENT FURNACE

Name and No. of furnace _____
 Size of fresh air intake _____
 Outside size of chimney _____
 Does chimney have metal stack inside? _____
 Size of school room heat ducts _____
 How high above floor is heat register? _____
 Size of school room foul air outlet _____
 Is foul air removed through chimney or separate duct? _____
 Is lower edge of foul air register level with floor? _____
 Size of evaporating pan _____

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 120 Kind Slate Condition good
 Dictionaries—No. of advanced 1 Copyright 1936 Condition good
 No. of elementary 6 Copyright 1928-35 Condition good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 3 Condition good
 Maps—No. 8 State Map? yes Condition good
 Globes—No. 1 Diameter of 12 inch Kind Suspension Condition good
 Desks—No. of single 18 No. of double 2 Do they fit the pupils? yes Which do not? _____

 Is seat-work material provided? yes How kept In library
 Water Supply—Drinking Fountain? yes Individual Cups? _____ Condition good
 Facilities for Washing Hands—Kind Wash stand, basin, soap, and towels
 Library—No. of Volumes 93 Condition good Greatest need Fiction books
 Latest encyclopedia—Kind World Book No. of volumes 20 Copyright date 1938
 Outbuildings—No. Two Distance apart 50 ft Concealed Entrance yes
 Is there a boys' urinal? yes Condition good Lighted? _____ Toilet Paper yes
 Improvement needed: _____
 Remarks: _____

Report on Rural School House, by

Rose M. Vohs teacher

DATE October 30, 1939 District No. 74 County of Rice
 School Site: Acres one-half Fence yes No. of trees 27 Condition of site Good
 Building: Of what material Wood When erected _____ Outside condition Good
 Inside condition Good No. of school rooms one
 School room: Length 25 feet Width 21 feet Height 12 ft.
 Length _____ Width _____ Height _____

What other rooms in building: one hall
 If building was erected after June 1, 1913, have plans been approved by the State? Erected before 1913
 Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system L. J. Mueller Furnace Co. Name and No. of furnace _____
 When installed about 25 yrs. ago Size of fresh air intake _____
 Diameter of fire pot 19 in Diameter outside jacket 36 in Outside size of chimney _____
 *Size of intake 14" x 10" Size of foul air outlet 14" x 16" Does chimney have metal stack inside? _____
 Is foul air removed with smoke through chimney? yes Size of school room heat ducts _____
 Is there a separate chimney for each room? yes How high above floor is heat register? _____
 Outside dimensions of each chimney 16" x 16" Size of school room foul air outlet _____
 If one chimney for all rooms, give outside dimensions ✓ Is foul air removed through chimney or separate duct? _____
 Does chimney have a metal stack inside? yes Is lower edge of foul air register level with floor? _____
 Size of evaporating pan 15" x 4" Size of evaporating pan _____
 Is the building heated by means of a steam plant? No If so, fill out the blanks under Basement Furnace.

BASEMENT FURNACE

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 135 sq. ft. Kind slate Condition good
Dictionaries—No. of advanced 1 Copyright 1909 Condition Fair
No. of elementary 10 Copyright 6-1935 Condition Good & Fair
Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 35 Condition Good
Maps—No. 9 State Map? yes Condition Good
Globes—No. 1 Diameter of 12 inches Kind Suspension Condition Poor
Desks—No. of single 32 No. of double 0 Do they fit the pupils? yes Which do not? ✓

Is seat-work material provided? yes How kept closed cupboards
 Water Supply—Drinking Fountain? yes Individual Cups? no Condition Fair
 Facilities for Washing Hands—Kind Basin, soap and paper towels
 Library—No. of Volumes 287 Condition Fair Greatest need Informational
 Latest encyclopedia—Kind World Book No. of volumes 20 Copyright date 1936
 Outbuildings—No. two Distance apart 53 ft. Concealed Entrance yes
 Is there a boys' urinal? yes Condition Fair Lighted? yes Toilet Paper yes

Improvement needed: He should have made window
Remarks: space; shades should be in the middle
of window. Work table and chairs should
be supplied.

Report on Rural School House, by Irene L. Abo teacher

DATE Nov. 9, 1939 District No. 75 County of Rice
 School Site: Acres 1/2 Fence no. No. of trees 6 Condition of site fair
 Building: Of what material stucco When erected 1980 Outside condition good
 Inside condition good No. of school rooms 1
 School room: Length 23 1/2 ft. Width 17 ft. Height 9 1/2 ft.
 Length Width Height

What other rooms in building: cloak hall
 If building was erected after June 1, 1913, have plans been approved by the State?
 Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system Waterbury
 When installed 1930
 Diameter of fire pot 17 in. Diameter outside jacket 24 1/2 in.
 *Size of intake 13 x 23 Size of foul air outlet 15 x 22
 Is foul air removed with smoke through chimney? yes
 Is there a separate chimney for each room?
 Outside dimensions of each chimney 21 x 27
 If one chimney for all rooms, give outside dimensions 24 x 27
 Does chimney have a metal stack inside? no
 Size of evaporating pan 14 in. by 9 in.
 Is the building heated by means of a steam plant? no

BASEMENT FURNACE

Name and No. of furnace
 Size of fresh air intake
 Outside size of chimney
 Does chimney have metal stack inside?
 Size of school room heat ducts
 How high above floor is heat register?
 Size of school room foul air outlet
 Is foul air removed through chimney or separate duct?
 Is lower edge of foul air register level with floor?
 Size of evaporating pan
 If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 92 sq. ft. Kind slate Condition good
 Dictionaries—No. of advanced 4 Copyright 1925 Condition good
 No. of elementary 2 Copyright 1924 Condition good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 3 Condition fair
 Maps—No. 7 State Map? yes Condition good
 Globes—No. 1 Diameter of 12" Kind suspension Condition good
 Desks—No. of single 15 No. of double 1 Do they fit the pupils? yes Which do not?

Is seat-work material provided? yes How kept well
 Water Supply—Drinking Fountain? X Individual Cups? Condition good
 Facilities for Washing Hands—Kind Basin - Paper towels
 Library—No. of Volumes Condition fair Greatest need Reference Books
 Latest encyclopedia—Kind World Book No. of volumes 19 Copyright date 1937
 Outbuildings—No. 2 Distance apart 40 ft. Concealed Entrance yes
 Is there a boys' urinal? yes Condition fair Lighted? yes Toilet Paper yes
 Improvement needed:

Remarks: Both outbuildings should be painted inside.

Report on Rural School House, by Bert Traylor teacher

DATE Oct. 25 1937 District No. 76 County of Rice
 School Site: Acres 1 Fence no No. of trees 268 Condition of site Fair
 Building: Of what material lumber When erected — Outside condition Good
 Inside condition Good No. of school rooms 2
 School room: Length 30 ft Width 28 ft Height 12 ft
 Length 30 ft Width 28 ft Height 12 ft
 What other rooms in building: 2 libraries - 2 halls
 If building was erected after June 1, 1913, have plans been approved by the State? —
 Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system _____
 When installed _____
 Diameter of fire pot _____ Diameter outside jacket _____
 *Size of intake _____ Size of foul air outlet _____
 Is foul air removed with smoke through chimney? _____
 Is there a separate chimney for each room? _____
 Outside dimensions of each chimney _____
 If one chimney for all rooms, give outside dimensions _____
 Does chimney have a metal stack inside? _____
 Size of evaporating pan _____
 Is the building heated by means of a steam plant? _____

BASEMENT FURNACE

Name and No. of furnace Hercules -
 Size of fresh air intake 24 X 30
 Outside size of chimney 20 X 28
 Does chimney have metal stack inside? no
 Size of school room heat ducts 24 X 30
 How high above floor is heat register? 8 ft.
 Size of school room foul air outlet 24 X 30
 Is foul air removed through chimney or separate duct? yes
 Is lower edge of foul air register level with floor? 2 in. from floor
 Size of evaporating pan 22 X 4 X 3 1/2

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 320 sq ft. Kind State & Cardboard Condition good
 Dictionaries—No. of advanced 9 Copyright 1931 Condition good
 No. of elementary _____ Copyright _____ Condition _____
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 3 Condition fair
 Maps—No. 8 State Map? yes Condition new
 Globes—No. 1 Diameter of 18 in. Kind Suspension Condition Fair
 Desks—No. of single 29 No. of double — Do they fit the pupils? yes Which do not? —
 Is seat-work material provided? yes How kept In cupboard.
 Water Supply—Drinking Fountain? yes Individual Cups? — Condition good
 Facilities for Washing Hands—Kind Basin and stand
 Library—No. of Volumes 379 Condition Fair Greatest need —
 Latest encyclopedia—Kind The World Book No. of volumes 14 Copyright date 1931
 Outbuildings—No. 2 Distance apart 50 ft. Concealed Entrance yes
 Is there a boys' urinal? yes Condition good Lighted? yes Toilet Paper yes
 Improvement needed: Window must be repaired.
 Remarks: _____

