



Rice County (Minn.).
Superintendent of Schools:
Reports on Rural School Houses.

Copyright Notice:

This material may be protected by copyright law (U.S. Code, Title 17). Researchers are liable for any infringement. For more information, visit www.mnhs.org/copyright.

Report on Rural School House, by Mary Kalkes teacher

DATE Oct. 30 1939 District No. 29 County of Rice
 School Site: Acres 1 Fence yes No. of trees 8 Condition of site Good
 Building: Of what material Cement and Brick When erected 1929 Outside condition Good
 Inside condition Good No. of school rooms 1
 School room: Length 32 1/2 Width 22 1/2 Height 12 ft.
 Length Width Height
 What other rooms in building: Library, classrooms, toilets, basement.
 If building was erected after June 1, 1913, have plans been approved by the State? yes.
 Heating and Ventilation: Has it been approved by the State? yes.

VENTILATING ROOM HEATER

Name of system
 When installed
 Diameter of fire pot Diameter outside jacket
 *Size of intake Size of foul air outlet
 Is foul air removed with smoke through chimney?
 Is there a separate chimney for each room?
 Outside dimensions of each chimney
 If one chimney for all rooms, give outside dimensions
 Does chimney have a metal stack inside?
 Size of evaporating pan
 Is the building heated by means of a steam plant?

BASEMENT FURNACE

Name and No. of furnace Marshalltown A 235
 Size of fresh air intake 18 x 24
 Outside size of chimney 27 x 42
 Does chimney have metal stack inside? yes.
 Size of school room heat ducts 24" x 34"
 How high above floor is heat register? 6 ft 10 in above floor
 Size of school room foul air outlet 2 each 18" by 24"
 Is foul air removed through chimney or ~~outside duct~~ yes.
 Is lower edge of foul air register level with floor? yes.
 Size of evaporating pan 3 gallons

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 100 Kind Slate Condition Good
 Dictionaries—No. of advanced 2 Copyright 1925 Condition Good
 No. of elementary 4 Copyright 1935 Condition Good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 4 Condition Good
 Maps—No. 9 State Map? Yes Condition Good
 Globes—No. 1 Diameter of 18" Kind Suspension Condition Good
 Desks—No. of single 36 No. of double none Do they fit the pupils? yes Which do not? none

Is seat-work material provided? Yes How kept In cupboard
 Water Supply—Drinking Fountain? Yes Individual Cups? No Condition No
 Facilities for Washing Hands—Kind Wash stand and basin, paper towels
 Library—No. of Volumes 90 Condition Fair Greatest need Int. Fiction
 Latest encyclopedia—Kind World Book No. of volumes — Copyright date 1931
 Outbuildings—No. None Distance apart — Concealed Entrance —
 Is there a boys' urinal? No Condition Good Lighted? yes Toilet Paper yes

Improvement needed:

Remarks:

Toilets are chemical.

Report on Rural School House, by

Verina M. Olsen

teacher

DATE Oct. 30, 1939 District No. 80 County of RiceSchool Site: Acres 4 Fence wires No. of trees 8 Condition of site GoodBuilding: Of what material lumber When erected 1877 Outside condition FairInside condition Fair No. of school rooms 1School room: Length 21' 25" Width 15' 26" Height 9' 2 1/4"

Length _____ Width _____ Height _____

What other rooms in building: 1 front hall

If building was erected after June 1, 1913, have plans been approved by the State? _____

Heating and Ventilation: Has it been approved by the State? No

VENTILATING ROOM HEATER

Name of system Estate heatrolaWhen installed 1933Diameter of fire pot 11 1/2" Diameter outside jacket 23 1/2" x 24"

*Size of intake _____ Size of foul air outlet _____

Is foul air removed with smoke through chimney? No

Is there a separate chimney for each room? _____

Outside dimensions of each chimney 24" x 24"

If one chimney for all rooms, give outside dimensions _____

Does chimney have a metal stack inside? NoSize of evaporating pan 11 1/2" long - 5" in diamIs the building heated by means of a steam plant? No

BASEMENT FURNACE

Name and No. of furnace _____

Size of fresh air intake _____

Outside size of chimney _____

Does chimney have metal stack inside? _____

Size of school room heat ducts _____

How high above floor is heat register? _____

Size of school room foul air outlet _____

Is foul air removed through chimney or separate duct? _____

Is lower edge of foul air register level with floor? _____

Size of evaporating pan _____

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 73 Kind slate Condition Fair
 Dictionaries—No. of advanced _____ Copyright _____ Condition _____
 No. of elementary 4 Copyright 1935 Condition Good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 2 Condition Good
 Maps—No. 2 State Map? no Condition Good
 Globes—No. 1 Diameter of 16 in. Kind Pedestal Condition New
 Desks—No. of single 18 No. of double _____ Do they fit the pupils? yes Which do not? _____
 Is seat-work material provided? yes How kept cupboard and shelves
 Water Supply—Drinking Fountain? yes Individual Cups? _____ Condition Good
 Facilities for Washing Hands—Kind sinks - paper towels
 Library—No. of Volumes 195 Condition Fair & Good Greatest need 028 books
 Latest encyclopedia—Kind Compton's No. of volumes 15 Copyright date 1937
 Outbuildings—No. 2 Distance apart 21 5/6 ft. Concealed Entrance Girls' only
 Is there a boys' urinal? no Condition _____ Lighted? yes Toilet Paper yes
 Improvement needed: more wall maps
 Remarks: Besides 3 roller maps we have the
McConnell's Series on pedestal.

Report on Rural School House, by Arnell Olstad teacher

DATE October 25, 1939 District No. 81 County of Rice
School Site: Acres 1/2 acre Fence yes No. of trees 9 Condition of site Good
Building: Of what material wood When erected 1923 Outside condition Very Good
Inside condition Very Good No. of school rooms 1
School room: Length 27 feet Width 20 4/3 feet Height 12 feet
Length _____ Width _____ Height _____
What other rooms in building: wash room, cloak room, library, entry
If building was erected after June 1, 1913, have plans been approved by the State? yes
Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system Waterbury System
When installed 1937
Diameter of fire pot 22 in. Diameter outside jacket 36 in.
*Size of intake 13" by 26" Size of foul air outlet 18" by 22"
Is foul air removed with smoke through chimney? yes
Is there a separate chimney for each room? no
Outside dimensions of each chimney _____
If one chimney for all rooms, give outside dimensions 18" by 30"
Does chimney have a metal stack inside? yes
Size of evaporating pan 8" by 25"
Is the building heated by means of a steam plant? no

BASEMENT FURNACE

Name and No. of furnace _____
Size of fresh air intake _____
Outside size of chimney _____
Does chimney have metal stack inside? _____
Size of school room heat ducts _____
How high above floor is heat register? _____
Size of school room foul air outlet _____
Is foul air removed through chimney or separate duct? _____
Is lower edge of foul air register level with floor? _____
Size of evaporating pan _____

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 10.5 Kind Slate Condition Good
 Dictionaries—No. of advanced 1 Copyright 1939 Condition Very Good
 No. of elementary 6 Copyright 1935 Condition Very Good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 3 Condition Good
 Maps—No. 41 State Map? Yes Condition Fair
 Globes—No. 1 Diameter of 12 inches Kind Suspension Condition Good
 Desks—No. of single 16 No. of double 0 Do they fit the pupils? Yes Which do not? -
 Is seat-work material provided? Yes How kept Very Good
 Water Supply—Drinking Fountain? Yes Individual Cups? No Condition Very Good
 Facilities for Washing Hands—Kind Wash basin, paper towels, liquid soap
 Library—No. of Volumes 109 Condition Fair Greatest need Primary books
 Latest encyclopedia—Kind World Book No. of volumes 18 Copyright date 1939
 Outbuildings—No. 2 Distance apart 52 feet Concealed Entrance Yes
 Is there a boys' urinal? Yes Condition Very Good Lighted? Yes Toilet Paper Yes
 Improvement needed: One more reader for Grade I
 Remarks: The toilets are painted inside. The ceiling of the school room was insulated, this last summer. The walls and ceiling were painted a light cream. Our books and workbooks are all sufficient except in Grade I.

Report on Rural School House, by

Leona Kunne

teacher

DATE October 30 1939 District No. 83-100 County of Rice
 School Site: Acres _____ Fence No No. of trees 10 Condition of site Good
 Building: Of what material Wood When erected _____ Outside condition Good
 Inside condition Good No. of school rooms 1
 School room: Length 25' Width 17' Height 12'
 Length _____ Width _____ Height _____
 What other rooms in building: Entry
 If building was erected after June 1, 1913, have plans been approved by the State? Remodeled
 Heating and Ventilation: Has it been approved by the State? Yes

VENTILATING ROOM HEATER

Name of system _____
 When installed 1939
 Diameter of fire pot 18" Diameter outside jacket 3'x3'
 *Size of intake 23"x9" Size of foul air outlet 13"x15"
 Is foul air removed with smoke through chimney? No
 Is there a separate chimney for each room? Yes
 Outside dimensions of each chimney 20" x 22"
 If one chimney for all rooms, give outside dimensions _____
 Does chimney have a metal stack inside? Yes
 Size of evaporating pan 36" x 6"
 Is the building heated by means of a steam plant? No

BASEMENT FURNACE

Name and No. of furnace _____
 Size of fresh air intake _____
 Outside size of chimney _____
 Does chimney have metal stack inside? _____
 Size of school room heat ducts _____
 How high above floor is heat register? _____
 Size of school room foul air outlet _____
 Is foul air removed through chimney or separate duct? _____
 Is lower edge of foul air register level with floor? _____
 Size of evaporating pan _____

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 100 Kind Slate Condition Good
 Dictionaries—No. of advanced 2 Copyright 1936 Condition New
 No. of elementary 6 Copyright 1936, Condition Good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 2 Condition Fair
 Maps—No. 8 State Map? Yes Condition Good
 Globes—No. 1 Diameter of 12" Kind Suspension Condition Good
 Desks—No. of single 16 No. of double 0 Do they fit the pupils? Yes Which do not?

Is seat-work material provided? Yes How kept on shelves
 Water Supply—Drinking Fountain? Yes Individual Cups? No Condition Good
 Facilities for Washing Hands—Kind Dipper, pan, pail, soap, paper towels
 Library—No. of Volumes 60 Condition Fair to Good Greatest need Reference
 Latest encyclopedia—Kind Comptons No. of volumes 15 Copyright date 1937
 Outbuildings—No. 2 Distance apart 50 Concealed Entrance Yes
 Is there a boys' urinal? Yes Condition New Lighted? Yes Toilet Paper Yes

Improvement needed:

Remarks:

Report on Rural School House, by Rita M. Schenck teacher

DATE October 30 1939 District No. 84 County of Rice
 School Site: Acres 1 Fence yes No. of trees 6 Condition of site fair
 Building: Of what material wood When erected before 1900 Outside condition fair
 Inside condition good No. of school rooms 1
 School room: Length 24 ft. Width 16 1/2 ft. Height 12 1/2 ft.
 Length 24 ft. Width 16 1/2 ft. Height 12 1/2 ft.
 What other rooms in building: (entry, woodshed)
 If building was erected after June 1, 1913, have plans been approved by the State? ?
 Heating and Ventilation: Has it been approved by the State? ?

VENTILATING ROOM HEATER

Name of system Riverside Heater
 When installed before 1915
 Diameter of fire pot 20" Diameter outside jacket 45"
 *Size of intake 31" Size of foul air outlet 31"
 Is foul air removed with smoke through chimney? yes
 Is there a separate chimney for each room? yes
 Outside dimensions of each chimney 26" x 22"
 If one chimney for all rooms, give outside dimensions
 Does chimney have a metal stack inside? yes
 Size of evaporating pan
 Is the building heated by means of a steam plant?

BASEMENT FURNACE

Name and No. of furnace
 Size of fresh air intake
 Outside size of chimney
 Does chimney have metal stack inside?
 Size of school room heat ducts
 How high above floor is heat register?
 Size of school room foul air outlet
 Is foul air removed through chimney or separate duct?
 Is lower edge of foul air register level with floor?
 Size of evaporating pan

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 100 Kind slate Condition Good
Dictionaries—No. of advanced 2 Copyright 1936 Condition Good
No. of elementary 6 Copyright 1936 Condition Good
Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 3 Condition Good
Maps—No. 8 State Map? yes Condition good
Globes—No. 1 Diameter of 12 in. Kind Stand Condition Good
Desks—No. of single 29 No. of double _____ Do they fit the pupils? yes Which do not? _____
Is seat-work material provided? yes How kept In cupboard
Water Supply—Drinking Fountain? yes Individual Cups? _____ Condition Good
Facilities for Washing Hands—Kind stand, basin, pouring method
Library—No. of Volumes 70 Condition Good Greatest need fiction, encyclopaedia
Latest encyclopedia—Kind _____ No. of volumes _____ Copyright date _____
Outbuildings—No. 3 Distance apart 50 ft. Concealed Entrance yes
Is there a boys' urinal? yes Condition Good Lighted? yes Toilet Paper yes
Improvement needed: _____
Remarks: _____

Report on Rural School House, by Joane V. Bestul teacher

DATE Oct. 30 1939 District No. 87 County of Rice
 School Site: Acres 1/2 Fence _____ No. of trees 25 Condition of site Good
 Building: Of what material Wooden When erected 51 yrs. ago Outside condition Good
 Inside condition Good No. of school rooms 1
 School room: Length 26 ft. Width 19 ft. Height 9 ft. 2 in.
 Length _____ Width _____ Height _____
 What other rooms in building: Large hall, basement
 If building was erected after June 1, 1913, have plans been approved by the State? _____
 Heating and Ventilation: Has it been approved by the State? Yes

VENTILATING ROOM HEATER

Name of system Seamless Heater
 When installed 15 yrs. ago
 Diameter of fire pot 20" Diameter outside jacket 35"
 *Size of intake 22 x 28" Size of foul air outlet 26 x 10"
 Is foul air removed with smoke through chimney? Yes
 Is there a separate chimney for each room? _____
 Outside dimensions of each chimney _____
 If one chimney for all rooms, give outside dimensions 48 x 22"
 Does chimney have a metal stack inside? _____
 Size of evaporating pan _____

BASEMENT FURNACE

Name and No. of furnace _____
 Size of fresh air intake _____
 Outside size of chimney _____
 Does chimney have metal stack inside? _____
 Size of school room heat ducts _____
 How high above floor is heat register? _____
 Size of school room foul air outlet _____
 Is foul air removed through chimney or separate duct? _____
 Is lower edge of foul air register level with floor? _____
 Size of evaporating pan _____

Is the building heated by means of a steam plant? _____ If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 125 Kind Slate Condition Good
 Dictionaries—No. of advanced 2 Copyright 36 Condition V. G.
 No. of elementary 6 Copyright 35 Condition V. G.
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 3 Condition Good
 Maps—No. 9 State Map? yes - on roller Condition Good
 Globes—No. 1 Diameter of 12" Kind _____ Condition Good
 Desks—No. of single 16 No. of double - Do they fit the pupils? yes Which do not? -
 Is seat-work material provided? yes How kept in large cupboard
 Water Supply—Drinking Fountain? yes Individual Cups? - Condition Good
 Facilities for Washing Hands—Kind Wash stand - soap - paper towels
 Library—No. of Volumes 221 Condition Good Greatest need Lower grades
 Latest encyclopedia—Kind New World Book No. of volumes 20 Copyright date 1938
 Outbuildings—No. 2 Distance apart 65 ft Concealed Entrance yes
 Is there a boys' urinal? yes Condition Good Lighted? yes Toilet Paper yes
 Improvement needed: Exterior of building could be painted
 Remarks: A new piano was purchased this year. The swings were fixed. Toilets were painted inside.

Report on Rural School House, by Lorraine R. Andersen teacher

DATE October 25 1939 District No. 89 County of Rice
 School Site: Acres 3/5 Fence yes No. of trees 11 little ones Condition of site Fair
 Building: Of what material wood When erected 1906 Outside condition Average
 Inside condition fair to good No. of school rooms 1
 School room: Length 26 Width 19' Height 9' 9"
 Length 30' (Hall) Width 20' Height
 What other rooms in building: 14 all - woodshed
 If building was erected after June 1, 1913, have plans been approved by the State?
 Heating and Ventilation: Has it been approved by the State?

VENTILATING ROOM HEATER

Name of system Waterman Waterbury
 When installed 1937
 Diameter of fire pot 21" Diameter outside jacket 3' X 3'
 *Size of intake 17" X 16" Size of foul air outlet 14" X 16"
 Is foul air removed with smoke through chimney? yes
 Is there a separate chimney for each room? yes
 Outside dimensions of each chimney
 If one chimney for all rooms, give outside dimensions 26" X 24"
 Does chimney have a metal stack inside?
 Size of evaporating pan 8" X 25"
 Is the building heated by means of a steam plant?

BASEMENT FURNACE

Name and No. of furnace
 Size of fresh air intake
 Outside size of chimney
 Does chimney have metal stack inside?
 Size of school room heat ducts
 How high above floor is heat register?
 Size of school room foul air outlet
 Is foul air removed through chimney or separate duct?
 Is lower edge of foul air register level with floor?
 Size of evaporating pan

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 142' Kind slate Condition good
 Dictionaries—No. of advanced 2 Copyright 1936 Condition good
 No. of elementary 6 Copyright 1938 Condition good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 2+ Condition good
 Maps—No. 8 State Map? yes Condition Fair to good
 Globes—No. 1 Diameter of 12" Kind suspension Condition good
 Desks—No. of single 14 No. of double 0 Do they fit the pupils? yes Which do not? _____

 Is seat-work material provided? yes How kept in a cupboard
 Water Supply—Drinking Fountain? yes Individual Cups? no Condition good
 Facilities for Washing Hands—Kind yes - fair - pouring
 Library—No. of Volumes 220 Condition Fair to good Greatest need primary
 Latest encyclopedia—Kind World Book No. of volumes 11 Copyright date 19027
 Outbuildings—No. 2 Distance apart 60' Concealed Entrance yes
 Is there a boys' urinal? yes Condition fair Lighted? yes Toilet Paper yes
 Improvement needed: _____
 Remarks: _____

Report on Rural School House, by Ethel Moring teacher

DATE Oct. 30, 1937 District No. 92 County of Rice
 School Site: Acres About 4.2 Fence No No. of trees 9 Condition of site Good
 Building: Of what material Wood When erected _____ Outside condition Fair
 Inside condition Good No. of school rooms One
 School room: Length 24' Width 16' Height 8 3/4'
 Length _____ Width _____ Height _____
 What other rooms in building: Hall
 If building was erected after June 1, 1913, have plans been approved by the State? _____
 Heating and Ventilation: Has it been approved by the State? Yes

VENTILATING ROOM HEATER

Name of system Waterman Waterbury
 When installed About 7 yrs. ago
 Diameter of fire pot 15" Diameter outside jacket 30" x 30"
 *Size of intake 9" x 23" Size of foul air outlet 16" x 24"
 Is foul air removed with smoke through chimney? Yes
 Is there a separate chimney for each room? One room
 Outside dimensions of each chimney 23" x 23"
 If one chimney for all rooms, give outside dimensions 23" x 23"
 Does chimney have a metal stack inside? Not known
 Size of evaporating pan A teakettle is used
 Is the building heated by means of a steam plant? No

BASEMENT FURNACE

Name and No. of furnace _____
 Size of fresh air intake _____
 Outside size of chimney _____
 Does chimney have metal stack inside? _____
 Size of school room heat ducts _____
 How high above floor is heat register? _____
 Size of school room foul air outlet _____
 Is foul air removed through chimney or separate duct? _____
 Is lower edge of foul air register level with floor? _____
 Size of evaporating pan _____
 If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 83 Kind slate Condition Good
 Dictionaries—No. of advanced 2 Copyright 1936 Condition Good
 No. of elementary 4 Copyright 1929, 1931 Condition Fair
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 2-4 Condition Good
 Maps—No. 8 State Map? yes Condition Good
 Globes—No. One Diameter of 12" Kind suspension Condition Fair
 Desks—No. of single 9 No. of double none Do they fit the pupils? yes Which do not? —
 Is seat-work material provided? yes How kept In cupboards
 Water Supply—Drinking Fountain? yes Individual Cups? — Condition Good
 Facilities for Washing Hands—Kind Wash basin and stand
 Library—No. of Volumes 202 Condition Fair Greatest need Lower grades
 Latest encyclopedia—Kind World Book No. of volumes 13 Copyright date 1930
 Outbuildings—No. Two Distance apart over 50 ft. Concealed Entrance yes
 Is there a boys' urinal? yes Condition new Lighted? one window Toilet Paper yes
 Improvement needed: A few desks need repair.
 Remarks:

Report on Rural School House, by Agnes Rehak teacher

DATE October 30, 1939 District No. 93 County of Rice
 School Site: Acres 1/2 Fence No. No. of trees 24 Condition of site Very good
 Building: Of what material Wooden (frame) When erected 1865 Outside condition Excellent
 Inside condition Excellent No. of school rooms 1
 School room: Length 24 ft. Width 17 ft. Height 9 1/2 ft.
 Length _____ Width _____ Height _____
 What other rooms in building: Hall or entry
 If building was erected after June 1, 1913, have plans been approved by the State? _____
 Heating and Ventilation: Has it been approved by the State? Yes

VENTILATING ROOM HEATER

Name of system _____
 When installed _____
 Diameter of fire pot _____ Diameter outside jacket _____
 *Size of intake _____ Size of foul air outlet _____
 Is foul air removed with smoke through chimney? _____
 Is there a separate chimney for each room? _____
 Outside dimensions of each chimney _____
 If one chimney for all rooms, give outside dimensions _____
 Does chimney have a metal stack inside? _____
 Size of evaporating pan _____
 Is the building heated by means of a steam plant? _____

BASEMENT FURNACE

Name and No. of furnace Holland No. 1900
 Size of fresh air intake 9" X 34"
 Outside size of chimney 25 1/2" X 21 1/2"
 Does chimney have metal stack inside? No
 Size of school room heat ducts 14 1/2" X 10 1/2"
 How high above floor is heat register? 6 ft. above
 Size of school room foul air outlet 11" by 13"
 Is foul air removed through chimney or separate duct? _____
 Is lower edge of foul air register level with floor? Yes
 Size of evaporating pan 14 gal. tank with 2nd
 Is the building heated by means of a steam plant? _____ If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

land drop humidifier

Remarks:

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 100 Kind Slate Condition Excellent
 Dictionaries—No. of advanced 2 Copyright 1936 Condition Excellent
 No. of elementary 13 Copyright 1935, 29 Condition Excellent
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 6 Condition Very good
 Maps—No. 8 State Map? Yes Condition New
 Globes—No. 1 Diameter of 12 inch Kind Suspension Condition Very good
 Desks—No. of single 19 No. of double _____ Do they fit the pupils? Yes Which do not? _____
 Is seat-work material provided? Yes How kept In cupboard and in boxes
 Water Supply—Drinking Fountain? Covered container with faucet Individual Cups? Yes Condition Excellent
 Facilities for Washing Hands—Kind Basin, soap
 Library—No. of Volumes 218 Condition Very good + Greatest need For Primary grades
 Latest encyclopedia—Kind The World Book No. of volumes 10 Copyright date 1927
 Outbuildings—No. Two Distance apart 50 ft. Concealed Entrance Yes
 Is there a boys' urinal? Yes Condition Very good Lighted? _____ Toilet Paper Yes
 Improvement needed: _____

Remarks: There are 3 heat registers and 3 foot grills at level of floor. Two cold or fresh air vents benched over them. Heat registers are at the other end of room about 6 ft. from floor. The foot warmers are just at bases. Area of all heat ducts, 308 sq. in. Heating and ventilating system was changed to conform with state requirements.

Report on Rural School House, by Grace C. Ludwig teacher

DATE Oct. 30 19339 District No. 97 County of Rice

School Site: Acres 1 1/2 Fence yes No. of trees sits in woods Condition of site good

Building: Of what material wood When erected — Outside condition good

Inside condition good No. of school rooms 1

School room: Length 25' Width 19' Height 12'

Length — Width — Height —

What other rooms in building: woodshed

If building was erected after June 1, 1913, have plans been approved by the State? yes

Heating and Ventilation: Has it been approved by the State? yes

VENTILATING ROOM HEATER

Name of system Convection Heater

When installed —

Diameter of fire pot 16" Diameter outside jacket 3 1/2'

*Size of intake 12" Size of foul air outlet 12"

Is foul air removed with smoke through chimney? yes

Is there a separate chimney for each room? —

Outside dimensions of each chimney 21 1/2" x 30 1/2"

If one chimney for all rooms, give outside dimensions —

Does chimney have a metal stack inside? yes

Size of evaporating pan 6" x 10"

Is the building heated by means of a steam plant? —

BASEMENT FURNACE

Name and No. of furnace —

Size of fresh air intake —

Outside size of chimney —

Does chimney have metal stack inside? —

Size of school room heat ducts —

How high above floor is heat register? —

Size of school room foul air outlet —

Is foul air removed through chimney or separate duct? —

Is lower edge of foul air register level with floor? —

Size of evaporating pan —

If so, fill out the blanks under Basement Furnace.

*If circular, give circumference; if rectangular, give length and width.

EQUIPMENT OF SCHOOL

Blackboard—No. of square feet per room 71 Kind slate Condition good
 Dictionaries—No. of advanced 5 Copyright 1925+1992 Condition fair
 No. of elementary 8 Copyright 1935 Condition good
 Supplementary Readers—No. of sets for each pupil (not counting books over 10 years old) 2 Condition good
 Maps—No. 23 State Map? yes Condition fair
 Globes—No. 1 Diameter of 12" Kind suspension Condition fair
 Desks—No. of single 19 No. of double - Do they fit the pupils? yes Which do not? -
 Is seat-work material provided? yes How kept mostly w/bks.
 Water Supply—Drinking Fountain? yes Individual Cups? - Condition good
 Facilities for Washing Hands—Kind wash dish - soap - paper towels
 Library—No. of Volumes 219 Condition fair Greatest need Elem grades
 Latest encyclopedia—Kind Old Bk & Comp No. of volumes 19 + 15 Copyright date 1935 + 1937
 Outbuildings—No. 2 Distance apart over 50 ft Concealed Entrance yes
 Is there a boys' urinal? yes Condition yes - good Lighted? yes Toilet Paper yes
 Improvement needed: Doors need weather-strips, stove
 Remarks: picket needs leveling - shadow need repair