

October 8, 2020

Kristin Beach  
101 Creekside Crossing  
STE 1700-191  
Brentwood, TN. 37027

[aureliasings@gmail.com](mailto:aureliasings@gmail.com)

To Whom It May Concern:

On 10-5-20, a preliminary soil evaluation was conducted at Tax map 163 parcel 49.00 Bunker Hill Road in Rutherford County for the feasibility for subsurface sewage disposal systems (SSDS).

The soils contacted consisted primarily of Barfield, Talbott and Gladeville Rock Outcropping. These soils are considered unfavorable for SSDS by standard evaluation at this time due to shallow depths to rock and/or clay. Other features observed that would impact the installation of any new SSDS are drains.

Some similar and /or dissimilar soils may be encountered with a more intensive evaluation.

Due to dense vegetation and unclear property boundaries, a more intensive evaluation was unable to be performed.

If you have questions concerning this matter, please advise.

Sincerely,



Jay Andrews  
Soil Scientist  
License #42



