



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes) Synergy Groups Medical	Manufacturer <i>Health o meter</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # <i>4020098973</i>	Customer P.O. #
Routine Inspection (2) <i>1/2/2025</i>	Incoming Inspection (3) <i>1/2/2026</i>	Model # <i>402</i>	Equipment Description: <i>scale</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		<i>/</i>	
Chassis, Knobs, Switches and Connectors		<i>/</i>	
Meters, Gauges, Lamps and Lenses		<i>/</i>	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>00</i>			
Chassis Leakage (< 100 uA) <i>00</i>			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: <i>BE</i>



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes): Synergy Groups Medical	Manufacturer: <i>Quest</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial #: <i>180913D0709</i>	Customer P.O. #
Routine Inspection: (2) <i>1/2/2025</i>	Incoming Inspection: (3) <i>1/2/2026</i>	Model #: <i>642E</i>	Equipment Description: <i>Centrifuge</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		/	
Chassis, Knobs, Switches and Connectors		/	
Meters, Gauges, Lamps and Lenses		/	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>250</i>			
Chassis Leakage (< 100 uA) <i>110</i>			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: <i>BE</i>

RPM 3400 - 3851
3



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes) Synergy Groups Medical	Manufacturer <i>Kennmore</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # <i>55256</i>	Customer P.O. #
Routine Inspection (2) <i>11/2/2025</i>	Incoming Inspection (3) <i>11/2/2026</i>	Model # <i>MCKB21RFV</i>	Equipment Description: <i>Frig.</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		/	
Chassis, Knobs, Switches and Connectors		/	
Meters, Gauges, Lamps and Lenses		/	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>0</i>			
Chassis Leakage (< 100 uA) <i>0</i>			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: <i>BE</i>



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes): Synergy Groups Medical	Manufacturer: accucold	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial #: ADA305AF20210400190	Customer P.O. #
Routine Inspection: (2) 1/2/2025	Incoming Inspection: (3) 1/2/2026	Model #: ADA305AF	Equipment Description: Freezer

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		✓	
Chassis, Knobs, Switches and Connectors		✓	
Meters, Gauges, Lamps and Lenses		✓	
Fans & Filters / Tubing, Hoses & "O" - Rings		✓	
Drive Motor / Pump / Compressor and Gearing		✓	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: BE



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility: (Changes) Synergy Groups Medical	Manufacturer —	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # —	Customer P.O. #
Routine Inspection (2) 1/2/2025	Incoming Inspection (3) 1/2/2026	Model # —	Equipment Description: BP

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED		COMMENTS	PASS FAIL
Power Cord, Plug & Strain Relief's			✓
Chassis, Knobs, Switches and Connectors			✓
Meters, Gauges, Lamps and Lenses			✓
Fans & Filters / Tubing, Hoses & "O" - Rings			✓
Drive Motor / Pump / Compressor and Gearing			✓
PERFORM ELECTRICAL SAFETY INSPECTION		COMMENTS	PASS FAIL
Grounding Resistance (< 50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: BE



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes) Synergy Groups Medical	Manufacturer <i>SECA</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # <i>5769289175603</i>	Customer P.O. #
Routine Inspection (2) <i>1/24/2025</i>	Incoming Inspection (3) <i>1/2/2026</i>	Model # <i>220</i>	Equipment Description: <i>Scale</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		<i>/</i>	
Chassis, Knobs, Switches and Connectors		<i>/</i>	
Meters, Gauges, Lamps and Lenses		<i>/</i>	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>0</i>			
Chassis Leakage (< 100 uA) <i>0</i>			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: <i>BE</i>



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes) Synergy Groups Medical	Manufacturer <i>McKesson</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # <i>197T1006596</i>	Customer P.O. #
Routine Inspection (2) <i>1/2/2025</i>	Incoming Inspection (3) <i>1/2/2026</i>	Model # <i>120</i>	Equipment Description: <i>UA</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		<i>/</i>	
Chassis, Knobs, Switches and Connectors		<i>/</i>	
Meters, Gauges, Lamps and Lenses		<i>/</i>	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>0</i>			
Chassis Leakage (< 100 uA) <i>0</i>			
Completion Date: 01/02/2025	Work Order Reference 250001	Labor Hours	Inspector: <i>BC</i>



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date 01/02/2025	Facility (Changes) Synergy Groups Medical	Manufacturer <i>welch Allyn</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # <i>100000740121</i>	Customer P.O. #
Routine Inspection (2) <i>1/2/2025</i>	Incoming Inspection (3) <i>1/2/2026</i>	Model # <i>CP 150</i>	Equipment Description: <i>EKG</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		☒	
Chassis, Knobs, Switches and Connectors		☒	
Meters, Gauges, Lamps and Lenses		☒	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>275</i>			
Chassis Leakage (< 100 uA) <i>.101</i>			
Completion Date 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: <i>BE</i>



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes) Synergy Groups Medical	Manufacturer: <i>Scientific</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # <i>36712</i>	Customer P.O. #
Routine Inspection (2) <i>1/2/2025</i>	Incoming Inspection (3) <i>1/2/2026</i>	Model #	Equipment Description: <i>Freezer</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		☒	
Chassis, Knobs, Switches and Connectors		☒	
Meters, Gauges, Lamps and Lenses		☒	
Fans & Filters / Tubing, Hoses & "O" - Rings		☒	
Drive Motor / Pump / Compressor and Gearing		☒	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>0</i>			
Chassis Leakage (< 100 uA) <i>0</i>			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: <i>B&F</i>



ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 01/02/2025	Facility (Changes) Synergy Groups Medical	Manufacturer <i>Edge Star</i>	Equipment Control #
Requested By: Shahista	Location: 3281 Rocky Creek Dr. #500 Missouri City, TX 77459	Serial # <i>10810</i>	Customer P.O. #
Routine Inspection (2) <i>1/2/2025</i>	Incoming Inspection (3) <i>1/2/2026</i>	Model # <i>MCK 895RFV</i>	Equipment Description: <i>Freezer</i>

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		☒	
Chassis, Knobs, Switches and Connectors		☒	
Meters, Gauges, Lamps and Lenses		☒	
Fans & Filters / Tubing, Hoses & "O" - Rings		☒	
Drive Motor / Pump / Compressor and Gearing		☒	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance ($< .50$ Ohm's) <i>0</i>			
Chassis Leakage (< 100 uA) <i>0</i>			
Completion Date: 01/02/2025	Work Order Reference: 250001	Labor Hours	Inspector: <i>BE</i>