



## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Abbott	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # AF20033014	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # Afinian Z	Equipment Description: Analyzer

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Omron	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 20131202379LG	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # BP7911T	Equipment Description: BP

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings		X	
Drive Motor / Pump / Compressor and Gearing		X	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Horizon	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 520612-1068	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # 642	Equipment Description: Centrifuge

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT,CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing		X	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 315			
Chassis Leakage (< 100 uA) .121			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>






## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Horizon	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 170313CA064	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # 642E	Equipment Description: Centrifuge

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT,CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing		X	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 316			
Chassis Leakage (< 100 uA) .124			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>






## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer EPPendorf	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 5703KM522361	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # 5702R	Equipment Description: Centrifuge

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT,CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) .261			
Chassis Leakage (< 100 uA) .110			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Mortara	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 116430534177	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # Eli 250	Equipment Description: ECG

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT,CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Mortara	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 119360000247	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # Eli 250	Equipment Description: ECG

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Scientific	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # KDW0128F92205128	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # K205ULT	Equipment Description: Freezer

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>






## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Summit	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # A070800147	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model #	Equipment Description: Freezer

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings		X	
Drive Motor / Pump / Compressor and Gearing		X	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer FrigiDaire	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # BA41704621	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # FRAE2024AW6	Equipment Description: Fridge

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer FrigiDaire	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # A13772504	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model #	Equipment Description: Fridge

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Chander	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # C21018216	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # HM200P	Equipment Description: Height Measurement

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT,CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>






## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Health O Meter	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 03647	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # 1100L	Equipment Description: Scale

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Berrcon	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # C04200378845	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # JXB-178	Equipment Description: Temp Probe

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer McKesson	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # 197TI008440	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # 120	Equipment Description: Urine Analyzer

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings			
Drive Motor / Pump / Compressor and Gearing			
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>





## ELECTRICAL SAFETY INSPECTION REPORT

Requisition Date: 4/22/25	Facility: Synergy Groups Medical	Manufacturer Welch Allyn	Equipment Control #
Requested By: Shahista	Location: 8121 Broadway St. #120/111 Houston, TX 77061	Serial # JA0028272	Customer P.O. #
Routine Inspection Annual	Incoming Inspection 4/22/2026	Model # 53NT0	Equipment Description: Vital Monitor

INSPECTION PROCEDURE		INSPECTION DATA	
INSPECT, CLEAN & LUBRICATE AS REQUIRED	COMMENTS	PASS	FAIL
Power Cord, Plug & Strain Relief's		X	
Chassis, Knobs, Switches and Connectors		X	
Meters, Gauges, Lamps and Lenses		X	
Fans & Filters / Tubing, Hoses & "O" - Rings		X	
Drive Motor / Pump / Compressor and Gearing		X	
PERFORM ELECTRICAL SAFETY INSPECTION	COMMENTS	PASS	FAIL
Grounding Resistance (< .50 Ohm's) 0			
Chassis Leakage (< 100 uA) 0			
Completion Date: 04/22/2025	Work Order Reference: 250121	Labor Hours	Inspector: <i>BE</i>