


Payload 3 Daily Flight Report



Date: 2021-07-19

Flight Campaign ID: P3C1

Airport, FBO ID, City: Fairbanks International Airport (PAFA) - Fairbanks, AK

Aircraft: N615AR

Domain: 19 (Taiga)

Sites Flown: HEAL (Healy)
Days left in Domain: 29

Report Author: Michael Wussow

Lidar Operators: Michael Wussow **Flight Hours**: 02:45

Spectrometer Operators: Elissa Barris **Hours until maintenance**: 46.97 **Pilots**: Vince Maarschalkerweerd, Stephen Brawders **GPS Instruments**: C-FAI1, U-GRNX

Ground Crew: John Adler

Summary

Lines were flown at HEAL today with clear skies at the start of solar angle giving way to cumulus and creeping cirrus clouds. The priority lines were finished in "green" conditions. Bridget and Murph, members of AOP Science, were on the ground today at HEAL with calibration tarps set up. Four lines were collected over the tarps, although conditions were not completely clear for those lines.

Concerns

An instantaneous NIS pressure spike reading was experienced in flight today. It is thought to be a glitch with the chamber pressure gauge. This happens from time to time, and the gauge will be reset tomorrow if it does not right itself overnight.

Comments

Lines flown for tarp collections, in order: 22, 23, 1, 22.

Daily Coverage

Estimated Cloud Cover Key

Green:	Yellow:	Red:
0-10%	11-50%	>50%

D19|HEAL

Line #	9	10	11	12	13	14	22	23	32	33
Lidar	√	✓	✓	✓	✓	✓	✓	✓	✓	✓
Spectrometer	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Camera	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Cloud Cover										

Total number of lines flown: 10

Flight Screenshots

The state of the state o

Lidar NIS

Pictures



Camera phone image of the tarps set up near the Healy NEON Tower. Nice shot Elissa!



Conditions towards the beginning of today's flight

Cumulative Domain Coverage

D19 | BONA (Caribou Creek and Poker Flats Watershed)

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
Г	41	42	43	44	45	46														

Flown: 7% (3/46) Green: 7% (3/46) Yellow: 0% (0/46) Red: 0% (0/46)

D19 | DEJU (Delta Junction)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
21	22	23	24	25	26	27	28	29	30	31	32								

Flown: 0% (0/32) Green: 0% (0/32) Yellow: 0% (0/32) Red: 0% (0/32)


D19 | HEAL (Healy)

		, -	· / /																
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
21	22	23	24	25	26	27	28	29	30	31	32	33							


Flown: 79% (26/33) Green: 70% (23/33) Yellow: 9% (3/33) Red: 0% (0/33)

Weather Forecast


Fairbanks, AK (PAFA, BONA)



Healy, AK (HEAL)



Delta Junction, AK (DEJU)



Cloud Cover (%) Chance of Precip. (%)

source: wunderground.com

Flight Collection Plan for 20 July 2021

Flyority 1

Collection Area: Healy (HEAL)

Flight Plan Name: D19_HEAL_R3_P1_v1_Q780

On-station Time: 1830 UTC / 1030 L

Flyority 2

Collection Area: Caribou Creek - Poker Flats Watershed (BONA)

Flight Plan Name: D19_BONA_C1_P1_v1_Q780

On-station Time: 1830 UTC / 1030 L

Flyority 3

Collection Area: Delta Junction (DEJU) – Priority Flight Box 1 & 2

Flight Plan Name: D19_DEJU_R1_P1_v5_Q780, D19_DEJU_R1_P2_v5_Q780

On-station Time: 1820 UTC / 1020 L

Crew: John (Lidar), Mike (NIS), Elissa (Ground)