

**SURVEY EXAMINED AND
ACCEPTED BY PURCHASERS**

DATE 4/27/2020



02-19-18

Survey completed 02-14-18
Scale: 1" = 100'
Job No. 180028
Surveyor TLK #6119
Plot Date: 02-19-18