CITY OF BELMONT

COLLECTIONS

ANNUAL

REPORT 2018

WQCS00046

CITY OF BELMONT

COLLECTIONS PERFORMANCE

REPORT FOR 2018

Responsible Entity:

Adrian Miller, City Manager

Person in Charge/Contact:

Gary Gallagher, Collections ORC

WQCS00046

Description of Collections System

The City of Belmont maintains a collection system that consists of 89.95 miles of gravity lines. The collection lines we maintain range in size from 6" to 24" in diameter. The City of Belmont reports any and all overflows from our collections system to NCDWQ immediately.

Performance:

Overflow's reported for January to December 2018

1/02/2018, 1st manhole at Belle Meade Lift Station (4080 Belle Meade Cir.), 800 gallons

1/27/2018, 3 Linestowe Dr., 920 gallons

2/12/2018, 127 Morning Glory Ave., 736 gallons

2/13/2018, 1711 Cardinal Ct., 520 gallons

5/29/2018, Stowe Lift Station (2099 Oaks Parkway), 800 gallons

9/16/2018, Cason Lift Station (773 Cason St.), 1440 gallons

9/30/2018, Clay Street Right of Way, 824 gallons

10/05/2018, Morgan's Branch Rd. at Southpoint Rd., 2475 gallons

10/11/2018, Cason Lift Station (773 Cason St.), 448 gallons

10/23/2018, 214 Plant Allen Rd., 2800 gallons

Notification:

A copy of this report has been placed on the City of Belmont's website, www.cityofbelmont.org. Inquiries, questions or concerns may be addressed to Mr. Gary Gallagher, at City of Belmont Public Works, 1401 East Catawba Street, Belmont, NC 28012, telephone number 704-901-2072.

Certification:

I certify under penalty of law that this report is complete and accurate to the best of my knowledge. I further understand that this report has been made available to the users or customers of the City of Belmont's collection system.

(Signature)

Responsible Person

Title: City Manager

Entity: City of Belmont

Date