

City of Kettering Maintained Bridges
 Bridge Condition Listing
 September 2021

Bridge	Current Condition Rating	Load Restrictions	Structure Type	Status	Funding	Estimated Rehab/Replace Cost	Estimated Construction Year
West Ave	3R	Y	Concrete box beams	Fair to serious condition; inspecting quarterly, east half closed	OPWC & ODOT applications pending	\$450,000 - \$570,000	TBD
Ansel Drive	3P	Y	Concrete box beams	Scheduled for superstructure replacement in 2022	ODOT Municipal Bridge / City	\$460,000	2022
Danube Court	3P	Y	Concrete box beams	Scheduled for superstructure replacement in 2024	ODOT Municipal Bridge / City	\$700,000	2024
Flesher Ave	5P	Y	Concrete slab	Fair condition; inspecting annually	Multiple unsuccessful OPWC applications	\$500,000	2023
Galewood Street	5A	N	Concrete box beams	Fair to poor condition; inspecting annually	ARPA?	\$900,000	2023
Display Lane	5A	N	Concrete elliptical/box culvert	Fair condition; inspecting annually	ARPA?	\$400,000	2023
Parklawn Drive	5A	N	Three-sided concrete culvert	Fair condition; inspecting annually	ARPA?	\$300,000	2023
Hempstead Station (south)	5A	N	Metal arch pipe culvert	Fair condition; inspecting annually		\$400,000	2024
West Stroop & Southern	5A	N	Circular concrete & metal culverts	Fair condition; inspecting annually		\$500,000 - \$1,000,000	TBD
Gentile Park bridge	5A	N	Concrete box beams	Fair condition; inspecting annually			
Hackney Drive (west of Pobst)	6A	N	Concrete box beams	Satisfactory condition; inspecting annually			
Hackney Drive (north of Patricia)	6A	N	Precast concrete box	Satisfactory condition; inspecting annually			
Hempstead Station (north)	6A	N	Precast concrete box	Satisfactory condition; inspecting annually			
Wiltshire & Broadmoor	6A	N	Three-sided & circular concrete culverts	Satisfactory condition; inspecting annually			
Rembrandt Blvd	7A	N	Metal arch pipe culvert	Good condition, inspecting biennially			
Tait Road	7A	N	Three-sided concrete culvert	Good condition, inspecting biennially			
Delco Park	7A	N	Concrete box beams	Good condition, inspecting biennially			
Gaylord Ave	7A	N	Precast concrete box	Good condition, inspecting biennially			
Circleview Drive	7A	N	Precast concrete box	Good condition, inspecting biennially			
South Blvd	7A	N	Precast concrete box	Good condition, inspecting biennially			
Public Service Yard - north	8A	N	Precast concrete arch	Good condition, inspecting biennially			
Public Service Yard - south	8A	N	Precast concrete arch	Good condition, inspecting biennially			
Burchdale Street	8A	N	Precast concrete arch	Good condition, inspecting biennially			
Vale Drive	8A	N	Three-sided precast concrete culvert	Good condition, inspecting biennially			
Ghent Ave	8A	N	Three-sided precast concrete culvert	Good condition, inspecting biennially			
Schantz Ave	9A	N	Concrete slab	New structure, inspecting biennially			
Ridgeway Road	9A	N	Plate girder w/concrete deck	New structure, inspecting biennially			