



- LEGEND**
- CITY PARK
 - WATER TOWER
 - CITY HALL: POLICE DEPARTMENT
 - SCHOOL
 - CEMETARY
 - CHURCH

- 500 CONTOUR LINES
- CURB AND GUTTER EXISTS
- DRAINAGE FACILITY - GOOD CONDITION
- DRAINAGE FACILITY - OVERGROWN WITH VEGETATION OR PARTIALLY CLOGGED
- DRAINAGE FACILITY - PARTIALLY CRUSHED
- REFERENCE TO DRAINAGE STRUCTURE (SEE DRAINAGE STRUCTURE INVENTORY TABLE)
- LOCALIZED FLOODING HAS OCCURRED

