

Application/Permit Information Report - Inspections

Appl/Permit:	880215		Application Date:	vate: 02/13/2018		Tax Parcel:	9010260010			
Site Address:	5125 Grand Loop		Status:	Issued		Community Area:				
Applicant:	Point Ruston, LLC		Expiration Date:	11/06/2018		Owner:	POINT RUSTON SILVER CLOUD			
Address:	5219 N SHIRLEY ST #: TACOMA, WA 98407	100	Туре:	Building (Commerc	cial)	Address:	103 118th AV SE Suite 300 BELLEVUE, WA 98005			
Project Name:	Point Ruston Silver Cloud Hotel (Building 17)									
Work Description:	: RST 17-1526 The development of Building 17 (the Silver Cloud Hotel) of the Point Ruston Master Development Plan will include approximately 194 hotel rooms (approximately 97,916-square-feet), approximately 60,492-square-feet of accessory banquet, restaurant, hotel operations, and amenity space. The building also includes below ground parking (approximately 177 stalls) and screened surface parking (approximately 17 stalls) to service the hotel.									
Inspector	Inspector Phone	Department		Inspection Date	Inspection 7	Гуре	Inspection Result			
Eric Eagle	253-798-7241	BUILDING DI	VISION	05/10/2018	Courtesy Ir	nspection	Partial Approved			
Looked at concrete shearwall on grid line 1 from lines C-E Ok to pour once Engineer and Special Inspector approved										
Eric Eagle	253-798-7241	BUILDING DI	VISION	05/08/2018	Energy		Partial Approved			
	ebar in Shearwall on grid l once Engineer and specia			rner.						
Nick Waggood	253-798-6857	BUILDING DI	VISION	05/02/2018	Frame		Comment			
Contractor	canceled over the phone									
Nick Waggood	253-798-6857	BUILDING DI	VISION	05/02/2018	Slab/Slab II	nspection	Partial Approved			
remaining le	evel 1 slab ok to pour subj	ect to special in	spection and engin	eering approval.						
Nick Waggood	253-798-6857	BUILDING DI	VISION	04/27/2018	Comment		Comment			
 Columns and shearwalls confirmed in pour areas 1, 2 during previous site visits. Columns and walls for stairwell 1, as well as shearwalls in pour area 3 between grid E&D and 5&7 ok to pour subject to special inspection. 										
Nick Waggood	253-798-6857	BUILDING DI	VISION	04/18/2018	Slab/Slab II	nspection	Partial Approved			
 Level 1 Pour area 3 - Area starts along gridline H at the closer strip, extends north between gridline 5 and 6 and completes the deck in that area. Special inspector and engineer were onsite during inspection, engineer had monitor corrections that were being completed and confirmed by 										
			H, F 8:00-11:30 and		0-11:30 and 1	oma, Washington 984 .2:30-4:00 (253)798-				

Inspector	Inspector Phone	Department	Inspection Date	Inspection Type	Inspection Result					
	253-798-6857									
special inspec 5. Ok to pour		tion and structural engineers a	pproval.							
Nick Waggood	253-798-6857	BUILDING DIVISION	04/05/2018	Slab/Slab Inspection	Partial Approved					
 Level 1 Pour area 2 - Area starts along gridline H at the closer strip, extends south between gridline 6 and 7 to edge of slab Ok to pour pending special inspection and structural engineers approval. 										
Nick Waggood	253-798-6857	BUILDING DIVISION	03/29/2018	Slab/Slab Inspection	Partial Approved					
 Level 1 Pour area - first pour is designated as "pour 2" on Approved plans. Area starts along gridline H at the closer strip, extends north between gridline 5 and 6 and stays south of the tendon running along gridline E. Steel sleeves for plumbing were installed at 2 sheer head zone locations. Additional Hairpins installed at anchorage zones that had conduits within 6 inches per plan. Special inspector onsite during inspection and confirmed additional requirements from engineer were completed as well as tendon elevations and locations. Ok to pour pending special inspection and structural engineers approval. 										
Nick Waggood	253-798-6857	BUILDING DIVISION	03/22/2018	Slab/Slab Inspection	Comment					

Contractor canceled over email, per Don.