Table 1. Fire Debris Removal Real Time and Community Air Monitoring, PM10 Average Concentration, Sonoma County

May 2018 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 Real Time Monitors ____ Fairway Knoll Lane Deauville Place Vintage Circle Crown Hill Drive Sundown Trail Community Area Monitors Oak Leaf Drive ECC CAM 4 ECC CAM 6 ECC CAM 7 Legend Data not collected. Reasons for no data collection at sites include: raining (natural dust suppression) and site not yet or no longer being tested Below Target Criteria Exceeds Target