


MORMON HOLLOW BRIDGE, WENDELL STATE FOREST

Landing Reinforcement for Certificate Of Compliance



A. NORTHWEST LANDING

Before



Erosion by abutment (6.2025)

After



Rock reinforcement to prevent erosion. Left: larger context. Right: detail. (9.2025)

B. SOUTHWEST LANDING

Before



Erosion by abutment (6.2025)

After



Rock reinforcement to prevent erosion. Left: larger context. Right: detail. (9.2025)