

PARK DRAIN
100' R/W

N61°43'00"E

IRON ROD SET #9761

N28°17'00"W

EXISTING POWER POLE
617.69' EXISTING ANCHOR

IPON BOD SET #0761

EXISTING STORM- DRAIN CLEANOUT IN CONCRETE

5.162 AC.

S. MAIN STREET - NM HIGHWAY 478
100' R/W

SURVEYOR'S CERTIFICATION

I, JERRY W. GREINER, A NEW MEXICO PROFESSIONAL SURVEYOR CERTIFY THAT I CONDUCTED AND AM RESPONSIBLE FOR THIS SURVEY, THAT THIS SURVEY IS TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF, AND THAT THIS SURVEY AND PLAT MEET THE MINIMUM STANDARDS FOR SURVEYING IN NEW MEXICO.

DATE OF SURVEY 10/11/10

KERY/WS GREINER. PS 9761



TIERRA SURVEYS, LLC.

P.O. Box 1857
Mesilla Park, NM 88047
(575) 520-6505
File Id: 18051.dwo

