LOCATION INFORMATION		SYSTEM-OWNED PORTION										CUSTOMER-OWNED PORTION							
Unique Service Line ID	Street Address	OTHER LOCATIONAL IDENTIFIER	System-Owned Portion Service line Material Classification	Lead Connector Present?	If Material Anything Other Than "Lead" in Column E, Was Material Previously Lead	Service Line Installation Year	*Service Line Size (inches)*	Basis of Material Classification	Was The Service Line Material Field Verified	Describe The Field Verification Method	Enter the Date of Field Verification	Customer-Owned Portion Service Line Material	Service Line Installation Year	Service Line Size (inches)	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Verification Method	Date of Field Verification Method	Entire Service Line Material Classification (if error or"Missing Information" appears, ensure all required columns are filled correctly. See instructions)
2	2600 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
3	2606 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
4	2612 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
5	2618 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
6	2624 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
7	2630 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
8	2636 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
9	2642 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
10	2666 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
11	2672 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
12	2678 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
13	2684 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
14	2690 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
15	2696 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
16	2691 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
17	2685 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
18	2679 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
19	2673 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
20	2667 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
21	2661 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
22	2654 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
23	2660 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
24	2666 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
25	2672 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
26	2678 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
27	2684 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
28	2690 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
29	2696 SEAN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
30	2700 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
31	2704 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
32	2708 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
33	2712 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
34	2716 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
35	2720 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
36	2724 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
37	2728 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
38	2732 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
39	2736 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
40	2740 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
41	2744 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
42	2748 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
43	2752 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
44	2756 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
45	2760 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
46	2764 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
47	2768 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
48	2783 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
49	2779 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
50	2775 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
51	2771 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
52	2767 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
53	2763 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
54	2759 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
55	2755 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
56	2751 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
57	2747 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
58	2743 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
59	2739 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
60	2735 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
61	2731 KILCONWAY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
62	3719 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
63	3717 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
64	3715 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
65	3713 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
66	3711 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
67	3709 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
68	3707 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
69	3705 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
70	3703 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
71	3701 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
72	2700 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
73	2704 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
74	2708 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
75	2712 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
76	2716 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
77	2720 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
78	2724 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
79	2728 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
80	2732 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
81	2736 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
82	2740 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
83	2744 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
84	2748 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
85	2752 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
86	2756 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
87	2760 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
88	2783 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
89	2779 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
90	2763 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
91	2759 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
92	2787 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
93	2775 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
94	2771 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
95	2767 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
96	2755 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
97	2751 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead

98	2747 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
99	2743 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
100	2739 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
101	2735 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
102	2731 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
103	3665 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
104	3661 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
105	3657 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
106	3653 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
107	3649 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
108	3645 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
109	3641 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
110	3637 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
111	3633 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
112	3629 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
113	3625 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
114	2649 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
115	2647 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
116	2645 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
117	2641 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
118	2637 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
119	2633 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
120	2625 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
121	2621 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
122	2617 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
123	2613 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
124	2609 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
125	2605 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
126	2603 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
127	2601 DUHALLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/22/2024	Non-lead
128	2620 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
129	2622 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
130	2624 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
131	2626 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
132	2628 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
133	2630 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
134	2632 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
135	2634 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
136	2638 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
137	2640 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
138	2642 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
139	2644 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
140	2646 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
141	2648 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
142	2650 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
143	2700 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
144	2704 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
145	2708 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
146	2712 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
147	2716 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
148	2720 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
149	2724 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
150	2728 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
151	2732 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
152	2736 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
153	2740 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
154	2744 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
155	2748 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
156	2752 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
157	2756 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
158	2760 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
159	3600 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
160	3604 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
161	3608 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
162	3612 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
163	3616 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
164	3620 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
165	3624 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
166	3628 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
167	3632 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
168	3636 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
169	3640 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
170	3644 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
171	3700 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
172	3704 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
173	3708 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
174	3712 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
175	3716 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
176	3720 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
177	3724 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
178	3728 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
179	3732 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
180	3736 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
181	3740 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
182	3744 ATHY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/23/2024	Non-lead
183	3898 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
184	3896 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
185	3892 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
186	3888 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
187	3884 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
188	3880 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
189	3876 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
190	3872 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
191	3868 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
192	3864 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
193	3860 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
194	3856 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
195	3852 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
196	3872 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
198	3860 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
199	3854 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
200	3848 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
201	3842 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
202	3836 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead

203	3830 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
204	3837 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
205	3843 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
206	3849 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
207	3855 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
208	3861 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
209	3867 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
210	3873 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
211	3879 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
212	3885 SHAMROCK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
213	3836 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
214	3832 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
215	3828 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
216	3824 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
217	3820 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
218	3816 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/4/2024	Non-lead
219	2694 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
220	2692 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
221	2690 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
222	2688 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
223	2686 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
224	2684 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
225	2682 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
226	2680 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
227	2668 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
228	2664 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
229	2660 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
230	2656 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
231	2652 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
232	2648 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
233	2644 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
234	2640 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
235	2636 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
236	2632 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
237	2628 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
238	2624 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
239	2620 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
240	2616 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
241	2612 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
242	2608 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
243	2604 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
244	2600 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
245	3794 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
246	3790 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
247	3786 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
248	3782 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
249	3778 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
250	3774 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
251	3770 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
252	3766 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
253	3762 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
254	3758 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
255	3759 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
256	3763 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
257	3767 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
258	3771 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
259	3775 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
260	3779 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
261	3783 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
262	3787 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
263	3791 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
264	3795 CORK PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
265	2655 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
266	2659 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
267	2663 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
268	2667 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
269	2675 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
270	2677 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
271	2679 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
272	2681 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
273	2683 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
274	2685 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
275	2687 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
276	2689 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
277	2691 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
278	2693 LEIX WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/5/2024	Non-lead
279	3780 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
280	3778 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
281	3776 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
282	3774 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
283	3772 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
284	3770 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
285	2682 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
286	2680 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
287	2678 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
288	2676 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
289	2674 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
290	2672 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
291	2670 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
292	2668 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
293	3764 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
294	3762 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
295	3760 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
296	3758 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
297	3756 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
298	3754 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
299	3752 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
300	3750 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
301	3746 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
302	3744 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
303	3742 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
304	3740 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
305	3738 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
306	3736 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead

307	3734 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
308	3732 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
309	3730 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
310	3728 MYRNA LN	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
311	2673 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
312	2675 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
313	2677 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
314	2679 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
315	2681 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
316	2683 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
317	2685 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
318	2687 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
319	2689 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
320	2691 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
321	2693 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
322	2688 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
323	2686 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
324	2684 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
325	2682 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
326	2680 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
327	2678 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
328	2676 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
329	2674 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
330	2672 CROMWELL RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
331	2667 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
332	2669 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
333	2671 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
334	2673 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
335	2675 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
336	2677 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
337	2679 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
338	2681 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
339	2683 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
340	2687 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
341	2689 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
342	2691 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
343	2693 STAMFORD RW	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
344	3748 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
345	3746 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
346	3744 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
347	3742 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
348	3740 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
349	3738 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	2/26/2024	Non-lead
350	3600 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
351	3606 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
352	3612 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
353	3618 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
354	3624 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
355	3630 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
356	3636 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
357	3642 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
358	3648 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
359	3654 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
360	3660 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
361	3666 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
362	3672 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
363	3678 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
364	3732 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
365	3734 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
366	3736 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
367	3738 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
368	3740 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
369	2575 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
370	2573 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
371	2571 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
372	2569 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
373	2563 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
374	2561 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
375	2559 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
376	2557 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
377	2555 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
378	2553 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
379	2551 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
380	2549 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
381	2547 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
382	2548 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
383	2550 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
384	2552 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
385	2556 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
386	2558 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
387	2560 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
388	2562 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
389	2564 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
390	2566 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
391	2568 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
392	2570 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
393	2572 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
394	2574 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
395	2576 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
396	3742 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
397	3744 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
398	3746 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
399	3748 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
400	3750 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
401	3752 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
402	3754 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
403	3756 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
404	2569 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
405	2567 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
406	2565 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
407	2563 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
408	2561 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
409	2555 ADAMS CT	S

411	2551 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
412	2549 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
413	2547 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
414	2548 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
415	2550 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
416	2552 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
417	2554 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
418	2556 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
419	2558 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
420	2560 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
421	2562 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
422	2564 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
423	2566 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
424	2568 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
425	2570 ADAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
426	3760 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
427	3762 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
428	3764 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
429	3766 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
430	3768 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
431	3770 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
432	3772 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
433	3774 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
434	3776 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
435	3778 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
436	3780 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
437	3782 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
438	3784 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
439	3786 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
440	3788 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
441	3790 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
442	3792 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
444	3804 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
445	3808 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
446	3812 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
447	3816 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
448	3820 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
449	2600 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
450	2606 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
451	2624 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
452	2630 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
453	2636 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
454	2642 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
455	2648 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
456	2649 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
457	2643 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
458	2637 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
459	2631 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
460	2625 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
461	2619 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
462	2613 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
463	2607 CASHLEA CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
464	3837 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
465	3793 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
466	3791 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
467	3789 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
468	3785 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
469	3783 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
470	3781 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
471	3779 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
472	3775 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
473	3773 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
474	3771 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
475	3769 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
476	2600 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
477	2606 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
478	2612 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
479	2618 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
480	2624 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
481	2630 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
482	2636 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
483	2642 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
484	2648 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
485	2654 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
486	2660 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
487	2666 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
488	2667 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
489	2661 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
490	2655 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
491	2649 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
492	2643 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
493	2637 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
494	2631 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
495	2625 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
496	2619 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
497	2613 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
498	2607 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
499	2601 FARNEE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
500	2600 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
501	2606 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
502	2612 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
503	2618 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
504	2624 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
505	2630 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
506	2636 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
507	2642 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
508	2648 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
509	2654 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
510	2660 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
511	2666 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
512	2667 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
513	2661 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
514	2655 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
515	2649 TYRONE CT	S SA

516	2643 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
517	2637 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
518	2631 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
519	2625 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
520	2619 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
521	2613 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
522	2607 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
523	2601 TYRONE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/12/2024	Non-lead
524	3729 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
525	3725 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
526	3723 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
527	3721 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
528	3719 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
529	3715 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
530	3713 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
531	3711 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
532	3732 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
533	3740 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
534	3748 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
535	3756 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
536	3764 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
537	3772 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
538	3780 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
539	3788 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
540	3789 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
541	3781 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
542	3773 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
543	3765 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
544	3757 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
545	3749 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
546	3741 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
547	3733 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
548	3725 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
549	3717 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
550	3709 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
551	3701 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
552	3667 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
553	3665 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
554	3663 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
555	3659 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
556	3655 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
557	3651 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
558	3643 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
559	3639 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
560	3635 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
561	3631 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
562	3627 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
563	3625 ERRIS CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/18/2024	Non-lead
564	3645 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
565	3641 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
566	3637 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
567	3633 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
568	3629 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
569	3625 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
570	3617 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
571	3613 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
572	3609 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
573	3605 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
574	3603 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
575	3601 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/14/2024	Non-lead
576	2554 OLMSTEAD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/8/2024	Non-lead
577	2593 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
578	2591 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
579	2589 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
580	2587 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
581	2585 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
582	2583 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
583	2581 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
584	2579 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
585	2577 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
586	2575 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
587	2573 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
588	2571 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
589	2569 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
590	2567 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
591	3900 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
592	3906 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
593	3912 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
594	3918 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
595	3936 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
596	3942 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
597	3948 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
598	3954 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
599	3960 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
600	3966 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
601	3972 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
602	3978 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
603	3984 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
604	3990 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
605	3991 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
606	3987 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
607	3985 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
608	3981 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
609	3979 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
610	3975 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
611	3973 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
612	3969 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
613	3967 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
614	3961 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
615	3963 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
616	3957 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
617	3955 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
618	3951 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection

620	3945 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
621	3943 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
622	3939 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
623	3937 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
624	3933 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
625	3931 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
626	3925 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
627	3923 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
628	3921 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
629	3919 HAUSSMAN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
630	3900 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
631	3906 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
632	3912 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
633	3918 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
634	3924 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
635	3930 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
636	3936 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
637	3942 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
638	3948 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
639	3954 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
640	3960 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
641	3966 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
642	3972 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
643	3977 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
644	3973 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
645	3967 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
646	3961 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
647	3955 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
648	3949 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
649	3943 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
650	3937 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
651	3931 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
652	3925 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
653	3919 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
654	3913 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
655	3907 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
656	3901 CHATHAM CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/19/2024	Non-lead
657	3901 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
658	3907 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
659	3913 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
660	3919 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
661	3925 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
662	3931 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
663	3937 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
664	3943 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Copper	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
665	3949 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
666	3955 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
667	3961 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
668	3967 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
669	3973 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
670	3979 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
671	3978 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
672	3972 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
673	3966 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
674	3960 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
675	3954 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
676	3948 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
677	3942 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
678	3936 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
679	3930 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
680	3924 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
681	3918 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
682	3912 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
683	3906 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
684	3900 SAVANNAH CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
685	3901 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
686	3907 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
687	3913 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
688	3919 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
689	3925 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
690	3931 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
691	3937 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
692	3943 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
693	3949 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
694	3955 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
695	3961 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
696	3967 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
697	3973 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
698	3979 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
699	3978 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
700	3972 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
701	3966 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
702	3960 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
703	3954 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
704	3948 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
705	3942 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
706	3936 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
707	3930 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
708	3924 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
709	3918 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
710	3912 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
711	3906 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
712	3900 STEIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
713	3901 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
714	3907 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
715	3913 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
716	3919 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
717	3925 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
718	3931 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
719	3937 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
720	3943 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
721	3949 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
722	3955 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plast

724	3967 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
725	3973 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
726	3979 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
727	3978 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
728	3972 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
729	3966 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
730	3960 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
731	3954 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
732	3948 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
733	3942 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
734	3936 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
735	3930 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
736	3924 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
737	3918 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
738	3912 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
739	3906 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
740	3900 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/21/2024	Non-lead
741	3900 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
742	3906 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
743	3912 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
744	3918 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
745	3924 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
746	3930 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
747	3936 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
748	3942 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
749	3948 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
750	3954 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
751	3960 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
752	3966 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
753	3972 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
754	3978 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
755	3979 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
756	3973 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
757	3967 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
758	3961 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
759	3955 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
760	3949 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
761	3943 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
762	3937 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
763	3931 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
764	3925 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
765	3919 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
766	3913 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
767	3907 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
768	3901 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
772	3900 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
773	3906 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
774	3912 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
775	3918 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
776	3924 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
777	3930 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
778	3936 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
779	3942 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
780	3948 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
781	3954 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
782	3960 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
783	3966 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
784	3972 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
785	3978 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
786	3979 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
787	3973 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
788	3967 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
789	3961 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
790	3955 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
791	3949 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
792	3943 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
793	3937 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
794	3931 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
795	3925 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
796	3919 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
797	3913 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
798	3911 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
799	3901 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
800	3901 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
801	3907 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
802	3913 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
803	3919 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
804	3925 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
805	3931 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
806	3937 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
807	3943 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
808	3949 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
809	3955 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
810	3961 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
811	3967 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
812	3973 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
813	3979 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
814	3978 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
815	3972 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
816	3966 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
817	3960 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
818	3954 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
819	3948 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
820	3942 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
821	3936 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
822	3930 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
823	3924 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
824	3918 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
825	3912 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
826	3906 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
827	3900 RESTON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/26/2024	Non-lead
828	3901 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
829	3907 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
830	3913 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Pl

831	3919 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
832	3925 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
833	3931 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
834	3937 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
835	3943 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
836	3949 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
837	3955 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
838	3961 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
839	3967 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
840	3973 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
841	3979 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
842	3985 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
843	3984 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
844	3986 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
845	3980 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
846	3978 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
847	3974 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
848	3972 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
849	3968 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
850	3966 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
851	3962 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
852	3960 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
853	3956 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
854	3954 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
855	3950 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
856	3948 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
857	3944 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
858	3942 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
859	3938 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
860	3936 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
861	3932 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
862	3930 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
863	3926 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
864	3924 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
865	3920 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
866	3918 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
867	3914 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
868	3912 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
869	3908 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
870	3906 GEDDES CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
871	2594 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
872	2590 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
873	2586 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
874	2582 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
875	3855 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
876	3849 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
877	3843 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
878	3837 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
879	3831 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
880	3825 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
881	3819 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
882	3813 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
883	3807 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
884	3801 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
885	3800 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
886	3806 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
887	3812 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
888	3818 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
889	3824 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
890	3830 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
891	3836 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
892	3842 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
893	3848 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
894	3854 HOWARD CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
895	2560 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
896	2558 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
897	2556 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
898	2554 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
899	2552 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
900	2550 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
901	2548 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
902	2546 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
903	2544 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
904	2542 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
905	2540 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
906	2538 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
907	2536 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
908	2534 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
909	2532 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
910	2530 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
911	2528 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
912	2526 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
913	2524 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
914	2522 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
915	3897 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
916	3891 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
917	3885 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
918	3879 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
919	3873 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
920	3867 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
921	3861 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
922	3855 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
923	3849 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
924	3843 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
925	3837 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
926	3831 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
927	3825 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
928	3819 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
929	3813 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
930	3807 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
931	3801 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
932	3800 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
933	3806 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960

935	3818 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
936	3824 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
937	3830 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
938	3836 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
939	3842 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
940	3848 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
941	3854 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
942	3860 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
943	3872 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
944	3878 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
945	3884 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
946	3890 CROFTON WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	3/28/2024	Non-lead
947	3879 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
948	3873 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
949	3867 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
950	3861 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
951	3855 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
952	3849 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
953	3843 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
954	3837 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
955	3831 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
956	3825 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
957	3819 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
958	3813 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
959	3807 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
960	3801 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
961	3800 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
962	3806 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
963	3812 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
964	3818 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
965	3824 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
966	3830 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
967	3836 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
968	3842 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
969	3848 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
970	3854 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
971	3860 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
972	3866 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
973	3872 KENT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/1/2024	Non-lead
974	3873 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
975	3869 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
976	3865 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
977	3861 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
978	3857 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
979	3853 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
980	3849 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
981	3845 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
982	3841 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
983	3837 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
984	3833 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
985	3829 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
986	3825 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
987	3821 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
988	3811 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
989	3809 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
990	3807 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
991	3805 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
992	3803 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
993	3801 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
994	3799 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
995	3797 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
996	3795 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
997	3793 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
998	3791 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
999	3789 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1000	3787 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1001	3785 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1002	3783 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1003	3781 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1004	3779 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1005	3777 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1006	3775 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1007	3773 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1008	3771 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1009	3769 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1010	3767 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1011	3765 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1012	3763 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1013	3761 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1014	3759 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1015	3757 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1016	3755 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1017	3753 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1018	3751 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1019	3749 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1020	3747 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1021	3745 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1022	3743 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1023	3741 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1024	3739 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1025	3737 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1026	3735 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1027	3733 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1028	3731 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1029	3729 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1030	3727 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1031	3725 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1032	3723 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1033	3721 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1034	3719 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1035	3717 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1036	3715 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1037	3713 FAIRFAX

1039	3709 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1040	3707 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1041	3705 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1042	3703 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1043	3701 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1044	3700 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1045	3702 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1046	3704 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1047	3706 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1048	3708 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1049	3710 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1050	3712 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1051	3714 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1052	3716 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1053	3718 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1054	3720 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1055	3722 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1056	3724 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1057	3726 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1058	3728 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1059	3730 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1060	3732 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1061	3734 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1062	3736 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1063	3738 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1064	3740 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1065	3742 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1066	3744 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1067	3746 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1068	3748 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1069	3750 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1070	3752 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1071	3754 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1072	3756 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1073	3758 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1074	3760 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1075	3762 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1076	3764 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1077	3766 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1078	3768 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1079	3770 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1080	3772 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1081	3774 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1082	3776 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1083	3778 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1085	3782 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1086	3784 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1087	3786 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1088	3818 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1089	3820 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1090	3822 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1091	3824 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1092	3826 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1093	3828 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1094	3830 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1095	3832 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1096	3834 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1097	3836 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1098	3838 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1099	3840 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1100	3842 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1101	3844 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1102	3846 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1103	3848 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1104	3850 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1105	3852 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1106	3854 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1107	3856 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1108	3858 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1109	3860 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1110	3862 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1111	3864 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1112	3866 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1113	3868 FAIRFAX WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/2/2024	Non-lead
1114	2455 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1115	2453 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1116	2451 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1117	2449 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1118	2447 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1119	2445 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1120	2443 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1121	2441 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1122	2439 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1123	2437 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1124	2435 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1125	2433 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1126	2431 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1127	2429 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1128	2427 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1129	2425 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1130	2423 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1131	2421 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1132	2419 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1133	2417 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1134	2415 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1135	2413 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1136	2411 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1137	2409 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1138	2407 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1139	2405 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1140	2403 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1141

1144	2375 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1145	2373 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1146	2371 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1147	2369 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1148	2347 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/4/2024	Non-lead
1149	2365 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1150	2363 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1151	2361 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1152	2378 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1153	2376 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1154	2374 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1155	2372 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1156	2370 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1157	2368 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1158	2366 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1159	2364 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1160	2362 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1161	2360 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1162	2358 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1163	2356 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1164	2354 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1165	2352 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1166	2350 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1167	2348 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1168	2342 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1169	2340 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1170	2338 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1171	2336 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1172	2334 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1173	2332 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1174	2330 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1175	2328 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1176	2326 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1177	2324 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1178	2322 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1179	2320 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1180	2318 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1181	2316 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1182	2314 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1183	2312 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1184	2310 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1185	2308 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1186	2306 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1187	2304 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/3/2024	Non-lead
1188	2301 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1189	2303 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1190	2305 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1191	2307 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1192	2309 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1193	2311 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1194	2313 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1195	2315 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1196	2317 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1197	2319 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1198	2321 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1199	2323 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1200	2325 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1201	2327 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1202	2329 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1203	2331 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1204	2333 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1205	2335 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1206	3727 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1207	3729 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1208	3731 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1209	3733 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1210	3735 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1211	3737 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1212	3739 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1213	3741 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1214	3743 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1215	3745 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1216	3747 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1217	3749 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1218	3751 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1219	3753 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1220	3755 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1221	3757 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1222	3759 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1223	3761 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1224	3763 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1225	3765 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1226	3767 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1227	3769 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1228	3771 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1229	3773 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1230	3775 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1231	3777 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1232	3801 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1233	3803 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1234	3805 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1235	3807 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1236	3809 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1237	3811 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1238	3813 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1239	3815 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1240	3817 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1241	3819 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1242	3821 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1243	3823 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1244	3825 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1245	3827 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the me

1248	3833 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1249	3835 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1250	3837 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1251	3839 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1252	3841 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1253	3843 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1254	3845 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1255	3847 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1256	3849 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1257	3851 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1258	3853 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1259	3855 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1260	3857 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1261	3859 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1262	3861 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1263	3863 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1264	3865 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1265	3867 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1266	3869 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1267	3871 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1268	3873 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1269	3875 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1270	3877 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1271	3879 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1272	3881 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1273	3883 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1274	3885 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1275	3887 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1276	3886 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1277	3884 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1278	3882 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1279	3880 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1280	3878 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1281	3876 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1282	3874 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1283	3872 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1284	3870 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1285	3868 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1286	3866 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1287	3864 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1288	3862 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1289	3860 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1290	3858 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1291	3856 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1292	3854 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1293	3852 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1294	3850 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1295	3848 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1296	3846 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1297	3844 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1298	3842 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1299	3840 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1300	2470 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1301	2468 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1302	2466 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1303	2464 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1304	2462 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1305	2460 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1306	2458 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1307	2456 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1308	2454 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1309	2452 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1310	2450 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1311	2448 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1312	2446 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1313	2444 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1314	2442 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1315	2440 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1316	2438 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1317	2436 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1318	2434 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1319	2432 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/8/2024	Non-lead
1320	3829 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1321	3831 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1322	3833 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1323	3835 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1324	3837 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1325	3839 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1326	3841 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1327	3843 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1328	3845 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1329	3847 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1330	3849 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1331	3851 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1332	3850 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1333	3848 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1334	3846 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1335	3844 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1336	3842 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1337	3840 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1338	3838 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1339	3836 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1340	3834 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1341	3832 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1342	3830 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1343	3828 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1344	3826 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1345	3824 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1346	3818 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1347	3816 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1348	3814 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1349	3812 ANNAPOLIS CT	S S

1352	3806 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1353	3804 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1354	3802 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1355	3800 ANNAPOLIS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/9/2024	Non-lead
1356	2265 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1357	2263 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1358	2261 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1359	2259 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1360	2257 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1361	2251 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1362	2249 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1363	2247 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1364	2245 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1365	2243 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1366	2241 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1367	2239 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1368	2237 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1369	2235 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1370	2233 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1371	2231 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1372	2229 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1373	2227 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1374	2225 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1375	2223 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1376	2221 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1377	2219 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1378	2217 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1379	2215 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/10/2024	Non-lead
1380	3700 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1381	3706 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1382	3712 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1383	3718 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1384	3724 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1385	3730 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1386	3736 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1387	3742 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1388	3748 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1389	3754 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1390	3760 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1391	3766 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1392	3767 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1393	3761 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1394	3755 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1395	3749 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1396	3743 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1397	3737 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1398	3731 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1399	3725 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1400	3719 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1401	3713 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1402	3707 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1403	3701 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1404	3700 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1405	3706 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1406	3712 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1407	3718 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1408	3724 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1409	3730 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1410	3736 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1411	3742 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1412	3748 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1413	3754 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1414	3760 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1415	3766 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1416	3772 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1417	3773 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1418	3767 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1419	3761 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1420	3755 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1421	3749 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1422	3743 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1423	3737 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1424	3731 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1425	3725 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1426	3719 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1427	3713 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1428	3707 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1429	3701 BRUNSWICK CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1430	3700 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1431	3704 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1432	3708 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1433	3712 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1434	3716 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1435	3720 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1436	3724 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1437	3728 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1438	3732 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1439	3736 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1440	3740 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1441	3744 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1442	3748 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1443	3752 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1444	3756 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1445	3760 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1446	3764 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1447	3768 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1448	3772 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1449	3776 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1450	3780 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1451	3784 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1452	3788 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1453	3792 PALOS V

1456	3812 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1457	3818 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1458	3824 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1459	3830 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1460	3836 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1461	3842 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1462	3848 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1463	3854 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1464	3860 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1465	3866 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1466	3872 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/16/2024	Non-lead
1467	2500 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1468	2504 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1469	2508 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1470	2512 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1471	2516 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1472	2520 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1473	2524 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1474	2528 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1475	2532 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1476	2536 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1477	2540 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1478	2544 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1479	2545 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1480	2541 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1481	2537 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1482	2533 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1483	2529 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1484	2525 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1485	2521 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1486	2517 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1487	2513 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1488	2509 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1489	2505 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1490	2501 POMEROY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1491	3793 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1492	3789 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1493	3785 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1494	3781 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1495	3777 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1496	3773 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1497	3769 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1498	3765 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1499	3761 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1500	3757 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1501	3753 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1502	3749 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1503	3745 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1504	3741 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1505	3737 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1506	3733 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1507	3729 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1508	3721 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1509	3717 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1510	3713 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1511	3709 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1512	3705 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1513	3701 PALOS VERDES	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1516	3679 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1517	3673 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1518	3667 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1519	3661 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1520	3655 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1521	3649 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1522	3643 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1523	3637 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1524	3631 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1525	3625 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1526	3619 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1527	3613 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1528	3607 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1529	3606 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1530	3612 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1531	3618 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1532	3624 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1533	3630 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1534	3636 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1535	3642 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1536	3648 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1537	3654 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1538	3660 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1539	3666 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1540	3672 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1541	3678 GEORGETOWN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/18/2024	Non-lead
1542	2112 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1543	2116 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1544	2120 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1545	2124 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1546	2128 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1547	2132 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1548	2136 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1549	2140 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1550	3661 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1551	3655 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1552	3649 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1553	3643 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1554	3637 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1555	3631 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1556	3625 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1557	3619 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1558	3613 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1559	3607 BALDWIN HILLS	S SAN FRAN., CA

1562	3606 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1563	3612 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1564	3618 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1565	3624 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1566	3630 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1567	3636 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1568	3642 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1569	3648 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1570	3654 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1571	3660 BALDWIN HILLS	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1572	2148 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1573	2152 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1574	2156 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1575	2160 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1576	2164 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1577	2168 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1578	2172 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1579	2176 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1580	2180 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1581	2184 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1582	2188 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1583	2192 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1584	3667 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1585	3661 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1586	3655 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1587	3649 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1588	3643 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1589	3637 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1590	3631 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1591	3625 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1592	3619 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1593	3613 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1594	3607 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1595	3601 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1596	3600 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1597	3606 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1598	3612 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1599	3618 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1600	3624 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1601	3630 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1602	3636 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1603	3642 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1604	3648 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1605	3654 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1606	3660 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1607	3666 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1608	3672 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1609	3678 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1610	3684 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1611	3690 BETTMAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/19/2024	Non-lead
1612	3697 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1613	3691 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1614	3685 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1615	3679 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1616	3673 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1617	3667 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1618	3661 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1619	3655 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1620	3649 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1621	3643 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1622	3637 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1623	3631 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1624	3625 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1625	3619 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1626	3613 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1627	3607 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1628	3601 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1629	3600 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1630	3606 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1631	3612 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1632	3618 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1633	3624 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1634	3630 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1635	3636 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1636	3642 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1637	3648 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1638	3654 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1639	3660 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1640	3666 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1641	3672 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1642	3678 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1643	3684 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1644	3690 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1645	3696 BASSETT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1646	3697 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1647	3691 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1648	3685 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1649	3679 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1650	3673 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1651	3667 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection		Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1652	3661 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1653	3655 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1654	3649 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1655	3643 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1656	3637 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1657	3631 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1658	3625 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1659	3619 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1660	3613 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1661	3607 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1662	3601 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1663	3600 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75

1666	3618 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1667	3624 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1668	3630 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1669	3636 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1670	3642 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1671	3648 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1672	3654 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1673	3660 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1674	3666 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1675	3672 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1676	3678 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1677	3684 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1678	3690 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1679	3696 GILBERT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/22/2024	Non-lead
1680	2256 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1681	2258 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1682	2260 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1683	2262 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1684	2264 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1685	2266 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1686	2268 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1687	2270 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1688	2272 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1689	2274 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1690	2276 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1691	2278 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1692	2280 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1693	2282 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1694	2284 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1695	2286 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1696	2288 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1697	2290 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1698	2292 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1699	2294 GREENDALE DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1700	2401 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1701	2403 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1702	2405 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1703	2407 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1704	2409 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1705	2411 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1706	2413 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1707	2415 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1708	2417 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1709	2419 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1710	2421 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1711	2423 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1712	2425 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1713	2427 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1714	2429 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1715	2431 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1716	2433 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1717	2435 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1718	2437 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1719	2439 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1720	2441 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1721	2443 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1722	2445 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1723	2447 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1724	2449 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1725	2451 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1726	2453 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1727	2455 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1728	2457 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1729	2459 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1730	2461 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1731	2463 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1732	2465 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1733	2467 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1734	2469 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1735	2471 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1736	2477 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1737	2479 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1738	2481 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1739	2483 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1740	2485 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1741	2487 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1742	2489 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1743	2491 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1744	2493 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1745	2495 ROWNTREE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/23/2024	Non-lead
1746	2476 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1747	2472 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1748	2468 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1749	2464 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1750	2460 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1751	2456 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1752	2452 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1753	2448 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1754	2444 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1755	2440 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1756	2436 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1757	2432 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1758	2428 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1759	2424 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1760	2420 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1761	2416 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1762	2408 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1763	2404 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1764	2400 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1765	2401 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1766	2405 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1767

1770	2433 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1771	2437 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1772	2441 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1773	2445 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1774	2449 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1775	2453 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1776	2457 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1777	2461 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1778	2465 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1779	2469 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1780	2473 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1782	2477 WESTCHESTER CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/24/2024	Non-lead
1783	2484 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1784	2478 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1785	2472 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1786	2466 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1787	2460 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1788	2454 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1789	2448 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1790	2442 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1791	2436 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1792	2430 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1793	2424 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1794	2418 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1795	2412 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1796	2406 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1797	2400 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1798	2401 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1799	2407 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1800	2413 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1801	2419 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1802	2425 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1803	2431 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1804	2437 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1805	2443 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1806	2449 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1807	2455 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1808	2461 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1809	2467 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1810	2473 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1811	2479 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1812	2485 WILLIAMS CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1813	3716 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1815	3708 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1816	3704 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1817	3700 RADBURN DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/25/2024	Non-lead
1818	2460 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1819	2454 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1820	2448 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1821	2442 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1822	2436 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1823	2430 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1824	2424 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1825	2418 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1826	2412 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1827	2406 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1828	2400 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1829	2401 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1830	2407 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1831	2413 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1832	2419 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1833	2425 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1834	2431 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1835	2437 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1836	2443 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1837	2449 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1838	2455 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1839	2461 WILLIAMSBURG	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1840	2448 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1841	2442 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1842	2436 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1843	2430 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1844	2424 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1845	2418 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1846	2412 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1847	2406 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1848	2400 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1849	2401 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1850	2407 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1851	2413 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1852	2419 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1853	2425 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1854	2431 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1855	2437 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1856	2443 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1857	2449 WREN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1858	2454 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1859	2448 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1860	2442 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1861	2436 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1862	2430 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1863	2424 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1864	2418 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1865	2412 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1866	2406 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1867	2400 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1868	2401 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1869	2407 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1870	2413 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1871	2419 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1872	2425 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1873	2431 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection

1876	2449 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1877	2455 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1878	2461 WRIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1879	2466 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1880	2460 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1881	2454 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1882	2448 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1883	2442 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1884	2436 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1885	2430 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1886	2424 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1887	2418 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1888	2412 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1889	2406 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1890	2400 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1891	2401 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1892	2407 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1893	2413 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1894	2419 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1895	2425 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1896	2431 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1897	2437 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1898	2443 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1899	2449 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1900	2455 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1901	2461 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1902	2467 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1903	2473 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1904	2479 UNWIN CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1905	2464 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1906	2460 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1907	2456 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1908	2452 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1909	2448 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1910	2444 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1911	2440 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1912	2436 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1913	2432 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1914	2428 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1915	2424 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1916	2420 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1917	2412 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1918	2408 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1919	2404 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1920	2400 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1921	2401 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1922	2405 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1923	2409 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1924	2413 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1925	2417 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1926	2421 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1927	2425 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1928	2429 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1929	2433 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1930	2439 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1931	2441 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1932	2445 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1933	2449 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1934	2453 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1935	2457 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1936	2461 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1937	2465 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1938	2469 LIBERTY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	4/29/2024	Non-lead
1939	3425 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1940	3401 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1941	3395 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1942	3375 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1943	3355 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1944	3325 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1945	3301 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1946	3295 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1947	3275 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1948	3255 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1949	3225 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1950	3201 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1951	3195 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1952	3165 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1953	3160 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1954	3190 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1955	3230 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1956	3260 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1957	3290 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1958	3330 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1959	3360 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1960	3390 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1961	3420 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1962	3440 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1963	2595 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1964	2575 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1965	2565 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1966	2555 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1967	2545 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1968	2535 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1969	2525 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1970	2515 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1971	2511 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1972	2505 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1973	2501 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1974	2495 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1975	2475 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1976	2465 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1977	2455 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead

1980	2425 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1981	2421 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1982	2415 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1983	2411 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1984	2405 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1985	2401 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1986	2400 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1987	2404 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1988	2410 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1989	2414 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1990	2420 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1991	2424 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1992	2430 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1993	2434 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1994	2440 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1995	2450 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1996	2460 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	5/13/1905	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1997	2470 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1998	2480 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
1999	2490 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2000	2500 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2001	2504 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2002	2510 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2003	2514 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2004	2520 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2005	2530 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2006	2540 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2007	2550 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2008	2560 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2009	2570 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2010	2580 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2011	2590 BANTRY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/7/2024	Non-lead
2012	2585 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2013	2575 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2014	2565 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2015	2555 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2016	2545 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2017	2535 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2018	2525 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2019	2515 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2020	2501 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2021	2495 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2022	2485 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2023	2475 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2024	2465 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2025	2455 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2026	2435 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2027	2425 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2028	2415 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2029	2405 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2030	2401 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2031	2400 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2032	2410 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2033	2420 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2034	2430 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2035	2440 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2036	2450 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2037	2460 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2038	2470 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2039	2480 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2040	2490 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2041	2500 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2042	2504 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2043	2510 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2044	2520 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2045	2530 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2046	2540 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2047	2550 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2048	2560 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2049	2570 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2050	2580 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2051	2590 ARDEE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/8/2024	Non-lead
2052	2585 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2053	2575 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2054	2565 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2055	2555 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2056	2545 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2057	2525 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2058	2515 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2059	2501 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2060	2495 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2061	2475 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2062	2465 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2063	2445 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2064	2435 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2065	2421 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2066	2415 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2067	2401 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2068	2400 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2069	2410 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2070	2420 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2071	2430 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2072	2440 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2073	2450 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2074	2460 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2075	2470 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2076	2480 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2077	2490 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2078	2500 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2079	2510 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2080	2520 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2081	2540 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2082	2550 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2083	2560 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field

2084	2570 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2085	2580 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2086	2590 TARA LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2087	2206 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2088	2212 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2089	2218 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2090	2224 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2091	2230 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2092	2236 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2093	2242 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2094	2248 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2095	2254 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2096	2260 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2097	2266 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2098	2272 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2099	2278 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2100	2300 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2101	2304 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2102	2308 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2103	2312 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2104	2316 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2105	2320 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2106	2324 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2107	2328 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2108	2332 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2109	2336 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2110	2340 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2111	2344 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2112	2348 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2113	2352 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2114	2356 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2115	2368 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2116	2372 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2117	2376 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2118	2380 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2119	2410 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2120	2420 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2121	2500 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2122	2504 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2123	2510 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2124	2520 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2125	2530 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2126	2525 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2127	2515 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2128	2505 WENTWORTH DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2129	2450 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2130	2460 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2131	2470 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2132	2480 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2133	2490 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2134	2520 TURNBERRY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2135	2530 TURNBERRY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2136	2515 TURNBERRY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2137	2505 TURNBERRY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2138	2501 TURNBERRY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2139	2510 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2140	2520 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2141	2520 ST. CLOUD DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2142	2600 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2143	2604 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2144	2620 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2145	2630 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2146	2640 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2147	2650 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2148	2660 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2149	2670 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2150	2680 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2151	2700 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2152	2710 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2153	2720 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2154	2730 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2155	2740 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2156	2750 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2157	2760 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2158	2770 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2159	2500 ALBRIGHT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2160	2510 ALBRIGHT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2161	2518 ALBRIGHT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2162	2509 ALBRIGHT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2163	2501 ALBRIGHT WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2164	2800 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2165	2804 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2166	2810 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2167	2820 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2168	2830 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2169	2840 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2170	2850 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2171	2860 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2172	2870 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2173	2880 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2174	2890 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2175	2900 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2176	2908 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2177	2912 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2178	16 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2179	20 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2180	24 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2181	25 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2182	23 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2183	21 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2184	19 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2185	17 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2186	15 SUMMIT CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30

2188	2932 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2189	2940 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2190	2948 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2191	2956 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2192	2606 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2193	2608 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2194	2610 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2195	2612 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2196	2614 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2197	2616 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2198	2618 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2199	2619 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2200	2617 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2201	2615 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2202	2613 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2203	2611 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2204	2609 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2205	2607 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2206	2605 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2207	2603 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2208	2601 GELLERT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2209	11 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2210	12 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2211	13 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2212	14 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2213	15 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2214	16 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2215	17 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2216	18 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2217	19 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2218	20 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2219	21 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2220	22 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2221	23 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2222	24 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2223	25 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2224	26 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2225	27 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2226	28 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2227	29 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2228	30 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2229	31 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2230	32 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2231	33 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2232	34 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2233	35 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2234	36 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2235	37 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2236	38 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2237	39 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2238	40 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2239	41 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2240	42 VISTA CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/13/2024	Non-lead
2241	2965 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2242	2957 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2243	2949 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2244	2941 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2245	2933 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2246	2925 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2247	2917 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2248	2909 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2249	2901 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2250	2895 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2251	2885 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2252	2875 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2253	2865 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2254	2855 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2255	2845 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2256	2835 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2257	2825 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2258	2815 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2259	2805 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2260	2801 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2261	2775 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2262	2765 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2263	2755 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2264	2745 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2265	2735 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2266	2725 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2267	2701 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2268	2695 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2269	2685 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2270	2675 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2271	2655 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2272	2645 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2273	2635 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2274	2625 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2275	2615 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2276	2601 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2277	2575 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2278	2565 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2279	2555 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2280	2545 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2281	2535 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2282	2525 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2283	2515 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2284	2505 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2285	2501 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2286	2495 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2287	2485 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2288	2475 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2289	2465 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2290	2455 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2291	2445 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No

2292	2441 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2293	2435 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2294	2431 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2295	2425 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2296	2421 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2297	2415 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2298	2411 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2299	2405 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2300	2375 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2301	2353 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2302	2349 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2303	2345 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2304	2341 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2305	2337 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2306	2333 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2307	2329 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2308	2325 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2309	2313 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2310	2309 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2311	2305 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2312	2301 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2313	2291 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2314	2285 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2315	2279 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2316	2273 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2317	2267 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2318	2261 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2319	2255 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2320	2249 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2321	2243 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2322	2237 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2323	2231 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2324	2225 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2325	2219 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2326	2213 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2327	2207 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2328	2201 SHANNON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/23/2024	Non-lead
2329	2300 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2332	2320 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2333	2324 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2334	2330 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2335	2340 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2336	2350 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2337	2360 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2338	2370 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2339	2380 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2340	2390 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2341	2400 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2342	2404 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2343	2410 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2344	2414 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2345	2420 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2346	2430 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2347	2440 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2348	2450 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2349	2460 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2350	2470 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2351	2480 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2352	2490 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2353	2500 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2354	2520 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2355	2530 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2356	2525 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2357	2515 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2358	2505 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2359	2501 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2360	2495 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2361	2485 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2362	2475 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2363	2465 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2364	2445 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2365	2435 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2366	2431 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2367	2421 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2368	2415 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2369	2411 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2370	2405 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2371	2401 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2372	2391 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2373	2381 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2374	2371 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2375	2361 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2376	2351 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2377	2341 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2378	2331 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2379	2321 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2380	2309 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2381	2305 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2382	2301 OLYMPIC DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2383	2401 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2384	2415 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2385	2425 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2386	2455 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2387	2475 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2388	2485 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2389	2495 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2390	2501 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2391	2515 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2392	2525 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2393	2535 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2394	2545 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2395	2555 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2396	2565 GALWAY PL	S SAN FRAN., CA

2398	2480 GALWAY PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/9/2024	Non-lead
2399	3280 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2400	3260 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2401	3240 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2402	3220 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2403	3210 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2404	3200 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2405	3190 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2406	3180 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2407	3170 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2408	3160 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2409	3156 DUBLIN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2410	3152 DUBLIN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2411	3148 DUBLIN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2412	3144 DUBLIN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2413	3140 DUBLIN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2414	3136 DUBLIN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2415	3132 DUBLIN CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2416	3130 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2417	3120 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2418	3110 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2419	3100 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2420	3090 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2421	3080 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2422	3060 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2423	3050 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2424	3040 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2425	3020 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2426	3010 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2427	2990 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Plastic	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2428	2980 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2429	2970 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2430	2966 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2431	2960 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2432	2954 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2433	2948 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2434	2942 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2435	2934 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2436	2930 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2437	2926 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2438	2922 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2439	2914 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2440	2910 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2441	2904 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2442	2905 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2443	2911 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2444	2923 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2445	2927 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2446	2931 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2447	2937 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2448	2955 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2449	2961 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2450	2967 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2451	2981 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2452	3015 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2453	3025 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2454	2300 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2455	2310 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2456	2320 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2457	2330 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2458	2340 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2459	2350 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2460	2360 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2461	2370 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2462	2380 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2463	2390 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2464	2400 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2465	2410 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2466	2420 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2467	2430 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2468	2440 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2469	2450 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2470	2460 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2471	2470 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2472	2480 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2473	2485 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2474	2475 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2475	2465 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2476	2455 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2477	2445 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2478	2435 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2479	2425 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2480	2415 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2481	2401 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2482	2395 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2483	2385 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2484	2375 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2485	2365 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2486	2355 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2487	2345 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2488	2335 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2489	2325 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2490	2315 ERIN PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2491	3095 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2492	2305 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2493	2311 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2494	2315 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2495	2325 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2496	2335 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2497	2345 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2498	2355 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2499	2365 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2500	2375 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75

2502	2395 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2503	2390 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2504	2380 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2505	2370 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2506	2360 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2507	2350 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2508	2340 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2509	2330 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2510	2320 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2511	2310 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2512	2304 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2513	2300 BOURBON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/30/2024	Non-lead
2514	3135 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2515	3155 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2516	3175 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2517	3185 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2518	3195 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2519	3201 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2520	3215 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2521	3225 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2522	3245 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2523	3265 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2524	3275 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2525	3285 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	3/4'	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2526	3295 DUBLIN DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/11/2024	Non-lead
2527	2305 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2528	2311 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2529	2315 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2530	2319 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2531	2325 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2532	2331 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2533	2335 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2534	2345 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2535	2355 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2536	2365 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2537	2375 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2538	2385 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2539	2395 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2540	2401 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2541	2415 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2542	2425 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2543	2435 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2544	2445 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2545	2455 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2546	2465 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2547	2475 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2548	2501 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2549	2505 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2550	2511 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2551	2515 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2552	2525 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2553	2535 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2554	2545 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2555	2555 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2556	2565 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2557	2575 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2558	2585 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2559	2595 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2560	2601 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2561	2605 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2562	2615 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2563	2625 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2564	2635 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2565	2645 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2566	2655 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2567	2665 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2568	2675 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2569	2685 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2570	2695 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2571	2775 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2572	2785 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2573	2860 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2574	2830 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2575	2800 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2576	2790 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2577	2780 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2578	2770 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2579	2760 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2580	2740 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2581	2700 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2582	2690 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2583	2680 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2584	2670 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Galvanized	1960	2"	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2585	2660 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2586	2650 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2587	2640 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2588	2630 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2589	2626 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2590	2620 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2591	2616 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2592	2610 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2593	2604 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2594	2600 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2595	2590 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2596	2580 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2597	2570 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2598	2560 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2599	2550 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2600	2540 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2601	2530 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2602	2520 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2603	2510 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection

2606	2490 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2607	2480 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2608	2470 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2609	2460 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2610	2450 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2611	2440 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2612	2430 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2613	2420 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2614	2410 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2615	2402 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2616	2955 CARLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2617	2965 CARLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2618	2975 CARLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2619	2985 CARLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2620	2970 CARLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2621	2960 CARLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2622	2950 CARLOW WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2623	2380 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2624	2370 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2625	2360 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2626	2350 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2627	2340 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2628	2330 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2629	2320 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2630	2318 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2631	2316 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2632	2314 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2633	2310 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2634	2304 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
2635	2310 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2636	2320 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2637	2330 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2638	2340 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2639	2350 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2640	2360 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2641	2370 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2642	2380 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2643	2390 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2644	2400 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2645	2410 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2646	2420 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2647	2430 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2648	2440 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2649	2450 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2650	2460 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2651	2470 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2652	2480 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2653	2500 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2654	2510 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2655	2520 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2656	2530 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2657	2540 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2658	2550 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2659	2560 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2660	2570 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2661	2580 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2662	2590 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2663	2600 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2664	2604 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2665	2610 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2666	2620 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2667	2630 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2668	2640 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2669	2650 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2670	2660 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2671	2670 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2672	2680 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2673	2690 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2674	2695 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2675	2685 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2676	2675 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2677	2665 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2678	2655 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2679	2645 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2680	2635 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2681	2631 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2682	2625 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2683	2615 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2684	2611 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2685	2605 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2686	2601 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2687	2575 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2688	2565 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2689	2555 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2690	2535 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2691	2525 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2692	2515 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2693	2501 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2694	2485 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2695	2475 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2696	2465 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2697	2455 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2698	2445 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2699	2435 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2700	2425 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2701	2415 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2702	2401 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2703	2365 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2704	2355 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2705	2345 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2706	2341 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2707	2335 DONEGAL AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2708	2325 DONEGAL

2710	2200 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2711	2206 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2712	2212 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2713	2218 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2714	2224 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2715	2230 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2716	2236 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2717	2248 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2718	2254 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2719	2249 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2720	2243 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2721	2219 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2722	2213 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2723	2207 ARCHDALE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Non-lead
2724	2202 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/17/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2725	2208 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2726	2214 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2727	2220 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2728	2226 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2729	2232 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2730	2238 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2731	2235 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2732	2229 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2733	2223 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2734	2217 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2735	2211 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2736	2205 BARRINGTON CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2737	2202 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2738	2208 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2739	2214 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2740	2220 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2741	2230 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2742	2238 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2743	2237 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2744	2231 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2745	2219 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2746	2213 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2747	2207 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2748	2201 DOWNEY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/21/2024	Non-lead
2749	2200 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2750	2206 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2751	2212 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2752	2218 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2753	2224 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2754	2230 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2755	2236 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2756	2242 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2757	2280 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2758	2290 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2759	2300 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2760	2310 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2761	2320 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2762	2330 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2763	2340 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2764	2350 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2765	2360 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2766	2370 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2767	2380 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2768	2390 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2769	2400 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2770	2410 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2771	2420 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2772	2430 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2773	2440 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2774	2450 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2775	2460 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2776	2470 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2777	2480 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2778	2901 BURREN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2779	2905 BURREN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2780	2510 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2781	2520 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2782	2540 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2783	2550 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2784	2560 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2785	2570 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2786	2580 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2787	2600 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2788	2610 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2789	2620 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2790	2630 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2791	2640 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2792	2650 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2793	2660 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2794	2700 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2795	2710 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2796	2711 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2797	2701 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2798	2675 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2799	2669 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2800	2657 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2801	2645 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2802	2633 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2803	2621 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2804	2609 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2805	2601 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2806	2585 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2807	2571 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2808	2491 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2809	2485 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2810	2473 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2811	2461 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2812	2457 WEXFORD AV	S SAN FRAN

2814	2433 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2815	2421 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2816	2409 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2817	2401 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2818	2387 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2819	2361 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2820	2335 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2821	2333 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2822	2321 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2823	2309 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2824	2301 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2825	2285 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2826	2273 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2827	2261 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2828	2249 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2829	2237 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2830	2225 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2831	2213 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2832	2201 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
2833	2200 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2834	2204 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2835	2206 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2836	2208 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2837	2210 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2838	2212 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2839	2216 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2840	2218 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2841	2220 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2842	2222 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2843	2224 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2844	2226 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2845	2228 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2846	2230 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2847	2234 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2848	2236 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2849	2238 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2850	2242 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2851	2244 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2852	2246 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2853	2250 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2854	2252 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2855	2254 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2856	2256 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2857	2258 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2858	2260 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2859	2262 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2860	2264 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2861	2266 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2862	2268 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2863	2270 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2864	2272 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2865	2273 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2866	2271 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2867	2269 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2868	2267 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2869	2265 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2870	2263 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2871	2261 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2872	2259 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2873	2257 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2874	2253 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2875	2251 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2876	2247 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2877	2225 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2878	2223 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2879	2221 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2880	2219 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2881	2217 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2882	2215 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2883	2211 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2884	2209 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2885	2207 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2886	2205 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2887	2201 KENRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2888	2200 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2889	2206 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2890	2212 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2891	2218 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2892	2224 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2893	2230 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2894	2236 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2895	2242 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2896	2248 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2897	2254 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2898	2260 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2899	2266 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2900	2272 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2901	2278 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2902	2284 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2903	2290 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2904	2267 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2905	2261 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2906	2255 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2907	2249 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2908	2243 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2909	2237 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Galvanized	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2910	2231 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2911	2225 DERRY WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/31/2024	Non-lead
2912	2200 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2913	2204 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2914	2208 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2915	2212 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2916	2216 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2917	2220 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960

2918	2224 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2919	2228 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2920	2232 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2921	2236 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2922	2240 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2923	2246 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2924	2248 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2925	2252 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2926	2256 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2927	2260 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2928	2264 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2929	2268 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2930	2272 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2931	2276 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2932	2280 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2933	2284 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2934	2288 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2935	2299 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2936	2297 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2937	2293 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2938	2289 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2939	2285 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2940	2281 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2941	2277 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2942	2241 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2943	2231 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2944	2225 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2945	2221 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2946	2217 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2947	2213 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2948	2207 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2949	2201 DELVIN WY	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	5/29/2024	Non-lead
2950	2590 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2951	112 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2952	116 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2953	118 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2954	120 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2955	122 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2956	124 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2957	126 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2958	128 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2959	130 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2960	132 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2961	134 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2962	136 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2963	138 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2964	150 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2965	157 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2966	155 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2967	153 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2968	151 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2969	149 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2970	147 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2971	145 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2972	143 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2973	141 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2974	139 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2975	137 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2976	135 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2977	133 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2978	131 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2979	129 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2980	127 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2981	125 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2982	123 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2983	121 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2984	119 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2985	117 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2986	115 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2987	113 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2988	111 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2989	109 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2990	107 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2991	105 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2992	103 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2993	101 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
2994	100 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
2995	102 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
2996	104 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
2997	106 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
2998	108 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
2999	110 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3000	112 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3001	114 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3002	116 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3003	118 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3004	120 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3005	122 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3006	124 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3007	126 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3008	128 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3009	130 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3010	132 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3011	134 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3012	136 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3013	138 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3014	140 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3015	142 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3016	144 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3017	146 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3018	148 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3019	150 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3020	152 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3

3022	156 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3023	158 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3024	160 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3025	162 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3026	164 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3027	166 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3028	168 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3029	170 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3030	172 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3031	174 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3032	176 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3033	178 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3034	180 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3035	182 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3036	184 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3037	30 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3038	32 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3039	12 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3040	14 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3041	16 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3042	18 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3043	20 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3044	22 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3045	24 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3046	23 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3047	19 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3048	17 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3049	15 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3050	13 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3051	36 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3052	38 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3053	40 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3054	42 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3055	44 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3056	46 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3057	47 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3058	45 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3059	43 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3060	41 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3061	39 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3062	37 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3063	35 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3064	33 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3065	31 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3066	29 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3067	27 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3068	25 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3069	23 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3070	21 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3071	19 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3072	17 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3073	15 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3074	13 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3075	11 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3076	10 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3077	12 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3078	14 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3079	16 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3080	18 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3081	20 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3082	19 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3083	17 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3084	13 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3085	11 CANYON CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3086	564 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3087	551 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3088	549 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3089	547 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3090	541 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3091	539 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3092	533 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3093	531 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3094	519 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3095	513 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3097	20 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3098	26 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3099	30 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3100	34 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3101	40 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3102	46 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3103	50 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3104	54 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3105	56 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3106	60 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3107	64 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3108	63 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3109	59 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3110	55 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3111	51 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3112	47 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3113	43 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3114	39 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3115	35 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3116	31 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3117	27 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3118	23 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3119	19 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3120	15 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3121	11 WAVERLY CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3122	502 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3123	506 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3124	510 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3125	514 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6

3127	520 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3128	524 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3130	538 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3131	542 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3132	546 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3133	10 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3134	12 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3135	16 SEVILLE WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3136	181 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3137	179 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3138	177 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3139	175 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3140	173 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3141	171 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3142	169 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3143	167 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3144	165 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3145	163 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3146	159 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3147	157 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3148	155 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3149	153 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3150	151 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3151	149 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3152	147 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3153	145 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3154	143 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3155	141 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3156	139 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3157	133 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3158	131 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3159	129 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3160	127 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3161	125 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3162	123 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3163	121 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3164	119 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3165	117 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3166	115 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3167	113 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3168	111 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3169	109 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3170	107 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3171	105 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3172	101 VALLEYVIEW WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3174	2296 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3205	2255 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3206	2255 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3210	2298 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3211	2300 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3212	2400 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3217	2350 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3219	2570 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	3	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3220	3500 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3221	3540 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3222	3560 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3224	3700 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3225	3700 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3247	3840 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3248	3840 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3249	3840 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3250	3964 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3251	3961 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3263	3440 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3264	3440 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3265	3440 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3267	3550 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3290	3541 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3296	2525 WEXFORD AV	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Plastic	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3300	1 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3301	35A APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3302	39B APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3303	39D APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3304	51D APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3305	39D APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3306	65A APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3307	61A APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3310	1 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1960	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1960	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3314	2679 MEATH DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1985	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1985	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3315	3515 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1985	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1985	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3353	2302 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3354	2304 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3355	2306 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3356	2308 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3358	2312 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3359	2314 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3360	2316 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3361	2318 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3362	2320 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3363	2322 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3364	2324 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3365	2326 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3366	2328 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3367	2330 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3368	2329 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3369	2327 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3370	2325 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3371	2323 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3372	2321 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3373	2319 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3374	2317 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3375	2315 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3376	2313 KRIS

3378	2309 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3379	2307 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3380	2305 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3381	2303 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3382	2402 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3383	2404 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3384	2406 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3385	2408 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3386	2410 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3387	2412 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3388	2414 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3389	2416 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3390	2409 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3391	2407 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3392	2405 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3393	2403 EMILY LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3394	2316 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3395	2318 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3396	2320 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3397	2322 KRISTIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3398	2319 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3399	2317 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3400	2315 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3401	2313 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3402	2311 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3403	2309 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3404	2307 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3405	2305 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3406	2303 JULIE LN	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1987	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1987	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3410	2380 GALWAY DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1988	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1988	2"	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3418	16 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1991	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1991	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3419	18 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1991	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1991	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3420	22 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1991	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1991	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3424	3451 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1994	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1994	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3430	3963-D CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1994	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1994	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3431	3963-E CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1994	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1994	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3432	23 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1994	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1994	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3433	11 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1994	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1994	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3434	17 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1994	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1994	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3435	19 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1994	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1994	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3436	3475 OAKMONT DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3437	21 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3438	15 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3439	9 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3440	7 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3441	5 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3442	3 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3443	1 SUNRISE CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/10/2024	Non-lead
3444	33 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3445	31 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3446	29 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3447	27 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3448	25 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3449	23 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3450	21 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3451	19 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3452	17 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3453	15 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3454	11 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3455	9 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3456	7 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3457	3 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3458	2 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3459	6 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3460	8 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3461	10 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3462	18 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3463	20 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3464	22 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3465	24 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3466	26 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3467	28 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3468	30 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3469	32 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3470	34 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3471	36 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3472	41 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3473	39 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3474	37 MOONLIGHT CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1995	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1995	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3477	3885 CARTER DR #202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3478	3885 CARTER DR #302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3479	3885 CARTER DR #102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3480	3885 CARTER DR #301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3481	3885 CARTER DR #101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3482	3885 CARTER DR #201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3483	3885 CARTER DR #103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3484	3885 CARTER DR #303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3485	3885 CARTER DR #203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3486	3885 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3487	3885 CARTER DR #306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3488	3885 CARTER DR #206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3489	3885 CARTER DR #106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3490	3885 CARTER DR #207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3491	3885 CARTER DR #107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3492	3885 CARTER DR #307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3493	3885 CARTER DR #304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3494	3885 CARTER DR #104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3495	3885 CARTER DR #204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3496	3885 CARTER DR #205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3497	3885 CARTER DR #105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3498	3885 CARTER DR #305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3499	3855 CARTER DR #103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75

3502	3855 CARTER DR #102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3503	3855 CARTER DR #302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3504	3855 CARTER DR #202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3505	3855 CARTER DR #101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3506	3855 CARTER DR #201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3507	3855 CARTER DR #301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3508	3855 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3509	3855 CARTER DR #107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3510	3855 CARTER DR #207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3511	3855 CARTER DR #307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3512	3855 CARTER DR #106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3513	3855 CARTER DR #206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3514	3855 CARTER DR #306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3515	3855 CARTER DR #205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3516	3855 CARTER DR #204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3517	3855 CARTER DR #105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3518	3855 CARTER DR #304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3519	3855 CARTER DR #305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3520	3855 CARTER DR #104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3521	3885 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1996	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3524	2 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3525	6 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3526	8 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3527	10 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3528	12 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3529	16 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3530	18 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3531	20 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3532	22 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3533	26 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3534	28 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3535	30 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3536	32 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3537	36 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3538	50 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3539	52 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3540	56 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3541	60 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3542	62 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3543	61 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3544	59 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3545	55 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3546	51 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3547	39 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3548	37 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3549	35 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3550	33 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3551	31 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3552	29 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3553	27 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3554	25 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3555	23 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3556	21 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3557	19 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3558	17 BUENA VISTA RD	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3559	3865 CARTER DR #107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3560	3865 CARTER DR #207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3561	3865 CARTER DR #307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3562	3865 CARTER DR #104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3563	3865 CARTER DR #204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3564	3865 CARTER DR #304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3565	3865 CARTER DR #106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3566	3865 CARTER DR #206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3567	3865 CARTER DR #306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3568	3865 CARTER DR #305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3569	3865 CARTER DR #205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3570	3865 CARTER DR #105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3571	3865 CARTER DR #101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3572	3865 CARTER DR #201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3573	3865 CARTER DR #301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3574	3865 CARTER DR #102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3575	3865 CARTER DR #202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3576	3865 CARTER DR #302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3577	3865 CARTER DR #103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3578	3865 CARTER DR #203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3579	3865 CARTER DR #303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1999	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	1999	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3587	3875 CARTER DR #204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3588	3875 CARTER DR #304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3589	3875 CARTER DR #104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3590	3875 CARTER DR #206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3591	3875 CARTER DR #107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3592	3875 CARTER DR #207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3593	3875 CARTER DR #307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3594	3875 CARTER DR #306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3595	3875 CARTER DR #305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3596	3875 CARTER DR #106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3597	3875 CARTER DR #205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3598	3875 CARTER DR #105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3599	3875 CARTER DR #101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3600	3875 CARTER DR #201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3601	3875 CARTER DR #301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3602	3875 CARTER DR #202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3603	3875 CARTER DR #102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3604	3875 CARTER DR #302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3605	3875 CARTER DR #303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3606	3875 CARTER DR #203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3607	3875 CARTER DR #103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2001	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2001	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3608	2280 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2002	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2002	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3609	2280 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2002	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2002	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3610	3228 ST. PATRICK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3611	3232 ST. PATRICK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3612	3236 ST. PATRICK CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003

3615	5227 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3616	5229 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3617	5233 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3618	5232 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3619	5228 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3620	5226 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3621	5222 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3622	5208 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3623	5206 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3624	5202 BELFAST CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3625	7207 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3626	7209 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3627	7223 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3628	7227 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3629	7229 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3630	7233 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3631	7235 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3632	7237 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3633	7239 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3634	7238 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3635	7236 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3636	7232 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3637	7228 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3638	7226 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3639	7222 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3640	7208 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3641	7206 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3642	7202 SHANNON PARK	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2003	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
3646	3721 CARTER DR#2102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3647	3721 CARTER DR#2202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3648	3721 CARTER DR#2302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3649	3721 CARTER DR#2103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3650	3721 CARTER DR#2203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3651	3721 CARTER DR#2303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3652	3721 CARTER DR#2104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3653	3721 CARTER DR#2204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3654	3721 CARTER DR#2304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3655	3721 CARTER DR#2105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3656	3721 CARTER DR#2205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3657	3721 CARTER DR#2305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3658	3721 CARTER DR#2306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3659	3721 CARTER DR#2206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3660	3721 CARTER DR#2106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3661	3721 CARTER DR#2107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3662	3721 CARTER DR#2207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3663	3721 CARTER DR#2307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3664	3721 CARTER DR#2308	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3665	3721 CARTER DR#2208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3666	3721 CARTER DR#2108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3667	3721 CARTER DR#2309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3668	3721 CARTER DR#2209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3669	3721 CARTER DR#2109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3670	3721 CARTER DR#2201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3671	3721 CARTER DR#2101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3673	3721 CARTER DR#1108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3674	3721 CARTER DR#1208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3675	3721 CARTER DR#1308	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3676	3721 CARTER DR#1109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3677	3721 CARTER DR#1209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3678	3721 CARTER DR#1309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3679	3721 CARTER DR#1201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3680	3721 CARTER DR#1101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3681	3721 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3682	3721 CARTER DR#1102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3683	3721 CARTER DR#1202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3684	3721 CARTER DR#1302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3685	3721 CARTER DR#1103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3686	3721 CARTER DR#1203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3687	3721 CARTER DR#1303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3688	3721 CARTER DR#1104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3689	3721 CARTER DR#1204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3690	3721 CARTER DR#1304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3691	3721 CARTER DR#1105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3692	3721 CARTER DR#1205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3693	3721 CARTER DR#1305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3694	3721 CARTER DR#1106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3695	3721 CARTER DR#1206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3696	3721 CARTER DR#1306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3697	3721 CARTER DR#1307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3698	3721 CARTER DR#1207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3699	3721 CARTER DR#1107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Copper	2004	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
3700	2200 GELLERT #6411	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3701	2200 GELLERT #6311	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3702	2200 GELLERT #6211	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3703	2200 GELLERT #6111	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3704	2200 GELLERT #6212	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3705	2200 GELLERT #6412	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3706	2200 GELLERT #6312	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3707	2200 GELLERT #6112	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3708	2200 GELLERT #6409	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3709	2200 GELLERT #6309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3710	2200 GELLERT #6209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3711	2200 GELLERT #6109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3712	2200 GELLERT #6410	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3713	2200 GELLERT #6310	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3714	2200 GELLERT #6210	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3715	2200 GELLERT #6110	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3716	2200 GELLERT #6108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3717	2200 GELLERT #6208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3718	2200 GELLERT #6207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3719	2200 GELLERT #6407	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3720	2200 GELLERT #6408	S SA

3723	2200 GELLERT #6307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3724	2200 GELLERT #6102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3725	2200 GELLERT #6202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3726	2200 GELLERT #6302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3727	2200 GELLERT #6402	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3728	2200 GELLERT #6301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3729	2200 GELLERT #6401	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3730	2200 GELLERT #6201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3731	2200 GELLERT #6101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3732	2200 GELLERT #6404	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3733	2200 GELLERT #6304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3734	2200 GELLERT #6204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3735	2200 GELLERT #6104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3736	2200 GELLERT #6103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3737	2200 GELLERT #6203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3738	2200 GELLERT #6303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3739	2200 GELLERT #6403	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3740	2200 GELLERT #6105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3741	2200 GELLERT #6205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3742	2200 GELLERT #6305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3743	2200 GELLERT #6405	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3744	2200 GELLERT #6406	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3745	2200 GELLERT #6306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3746	2200 GELLERT #6206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3747	2200 GELLERT #6106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3748	2210 GELLERT #5411	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3749	2210 GELLERT #5311	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3750	2210 GELLERT #5211	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3751	2210 GELLERT #5111	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3752	2210 GELLERT #5412	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3753	2210 GELLERT #5312	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3754	2210 GELLERT #5212	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3755	2210 GELLERT #5112	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3756	2210 GELLERT #5109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3757	2210 GELLERT #5409	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3758	2210 GELLERT #5309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3759	2210 GELLERT #5209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3760	2210 GELLERT #5410	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3761	2210 GELLERT #5310	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3762	2210 GELLERT #5210	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3763	2210 GELLERT #5110	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3764	2210 GELLERT #5108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3765	2210 GELLERT #5208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3766	2210 GELLERT #5307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3767	2210 GELLERT #5407	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3768	2210 GELLERT #5408	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3769	2210 GELLERT #5308	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3770	2210 GELLERT #5107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3771	2210 GELLERT #5207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3772	2210 GELLERT #5102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3773	2210 GELLERT #5202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3774	2210 GELLERT #5302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3775	2210 GELLERT #5402	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3776	2210 GELLERT #5201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3777	2210 GELLERT #5301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3778	2210 GELLERT #5401	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3779	2210 GELLERT #5101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3780	2210 GELLERT #5404	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3781	2210 GELLERT #5304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3782	2210 GELLERT #5204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3783	2210 GELLERT #5104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3784	2210 GELLERT #5103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3785	2210 GELLERT #5203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3786	2210 GELLERT #5403	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3787	2210 GELLERT #5303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3788	2210 GELLERT #5105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3789	2210 GELLERT #5205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3790	2210 GELLERT #5206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3791	2210 GELLERT #5106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3792	2210 GELLERT #5405	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3793	2210 GELLERT #5305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3794	2210 GELLERT #5306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3795	2210 GELLERT #5406	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2006	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2006	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3796	2220 GELLERT #4411	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3797	2220 GELLERT #4112	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3798	2220 GELLERT #4311	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3799	2220 GELLERT #4212	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3800	2220 GELLERT #4111	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3801	2220 GELLERT #4412	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3802	2220 GELLERT #4211	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3803	2220 GELLERT #4312	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3804	2220 GELLERT #4110	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3805	2220 GELLERT #4210	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3806	2220 GELLERT #4310	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3807	2220 GELLERT #4410	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3808	2220 GELLERT #4409	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3809	2220 GELLERT #4309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3810	2220 GELLERT #4209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3811	2220 GELLERT #4109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3812	2220 GELLERT #4107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3813	2220 GELLERT #4207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3814	2220 GELLERT #4307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3815	2220 GELLERT #4407	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3816	2220 GELLERT #4408	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3817	2220 GELLERT #4308	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3818	2220 GELLERT #4208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3819	2220 GELLERT #4108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3820	2220 GELLERT #4101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3821	2220 GELLERT #4201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3822	2220 GELLERT #4301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3823	2220 GELLERT #4401	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at

3827	2220 GELLERT #4102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3828	2220 GELLERT #4403	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3829	2220 GELLERT #4303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3830	2220 GELLERT #4203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3831	2220 GELLERT #4103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3832	2220 GELLERT #4104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3833	2220 GELLERT #4204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3834	2220 GELLERT #4304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3835	2220 GELLERT #4404	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3836	2220 GELLERT #4405	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3837	2220 GELLERT #4305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3838	2220 GELLERT #4205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3839	2220 GELLERT #4105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3840	2220 GELLERT #4106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3841	2220 GELLERT #4206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3842	2220 GELLERT #4306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3843	2220 GELLERT #4406	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3845	2230 GELLERT #3411	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3846	2230 GELLERT #3311	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3847	2230 GELLERT #3412	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3848	2230 GELLERT #3312	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3849	2230 GELLERT #3110	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3850	2230 GELLERT #3210	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3851	2230 GELLERT #3310	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3852	2230 GELLERT #3410	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3853	2230 GELLERT #3408	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3854	2230 GELLERT #3308	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3855	2230 GELLERT #3208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3856	2230 GELLERT #3108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3857	2230 GELLERT #3409	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3858	2230 GELLERT #3309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3859	2230 GELLERT #3209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3860	2230 GELLERT #3109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3861	2230 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3862	2230 GELLERT #3407	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3863	2230 GELLERT #3307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3864	2230 GELLERT #3207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3865	2230 GELLERT #3107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3866	2230 GELLERT #3403	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3867	2230 GELLERT #3303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3868	2230 GELLERT #3203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3869	2230 GELLERT #3103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3870	2230 GELLERT #3401	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3871	2230 GELLERT #3301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3872	2230 GELLERT #3201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3873	2230 GELLERT #3101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3874	2230 GELLERT #3104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3875	2230 GELLERT #3204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3876	2230 GELLERT #3304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3877	2230 GELLERT #3404	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3878	2230 GELLERT #3102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3879	2230 GELLERT #3202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3880	2230 GELLERT #3302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3881	2230 GELLERT #3402	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3883	2230 GELLERT #3205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3884	2230 GELLERT #3305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3885	2230 GELLERT #3405	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3886	2230 GELLERT #3106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3887	2230 GELLERT #3206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3888	2230 GELLERT #3306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3889	2230 GELLERT #3406	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3890	21 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3891	21 CHATEAU CT	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-Lead - Plastic	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3892	2200 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/3/2024	Non-lead
3893	2210 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3894	2220 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3895	2250 GELLERT #2411	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3896	2250 GELLERT #2311	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3897	2250 GELLERT #2211	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3898	2250 GELLERT #2111	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3899	2250 GELLERT #2412	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3900	2250 GELLERT #2312	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3901	2250 GELLERT #2212	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3902	2250 GELLERT #2112	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3903	2250 GELLERT #2110	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3904	2250 GELLERT #2210	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3905	2250 GELLERT #2310	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3906	2250 GELLERT #2410	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3907	2250 GELLERT #2108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3908	2250 GELLERT #2208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3909	2250 GELLERT #2308	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3910	2250 GELLERT #2408	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3911	2250 GELLERT #2109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3912	2250 GELLERT #2209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3913	2250 GELLERT #2409	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3914	2250 GELLERT #2309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3915	2250 GELLERT #2107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3916	2250 GELLERT #2207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3917	2250 GELLERT #2307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3918	2250 GELLERT #2407	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3919	2250 GELLERT #2103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3920	2250 GELLERT #2401	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3921	2250 GELLERT #2301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3922	2250 GELLERT #2201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3923	2250 GELLERT #2101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3924	2250 GELLERT #2404	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3925	2250 GELLERT #2102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3926	2250 GELLERT #2202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3927	2250 GELLERT #2302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3928	2250 GELLERT #2402	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3929	2250 GELLERT #2403	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024

3933	2250 GELLERT #2405	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3934	2250 GELLERT #2306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3935	2250 GELLERT #2406	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3936	2250 GELLERT #2104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3937	2250 GELLERT #2204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3938	2250 GELLERT #2304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3939	2250 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3940	3988 FLEETWOOD DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3941	3988 FLEETWOOD DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3942	2260 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3943	2260 GELLERT #1411	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3944	2260 GELLERT #1311	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3945	2260 GELLERT #1211	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3946	2260 GELLERT #1111	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3947	2260 GELLERT #1412	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3948	2260 GELLERT #1312	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3949	2260 GELLERT #1212	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3950	2260 GELLERT #1112	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3951	2260 GELLERT #1110	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3952	2260 GELLERT #1210	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3953	2260 GELLERT #1310	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3954	2260 GELLERT #1410	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3955	2260 GELLERT #1108	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3956	2260 GELLERT #1208	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3957	2260 GELLERT #1308	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3958	2260 GELLERT #1408	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3959	2260 GELLERT #1109	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3960	2260 GELLERT #1209	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3961	2260 GELLERT #1309	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3962	2260 GELLERT #1409	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3963	2260 GELLERT #1107	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3964	2260 GELLERT #1207	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3965	2260 GELLERT #1307	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3966	2260 GELLERT #1407	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3967	2260 GELLERT #1101	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3968	2260 GELLERT #1201	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3969	2260 GELLERT #1301	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3970	2260 GELLERT #1401	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3971	2260 GELLERT #1402	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3972	2260 GELLERT #1302	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3973	2260 GELLERT #1202	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3974	2260 GELLERT #1102	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3975	2260 GELLERT #1103	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3976	2260 GELLERT #1203	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3977	2260 GELLERT #1303	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3978	2260 GELLERT #1403	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3979	2260 GELLERT #1104	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3980	2260 GELLERT #1204	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3981	2260 GELLERT #1304	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3982	2260 GELLERT #1404	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3983	2260 GELLERT #1105	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3984	2260 GELLERT #1205	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3985	2260 GELLERT #1305	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3986	2260 GELLERT #1405	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3987	2260 GELLERT #1406	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3988	2260 GELLERT #1306	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3989	2260 GELLERT #1206	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3990	2260 GELLERT #1106	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3991	2222 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2008	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2008	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3992	3855 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1996	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1996	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3994	2255 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1986	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1986	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3996	2200 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	1997	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3997	2210 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3998	2220 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
3999	2230 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4000	2250 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4001	2260 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2007	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4002	2280 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2002	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2002	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4003	2400 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2001	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2001	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4004	3500 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1991	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	1991	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4005	3540 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1991	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	1991	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4010	3840 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1984	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	1984	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4013	1 APPIAN WY	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	1984	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Plastic	1984	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4014	3721 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2004	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2004	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4017	3440 CARTER DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	1984	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	1984	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4018	534 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
4019	534 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
4020	536 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
4021	536 AVALON DR	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-Lead - Plastic	2013	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/4/2024	Non-lead
4023	2248 WESTBOROUGH BL #601	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2012	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Plastic	2012	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4025	2248 WESTBOROUGH BL #603	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2012	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Plastic	2012	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4026	2238 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2012	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Plastic	2012	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4028	2288 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2014	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Plastic	2014	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4029	2228 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2014	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Plastic	2014	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4030	2268 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2014	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Plastic	2014	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4031	2385 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2014	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2014	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4032	2310 TIPPERARY AV	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2015	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2015	0.75	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4033	3573 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4034	3573 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4035	2288 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4036	2268 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4037	2228 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4038	2238 WESTBOROUGH BL	S SAN FRAN., CA 94080	Non-Lead - Plastic	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/5/2024	Non-lead
4039	3581 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4040	3581 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4041	3535 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4042	3535 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4043	3581 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4044	3573 CALLAN BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-Lead - Copper	2016	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/13/2024	Non-lead
4045	2697 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4046	2685 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4047	2673 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Insp

4050	2625 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4051	2637 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4052	2661 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4053	3387 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4054	3381 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4055	3375 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4056	3369 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4057	3363 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4058	3357 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4059	3351 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4060	3337 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4061	3331 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4062	3325 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4063	3319 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4064	3313 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4065	3307 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4066	3301 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4067	2697 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4068	2685 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4069	2673 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4070	2601 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4071	2613 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4072	2625 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4073	2637 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4074	2661 BANTRY CT	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4075	3387 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4076	3381 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4077	3375 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4078	3369 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4079	3363 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4080	3357 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4081	3351 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4082	3337 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4083	3331 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4084	3325 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4085	3319 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4086	3313 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4087	3307 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4088	3301 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4089	3340 SHANNON PL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Plastic	2020	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4090	2233 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2021	1	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4091	2233 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4092	2233B GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4093	2233B GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4094	2233 GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead
4095	2233B GELLERT BL	S SAN FRAN., CA 94080	Non-Lead - Copper	No	No	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-Lead - Copper	2021	2	Field Inspection	Yes	Visual Inspection at the meter pit	6/6/2024	Non-lead