

CR NUMBER 16.9244	ACCIDENT DATE 4.22.16	ACCIDENT TIME 1438	DAY OF WEEK Friday	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 919 N. Mantua St.				WEATHER No Adverse
VEHICLE NO. 1		VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB Stranathan, Karen M. 5.18.73	DRIVER LAST FIRST MIDDLE DOB			
ADDRESS 1048 Deleone Dr.	ADDRESS			
CITY, STATE, ZIP PHONE NUMBER Kent OH 44240 330-328-6240	CITY, STATE, ZIP PHONE NUMBER			
DRIVER'S LICENSE NUMBER STATE RN560189 OH	DRIVER'S LICENSE NUMBER STATE			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Same	VEHICLE OWNER'S NAME LAST FIRST MIDDLE			
ADDRESS	ADDRESS			
CITY, STATE ZIP PHONE NUMBER	CITY, STATE, ZIP PHONE NUMBER			
VEHICLE YEAR MAKE MODEL COLOR 2014 Toyota Corolla Blue	VEHICLE YEAR MAKE MODEL COLOR			
LICENSE PLATE NUMBER STATE GBM7370 OH	LICENSE PLATE NUMBER STATE			
INSURANCE COMPANY Progressive Policy #901318139	INSURANCE COMPANY			
PARTS OF <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT VEHICLE DAMAGED All Parts Damaged	PARTS OF <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT VEHICLE DAMAGED			
DESCRIBE HOW ACCIDENT OCCURRED Vehicle #1 was driving in an Eastbound direction through the parking lot of 919 N. Mantua St. Vehicle #1 drove off the edge of the parking lot, through some brush and trees, and over a cliff. Vehicle #1 landed on its roof in the river and was facing West. The driver of Unit #1 was extracted from the river by the Kent F.D. The driver refused to talk without her attorney. The vehicle was towed from the river by Falls & Stebbins, then was towed to impound by Plaza Towing.				
OFFICER /SUPERVISOR SIGNATURE T. Cole / Sgt. [Signature] #255		SKETCH HOW ACCIDENT OCCURRED 		