


CR NUMBER 17-10067	ACCIDENT DATE 5-10-17	ACCIDENT TIME 1626	DAY OF WEEK WED.	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 319 S. Water St. Kent, OH 44240				WEATHER Clear
VEHICLE NO. 1		VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB Ritenour Tomi D. 3-29-51	DRIVER LAST FIRST MIDDLE DOB			
ADDRESS 321 N. Depeyster St.	ADDRESS			
CITY, STATE, ZIP Kent, OH 44240	PHONE NUMBER (330) 676-7600		CITY, STATE, ZIP	
DRIVER'S LICENSE NUMBER RM950868	STATE		DRIVER'S LICENSE NUMBER	
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Kent City School District		VEHICLE OWNER'S NAME LAST FIRST MIDDLE		
ADDRESS 321 N. Depeyster St.		ADDRESS		
CITY, STATE ZIP Kent, OH 44240		PHONE NUMBER (330) 676-6700		
VEHICLE YEAR MAKE MODEL COLOR 2011 Thomas BUS Yellow	VEHICLE YEAR MAKE MODEL COLOR			
LICENSE PLATE NUMBER STATE 07173 OH	LICENSE PLATE NUMBER STATE			
INSURANCE COMPANY		INSURANCE COMPANY		
PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input checked="" type="checkbox"/> LEFT <input type="checkbox"/> RIGHT 		PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT		
DESCRIBE HOW ACCIDENT OCCURRED Unit #1 was traveling through the parking lot on the east side of The Kent Police Dept. Unit #1 struck the radio tower located in the northwest corner of the parking lot. Unit #1 sustained minor damage. No damage was observed on the radio tower.				
OFFICER / SUPERVISOR SIGNATURE Ph. Bowen #214 / [Signature] 212		SKETCH HOW ACCIDENT OCCURRED		
		