

ਦਫ਼ਤਰ : ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮਾਨਸਾ।

ਟੈਲੀਫੋਨ/ਫੈਕਸ ਨੰ: 01652-232119

Email ID :- xen.mansa@gmail.com

ਪੱਤਰ ਨੰ.....4315

ਮਿਤੀ.....17.10.2023

ਵੱਲ,

ਪ੍ਰਿੰਸੀਪਲ,
ਦਸਮੇਸ਼ ਇੰਟਰਨੈਸ਼ਨਲ ਸਕੂਲ,
ਸਰਦੂਲਗੜ੍ਹ(ਮਾਨਸਾ)।


ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ। (ਸਾਲ 2022-23)

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰ. DIS/0081 ਮਿਤੀ 14/10/2022

ਤੁਹਾਡੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਇੰਚਾਰਜ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ। ਨਿਰੀਖਣ ਦੌਰਾਨ ਪਾਇਆ ਗਿਆ ਕਿ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ ਹੈ। ਇਸ ਲਈ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ 31/03/2023 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਨੱਥੀ/ ਸਰਟੀਫਿਕੇਟ


ਅਤੇ ਨਕਸ਼ਾ।


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ, ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 2 ਮਾਨਸਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 3650 ਮਿਤੀ 30/11/2022 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਰਿਪੋਰਟ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ

PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART-1

(To be filled by Head of the School/Institution)

- 1 Name of School : Dasmesh International School
- 2 Location : Khaira Road, Sardulgarh.
- 3 Plot Area : _____
- 4 Plinth Area : GF-14932 FF 14932 Sqfts. MA-752.5
- 5 Number of Stories : 02 Total 30616.5 SqFt
- 6 Year of Construction of Building : 2018 Sqfts
- 7 If the building has been constructed under the supervision of the qualified engineer, the following details may be given
- (A) Name of the Engineer with Qualification : Ashutosh Mittal B-tech (Civil)
- (b) Address of Engineer : Near Bohar wale chowk 'Maumandi'
- (C) Set of structural Drawing used in the Construction, if available : yes
- (d) Name & address of architect with qualification : Ashutosh mittal B-Tech (Civil)
- 8 Whether the building has been construed for the purpose of
- (a) School : Yes/No
- (b) Residential purpose & converted for use as a school : Yes/No
- 9 Whether used for Roof :
- (A) R.C.C. Slabs : Yes/No
- (b) R.S. Joists & Batons : Yes/No
- (C) Wooden joists & Batons : Yes/No
- (d) Arch (Brick) : _____
- 10 Material used for walls
- (a) Mud mortar : Yes/No
- (b) Cement Mortar : Yes/No
- (C) Plaster i. Lime Mortar : Yes/No
- ii. Cement Mortar : Yes/No
- 11 Flooring
- (a) Conglomerate : Yes/No
- (b) Perrazo : Yes/No
- (c) Brick/Paving : Yes/No
- 12 A detailed drawing indicating dimension of the room alongwith size and location of door and windows (attached).

B. Khilata

Principal
Dasmesh International School
Sardulgarh (Mansa)
Aff. No.-1631350 School Code-21393
Signature of the Head with seal

Building Safety Report (PART-II)


NAME OF SCHOOL:- Dasmesh International School, Sardulgarh


(District- MANSa)

As per report of Sh. Manjeet Singh Junior Engineer on his visually inspection on dated 04.01.2023 the above mentioned school seems visually safe subject to the following observations and conditions.

1. The Parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available
2. In case any addition, alteration, expansion and modification to this building are required/to be done, regarding this, inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the school building 30616.5.sft which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2022-2023 Rs.Ten Thousand only vide GR. No. 2843501 Dated 06.12.2022
11. Fire safety Certificate is valid till 28.09.2023 and School will be responsible to get renewed fire safety Certificate within time limit.

As per visually inspection as reported by the concerned Junior Engineer the above building may be used for normal use up to 31.03.2023 Subject to the above conditions.


Junior Engineer


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋ: ਨਿ: ਵਿ:
ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਮਾਨਸਾ ।